

# LOH HENG

Automotive Repair Services  
Accident Insurance Claims

12-May-17

INDIA International Insurance Ptd Ltd

Singapore

Attn. : Motor Claim Department

Re : Estimated Quotation

Vehicle No. : SJG4308G Audi A5

Not Authorized  
1. B. 1  
Rehmy B. 1  
3 days

| S/N      | Description                                                  | Amount (\$S)       |
|----------|--------------------------------------------------------------|--------------------|
| <b>A</b> | <b>PART REPLACEMENT</b>                                      |                    |
|          | Rear bumper                                                  | \$ 1,347.00        |
|          | Rear bumper reinforcement                                    | \$ 756.00          |
|          | Rear bumper reverse sensor                                   | \$ 253.00          |
|          | Rear bumper spoiler                                          | \$ 289.00          |
|          |                                                              | \$ 2,645.00        |
|          | Less 5%                                                      | \$ 2,512.75        |
| <b>B</b> | <b>LABOUR CHARGES</b>                                        |                    |
|          | To remove and replace damaged parts and knock out tail panel | \$ 450.00          |
|          | To respray + putty on the replacement parts                  | \$ 680.00          |
|          | Sub-total                                                    |                    |
|          | <b>GRAND TOTAL OF A &amp; B</b>                              | <b>\$ 3,642.75</b> |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Block 176 #03-08 Sin Ming Autocare  
Sin Ming Drive  
Singapore 575721  
Tel : 64532237 / 64530797  
Fax : 64556384