

Please arrange to survey vehicle at
8 KAKI BUKIT AVENUE 4 - GATE 2
#07-48 PREMIER @ KAKI BUKIT
SINGAPORE 415875

ABWIN 諭輝

08/12/17 @ 1230hrs In

marion's Survey

LINDA LIAO
ABWIN SERVICE PTE LTD
DID: 67139417
Fax: 67139415
HP: 97519596

Date : 01/12/2017
TP Vehicle No. : SJM-8666-P
To : ECICS LIMITED
Attn : Motor Claim Department

Owner : ANMANI GENERAL CONSTRUCTION PTE LTD
NTUC INCOME INSURANCE CO-OPERATIVE LTD
Certificate No. : 200813721M
Vehicle No. : SLN-6519-R
Make & Model : HONDA VEZEL 1.5X A

Accident Date: 30/11/2017

Not Accident
all
taken place before party. 2/2 \$

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
-----	-------------	---------------	---------------

List Item

1	TAILGATE EMBLEM	vezel 8/12/17	35.00	✓
1	TAILGATE	3.5.5.0	953.60	✓
1	TAILGATE TOP GARNISH	11	720.00	X
1	TAILGATE LAMP RH	11	250.00	X
1	TAILGATE LAMP LH	11	250.00	X
1	TAILGATE WEATHERSTRIP		250.00	?
1	TAILGATE INNER TRIMBOARD		250.00	?
10	TAILGATE INNER TRIMBOARD CLIPS		50.00	?
1	REAR WINDSCREEN MOULDING	11	150.00	✓
1	REAR FENDER RH	11	950.00	X
1	REAR FENDER LH	11	1,250.00	X
1	REAR FENDER INNER SHIELD RH	11	285.00	X
1	REAR FENDER INNER SHIELD LH	11	285.00	X
1	TAILLAMP RH	11	580.60	X
1	TAILLAMP LH	11	580.60	X
1	SPARE TYRE PANEL	11	1,530.00	X
1	SPARE TYRE PANEL INSULATOR	11	485.00	X
1	SPARE TYRE COMPARTMENT COVER & TYRE BOARD	11	260.90	X
10	SPARE TYRE INSULATOR CLIPS	11	50.00	X
1	REAR END PANEL	11	480.60	X
1	REAR END PANEL BRACKET RH	11	65.00	X
1	REAR END PANEL BRACKET LH	11	65.00	X
1	REAR BUMPER	De	762.70	✓
10	REAR BUMPER CLIPS	11	50.00	✓
1	REAR BUMPER RETAINER RH	11	45.00	X
1	REAR BUMPER RETAINER LH	11	45.00	X
1	REAR BUMPER REFLECTOR RH	11	185.40	X
1	REAR BUMPER REFLECTOR LH	11	185.40	X
1	EXHAUST HEAT SHIELD	11	156.00	X

LINDA LIAO
ABWIN SERVICE PTE LTD
DID: 67139417
Fax: 67139415
HP: 97519596

Date : 01/12/2017
TP Vehicle No. : SJM-8666-P
To : ECICS LIMITED
Attn : Motor Claim Department

Owner : ANMANI GENERAL CONSTRUCTION PTE LTD
NTUC INCOME INSURANCE CO-OPERATIVE LTD
Certificate No. : 200813721M
Vehicle No. : SLN-6519-R
Make & Model : HONDA VEZEL 1.5X A

Accident Date: 30/11/2017

ESTIMATED REPAIR COST DETAILS

QTY	DESCRIPTION	REPAIR AMOUNT	SURVEYOR APP.
	Sub Total	\$11,205.80	
	Discount 25% on Parts	(\$2,801.45)	
		\$8,404.35	

Special Nett

1 REAR REVERSE CAMERA
1 REAR REVERSE SENSOR
1 REAR NUMBER PLATE & CASEING
Sub Total

17 \$480.00 X
shnd \$350.00 2005.2
17 \$45.00 X
\$875.00

Labour & Misc

TO STAIGHTEN AND PANEL BEAT ACCIDENT AREAS
TO SPRAY PAINT ON AFFECTED AREAS
TO APPLY TUFF KOTE
TO TRANSFER ALL REAR TAILGATE FITTING
TO REMOVE & INSTALL REAR WINDSCREEN
TO CHECK ALL NECESSARY WIRINGS
TO CONDUCT INTERIOR TRIMBOARD
TO INSTALL REVERSE CAMERA AND CHECK FUNCTIONALITY
TO INSTALL REVERSE SENSOR & CHECK FUNCTIONALITY
Sub Total

\$1,500.00 400
\$1,500.00 500
\$60.00 30
\$250.00 60
\$150.00 120
\$150.00 20
\$150.00 60
\$250.00 50
\$250.00
\$4,260.00

Sub Total \$13,539.35
GST 7% \$947.75
Total \$14,487.10

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

ABWIN SERVICE PTE LTD, 8 KAKI BUKIT AVENUE 4 - GATE 2, #07-48 PREMIER @ KAKI BUKIT, SINGAPORE 415875