

# Premium Automobiles Pte Ltd



## VEHICLE SERVICE HISTORY

**Name of Owner:** Mr Shastry Ashish Jaiprakash

**NRIC No.:** S7581936F

**Registration No.:** SKB3988P

**Vehicle Model:** A8L D4 3.0

**Chassis No:** WAUZZZ4H4BN014701

**Registration Date:** 14/03/2011

Date	Mileage (km)	Description of Work
11-01-17	73682	Pkg 1 / 7th Service Maintenance Replaced rear brake pads & discs Replaced hydraulic pump Replaced intake hose  Complaint: Aircon not cold Found: Sensor for refrigerant pressure/temperature no signal Action: Replaced aircon pressure switch  Complaint: RHR door centre pillar rubber loose Found: As above Action: Resecure RHR door centre pillar rubber  Remarks: Spare tyre old age Gave 15% discount on parts as goodwill gesture
21-01-16	65868	Pkg 2 / 6th Service Maintenance Aircon Treatment Replaced valve cover gasket Replaced suspension guide bushes Replaced vibration damper replaced Replaced crankshaft vibration damper Replaced idler roller Replaced belt tension damper  Complaint: Vehicle overheating Found: Thermostat jammed Action: Replaced thermostat
03-12-15	64778	Complaint: Aircon blowing hot air Found: Activation a/c compressor implausible Action: Replaced water pump, valve, housing & wires
30-01-15	57333	Pkg 1 / 5th Service Maintenance Aircon Treatment Replaced front spring dampers Replaced engine mountings Replaced upper guide links Replaced remote key battery Topped up hydraulic oil (not enough)  Remark: Rear tyre worn out
23-01-14	48434	4th Service Maintenance Aircon Treatment Renew coolant Replaced spark plugs Replaced ATF Replaced dust & pollen filter Replaced both front tyres Patched up RHR tyre (goodwill gesture)
12-08-13	44274	Complaint: Vehicle jerky when driving at slow speed Found: Tested, never encountered Action: Re-set gearbox basic setting & performed adaptation drive

27-05-13	41849	Complaint: Vehicle jerky Found: Gearbox software low Action: Update gearbox software  Complaint: Left rear seat cannot adjust at times Found: Drive unit for backrest seat defective Action: Replaced drive unit  Complaint: Knocking noise when driving Found: Lower arm bush crack Action: Replaced lower arm bush and wishbone
15-04-13	40465	Complaint: EPC warning light on Found: Cyl. No. 4 misfire Action: Replaced ignition coil and spark plug cyl. 4
09-04-13	40207	3rd Service Maintenance Replaced wiper blade Replaced car battery Replaced remote key battery  Check & Found: Brake vacuum pump oil leak Action: Brake vacuum pump replaced
06-11-12	34555	Complaint: Bootlid cannot close Found: Lid latch mechanical defect Action: Replaced latch
17-05-12	27507	Complaint: Front wipers not working Found: Wiper motor faulty Action: Replaced wiper motor
30-03-12	25859	2nd Service Maintenance
29-03-12	25859	Complaint: Aircon not cold Found: Coolant thermostat jammed Action: Replaced thermostat
27-07-11	14365	1st Service Maintenance  Complaint: When shifting to 2nd gear upon going downhill, car jerks Found: Tested and checked, no jerks encountered and no fault found Action: Performed engine gearbox basic setting and adaptation drive and cleaned the engine compartment as necessary
30-05-11	14903*	Complaint: Rear aluminium door trim warped Found: Aluminium trim rear LHS panel dented, door trim scratched Action: Replaced rear LHS door panel trim assembly
13-05-11	4997	Complaint: Left rear door ashtray lid cannot open Found: Ashtray lid hinge mechanism jammed Action: Replaced left rear door ashtray unit

\* - wrong mileage recorded

Prepared on 4/12/2017