

ASS. REC. BY:

REF: CS/AGI17023080 / Uvbn2 Special Instruction:

Surveyor: MariusASSIGNMENT (Office)From (Person): Lincoln Yeo of AGI Date/Time: 2:59pm @ 5/12/17

Estimated Cost: \_\_\_\_\_ Bill to: \_\_\_\_\_

OD / ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: SGA 5935G Insured: SLC 5541 Pat Workshop m/s Progressive Auto Tel: 6844 4620of No. 1 Kaki Bukit Ave 6 Autobay # 02-48/50Policy No: P10009506R00 Claim No: C10001179

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

Make of Veh: \_\_\_\_\_ D.O.A. 1/12/17  
(Client's Record)CA / REV / REP. / REV 24 HRS 'up'

H.O.D. Endorsement: \_\_\_\_\_

Date/Time: 3:38pm @ 5/12/17 Person Contacted: Mandy Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SGA 5935G-CC6/AGI17023025/Uka3 D.O.A: 1/12/17
	SLC 5541P-CC6/AGI17023025/Uka3 D.O.A: 1/12/17
<u>7/12/17</u>	Email Lincoln informed pending est from repairer by email
<u>5/2/18</u>	Email preli revised to Lincoln by email

Stryker Mercu

REF:

AGI/

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SGA59356at Workshop m/s PA Luck

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 75k.

IDAC Accident Report: \_\_\_\_\_ Consistent?: Yes or No

GIA / PR Seen: 2 Consistent?: Yes or NoEst. Repairs: 20 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SGA59356 Yr Regn: 2/12/15Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /Truck / Trailer or CAMake: Mazda 2 C.G. 1496Colour: Grey A/C: Insured / Std / NI / NASp. Reading: 19277 T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JM6DJ2HAA01100673Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/65R15

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 7 mm R/Bal. 7 mmL/Bal. 7 mm L/Bal. 7 mmD.O.A. \_\_\_\_\_ D.O.I. 6/12/17

Survey held at \_\_\_\_\_

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C Rear & R.P. Chassis frame / Body Structure affected due to collision.Date / Time Action / Instruction ATA 51332Dep 9k. 8 yrs. net 236685/1/18 confirmed d/s \$20,000 with and wong (Ref 14, 278-40, 4290)

RECEIVED 05 FEB 2018

Date/Time, File Pass to?

☐ : Preli. Report☐ : Final Report

1)

Date/Time, File Return to?

2) 5/2- typistReport Format: TPLump Sum / I.B.I: (\$) 20,000/2Days Of Repair: 20Resurvey No. of Trip: 3Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

) \$ + RS \$

) Photos

) Others

TOTAL



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL			Ref : CS/AGI17023080/Uvb	
(BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Date : 05-12-2017	
			Code : AGI	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SLC 5541P	Veh. Inspected	SGA 5935G	
Policy No.	P10009506R00	Coverage (\$)	0.00	
Claim No.	C10001179	Excess (\$)	0.00	
Assign From	LINCOLN YEO	Assign Date	05/12/2017	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	Colour			
Odometer	-	Steering		
Brakes	Modification			
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	01/12/2017	Inspection Date		
Survey held at	PROGRESSIVE AUTO PTE LTD NO.1 KAKI BUKIT AVE 6 #02-48/50 AUTOBAY SINGAPORE 417883			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX : (065) 62564315

Your ref: C10001179  
Our ref: CS/AGI17023080/Uvb

Date: 5/2/2018

The Motor Claims Department  
M/s AUTO & GENERAL INSURANCE (SINGAPORE) PTE LTD

Dear Sir/Madam

**PRELIMINARY ADVICE OF VEHICLE NO. SGA 5935G**


We thank for your instruction on 5/12/2017

Please be informed that we had conducted the inspection of the above mentioned vehicle on 6/12/2017 at the premises of M/s PROGRESSIVE AUTO PTE LTD and have the following to report:-

Workshop Estimate Amount	: S\$34,278.40
Revised Estimate Amount	: S\$20,000.00 (LUMP SUM)
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

**Description of Damage:**

The vehicle sustained damages at the front and rear portion. The chassis frame affected due to collision.



**Comments/Present Status:**

Damages Consistent

Yours faithfully,

MARCUS CHUA  
Licensed Appraiser

## Survey Department Check List (Case Handler)

Reference No.: CS | AGI 1703080 | Uvb  
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

**Admin (** ): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No	✓			
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

**Surveyor (** ): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form					
C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

### (2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

### (3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

### (4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 5/2/18  
Case Handler Date

\*C: Critical \*N: Non-Critical

21/05/2014

## Veron Chen (LKKAuto)

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Monday, 5 February 2018 11:09 AM  
**To:** 'Lincoln Yeo'  
**Cc:** SUR; 'Albert Hong'  
**Subject:** RE: Appoint LKK to conduct third party survey for SGA5935G , Our Ref: Claim: C10001179 , Claimed Policy: P10009506R00 , Policy Holder: Carol Tejosukmono  
**Attachments:** SGA 5935G PRELI ADVISED.pdf

Dear Lincoln,

Enclosed preliminary revised of vehicle SGA 5935G  
Date of survey: 6/12/2017  
Number of days:20 days

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Thursday, 7 December 2017 4:19 PM  
**To:** 'Lincoln Yeo' <lincoln.yeo@budgetdirect.com.sg>  
**Cc:** SUR <sur@lkkauto.com>; 'Albert Hong' <albert.hong@budgetdirect.com.sg>  
**Subject:** RE: Appoint LKK to conduct third party survey for SGA5935G , Our Ref: Claim: C10001179 , Claimed Policy: P10009506R00 , Policy Holder: Carol Tejosukmono

Dear Lincoln,

Please be informed that we have inspected the vehicle SGA 5935G on 6/12/2017

We are pending estimate from repairer.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

**From:** Admin-D (LKKAuto)

**Sent:** Tuesday, 5 December, 2017 4:21 PM

**To:** 'Lincoln Yeo' <[lincoln.yeo@budgetdirect.com.sg](mailto:lincoln.yeo@budgetdirect.com.sg)>; assignments <[assignments@lkkauto.com](mailto:assignments@lkkauto.com)>

**Cc:** SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>; 'Albert Hong' <[albert.hong@budgetdirect.com.sg](mailto:albert.hong@budgetdirect.com.sg)>

**Subject:** RE: Appoint LKK to conduct third party survey for SGA5935G , Our Ref: Claim: C10001179 , Claimed Policy: P10009506R00 , Policy Holder: Carol Tejosukmono

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Lincoln Yeo [<mailto:lincoln.yeo@budgetdirect.com.sg>]

**Sent:** Tuesday, 5 December, 2017 2:59 PM

**To:** assignments

**Cc:** SUR; Albert Hong

**Subject:** Appoint LKK to conduct third party survey for SGA5935G , Our Ref: Claim: C10001179 , Claimed Policy: P10009506R00 , Policy Holder: Carol Tejosukmono

Hi LKK,

Please accept the assignment & liaise with Mandy of Progressive Auto.  
Car is in the workshop.

Warmest Regards,

**Lincoln Yeo**  
**Manager, Claims**

T +65 6540 2180

F +65 6725 0853 (Claims)

M +65 8382 8999

E [lincoln.yeo@budgetdirect.com.sg](mailto:lincoln.yeo@budgetdirect.com.sg)

**Budget  
Direct  
insurance**

**Customer Care** +65 6221 2111

**Claims** +65 6221 2199

**Claims (Int.)** +65 6540 2199

190 Clemenceau Avenue  
#03-01, Singapore Shopping Centre  
Singapore 239924  
**[budgetdirect.com.sg](http://budgetdirect.com.sg)**



Auto & General Insurance (Singapore) Pte. Limited (Co. Reg. No. 201626103G) trading as **Budget Direct Insurance**.

**From:** Claims

**Sent:** Tuesday, 5 December 2017 2:46 PM

**To:** 'Progressive Auto' <[claims@progressiveauto.sg](mailto:claims@progressiveauto.sg)>

**Cc:** Albert Hong <[albert.hong@budgetdirect.com.sg](mailto:albert.hong@budgetdirect.com.sg)>

**Subject:** RE: ACCIDENT INVOLVING SGA 5935 G & SLC 5541 P ON 01/12/17 ALONG ECP TWDS PIE AT ABOUT 2230 HOUR

Dear Mandy,

As spoken with Mr Wong.

We will arrange LKK Auto Consultant Pte Ltd to go down to your workshop to survey SGA5935G.

Warmest Regards,

**Lincoln Yeo**  
**Manager, Claims**

**T** +65 6540 2180

**F** +65 6725 0853 (Claims)

**M** +65 8382 8999

**E** [lincoln.yeo@budgetdirect.com.sg](mailto:lincoln.yeo@budgetdirect.com.sg)

**Budget  
Direct  
insurance**

**Customer Care** +65 6221 2111

**Claims** +65 6221 2199

**Claims (Int.)** +65 6540 2199

190 Clemenceau Avenue

#03-01, Singapore Shopping Centre

Singapore 239924

[budgetdirect.com.sg](http://budgetdirect.com.sg)

Auto & General Insurance (Singapore) Pte. Limited (Co. Reg. No. 201626103G) trading as **Budget Direct Insurance**.

**From:** Progressive Auto [<mailto:claims@progressiveauto.sg>]

**Sent:** Tuesday, 5 December 2017 10:16 AM

**To:** Claims <[claims@budgetdirect.com.sg](mailto:claims@budgetdirect.com.sg)>

**Subject:** ACCIDENT INVOLVING SGA 5935 G & SLC 5541 P ON 01/12/17 ALONG ECP TWDS PIE AT ABOUT 2230 HOUR



Dear Officer in charge,

Good day.

Please send a list of surveyor name to arrange the surveyor down our workshop regarding as below.

We are instructed by our client to notify you of a road traffic accident on 01/12/17 at about 2230 hours along ECP TOWARD PIE involving our client's SGA 5935 G and SLC 5541 P driven by your insured or your insured's authorized driver at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client/ we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client /we shall proceed to repair the vehicle without further reference to you.

Please be informed that the said vehicle can be inspected at:

Name of workshop : Progressive Auto Pte Ltd

Address: No.1 Kaki Bukit Ave 6  
AutoBay #02-48/50  
Singapore 417883

Telephone no. : 6844 4620

Best Regards,  
Mandy Sin

**Progressive Auto Pte Ltd**

No.1 Kaki Bukit Ave 6  
AutoBay #02-48/50  
Singapore 417883  
Tel: 6844 4620  
Fax:6844 4625

---

**EMAIL DISCLAIMER**

The information contained in this email communication is confidential. You should only read, disclose, re-transmit, copy, distribute, act in reliance on or commercialize the information if you are authorized to do so. If you are not the intended recipient of this email communication, please notify the sender by replying to the email and destroy any electronic or paper copy of this message.

Any views expressed in this email communication are those of the individual sender. Progressive Auto Pte. Ltd. does not represent, warrant or guarantee that the integrity of this communication has been maintained or that the communication is free of errors, virus or interference.

Progressive Auto Pte. Ltd. asserts copyright in respect to this email

including any attachment. No part may be reproduced by any process or for any purpose without prior written permission.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

Veron Chen (LKKAuto)

---

**From:** Veron Chen (LKKAuto)  
**Sent:** Thursday, 7 December, 2017 4:19 PM  
**To:** 'Lincoln Yeo'  
**Cc:** SUR; 'Albert Hong'  
**Subject:** RE: Appoint LKK to conduct third party survey for SGA5935G , Our Ref: Claim: C10001179 , Claimed Policy: P10009506R00 , Policy Holder: Carol Tejosukmono

Dear Lincoln,

Please be informed that we have inspected the vehicle SGA 5935G on 6/12/2017

We are pending estimate from repairer.

Best Regards,

**Veron Chen** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Admin-D (LKKAuto)  
**Sent:** Tuesday, 5 December, 2017 4:21 PM  
**To:** 'Lincoln Yeo' <lincoln.yeo@budgetdirect.com.sg>; assignments <assignments@lkkauto.com>  
**Cc:** SUR <sur@lkkauto.com>; 'Albert Hong' <albert.hong@budgetdirect.com.sg>  
**Subject:** RE: Appoint LKK to conduct third party survey for SGA5935G , Our Ref: Claim: C10001179 , Claimed Policy: P10009506R00 , Policy Holder: Carol Tejosukmono

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

**G.Nivitha** | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Lincoln Yeo [<mailto:lincoln.yeo@budgetdirect.com.sg>]  
**Sent:** Tuesday, 5 December, 2017 2:59 PM  
**To:** assignments  
**Cc:** SUR; Albert Hong  
**Subject:** Appoint LKK to conduct third party survey for SGA5935G , Our Ref: Claim: C10001179 , Claimed Policy: P10009506R00 , Policy Holder: Carol Tejosukmono

Hi LKK,

Please accept the assignment & liaise with Mandy of Progressive Auto.  
Car is in the workshop.

Warmest Regards,

**Lincoln Yeo**  
**Manager, Claims**

T +65 6540 2180  
F +65 6725 0853 (Claims)  
M +65 8382 8999  
E [lincoln.yeo@budgetdirect.com.sg](mailto:lincoln.yeo@budgetdirect.com.sg)

**Budget  
Direct  
insurance**

**Customer Care** +65 6221 2111  
**Claims** +65 6221 2199  
**Claims (Int.)** +65 6540 2199

190 Clemenceau Avenue  
#03-01, Singapore Shopping Centre  
Singapore 239924  
[budgetdirect.com.sg](http://budgetdirect.com.sg)

Auto & General Insurance (Singapore) Pte. Limited (Co. Reg. No. 201626103G) trading as **Budget Direct Insurance**.

---

**From:** Claims  
**Sent:** Tuesday, 5 December 2017 2:46 PM  
**To:** 'Progressive Auto' <[claims@progressiveauto.sg](mailto:claims@progressiveauto.sg)>  
**Cc:** Albert Hong <[albert.hong@budgetdirect.com.sg](mailto:albert.hong@budgetdirect.com.sg)>  
**Subject:** RE: ACCIDENT INVOLVING SGA 5935 G & SLC 5541 P ON 01/12/17 ALONG ECP TWDS PIE AT ABOUT 2230 HOUR

Dear Mandy,

As spoken with Mr Wong.  
We will arrange LKK Auto Consultant Pte Ltd to go down to your workshop to survey SGA5935G.

Warmest Regards,

**Lincoln Yeo**  
**Manager, Claims**

T +65 6540 2180  
F +65 6725 0853 (Claims)  
M +65 8382 8999  
E [lincoln.yeo@budgetdirect.com.sg](mailto:lincoln.yeo@budgetdirect.com.sg)

# Budget Direct insurance

**Customer Care** +65 6221 2111

**Claims** +65 6221 2199

**Claims (Int.)** +65 6540 2199

190 Clemenceau Avenue  
#03-01, Singapore Shopping Centre  
Singapore 239924  
[budgetdirect.com.sg](http://budgetdirect.com.sg)

Auto & General Insurance (Singapore) Pte. Limited (Co. Reg. No. 201626103G) trading as **Budget Direct Insurance**.

**From:** Progressive Auto [<mailto:claims@progressiveauto.sg>]

**Sent:** Tuesday, 5 December 2017 10:16 AM

**To:** Claims <[claims@budgetdirect.com.sg](mailto:claims@budgetdirect.com.sg)>

**Subject:** ACCIDENT INVOLVING SGA 5935 G & SLC 5541 P ON 01/12/17 ALONG ECP TWDS PIE AT ABOUT 2230 HOUR

Dear Officer in charge,

Good day.

Please send a list of surveyor name to arrange the surveyor down our workshop regarding as below.

We are instructed by our client to notify you of a road traffic accident on 01/12/17 at about 2230 hours along ECP TOWARD PIE involving our client's SGA 5935 G and SLC 5541 P driven by your insured or your insured's authorized driver at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client/ we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client /we shall proceed to repair the vehicle without further reference to you.

Please be informed that the said vehicle can be inspected at:

Name of workshop : Progressive Auto Pte Ltd

Address: No.1 Kaki Bukit Ave 6  
AutoBay #02-48/50  
Singapore 417883

Telephone no. : 6844 4620

Best Regards,  
Mandy Sin

**Progressive Auto Pte Ltd**

No.1 Kaki Bukit Ave 6

AutoBay #02-48/50

Singapore 417883

Tel: 6844 4620

Fax:6844 4625

---

**EMAIL DISCLAIMER**

The information contained in this email communication is confidential. You should only read, disclose, re-transmit, copy, distribute, act in reliance on or commercialize the information if you are authorized to do so. If you are not the intended recipient of this email communication, please notify the sender by replying to the email and destroy any electronic or paper copy of this message.

Any views expressed in this email communication are those of the individual sender. Progressive Auto Pte. Ltd. does not represent, warrant or guarantee that the integrity of this communication has been maintained or that the communication is free of errors, virus or interference.

Progressive Auto Pte. Ltd. asserts copyright in respect to this email including any attachment. No part may be reproduced by any process or for any purpose without prior written permission.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

## Nivitha (LKK Auto)

---

**From:** Lincoln Yeo <lincoln.yeo@budgetdirect.com.sg>  
**Sent:** Tuesday, 5 December, 2017 2:59 PM  
**To:** assignments  
**Cc:** SUR; Albert Hong  
**Subject:** Appoint LKK to conduct third party survey for SGA5935G , Our Ref: Claim: C10001179 , Claimed Policy: P10009506R00 , Policy Holder: Carol Tejosukmono

Hi LKK,

Please accept the assignment & liaise with Mandy of Progressive Auto.  
Car is in the workshop.

Warmest Regards,

**Lincoln Yeo**  
**Manager, Claims**

T +65 6540 2180  
F +65 6725 0853 (Claims)  
M +65 8382 8999  
E [lincoln.yeo@budgetdirect.com.sg](mailto:lincoln.yeo@budgetdirect.com.sg)

**Budget  
Direct  
insurance**

**Customer Care** +65 6221 2111  
**Claims** +65 6221 2199  
**Claims (Int.)** +65 6540 2199

190 Clemenceau Avenue  
#03-01, Singapore Shopping Centre  
Singapore 239924  
[budgetdirect.com.sg](http://budgetdirect.com.sg)

Auto & General Insurance (Singapore) Pte. Limited (Co. Reg. No. 201626103G) trading as **Budget Direct Insurance.**

**From:** Claims  
**Sent:** Tuesday, 5 December 2017 2:46 PM  
**To:** 'Progressive Auto' <claims@progressiveauto.sg>  
**Cc:** Albert Hong <albert.hong@budgetdirect.com.sg>  
**Subject:** RE: ACCIDENT INVOLVING SGA 5935 G & SLC 5541 P ON 01/12/17 ALONG ECP TWDS PIE AT ABOUT 2230 HOUR

Dear Mandy,

As spoken with Mr Wong.  
We will arrange LKK Auto Consultant Pte Ltd to go down to your workshop to survey SGA5935G.



Warmest Regards,

**Lincoln Yeo**  
**Manager, Claims**

T +65 6540 2180  
F +65 6725 0853 (Claims)  
M +65 8382 8999  
E [lincoln.yeo@budgetdirect.com.sg](mailto:lincoln.yeo@budgetdirect.com.sg)

**Budget**  
**Direct**  
**insurance**

**Customer Care** +65 6221 2111  
**Claims** +65 6221 2199  
**Claims (Int.)** +65 6540 2199

190 Clemenceau Avenue  
#03-01, Singapore Shopping Centre  
Singapore 239924  
[budgetdirect.com.sg](http://budgetdirect.com.sg)

Auto & General Insurance (Singapore) Pte. Limited (Co. Reg. No. 201626103G) trading as **Budget Direct Insurance**.

**From:** Progressive Auto [<mailto:claims@progressiveauto.sg>]

**Sent:** Tuesday, 5 December 2017 10:16 AM

**To:** Claims <[claims@budgetdirect.com.sg](mailto:claims@budgetdirect.com.sg)>

**Subject:** ACCIDENT INVOLVING SGA 5935 G & SLC 5541 P ON 01/12/17 ALONG ECP TWDS PIE AT ABOUT 2230 HOUR

Dear Officer in charge,

Good day.

Please send a list of surveyor name to arrange the surveyor down our workshop regarding as below.

We are instructed by our client to notify you of a road traffic accident on 01/12/17 at about 2230 hours along ECP TOWARD PIE involving our client's SGA 5935 G and SLC 5541 P driven by your insured or your insured's authorized driver at the material time.

As a result of the accident, our client's vehicle has been damaged. Before our client/ we proceed to repair the damaged vehicle, please let us know within 2 working days of your receipt of this notice whether you or your insurer would like to conduct a pre-repair survey of the vehicle. If we do not receive any reply from you within the stipulated timeline, our client /we shall proceed to repair the vehicle without further reference to you.

Please be informed that the said vehicle can be inspected at:

Name of workshop : Progressive Auto Pte Ltd

Address: No.1 Kaki Bukit Ave 6  
AutoBay #02-48/50  
Singapore 417883

Telephone no. : 6844 4620

Best Regards,  
Mandy Sin

**Progressive Auto Pte Ltd**

No.1 Kaki Bukit Ave 6  
AutoBay #02-48/50  
Singapore 417883  
Tel: 6844 4620  
Fax: 6844 4625

---

**EMAIL DISCLAIMER**

The information contained in this email communication is confidential. You should only read, disclose, re-transmit, copy, distribute, act in reliance on or commercialize the information if you are authorized to do so. If you are not the intended recipient of this email communication, please notify the sender by replying to the email and destroy any electronic or paper copy of this message.

Any views expressed in this email communication are those of the individual sender. Progressive Auto Pte. Ltd. does not represent, warrant or guarantee that the integrity of this communication has been maintained or that the communication is free of errors, virus or interference.

Progressive Auto Pte. Ltd. asserts copyright in respect to this email including any attachment. No part may be reproduced by any process or for any purpose without prior written permission.

This email is sent by Auto & General (SEA) Services Pte. Limited or a related body corporate (Auto & General) and is for the intended addressee. The views expressed in this email and attachments (email) reflect the views of the stated author but may not reflect views of Auto & General. This email is confidential and subject to copyright. It may be privileged. If you are not the intended addressee, confidentiality and privilege have not been waived and any use, interference with, or disclosure of this email is unauthorised.

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type	Singapore NRIC
Owner ID	6233J
<b>Vehicle Details</b>	
Vehicle No.	SGA5935G
Vehicle to be Exported	No
Intended De-registration Date	06 Dec 2017
Vehicle Make	MAZDA
Vehicle Model	MAZDA2 5-DOOR HATCHBACK 1.5L SP.6EAT
Primary Colour	Grey
Manufacturing Year	2015
Engine No.	P520335601
Chassis No.	JM6DJ2HAA01100673
Maximum Power Output	85.0 kW (113 bhp)
Open Market Value	\$13,799.00
Original Registration Date	21 Dec 2015
First Registration Date	21 Dec 2015
Transfer Count	0
Actual ARF Paid	\$5,000.00 2500
<b>Intended PARF Rebate Details</b>	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	20 Dec 2025
PARF Rebate Amount	\$3,750.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date	20 Dec 2025
COE Category	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years)	10
QP Paid	\$59,200.00
COE Rebate Amount	\$47,582.00
<b>Total Rebate Amount</b>	<b>\$51,332.00</b>

The information contained herein is correct as at 06 Dec 2017

OK

**THE NEW LEXUS NX.**  
 ARRIVING IN JANUARY 2018.


Username / Email Add

password

Submit Qu.



Connect

 Sign Up New Account  
 Forget Password

**Post an Advertisement**  
 Sell it yourself! Advertise it at just  
**\$58 until it's SOLD!**

Post an Ad

Advertiser Login

Ways of Selling

Nov 2013, BMW X1 SDrive20i Selling \$108,800!


 Agent Maintained, Low Mileage  
 Showroom Condition! High  
 Paper value, Best Unit!  
 S/Sur Ad

**PRIME MOTOR & LEASING**

SCHUMYER CREDIT ENTERPRISES PTE LTD GROUP OF COMPANIES

 With over 200 units of vehicles  
 to choose from, ranging from  
 all European to Japanese Makes.

Browse by Category

Sort by Date Posted

20 results/page

2 vehicles

Mazda 2

Advanced Search

Submit

	Make	Model	Price	Depreciation	Reg Date	Eng Cap	Mileage	Veh Type	Status
<b>Search Selection</b>	Mazda 2		Any	Any	2015	Any	Any	Any	Available

**Mazda 2 1.5A HB Deluxe**

\$67,800

\$8,970 /yr

18-Mar-2015

1,496 cc

59,224 km

Hatchback

Available

 Reliable And Compact Japanese Hatchback Equipped With A 1.5L Engine And Mated To A 6 Speed Gearbox Ensuring You A Zippy Drive Around Town,  
 Yet Returning Good Fuel Efficiency! Spacious Cabin For Young ...

Select By Performance Premium Selection

Posted: 05-Dec-2017 Tags: 2015 Mazda 2, 2015 Mazda 2, Mazda 2, Mazda 2, Mazda 2, 2, 2, Used Mazda

Details

**Mazda 2 1.5A HB Deluxe**

\$70,800

\$9,150 /yr

26-May-2015

1,496 cc

25,000 km

Hatchback

Available

 Interest Rate At 1.99%, Agent Maintained! Brand New Condition! 1 Owner! Low Mileage! Extended Warranty! A Sleek Designed Hatchback, Equipped  
 With Numerous High Tech Features, For Your Comfort, Safety A...

Dickson Automobile

Posted: 22-Nov-2017 Tags: 2015 Mazda 2, 2015 Mazda 2, Mazda 2, Mazda 2, Mazda 2, 2, 2, used Mazda

Details

Save this search criteria, to get email alerts whenever a match is found.

Make

Model

Price

Depreciation

Reg Date

Eng Cap

Mileage

Veh Type

Status

For old advertisements, view Expired ads

20 results/page

sgCarMart is the number one car classifieds for parallel import cars, Toyota, Honda, Nissan, Mitsubishi & BMW. There are plenty of cars for sale, from vans, trucks, sedan cars, luxury cars, sports cars or station wagons, SUV, MPV, hatchback, to COE cars & OPC cars. You can also buy from a car auction, look up car loans, low mileage cars, car brands, carpark rates & car insurance. Find buy used Mazda 2, Mazda 2 Singapore, used Mazda 2 Singapore, used Mazda 2, used vehicles Singapore or even buy used Mazda 2 Singapore. We have new car dealers comprising parallel importers, authorised car dealers, and used car dealers on our site. Find new car price lists, new car launches and new car promotions. Visit our partner sites for job openings for Singapore jobs, massage services, real estate properties for sale, mover, car performance parts, car discussion, forum discussion, commercial vehicle leasing & COE results.

All prices and other information displayed on sgCarMart.com are gathered from sources and based on algorithms that are believed by sgCarMart.com to be reliable, but no assurance can be given that this information is accurate, complete or current. sgCarMart.com does not assume any responsibility for errors or omissions or warrant the accuracy of this information.

- Home
- New Car
- Used Car
- Sell Car
- Motoring Directory
- Products Guide
- Article
- Forum
- Tool & Tip

- About Us
- Careers
- Contact Us
- Sitemap

© 2004-2017 sgCarMart. All rights reserved.

- Terms of Service
- Privacy Policy
- Personal Data Protection Statement

Compare

# PROGRESSIVE AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6844 4620 FAX: 6844 4625 Email: claims@progressiveauto.sg

GST:200712509E RCB NO:200712509E

*N9 f Alford  
Hulu  
1/5 20.000  
6/12/17  
20 day.*

**M/S :** AUTO & GENERAL INSURANCE (SINGAPORE)  
SINGAPORE SHOPPING CENTRE  
190 CLEMENCEAU AVENUE  
#03-01 SINGAPORE 239924  
FAX: 67250611

ATTN: Motor Claim Department  
Your Ref No: SGA5935G  
Claim Type: Third Party  
Accident Date: 01-12-2017  
TP Veh Reg No: SLC5541P

**Estimate No:** EST0000537  
**Date:** 09 Dec 2017  
**Policy No:** 2100444207  
**Veh Reg No:** SGA5935G  
**Make/Model:** MAZDA 2  
**Chassis No:** JM6DJ2HAA01100673  
**Engine No:** P520335601  
**Reg. Date:** 21-12-2015

## Estimate Repair Cost to Vehicle No :SGA5935G

Description	U/Price	Quantity	List Price SS	Amount SS
SGA5935G MAZDA 2				
<b>List Price</b>				
1 Front Bonnet	703.0000	1 PC	Buc 703.00	✓
2 Front Bonnet Lock	171.0000	1 PC	Tw 171.00	✓
3 Front Bonnet Hinges	46.0000	2 PC	n 92.00	α
4 Front Bonnet Rubber	58.0000	1 PC	ner 58.00	✓
5 Front Bonnet Rubber Clips	4.5000	10 PCS	ner 45.00	✓
6 Front Support Panel	456.0000	1 PC	one 456.00	✓
7 Front Bonnet Lock Cover	11.0000	1 PC	one 11.00	✓
8 Front Support Centre Bracket	44.0000	1 PC	but 44.00	✓
9 Front Head Lamp	553.0000	2 PC	one 1,106.00	✓
10 Front Grille	107.0000	1 PC	SD 107.00	✓
11 Front Grille Emblem	32.0000	1 PC	one 32.00	✓
12 Front Grille Support	146.0000	1 PC	one 146.00	✓
13 Front Grille Top Garnish	178.0000	1 PCS	7.5 178.00	✓
14 Front Grille Side Moulding	159.0000	2 PCS	one 318.00	✓
15 Front Grille Top Garnish Clips	5.5000	4 PCS	11 22.00	α
16 Front Grille Top Garnish Rivets	5.5000	4 PCS	ner 22.00	✓
17 Front Bumper	833.0000	1 PC	7.5 833.00	✓
18 Front Bumper Reinforcement	501.0000	1 PC	7.5 501.00	✓
19 Front Bumper Inner Sponge	122.0000	1 PC	7.5 122.00	✓
20 Front Bumper Side Retainer	18.0000	2 PC	but 36.00	✓
21 Front Bumper Towing Cover	39.0000	1 PC	11 39.00	α
22 Front Bumper Lower Grille	89.0000	1 PC	11 89.00	α
23 Front Support Side Garnish	38.0000	2 PC	7.5 76.00	✓
24 Front Support Side Garnish Clips	5.5000	6 PCS	ner 33.00	✓
25 Front Horn	159.0000	1 PC	11 159.00	α
26 Front Air Cleaner Box	280.0000	1 PC	one 280.00	✓
27 Front Air Cleaner Air Duct	95.0000	1 PC	YWI 95.00	✓
28 Front Fender	389.0000	2 PC	Buc 778.00	1 PC
29 Front Washer Tank	59.0000	1 PC	11 59.00	α
30 Front Aircon Condenser	804.0000	1 PC	but/pur 804.00	✓
31 Front Bumper Support Bracket	80.0000	2 PC	but 160.00	✓
32 Front Radiator	1,491.0000	1 PC	but/pur 1,491.00	✓
33 Front Radiator Spare Tank	90.0000	1 PC	11 90.00	α
34 Front Radiator Fan Assy	991.0000	1 PCS	one/pur 991.00	✓
35 Rear Boot	912.0000	1 PC	but 912.00	✓
36 Rear Boot Hinge	33.0000	2 PC	11 66.00	α

*o/s n*

*M/S*

*10120*

# PROGRESSIVE AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883

TEL: 6844 4620 FAX: 6844 4625 Email: claims@progressiveauto.sg

GST:200712509E RCB NO:200712509E

M/S : AUTO & GENERAL INSURANCE (SINGAPORE)

SINGAPORE SHOPPING CENTRE

190 CLEMENCEAU AVENUE

#03-01 SINGAPORE 239924

FAX: 67250611

ATTN: Motor Claim Department

Your Ref No: SGA5935G

Claim Type: Third Party

Accident Date: 01-12-2017

TP Veh Reg No: SLC5541P

Estimate No: EST0000537

Date: 09 Dec 2017

Policy No: 2100444207

Veh Reg No: SGA5935G

Make/Model: MAZDA 2

Chassis No: JM6DJ2HAA01100673

Engine No: P520335601

Reg. Date: 21-12-2015

## Estimate Repair Cost to Vehicle No :SGA5935G

Description	U/Price	Quantity	List Price	Amount
			SS	SS
37 Rear Boot Shock Absorber	85.0000	2 PC	170.00	X
38 Rear Boot Reflector	222.0000	2 PC	444.00	X
39 Rear Boot Lock	203.0000	1 PC	203.00	—
40 Rear Boot Lock Outer Handle With Sensor	106.0000	1 PCS	106.00	—
41 Rear Boot Lock Catch	35.0000	1 PC	35.00	—
42 Rear Boot Rubber	161.0000	1 PC	161.00	—
43 Rear Boot Emblem (Mazda 2)	56.0000	1 PC	56.00	—
44 Rear Boot Emblem (SKYACTIV)	65.0000	1 PC	65.00	—
45 Rear Boot Centre Logo	59.0000	1 PC	59.00	—
46 Rear Boot Inner Cover Board	89.0000	1 PC	89.00	—
47 Rear Boot Inner Cover Board Clips	5.5000	9 PC	49.50	—
48 Rear Boot Inner Pull Handle Garnish	18.0000	1 PC	18.00	—
49 Rear Spare Tyre Panel	837.0000	1 PC	837.00	—
50 Rear Spare Tyre Top Cover Board	312.0000	1 PC	312.00	—
51 Rear Wheel Housing	850.0000	2 PC	1,700.00	1 PC
52 Rear Fender	908.0000	2 PC	1,816.00	—
53 Rear Fender Dust Cover	47.0000	2 PC	94.00	—
54 Rear Fender Dust Cover Clips	5.5000	6 PC	33.00	—
55 Rear Fender Inner Side Garnish	389.0000	2 PC	778.00	—
56 Rear Tail Lamp	728.0000	2 PC	1,456.00	—
57 Rear Tail Lamp <i>any panel (inner &amp; outer)</i>	593.0000	2 PCS	1,186.00	—
58 Rear Tail Lamp Clip	5.5000	2 PC	11.00	X
59 Rear End Panel	391.0000	1 PC	391.00	—
60 Rear End Panel Top Garnish	126.0000	1 PC	126.00	—
61 Rear End Panel Top Garnish Clips	5.5000	2 PC	11.00	X
62 Rear Bumper	851.0000	1 PC	851.00	—
63 Rear Bumper Side Retainer	26.0000	2 PC	52.00	—
64 Rear Bumper Center Inner Bracket	11.0000	1 PCS	11.00	—
65 Rear Bumper Centre Under Cover	89.0000	1 PC	89.00	—
66 Rear Boot Lower Clips	5.5000	4 PC	22.00	—
67 Rear Number Plate Lamp	64.0000	2 PC	128.00	—
68 Rear Seat LH	850.0000	1 PC	850.00	—
69 Rear Seat RH	850.0000	1 PC	850.00	—
70 Rear Door	926.0000	1 PC	926.00	—
71 Rear Door Lock	176.0000	1 PC	176.00	—
72 Rear Door Hinges	40.0000	2 PC	80.00	X
73 Rear Door Rubber	111.0000	1 PC	111.00	—
74 Rear Exhaust Silencer	1,054.0000	1 PC	1,054.00	—
75 Rear Exhaust Rubber	46.0000	2 PC	92.00	—

# PROGRESSIVE AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883  
 TEL: 6844 4620 FAX: 6844 4625 Email: claims@progressiveauto.sg  
 GST:200712509E RCB NO:200712509E

**M/S :** AUTO & GENERAL INSURANCE (SINGAPORE)  
 SINGAPORE SHOPPING CENTRE  
 190 CLEMENCEAU AVENUE  
 #03-01 SINGAPORE 239924  
 FAX: 67250611

ATTN: Motor Claim Department  
 Your Ref No: SGA5935G  
 Claim Type: Third Party  
 Accident Date: 01-12-2017  
 TP Veh Reg No: SLC5541P

**Estimate No:** EST0000537  
**Date:** 09 Dec 2017  
**Policy No:** 2100444207  
**Veh Reg No:** SGA5935G  
**Make/Model:** MAZDA 2  
**Chassis No:** JM6DJ2HAA01100673  
**Engine No:** P520335601  
**Reg. Date:** 21-12-2015

## Estimate Repair Cost to Vehicle No :SGA5935G

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
76 Centre Exhaust Pipe	1,152.000	1 PCS	1,152.00	X
77 Rear Compartment Board	450.0000	1 PC	450.00	X
78 Front Seat LH	980.0000	1 PC	980.00	X
79 Front Seat RH	980.0000	1 PC	980.00	X
80 Rear Shock Absorber	298.0000	2 PC	596.00	X
81 Rear Hub Bearing	212.0000	2 PC	424.00	X
82 Rear Axle Beam	1,980.000	1 PC	1,980.00	X
			33,185.50	
		Less 20%	6,637.10	26,548.40
<b>Special Net</b>				
83 Front Number Plate	50.0000	1 PC	50.00	205.00
84 Rear Bumper Sensor	300.0000	1 PC	300.00	205.00
85 Rear Number Plate	50.0000	1 PC	50.00	405.00
86 Brake Down Sign	120.0000	1 PCS	120.00	505.00
87 Rear Tyre	280.0000	2 PC	560.00	X
88 Rear Windscreen	80.0000	1 PC	80.00	405.00
			1,160.00	1,160.00
				350
<b>Labour</b>				
89 Towing Fees (King Dolley)	100.0000	1 PC	100.00	✓
90 Panel Beating	3,200.000	1 PC	3,200.00	2800
91 Check Wiring	120.0000	1 PC	120.00	30
92 To Remove & Replace Air Con Condenser and Change Gas	160.0000	1 PC	160.00	100
93 To Remove and Replace Radiator	80.0000	1 PC	80.00	X
94 To Remove & Replace Rear Windscreen	160.0000	1 PC	160.00	120
95 To Remove & Refit Roofing-seat and Up-Hole Stretch	250.0000	1 PCS	250.00	100
96 To Remove & Replace Bumper Sensor	80.0000	1 PC	80.00	50
97 To Remove & Replace Rear Under Carriage	350.0000	1 PCS	350.00	200
98 Spray Painting	1,600.000	1 PC	1,600.00	✓
99 To Spray Rust Proofing	120.0000	1 PC	120.00	✓
100 To mount vehicle on car o-liner	350.0000	1 PC	350.00	280
			6,570.00	6,570.00

5500



# PROGRESSIVE AUTO PTE LTD

NO. 1 KAKI BUKIT AVENUE 6 #02-48/50 AUTOBAY @ KAKI BUKIT SINGAPORE 417883  
TEL: 6844 4620 FAX: 6844 4625 Email: claims@progressiveauto.sg  
GST:200712509E RCB NO:200712509E

**M/S :** AUTO & GENERAL INSURANCE (SINGAPORE)  
SINGAPORE SHOPPING CENTRE  
190 CLEMENCEAU AVENUE  
#03-01 SINGAPORE 239924

FAX: 67250611

ATTN: Motor Claim Department

Your Ref No: SGA5935G

Claim Type: Third Party

Accident Date: 01-12-2017

TP Veh Reg No: SLC5541P

**Estimate No: EST0000537**

Date: 09 Dec 2017

Policy No: 2100444207

Veh Reg No: **SGA5935G**

Make/Model: MAZDA 2

Chassis No: JM6DJ2HAA01100673

Engine No: P520335601

Reg. Date: 21-12-2015

## Estimate Repair Cost to Vehicle No :SGA5935G

Description	U/Price	Quantity	List Price	Amount
			<u>SS</u>	<u>SS</u>
			Total	SS 34,278.40

TOTAL: SINGAPORE DOLLAR THIRTY FOUR THOUSAND TWO HUNDRED SEVENTY EIGHT AND CENTS FORTY ONLY

**For PROGRESSIVE AUTO PTE LTD**

AUTHORISED SIGNATURE

LKK Auto Consultants hence notify the repairer of the following:

- To resurface, refinish, or repaint
- To display damaged part(s) during resurvey
- Parts prices to be confirmed
- Third party claims on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AUTO & GENERAL INSURANCE (S) PL

Ref : CS/AGI17023080/Uvbn2

(BUDGET DIRECT INSURANCE)

190 CLEMENCEAU AVENUE #03-01

SINGAPORE SHOPPING CENTRESINGAPORE

239924

Date : 09-02-2018



Code : AGI

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLC 5541P	Veh. Inspected	SGA 5935G
Policy No.	P10009506R00	Coverage (\$)	0.00
Claim No.	C10001179	Excess (\$)	0.00
Assign From	LINCOLN YEO	Assign Date	05/12/2017

### 2. Vehicle Particulars & Condition

Make & Model	MAZDA 2 (A)	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JM6DJ2HAA01100673	Colour	GREY
Odometer	19277	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	185/65 R15	DUNLOP	7 mm
L/H Front Tyre	185/65 R15	DUNLOP	7 mm
R/H Rear Tyre	185/65 R15	DUNLOP	7 mm
L/H Rear Tyre	185/65 R15	DUNLOP	7 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR AND FRONT PORTION.THE CHASSIS FRAME AFFECTED DUE TO COLISSION.

DAMAGES SEE DETAILS.

### 5. General Information

Accident Date	01/12/2017	Inspection Date	06/12/2017
Survey held at	PROGRESSIVE AUTO PTE LTD NO.1 KAKI BUKIT AVE 6 #02-48/50 AUTOBAY SINGAPORE 417883		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.

B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	20 Working Days
-------------------------------------	-----------------



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 4

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SGA 5935G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BONNET	BUCKLED	703.00	703.00
1	FRONT BONNET LOCK	TWISTED	171.00	171.00
2	FRONT BONNET HINGES @\$46.00	TO REPAIR SEE LABOUR	92.00	-
1	FRONT BONNET RUBBER	NECESSARY	58.00	58.00
10	FRONT BONNET RUBBER CLIPS @\$4.50	NECESSARY	45.00	45.00
1	FRONT SUPPORT PANEL	CRACKED	456.00	456.00
1	FRONT BONNET LOCK COVER	CRACKED	11.00	11.00
1	FRONT SUPPORT CENTRE BRACKET	BENT	44.00	44.00
2	FRONT HEAD LAMP @\$553.00	CRACKED	1,106.00	1,106.00
1	FRONT GRILLE	BROKEN	107.00	107.00
1	FRONT GRILLE EMBLEM	CRACKED	32.00	32.00
1	FRONT GRILLE SUPPORT	CRACKED	146.00	146.00
1	FRONT GRILLE TOP GARNISH	DISTORTED	178.00	178.00
2	FRONT GRILLE SIDE MOULDING @\$159.00	CRACKED	318.00	318.00
4	FRONT GRILLE TOP GARNISH CLIPS @\$5.50	NOT NECESSARY	22.00	-
4	FRONT GRILLE TOP GARNISH RIVETS @\$5.50	NECESSARY	22.00	22.00
1	FRONT BUMPER	DISTORTED	833.00	833.00
1	FRONT BUMPER REINFORCEMENT	DISTORTED	501.00	501.00
1	FRONT BUMPER INNER SPONGE	TORN	122.00	122.00
2	FRONT BUMPER SIDE RETAINER @\$18.00	BENT	36.00	36.00
1	FRONT BUMPER TOWING COVER	NOT NECESSARY	39.00	-
1	FRONT BUMPER LOWER GRILLE	NOT NECESSARY	89.00	-
2	FRONT SUPPORT SIDE GARNISH @\$38.00	TORN	76.00	76.00
6	FRONT SUPPORT SIDE GARNISH CLIPS @\$5.50	NECESSARY	33.00	33.00
1	FRONT HORN	NOT NECESSARY	159.00	-
1	FRONT AIR CLEANER BOX	CRACKED	280.00	280.00
1	FRONT AIR CLEANER AIR DUCT	TWISTED	95.00	95.00
2	FRONT FENDER @\$389.00	N/S BUCKLED / O/S TO REPAIR SEE LABOUR	778.00	389.00
1	FRONT WASHER TANK	NOT NECESSARY	59.00	-
1	FRONT AIRCON CONDENSER	BENT / PUNCTURE	804.00	804.00
2	FRONT BUMPER SUPPORT BRACKET @\$80.00	BENT	160.00	160.00
1	FRONT RADIATOR	BENT / PUNCTURE	1,491.00	1,491.00

Report Ref No. CS/AGI17023080/Uvbn2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT RADIATOR SPARE TANK	NOT NECESSARY	90.00	-
1	FRONT RADIATOR FAN ASSY	CRACKED / JAMMED	991.00	991.00
1	REAR BOOT	BADLY DENTED	912.00	912.00
2	REAR BOOT HINGE @\$33.00	NOT NECESSARY	66.00	-
2	REAR BOOT SHOCK ABSORBER @\$85.00	NOT NECESSARY	170.00	-
2	REAR BOOT REFLECTOR @\$222.00	NOT NECESSARY	444.00	-
1	REAR BOOT LOCK	TWISTED / JAMMED	203.00	203.00
1	REAR BOOT LOCK OUTER HANDLE WITH SENSOR	SHORTED	106.00	106.00
1	REAR BOOT LOCK CATCH	BENT	35.00	35.00
1	REAR BOOT RUBBER	TWISTED	161.00	161.00
1	REAR BOOT EMBLEM (MAZDA 2)	NECESSARY	56.00	56.00
1	REAR BOOT EMBLEM (SKYACTIV)	NECESSARY	65.00	65.00
1	REAR BOOT CENTRE LOGO	NECESSARY	59.00	59.00
1	REAR BOOT INNER COVER BOARD	DEFORMED / CRACKED	89.00	89.00
9	REAR BOOT INNER COVER BOARD CLIPS @\$5.50	NECESSARY	49.50	49.50
1	REAR BOOT INNER PULL HANDLE GARNISH	TWISTED	18.00	18.00
1	REAR SPARE TYRE PANEL	CRUMPLED / BUCKLED	837.00	837.00
1	REAR SPARE TYRE TOP COVER BOARD	TORN	312.00	312.00
2	REAR WHEEL HOUSINGS @\$850.00	O/S DENTED / BUCKLED / N/S TO REPAIR SEE LABOUR	1,700.00	850.00
2	REAR FENDERS @\$908.00	BADLY DENTED / BUCKLED	1,816.00	1,816.00
2	REAR FENDER DUST COVERS @\$47.00	TORN	94.00	94.00
6	REAR FENDER DUST COVER CLIPS @\$5.50	NECESSARY	33.00	33.00
2	REAR FENDER INNER SIDE GARNISHS @\$389.00	DISTORTED	778.00	778.00
2	REAR TAIL LAMPS @\$728.00	CRACKED	1,456.00	1,456.00
2	REAR TAIL LAMP PANEL (INNER & OUTER) @\$593.00	DENTED / BENT	1,186.00	1,186.00
2	REAR TAIL LAMP CLIP @\$5.50	NOT NECESSARY	11.00	-
1	REAR END PANEL	BADLY DENTED	391.00	391.00
1	REAR END PANEL TOP GARNISH	DISTORTED	126.00	126.00
2	REAR END PANEL TOP GARNISHS @\$5.50	NOT NECESSARY	11.00	-
1	REAR BUMPER	DISTORTED	851.00	851.00
2	REAR BUMPER SIDE RETAINER @\$26.00	BENT	52.00	52.00

Report Ref No. CS/AGI17023080/Uvbn2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	REAR BUMPER CENTER INNER BRACKET	BENT	11.00	11.00
1	REAR BUMPER CENTRE UNDER COVER	DISTORTED	89.00	89.00
4	REAR BOOT LOWER CLIPS @\$5.50	NECESSARY	22.00	22.00
2	REAR NUMBER PLATE LAMP @\$64.00	CRACKED	128.00	128.00
1	REAR SEAT LH	BENT / TWISTED	850.00	850.00
1	REAR SEAT RH	BENT / TWISTED	850.00	850.00
1	REAR DOOR O/S	DENTED / WARPED	926.00	926.00
1	REAR DOOR LOCK	TWISTED	176.00	176.00
2	REAR DOOR HINGES @\$40.00	NOT NECESSARY	80.00	-
1	REAR DOOR RUBBER	NECESSARY	111.00	111.00
1	REAR EXHAUST SILENCER	BENT / CRACKED	1,054.00	1,054.00
2	REAR EXHAUST RUBBER @\$46.00	TORN	92.00	92.00
1	CENTRE EXHAUST PIPE	TO REPAIR SEE LABOUR	1,152.00	-
1	REAR COMPARTMENT BOARD	REPEATED	450.00	-
1	FRONT SEAT LH	TO REPAIR SEE LABOUR	980.00	-
1	FRONT SEAT RH	TO REPAIR SEE LABOUR	980.00	-
2	REAR SHOCK ABSORBER @\$298.00	NOT NECESSARY	596.00	-
2	REAR HUB BEARING @\$212.00	NOT NECESSARY	424.00	-
1	REAR AXLE BEAM	NOT NECESSARY	1,980.00	-
	LESS 20% DISCOUNT		-6,637.10	-4,810.50
			26,548.40	19,242.00
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	FRONT NUMBER PLATE (SN)	BROKEN	50.00	20.00
1	SET REAR BUMPER SENSOR (SN)	SHORTED	300.00	200.00
1	REAR NUMBER PLATE (SN)	BENT	50.00	40.00
1	BRAKE DOWN SIGN (SN)	DISTORTED	120.00	50.00
2	REAR TYRE @\$280.00 (SN)	SERVICEABLE	560.00	-
1	REAR WINDSCREEN SEALANT (SN)	NECESSARY	80.00	40.00
			1,160.00	350.00
	<b><u>LABOUR</u></b>			
	TOWING FEES (KING DOLLEY).		100.00	100.00

Report Ref No. CS/AGI17023080/Uvbn2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF FRONT BONNET HINGES,O/S FRONT FENDER,N/S REAR WHEEL HOUSING,CENTRE EXHAUST PIPE,FRONT SEAT LH AND FRONT SEAT RH.		3,200.00	2,800.00
	CHECK WIRING.		120.00	30.00
	TO REMOVE & REPLACE AIR CON CONDENSER AND CHANGE GAS.		160.00	100.00
	TO REMOVE AND REPLACE RADIATOR.	NOT NECESSARY	80.00	-
	TO REMOVE & REPLACE REAR WINDSCREEN.		160.00	120.00
	TO REMOVE & REFIT ROOFING-SEAT AND UP-HOLE STRETCH.		250.00	100.00
	TO REMOVE & REPLACE BUMPER SENSOR.		80.00	50.00
	TO REMOVE & REPLACE REAR UNDER CARRIAGE.		350.00	200.00
	SPRAY PAINTING.		1,600.00	1,600.00
	TO SPRAY RUST PROOFING.		120.00	120.00
	TO MOUNT VEHICLE ON CAR O-LINER.		350.00	280.00
			6,570.00	5,500.00
GRAND TOTAL			34,278.40	25,092.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				20,000.00

Report Ref No. CS/AGI17023080/Uvbn2

CHUA KANG SENG

Licensed Appraiser

**DISCLAIMER OF LIABILITY TO THIRD PARTIES:-** This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.