

ASS. REC. BY:

REF: CS/ANA F702 3082 / T19672 Special Instruction:

Surveyor:

ASSIGNMENT (Office)

From (Person):

Peggy Chan

of

AWAC

Date/Time:

2:46pm @ 5/12/17

Estimated Cost:

Bill to:

OD ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKR 6112X

Insured:

GBF 2359Y

at Workshop m/s

Performance

Tel:

6319 0174

of

303 Alexandra Road

Policy No:

AVCP SB 0088041700

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A.

2/12/17

(Client's Record)

CA / REV / REP. / REV 24 HRS

'wp'

13.12.2017 @ 10am - 12pm

H.O.D. Endorsement:

Date/Time:

3:53pm @ 5/12/17

Person Contacted:

Caroline

Vehicle IN ~~OUT~~

Date/Time	Action/Instruction (✓) Estimate	any
	SKR 6112X - X	
	GBF 2359Y - X	
10/01/18 @ 11.17am	confirmed with Caroline final Ag \$ 8168.95, 4 days.	
	cred \$ 1924, 19%.	

Signature

Tan Jiah

REF: AWAC

ASSIGNMENT

From:

Date: 13/12/17

Estimated Cost:

OD: ☒ TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKR 6112 X

at Workshop n/s

of 303 Alexandra Road

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

10am-12pm

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Ball. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS 10p

Vehicle: IN / OUT

Date: Person Contacted:

Date / Time

Action / Instruction

Veh No: SKR 6112 X

Yr Regn: 2015 Feb

Type: ☒ Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 316

C.C. 1598

Colour: white

A/C Insured / Std / NI / NA

Sp. Reading: 44472

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

WSA 3A1607 ONS38547

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ Inorder / Jammed / Leaked / Burnt or

Brake: ☒ Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205 / 60R16

R: 205 / 60R16

☒ ES / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 6 mm

R/Bal: 6 mm

L/Bal: 6 mm

L/Bal: 6 mm

D.O.A.

D.O.I. 13/12/2017

Survey held at

PML

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Frt O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Signature

10/1/2018

RECEIVED 10 JAN 2018

Date/Time File Pass to?

☐

: Preli. Report

☐

: Final Report

Date/Time File Return to?

2)

Days Of Repair: 4

Resurvey No. of Trip:

Survey Fee

Transportation

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Insp (\$)

☐

: Weekend (\$)

: \$ - \$

: Phone:

: Other:

Report Format:

Lump Sum / I.B.I. (\$)

TP
8168.75

TOTAL

250



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ALLIED WORLD ASSURANCE COMPANY LTD

Ref : CS/AWA17023082/T1qb

(SINGAPORE BRANCH)
60 ANSON ROAD #08-01 (8th FLOOR)
MAPLE TREE ANSON
SINGAPORE 079914

Date : 05-12-2017



Code : AWA

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBF 2359Y	Veh. Inspected	SKR 6112X
Policy No.	AVCP SB0088041700	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	PEGGY CHAN	Assign Date	05/12/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	02/12/2017	Inspection Date
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941	

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

Survey Department Check List (Case Handler)

Reference No.: 65/ANNA/7073082/7196
Policy Type: OD (TP) TP RES / TL / EVA

SKR 6112X

Case Handler

Typist

Admin (Catherine): Case handler to make sure all Information created by the assignment team are ACCURATE.

(1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

Surveyor (Tunfirah): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

✓			
---	--	--	--

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

✓			
✓			
✓			

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

--	--	--	--

Check By:

Case Handler

Date

10/01/18

Nivitha (LKK Auto)

From: Chan, Peggy <Peggy.Chan@awac.com> on behalf of Motorsurvey <Motorsurvey@awac.com>
Sent: Tuesday, 5 December, 2017 2:46 PM
To: LKK (assignments@lkkauto.com) (assignments@lkkauto.com)
Cc: SUR (sur@lkkauto.com); PBSP (pml-pbsp@simedarby.com.sg) (pml-pbsp@simedarby.com.sg)
Subject: TP Survey assignment for SKR 6112X DOA: 02/12/2017 Our ref: GBF 2359Y/HLF

The above captioned accident refers.

Pursuant to the Practice Directions Amendment No. 1 of 2016 which was effective on 1 April 2016, we like to advise that the third party claimant and we have consensus in the appointment of **Mr. Mohamad Taufikh / Mr. Mohammed Rasul**, as the Single Joint Expert to conduct the pre-repair survey of the third party claimant's vehicle.

Please conduct "THIRD PARTY" survey on without prejudice basis. The information as are follows:

3 rd Party Vehicle	:	SKR 6112 X
Insured Vehicle	:	GBF 2359 Y
Policy Number	:	AVCPSPB0088041700
Name of Workshop	:	Performance Motors Limited
Contact Number	:	6319 0174
Person to Contact	:	Caroline
Estimated Cost of repairs	:	\$10,726.91

Regards,
Claims Division

Copy to Performance Motors Limited via Email.

Note -

- (x)
1. This is to keep you informed that we have appointed surveyors to conduct inspection to your client's damaged vehicle on a without prejudice basis.
 2. **We are agreeable to have direct settlement with you in respect to your client's claim with quantum to be agreed.**
 3. **Please keep our motor surveyor and us informed so as to enable the surveyor to conduct a post repair inspection once your client's vehicle has been repaired and before returning the repaired vehicle to your customer.**
 4. Please send us all relevant supporting documents once your client's vehicle has been repaired.
 5. We will write to you again upon receiving your claims documents. Please do not construe this appointment of surveyor and our above request as an admission of liability.

The information contained in this e-mail and any attachments hereto is confidential. If you are not the intended recipient, you must not use or disseminate any of this information. If you have received this e-mail in error, please immediately notify the sender by reply e-mail and permanently delete the original e-mail (and any attachments hereto) and any copies or printouts thereof. Although this e-mail and any attachments hereto are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by Allied World Assurance Company Holdings, GmbH or its subsidiaries or affiliates, either jointly or severally, for any loss or damage arising in any way from its use.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 10 January, 2018 11:12 AM
To: PBSP; Taufikh (LKKAUTO); SUR
Subject: RE: FINAL REPORT / SKR6112X

Dear Caroline,

Confirm final fig \$8,168.95 before GST and 4 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP [mailto:pml-pbsp@simedarby.com.sg]
Sent: Tuesday, 9 January, 2018 5:16 PM
To: Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: Fw: FINAL REPORT / SKR6112X

resend to include SUR <sur@lkkauto.com>

From: PBSP
Sent: Tuesday, 9 January 2018 5:14 PM
To: taufikh@lkkauto.com
Subject: FINAL REPORT / SKR6112X

Dear Taufikh

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 4,362.00
Total Parts : 3,806.95
Total Labour & Parts : 8,168.95

Repair days: 4

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/12/2017 15:12
Date Of Accident	02/12/2017 14:00
Exact Location Of Accident	HENDERSON WAVES
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKR6112X
Insured/Policyholder	
Name Of Registered Owner	OON TZE PUAN
NRIC No	S7232645H
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-98779467
Alternative Phone No	OFFICE-98779467

Vehicle Particulars

Manufacturer	BMW
Model	316
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	AXA INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	NOTAVAIL
Cover Note Number	

Driver

Name of Driver	TEO SOO LIANG
NRIC No	S7640293J
Date Of Birth	10/12/1976
Occupation	INDOOR
Date Of Driving Pass	27/06/1996
Driving Experience	21 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-98779467
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	10A CANBERRA DRIVE #04-20
Postcode	768143
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	SPOUSE
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-

General Information of the Accident

Type Of Accident	COLLIDED INTO PARKED VEHICLE
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Was any body injured in the Accident?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	0

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

REFER TO ATTACH.

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GBF2359Y
Vehicle Make/Model/Colour	
Details Of Properties	
Name of Driver	CHUA TEOW KHOON
NRIC/Passport Number	S1301877D
Contact Number	90308225
Address	
Postcode	
Insurance Company Name	ALLIED WORLD ASSURANCE COMPANY, LTD
Nature Of Damage	
No. Of Passenger (Including Driver)	

Details of Witness

Name	
Phone Number	
Email Address	

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
 (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

G 4/12/17
Policyholder's Signature / Date & Time
12.50pm

Sketch Plan

Approved 4/12/17
Driver's Signature (If driver is not the policyholder) / Date & Time
12.50pm

4/12/17 1250
GARY POK CHAI HOON
Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 119941
Witnessed by Reporting Centre Personnel




Sketch Plan Pg. 2


Describe Circumstances of the Accident

Parked at Henderson Waves Carpark 1.
Realized it was hit by lorry at time of collection.
Construction worker informed me that their bus hit
by car and gave me his contact number.

Declaration

I/We declare the foregoing particulars are true in every respect.

 4/12/17
Policyholder's Signature / Date &
Time 12.50pm

 4/12/17 12.50pm
Driver's Signature (If driver is not the policyholder) / Date
& Time

4/12/17 1250

GARY P. H. CHAI HOON
Performance Motors Limited
303 Alexandra Road
Sime Darby Performance Centre
Singapore 150041
Witnessed by Reporting Centre
Personnel

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No. M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159541
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

290, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63443773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

04 DEC 2017

Estimate No. : b1 45049
Date Estimated : 04/12/2017
Prepared By : Gary Poh Chai Hoon

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -

Oon Tze Puan (Wen ZiFan)
10A Canberra Drive
#04-20
Eight Courtyards
Singapore 768143

- ACCOUNT - 40000

Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKR6112X	NS38547	25/02/2015	316iA/4	0

DESCRIPTION

To Replace front bumper, right front fender and attachment
include knocking cause by the accident

VALUE

1700 / 2,550.00

Painting front bumper, right front fender.

173 / 1153. 1,923.00

To carry out body cavity preservation.
(Per panel).

100 / 118.00

To replace right headlight including program
and conduct tests for proper function.

451 / 531.00

To check electrical wiring systems at the front section
for proper function including adjustments of headlights.

150 / 177.00

To remove old PDC assembly, replace damaged parts and
reconnect to new bumper including conduct checks for
proper function.

150 / 177.00

Sundries.

me 80 ? 150.00

Total Labour 1: 5,626.00

DESCRIPTION

FRT RH SIDE PANEL
FRONT SHOCK ABSORBER
FRT BUMPER TOP MOUNT
Holder
FRT BUMPER TRIM PRIMED (SRA)
RH COVER SPRAY NOZZLE PRIMED
TELESCOPING NOZZLE RH
RH HEADLIGHT (XENON)

QTY	PRIC
1	665.85
1	40.15
1	352.90
1	114.85
1	958.80
1	30.75
1	152.10
1	2,083.75

VALUE

del / 665.85

? / 40.15

? / 352.90

? / 114.85

del / 958.80

cut / 30.75

? / 152.10

cut / 2,083.75

Total Parts : 4,399.15

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 45049
Date Estimated : 04/12/2017
Prepared By : Gary Poh Chai Hoon

Page No. : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKR6112X	NS38547	25/02/2015	316iA/4	0

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. 0 Date No.Date&Time 13/12/17 @ 11am Excess \$Surveyor's Name Tan Jiah Sign [Signature]Surveyor's Tel 97495149 Authorised Yes/No

Authorised Date _____ Time _____

RESURVEY PARTS PHOTO _____ Yes/No

Surveyor's E-mail tanjiah@lkkauto.comNo. of Working Days Recommended 4 days

[Signature]
4/1/18

Labour 1	:	5,626.00
Parts	:	4,399.15
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	701.76
Grand Total	:	10,726.91

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY**

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

10092.95

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 45049
Date Estimated : 04/12/2017
Prepared By : Gary Poh Chai Hoon

Page No. :

REPAIR FOR -

Oon Tze Puan (Wen ZiFan)
10A Canberra Drive
#04-20
Eight Courtyards
Singapore 768143

- ACCOUNT - 705

Allied World Assurance Company, Ltd SG br:
60 Anson Road
#09-01 Mapletree Anson
Singapore 079914

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE		
SKR6112X	NS38547	25/02/2015	316iA/4	0		
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT			
To replace front bumper and attachments, front RH fender include knocking out dents caused by the accident	1700.00		1,700.00			
To spray paint front bumper and front RH fender	1731.00		1,731.00			
To carry out body cavity preservation. (Per panel).	100.00		100.00			
To replace RH xenon headlight include programming and conducting tests for proper function	451.00		451.00			
To check electrical wiring systems at the front section for proper function including adjustments of headlights.	150.00		150.00			
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.	150.00		150.00			
Sundries.	80.00		80.00			

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
FRT RH SIDE PANEL	665.85	1.00		665.85
FRT BUMPER TRIM PRIMED (SRA)	958.80	1.00		958.80
RH COVER SPRAY NOZZLE PRIMED	30.75	1.00		30.75
# PLAQUE 82MM *	67.80	1.00		67.80
RH HEADLIGHT (XENON)	2,083.75	1.00		2,083.75

SUPPLEMENTARY ITEMS

Total Labour :	4,362.00
Total Parts :	3,806.95
Total Labour & Parts :	8,168.95
Deduction for Excess :	0.00
Total Repair Costs less Excess:	8,168.95
GST @7%:	571.83
Grand Total :	8,740.78

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 45049
Date Estimated : 04/12/2017
Prepared By : Gary Poh Chai Hoon

Page No. :

REPAIR FOR -
Oon Tze Puan (Wen ZiFan)
10A Canberra Drive
#04-20
Eight Courtyards
Singapore 768143

- ACCOUNT - 705
Allied World Assurance Company, Ltd SG br.
60 Anson Road
#09-01 Mapletree Anson
Singapore 079914

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE
SKR6112X	NS38547	25/02/2015	316iA/4	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# PLAQUE 82MM *	67.80	1.00		67.80

Total Labour :	
Total Parts :	67.80
Total Labour & Parts :	67.80



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ALLIED WORLD ASSURANCE COMPANY LTD

Ref : CS/AWA17023082/T1qbn2

(SINGAPORE BRANCH)
60 ANSON ROAD #08-01 (8th FLOOR)
MAPLETREE ANSON
SINGAPORE 079914

Date : 16-01-2018



Code : AWA

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBF 2359Y	Veh. Inspected	SKR 6112X
Policy No.	AVCPSP0088041700	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	PEGGY CHAN	Assign Date	05/12/2017

2. Vehicle Particulars & Condition

Make & Model	B.M.W 316I	c.c	1598
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	WBA3A16070NS38547	Colour	WHITE
Odometer	49472	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	205/60 R16	BRIDGESTONE	6 mm
L/H Front Tyre	205/60 R16	BRIDGESTONE	6 mm
R/H Rear Tyre	205/60 R16	BRIDGESTONE	6 mm
L/H Rear Tyre	205/60 R16	BRIDGESTONE	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT O/S PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	02/12/2017	Inspection Date	13/12/2017
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **4 Working Days**



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SKR 6112X

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FRT RH SIDE PANEL (SN)	DENTED	665.85	665.85
1	FRONT SHOCK ABSORBER (SN)	NOT NECESSARY	40.15	-
1	FRT BUMPER TOP MOUNT (SN)	NOT NECESSARY	352.90	-
1	HOLDER (SN)	NOT NECESSARY	114.85	-
1	FRT BUMPER TRIM PRIMED (SRA)(SN)	DEFORMED	958.80	958.80
1	RH COVER SPRAY NOZZLE PRIMED (SN)	CUT	30.75	30.75
1	TELESCOPING NOZZLE RH (SN)	NOT NECESSARY	152.10	-
1	RH HEADLIGHT (XENON)(SN)	CUT	2,083.75	2,083.75
1	PLAQUE 82MM (ADDITIONAL)(SN)	NECESSARY	67.80	67.80
1	SUNDRIES (SN)	NECESSARY	150.00	80.00
			4,616.95	3,886.95
LABOUR				
	TO REPLACE FRONT BUMPER,RIGHT FRONT FENDER AND ATTACHMENT INCLUDE KNOCKING CAUSED BY THE ACCIDENT.		2,550.00	1,700.00
	PAINTING FRONT BUMPER,RIGHT FRONT FENDER.		1,923.00	1,731.00
	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL).		118.00	100.00
	TO REPLACE RIGHT HEADLIGHT INCLUDING PROGRAM AND CONDUCT TESTS FOR PROPER FUNCTION.		531.00	451.00
	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION INCLUDING ADJUSTMENTS OF HEADLIGHTS.		177.00	150.00
	TO REMOVE OLD PDC ASSEMBLY,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION.		177.00	150.00
			5,476.00	4,282.00
GRAND TOTAL			10,092.95	8,168.95
RECOMMENDED COST OF REPAIRS				8,168.95

Report Ref No. CS/AWA17023082/T1qbn2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.