

REPAIR DETAILS**Reference**

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 08 Dec 2017)
 Parts: 143 CHEVROLET CRUZE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Progressive Automotive Pte Ltd/SGN6085J/08/12/2017 13:32
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

006247

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BONNET HINGE - LH	0.00	0.00	*25.00F ✓
2	2		*RADIATOR TOP BUSH	0.00	0.00	*12.00F ✓
Sub Total (S\$)						37.00
+ Margin on L,N Items 10.00% (S\$)						3.70
Total Parts (S\$)						40.70

F=Franchise part.

Progressive Automotive Pte Ltd/SGN6085J/08/12/2017 13:32. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

SUPP 40.70

PARTS 3100.35

LAB. 1570.00

4711.05

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 05 Dec 2017)
 Parts: 143 CHEVROLET CRUZE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: Progressive Automotive Pte Ltd/SGN6085J/05/12/2017 11:39
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

00 6247

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1	NA	*FRONT BUMPER / CEA	0.00	0.00	*580.00 F ✓
2	10	NA	*FRONT BUMPER CLIPS / PC	0.00	0.00	*15.00 F ✓
3	2	NA	*FRONT BUMPER SIDE HOLDER - LH & RH / PC	0.00	0.00	*16.00 F ✓
4	1	NA	*FRONT BUMPER REINFORCEMENT ?	0.00	0.00	*520.00 F
5	2	NA	*FRONT BUMPER FOG LAMP UNIT - RH & LH ?	0.00	0.00	270.00 F
6	2	NA	*FRONT BUMPER FOG LAMP COVER - RH & LH < LH - CEA ✓ RH x PC	0.00	0.00	12*24.00 F ✓
7	1	NA	*FRONT BUMPER LOWER SPOILER CEA	0.00	0.00	*40.00 F
8	1	NA	*FRONT BUMPER GRILLE ASSY / CEA	0.00	0.00	*160.00 F ✓
9	1	NA	*FRONT BUMPER GRILLE LOGO / PC	0.00	0.00	*F
10	1	NA	*FRONT BUMPER TOP RUBBER ?	0.00	0.00	*F
11	1	NA	*BONNET / Bue	0.00	0.00	*850.00 F ✓
12	1	NA	*BONNET GRILLE / CEA	0.00	0.00	*120.00 F ✓
13	1	NA	*BONNET LOCK X NA	0.00	0.00	*F
14	1	NA	*BONNET RUBBER - CENTRE /	0.00	0.00	*35.00 F ✓
15	2	NA	*BONNET RUBBER SIDE - RH & LH / PC	0.00	0.00	*20.00 F ✓
16	2	NA	*BONNET RUBBER, SMALL - RH & LH /	0.00	0.00	*F
17	1	NA	*BONNET INSULATOR / Bue	0.00	0.00	*85.00 F ✓
18	712	NA	*BONNET INSULATOR CLIPS / PC	0.00	0.00	10*50*12.00 F ✓
19	1	NA	*SUPPORT PANEL ?	0.00	0.00	*F
20	1	NA	*CONDENSER ?	0.00	0.00	*235.00 F
21	1	NA	*RADIATOR ?	0.00	0.00	*480.00 F
22	1	NA	*RADIATOR FAN MOTOR ?	0.00	0.00	*F
23	1	NA	*RADIATOR FAN COWLING ?	0.00	0.00	*185.00 F
24	1	NA	*HEADLAMP UNIT - LH / CEA	0.00	0.00	*450.00 F ✓
25	1	NA	*HEADLAMP UNIT - RH ?	0.00	0.00	*450.00 F
26	1	NA	*WIPER TANK ASSY ?	0.00	0.00	*85.00 F
27	1	NA	*WIPER TANK MOTOR ?	0.00	0.00	*48.00 F
28	1	NA	*FRONT FENDER - LH / Bue	0.00	0.00	*450.00 F ✓
29	1	NA	*FRONT FENDER COWLING - LH ?	0.00	0.00	*48.00 F
30	10	NA	*FRONT FENDER COWLING CLIPS - LH / PC	0.00	0.00	*15.00 F ✓
31	1	NA	*HORN ?	0.00	0.00	*42.00 F
32	1	NA	*WIPER GARNISH - LH X	0.00	0.00	*38.00 F
33	1	NA	*SUPPORT TOP PANEL ?	0.00	0.00	*205.00 F
34	1	NA	*SUPPORT PANEL HEADLAMP ?	0.00	0.00	*70.00 F

F=Franchise part.

Sub Total (\$\$)
 + Margin on L,N Items 10.00% (\$\$)

5,554.00
 555.40

2818.50

Total Parts (\$\$)

6,109.40

3100.35

Progressive Automotive Pte Ltd/SGN6085J/05/12/2017 11:39. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	COOLANT	20.00
2	1	FRONT NUMBER PLATE W/CASING	35.00
Sub Total (S\$)			55.00

006247

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Paintwork Labour</u>			
1	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	850/ 950.00
<u>Labour Items</u>			
2	TO KNOCK OUT DENTS ON LH FRONT CHASSIS; CUT/WELD SUPPORT PANEL; REMOVE; REPLACE ACCIDENT PARTS	New	600-800 1,000.00
3	TO CHECK WIRING	New	20.00
4	TO REMOVE; REPLACE CONDENSER AND REFILL GAS	New	100.00
Gross Labour Cost (S\$)			2,070.00 1570

Progressive Automotive Pte Ltd/SGN6085J/05/12/2017 11:39. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

Our equipment include the latest and reliable CAR-O-LINER MARK 5 repair bench, draw aligner and the support dolly system to provide accurate re-alignment and speedy repairs.

5-6 Days.
Excess = \$250
Authorized.
part by part ?
before paint photos.
Emo Riap - 8880282
05/12/17