

22/03/2002

ASS. REC. BY:

REF: CS/MSG17023085/Kthbn2

Special Instructions:

Surveyor

Kenneth

ASSIGNMENT (Office)

merman

From (Person):

Catherine Thia

of

MSTN

Date/Time: 05-12-2017 2:50pm

Estimated Cost:

Bill to:

OD ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SDN 8500A

Insured:

SKM 9206R

at Workshop m/s

Alan's United

Tel:

6453 8586

of

Blk 7 Sin Ming Ind Est #0176

Policy No:

39979661DMA

Claim No:

539343

Sum Insured:

Excess:

Make of Veh:

D.O.A. 26-11-2017

(Client's Record)

CA / REV / REP. / REV 24 HRS 'Wp'

06-12-2017

H.O.D. Endorsement:

Date/Time:

05-12-2017 4:18pm

Person Contacted:

Kenny

Vehicle IN/OUT

Date/Time

Action/Instruction (✓) Estimate

SDN 8500A - x

skm 9206R - x

13/12-19:17 revert via preli merman

Part by Part \$1485.82+ (Red: 280.30, 15%)

REF: MSIG

ASSIGNMENT

SON 8500A

SJW 8879P

CP 15

From: Date: 6/12/17

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

SJW 8879P

at Workshop no:

Alan's United

of Blk 7 Sin Ming Ind Est # 01-76575642

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record):

Make of Veh:

(Policy Condition):

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report: Consistent? Yes or No

GIA / PR Seen: Consistent? Yes or No

Est. Repairs: days Res: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

'wp'

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Infiniti Q50

1991

Colour:

M. Black

Insured / Std / NI / NA

Sp Reading:

55735

Radio Insured / Std / NI / NA

Eng No:

C/No:

JN1BCAV3780480369

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD / A/Rim or

Tyre Size:

R:

225/55R17

R:

ES / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front:

R. Bal:

4 mm

Rear:

R. Bal:

2 mm

L. Bal:

0 mm

L. Bal:

2 mm

D.O.A:

26/11/17

D.O.A:

6/12/17

Survey held at:

Des. of Damages: Frt / Rear / OIS / NS / UIC / Rooftop or

Rear OIS

The UIC / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

7/12 File pass to Customer

15/12/2017

RECEIVED 15 DEC 2017

Date/Time: File Received:



Prelim. Report

12/12 Typist



Final Report

Date/Time: File Returned:

Days Of Repair: 2

Resurvey No. of Trip: 1

Add Fee:



Sta Insp: \$



Interview: \$



Tech Insp: \$



Repairs: \$

Survey Fee:

Transportation:

Other:

Total:

Grand Total:

200

10

210

Report Format:

TP

Lump Sum / B/B:

148582



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD			Ref : CS/MSG17023085/Ktb	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 05-12-2017	
			Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKM 9206R	Veh. Inspected	SDN 8500A	
Policy No.	39979661DMA	Coverage (\$)	0.00	
Claim No.	539343	Excess (\$)	0.00	
Assign From	MERIMEN (CATHERINE THIA)	Assign Date	05/12/2017	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	26/11/2017	Inspection Date	06/12/2017	
Survey held at	ALAN'S UNITED AUTO PTE LTD BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 SINGAPORE 575642			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING						
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd
Main	05 Dec 2017		05 Dec 2017 14:50 Assign			
						New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	----------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:

Mr Kok Miew Chei, ID: S1385120D

Main Claimant:

Kloon Risk Management Pte Ltd, Co. Reg. No.: 200720902M

Vehicle Reg. No.:

SDN8500A

Claim Type:

TP / 539343

Vehicle Reg. No. (Insured):

SKM9206R

Repairer:

Alans United Auto Pte Ltd (HQ) BLK 7 SIN MING INDUSTRIAL ESTATE #01-76, 575642 Sin Ming - Tel:

Handling Insurer:

MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]

Adjuster:

LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 06/12/2017]

Adj Asg. Remarks:

Car in and workshop requested for LKK as they are going down to survey one of the car tomorrow. Thank you.

Date of Loss:

26/11/2017 13:00 - :59

Policy/Cover Note No.:

39979661DMA
Coverage: 24/04/2017 - 23/04/2018

Policy No. (Claimant):

Excess:

View All

Compose Case Mail

ASSOCIATED MAIL RECEIVED

There are no mail for this case.

ALL ASSOCIATED TASKS

View All

Search Tasks

Create New Task

Complete

Due Date

Priority

Type

Task Group

Subject

Handler

Assigned By

Completed On

Created On

Done?

No results.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Catherine Thia Shi Yi

Date: 13 Dec 2017

Preliminary Advice

Insured Vehicle No	: SKM9206R	Accident Date	: 26/11/2017
TP Vehicle No	: SDN8500A	Assignment Date	: 05/12/2017
Make	: INFINITI Q50	Est. Duration of Repair	: 0.00
Date of Inspection	: 06/12/2017		
Inspection At	: ALANS UNITED AUTO PTE LTD (HQ) BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 SINGAPORE 575642		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear o/s. portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	1,765.82
Revised Amount	:S\$	1,285.83
Check Items (Estimated)	:S\$	400.00
Total	:S\$	1,685.83

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (x) The above survey was conducted on a 'without prejudice' basis.

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 05680

Vehicle Insured : SKM9206R
Accident Date : 26-Nov-2017

Date : 04-Dec-2017

Our Ref : 217185 (MSIG) / CHAN

PAGE : 1

KLOON RISK MANAGEMENT PTE LTD
71 DA SILVA LANE FORTUNA GARDEN
Singapore 549794

*Not Authorised
Resurvey B&P only*

ESTIMATED COST OF REPAIR FOR INFINITI Q50 PREMIUM SDN8500A =====

1 pc Rear bumper fascia

R 1,184.25 *✓*

1,184.25

Less 10% : 118.43

1,065.82

To putty and spray replaced parts

300.00 *220*

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

400.00 *700*

Total : S\$ 1,765.82
=====

Singapore Dollars One Thousand Seven Hundred
and Sixty Five and Cents Eighty Two Only

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey (including spray painting)
- To display (and part(s) during resurvey)
- Parts prices are subject to confirmation
- Third party claims on a "Without Prejudice" basis
- No illegal insurance practices allowed
- Supplemental claims are subject to investigation and
is subject to the relevant insurance company

Acknowledged:

Signature:

Date:

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : SKM9206R
Accident Date : 26-Nov-2017

Our Ref : 217185 (MSIG) / CHAN

KLOON RISK MANAGEMENT PTE LTD
71 DA SILVA LANE FORTUNA GARDEN
Singapore 549794

No. : 05680

Date : 04-Dec-2017

PAGE : 1

*Not Withheld
Resurvey B4 price*

ESTIMATED COST OF REPAIR FOR INFINITI Q50 PREMIUM SDN8500A

1 pc Rear bumper fascia

Buttress ~~1,184.25~~ *✓*

1,184.25

Less 10% : 118.43

1,065.82 *✓*

To putty and spray replaced parts

300.00 *220 ✓*

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

400.00 *7200 ✓*

Total : S\$ 1,765.82

Singapore Dollars One Thousand Seven Hundred
and Sixty Five and Cents Eighty Two Only

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplemental charges are allowed and is subject to confirmation

Acknowledged:
Signed:
Date:

*P 1065.82
L 420.00
1485.82 ✓
7 days
KENNETH PUS GEMM
Thomas.*

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17023085/KTBN2
Date: 19/12/2017

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	39979661DMA
Claimant:	SDN8500A	Insured Vehicle No:	SKM9206R
Vehicle No:		Nature of Claim:	TP
Date of Loss:	26/11/2017	Claim No:	539343

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SDN8500A	Engine No:	274AE011541A
Make & Model:	INFINITI Q50, 2.0 T Premium (A)	Chassis No:	JN1BCAV37Z0480369
Reg. Date:	22/09/2015 (Man. Year: 2015)	Odometer:	55735 km
Colour:	Metallic Black		
Engine Capacity:	1991 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/55R17	Rear Tyre Size:	225/55R17
Front Left Side:	Bridgestone 4 mm	Rear Left Side:	Bridgestone 2 mm
Front Right Side:	Bridgestone 4 mm	Rear Right Side:	Bridgestone 2 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	1,065.82	1,065.82	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	700.00	420.00	280.00	40.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,765.82	1,485.82	280.00	15.86
+ GST 7.00/7.00% (S\$)	123.61	104.01	19.60	15.86
Nett Amount (S\$)	1,889.43	1,589.83	299.60	15.86

INSPECTION

Date of Assignment:	05/12/2017	
Date Inspected:	06/12/2017 Inspected At:	Alans United Auto Pte Ltd (HQ) BLK 7 SIN MING INDUSTRIAL ESTATE #01-76 Singapore 575642

Estimated Period of Repair: 2.0 days

Adjuster: KENNETH KONG

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 19 Dec 2017)
Parts: 143 INFINITI Q50 2.0 T Premium (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SDN8500A)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER FASCIA	Buckled/Warped	1,184.25 FL	*1,184.25 FL
						F=Franchise part, L=ListItemDisc.
					Sub Total (S\$)	1,184.25
					- List Item Discount on L Items 10.00/10.00% (S\$)	118.43
					Total Parts (S\$)	1,065.82

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO PUTTY AND SPRAY REPLACED PARTS	New	300.00	220.00
2	TO REMOVE,CUT-OUT DAMAGED PARTS,PANEL BEATING,WELDING,ALIGN,REFIX AND TO RENEW ABOVE PARTS	New	400.00	200.00
Gross Labour Cost (\$\$)			700.00	420.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >