

SME MOTOR PTE LTD

1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit, Singapore 417883

Tel: 6747 6106 (6 Lines) Fax: 6744 2368

Email: service@smemotor.com.sg Website: www.smemotor.com.sg

Co. & GST Reg. No: 201119451E

INSURER: **MSIG Insurance (Singapore) Pte. Ltd. (HQ)****PARTICULARS OF CLAIM**

Claim Type:	OD (OWN DAMAGE)	Ref. No:	17/MSIG/OD-569 (12)
Policy No:	A28817353QMX	Date of Loss:	01/12/2017
Vehicle Reg. No.:	SKA7625R	Driveable?	
Driver Age/Info:	46 / FEMALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	CHEW MEI FONG	Contact No:	+6597269611
Driver:	CHEW MEI FONG		

Make/Model:	BMW 523i, 2.5 (A)	Vehicle Reg. Date:	31/03/2011
Vehicle Colour:	SILVER	Chassis No:	WBAFP32040C865439
Engine No:	10697716N52B25AF		
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair 14 (day)			

Not Authorised p/p
Make
Take up before party
Excess \$600
6 day

Description of Accident/Loss: FRONT VEHICLE SUDDENLY STOP. I CANNOT STOP IN TIME AND HIT VEHICLE B REAR PORTION.

Remarks: VEHICLE IN.

Present Location: SME MOTOR PTE LTD (KAKI BUKIT)

COST OF CLAIMS

	Amount
Parts	13,853.40
Miscellaneous Items	65.00
Labour	1,630.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (\$\$)	15,548.40
- Excess (\$\$)	600.00
Signature:	(\$\$) 14,948.40
Date:	+ GST 7.00% (\$\$) 1,046.39

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REPAIR DETAILS**Reference**

Part Source: MRM-SG

Version: 1.0 (Last Synchronised: 04 Dec 2017)

Parts: 143

BMW 523i 2.5 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's

(Price-denominated Standard List)

Print Code: SME Motor Pte Ltd/SKA7625R/04/12/2017 12:03

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BONNET <i>Buc</i>	0.00	0.00	*1,560.00 F
2	2		*FRT BONNET LOCK CATCH TOP (SIDES) <i>Surf/Twi</i>	0.00	0.00	*160.00 F
3	1		*FRT BONNET LOCK CATCH TOP (CENTER) <i>Twi</i>	0.00	0.00	*50.00 F
4	2		*FRT BONNET LOCK LOWER (SIDES) <i>Twi</i>	0.00	0.00	*390.00 F
5	1		*FRT BONNET LOCK CABLE <i>11</i>	0.00	0.00	*26.00 F
6	2		*FRT GRILLE <i>320</i>	0.00	0.00	*230.00 F
7	1		*FRT BUMPER <i>D.S</i>	0.00	0.00	*1,050.00 F
8	2		*FRT BUMPER RETAINER <i>0/5 Surf</i>	0.00	0.00	*36.00 F
9	1		*FRT BUMPER CENTER LOGO <i>nu</i>	0.00	0.00	*95.00 F
10	10		*FRT BUMPER CLIP <i>nu</i>	0.00	0.00	*20.00 F
11	1		*FRT BUMPER TOP RUBBER SEAL <i>Twi</i>	0.00	0.00	*35.00 F
12	1		*FRT BUMPER TOWING COVER <i>To.1</i>	0.00	0.00	*32.00 F
13	2		*FRT BUMPER PARKING SENSOR <i>shad</i>	0.00	0.00	*330.00 F
14	2		*FRT BUMPER PARKING SENSOR SEAL <i>nu</i>	0.00	0.00	*10.00 F
15	1		*FRT BUMPER LOWER GRILLE CENTER <i>11</i>	0.00	0.00	*60.00 F
16	2		*FRT BUMPER LOWER GRILLE SIDES <i>0/5 Twi</i>	0.00	0.00	*130.00 F
17	1		*FRT BUMPER INNER SPONGE <i>Cne</i>	0.00	0.00	*40.00 F
18	1		*FRT BUMPER REINFORCEMENT <i>DD</i>	0.00	0.00	*495.00 F
19	1		*FRT BUMPER PARKING SENSOR WIRE <i>To.1</i>	0.00	0.00	*120.00 F
20	2		*HEADLAMP <i>0/5 320</i>	0.00	0.00	*3,160.00 F
21	1		*RH HEADLAMP NOOZLE <i>nu</i>	0.00	0.00	*150.00 F
22	1		*HEADLAMP NOOZLE HOSE <i>To.1</i>	0.00	0.00	*60.00 F
23	1		*RH HEADLAMP NOOZLE COVER <i>To.1</i>	0.00	0.00	*50.00 F
24	1		*AIR BUFFER <i>D.S</i>	0.00	0.00	*240.00 F
25	1		*CENTER TOP PANEL (OUTER) <i>bul</i>	0.00	0.00	*165.00 F
26	2		*HEADLAMP PANEL <i>0/5 Surf</i>	0.00	0.00	*270.00 F
27	2		*HEADLAMP PANEL TOP GARNISH <i>0/5 Twi</i>	0.00	0.00	*60.00 F
28	1		*CENTER TOP PANEL (INNER) <i>11</i>	0.00	0.00	*90.00 F
29	1		*AIRCON CONDENSER <i>bul/pun</i>	0.00	0.00	*700.00 F
30	1		*RADIATOR <i>bul/pun</i>	0.00	0.00	*680.00 F
31	1		*RADIATOR FAN ASSY <i>SVC</i>	0.00	0.00	*850.00 F
32	2		*FRT BUMPER INNER GARNISH <i>D.S</i>	0.00	0.00	*100.00 F
33	1		*FRT BUMPER FOG LAMP RH <i>Cne</i>	0.00	0.00	*185.00 F
34	1		*FRT RH FENDER <i>DD/320</i>	0.00	0.00	*620.00 F
35	1		*FRT RH FENDER INNER COWLING (FRT) <i>To.1</i>	0.00	0.00	*120.00 F
36	10		*INNER COWLING CLIP <i>nu</i>	0.00	0.00	*25.00 F
37	2		*FRT FENDER INNER TOP GARNISH <i>To.1</i>	0.00	0.00	*140.00 F
38	12		*FRT FENDER INNER TOP GARNISH CLIP <i>nu</i>	0.00	0.00	*60.00 F

F=Franchise part.

Sub Total (\$\$)

12,594.00

+ Margin on L,N Items 10.00% (\$\$)

1,259.40 *9740*

SME Motor Pte Ltd/SKA7625R/04/12/2017 12:03. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	NUMBER PLATE	310 40.00 35 ✓
2	1	RADIATOR COOLANT	100 25.00 ✓
Sub Total (S\$)			65.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	WIRE CHECKING	New	30.00 ✓
2	REMOVE & REFIX AIRCON AND GAS	New	100.00 ✓
3	LABOUR CHARGE	New	700.00 600
4	SPRAY PAINTING	New	800.00 700
Gross Labour Cost (S\$)			1,630.00

SME Motor Pte Ltd/SKA7625R/04/12/2017 12:03. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

10895
102
11984.50
1490
13474.50