

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Joslin Lim

Date: 06 Dec 2017

Preliminary Advice

Vehicle No	: SKA7625R	Accident Date	: 01/12/2017
Make	: BMW 523I	Policy No.	: A28817353QMX
Assignment Date	: 05/12/2017	Excess	: S\$600.00
Date of Inspection	: 05/12/2017	Est. Duration of Repair	: 6.00
Inspection At	: SME MOTOR PTE LTD (KAKI BUKIT) 1 KAKI BUKIT AVE 6 #02-15, AUTOBAY @ KAKI BUKIT SINGAPORE 417883		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,548.40
Revised Amount	:S\$	9,795.00
Check Items (Estimated)	:S\$	3,526.60
Total	:S\$	13,321.60

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	66,000.00
COE / PARF Rebate	:S\$	46,345.00
Salvage Value	:S\$	
Margin for Repair	:S\$	19,655.00

Remarks

(X) The vehicle is economical for repair. Kindly let us have your approval please.

() The above survey was conducted on a 'without prejudice' basis.