

ASS. REC. BY:

REF: CS/MSG17023089 / U76172
Special Instruction:

SUPERVISOR:

ASSIGNMENT (Office)

From (Person):

Catherine Thia of MSIG Date/Time: 5/12/17 @ 2:44pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SFU 9751 A

Insured:

SJS 2286 K

at Workshop m/s

Jin Auto Services

Tel:

6289 8126

of

Blk 14 Defu Lane 10, # 01-412 539195

Policy No:

P28997667DMV

Claim No:

539356

Sum Insured:

Excess:

Make of Veh:

D.O.A.

3/12/17

(Client's Record)

CA / REV / REP. / REV 24 HRS

'wp'

H.O.D. Endorsement:

Date/Time:

4:19pm @ 5/12/17

Person Contacted:

Joyce

Vehicle IN / OUT

Date/Time

Action/Instruction (✓) Estimate

SFU 9751 A - X

SJS 2286 K - X

Surveillance (MORCU)

REF:

MS16/

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: SFU 975/A
 at Workshop m/s Jin Ang P.K.S
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: 17500
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: 2 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

\$200
 Vehicle: IN / OUT

Veh No: SFU 975/A Yr Regn: ST 05
 Type: M. Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or (M)
 Make: Nissan Sunny C.C. 1597
 Colour: Gold AC: Insured / Std / NI / NA
 Sp. Reading: 223872 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: JN1CFAN1680509977
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Modi: Nil / S/Rim / STD A/Rim or
 Tyre Size: F: 185/65 R15
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or FALKEN

Front 6 mm Rear 6 mm
 R/Bal. 6 mm L/Bal. 6 mm
 D.O.A. 3/12/17 D.O.I. 6/12/17
 Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear O/S
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction 27A 15053 2 yrs. 5 mth.

21/12/17 confund 2/5 & 1300 with Jours. (Red: 1095.65 : 45%)

RECEIVED 21 DEC 2017

Date/Time, File Pass to?

1) 21/12 Typst
 Date/Time, File Return to?

2)

Report Format :

Lump Sum / I.B.I: (\$

TP
1300

Days Of Repair: 2

Resurvey No. of Trip: 1

Add Fee:

☐ Site Insp (\$) \$ + RS \$
☐ Interview (\$) Photos
☐ Tech. Invs (\$) Others
☐ Weekend (\$)

Survey Fee:
 Transportation:

TOTAL

200
10
210



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG17023089/Ut6	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 05-12-2017	
		Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJS 2286K	Veh. Inspected	SFU 9751A
Policy No.	P28997667DMV	Coverage (\$)	0.00
Claim No.	539350	Excess (\$)	0.00
Assign From	MERIMEN (CATHERINE THIA)	Assign Date	05/12/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	03/12/2017	Inspection Date	
Survey held at	JIN AUTO SERVICES PTE LTD BLK 14 DEFU LANE 10 #01-412 SINGAPORE 539195		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Ref	Adj Submitted	Ins Approved	Status
Main	05 Dec 2017		05 Dec 2017 14:44 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	PERUMAL MANIMARAN, ID: S2715085C, Tel: +6591823198, Email: NOEMAIL		
Main Claimant:	TOO LEONG KOON, ID: S2006640G		
Vehicle Reg. No.:	SFU9751A	Date of Loss:	03/12/2017 09:00 - :59
Claim Type:	TP / 539350	Policy/Cover Note No.:	P28997667DMV (Comprehensive) Coverage: 04/08/2017 - 03/08/2018
Vehicle Reg. No. (Insured):	SJS2286K	Policy No. (Claimant):	
		Excess:	
Repairer:	Jin Auto Services Pte Ltd (Defu) Blk 14 Defu Lane 10, #01-410/412, 539195 Defu Lane - Tel: 6289 8126		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Catherine Thia Shi Yi - 6594 2545]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 06/12/2017]		
Driver/Custodian (Insured):	PERUMAL MANIMARAN (58 / Male), NRIC: S2715085C, Tel: +6591823198		
Adj Asg. Remarks:	SFU9751A can be inspected AT : Blk 14 Defu Lane 10 #01-412 Singapore 539195 Contact Person: Ms. Jouis Tel: 62898126		

ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Nur Amirah Binte Mohamed Yunos

From: Nabilah Rasol
Sent: Tuesday, December 05, 2017 10:43 AM
To: Nur Amirah Binte Mohamed Yunos
Subject: FW: Accident involving vehicle SFU9751A & SJS2286K ON 03/12/2017
Attachments: SFU9751A_03122017 NTUC (TP).pdf

Follow Up Flag: Follow up
Flag Status: Flagged

*A. Lim
✓
Jaya*

Thank you!

From: Joslin Lim
Sent: Tuesday, 5 December, 2017 10:35 AM
To: Catherine Thia <catherine_thia@sg.msigg-asia.com>; Nabilah Rasol <nabilah_rasol@sg.msigg-asia.com>
Cc: Christopher Chionh <christopher_chionh@sg.msigg-asia.com>; Jason Sim <Jason_Sim@sg.msigg-asia.com>; Foo Ai Ngoh <aingoh_foo@sg.msigg-asia.com>
Subject: FW: Accident involving vehicle SFU9751A & SJS2286K ON 03/12/2017

Hi Catherine and Nabilah

Fyna

Merry Christmas and Happy New Year

Joslin Lim

Senior Admin Officer, Claims Services (Motor)

Direct line +65 6643 1327 | Direct fax +65 6225 7402 | joslin_lim@sg.msigg-asia.com



MSIG



MSIG Insurance (Singapore) Pte. Ltd. 16 Raffles Quay, #24-01 Hong Leong Building, Singapore 048581 | Tel +65 6220 9644 | Fax +65 6225 6371 | Co. Reg. No. 200412212G | <http://www.msigg.com.sg/> | Follow us on



A member of **MS&AD** INSURANCE GROUP

From: Agnes Lee
Sent: Tuesday, 5 December, 2017 10:20 AM
To: Joslin Lim <joslin_lim@sg.msigg-asia.com>
Subject: FW: Accident involving vehicle SFU9751A & SJS2286K ON 03/12/2017

From: Jouis [<mailto:jouis@jinauto.com.sg>]
Sent: 05 December 2017 10:15
To: Claims <claims@sg.msigg-asia.com>
Subject: Accident involving vehicle SFU9751A & SJS2286K ON 03/12/2017

Without Prejudice

Dear Sir/Madam

Accident involving vehicle SFU9751A & SJS2286K ON 03/12/2017

We are assisting owner of SFU9751A to repair his motor vehicle to assist in his third party claim recovery against SJS2286K

Please be informed that SFU9751A can be inspected AT :

**Blk 14 Defu Lane 10
#01-412 Singapore 539195
Contact Person: Ms. Jouis
Tel: 62898126**

We would be appreciate if could revert to us on the liability urgently .

Your kind attention into the above is greatly appreciated.

With Regards,
Jouis Seow
Jin Auto Services Pte Ltd
Blk 14 #01-412 Defu Lane 10
Singapore 539195.

Tel : (65) 62898126
Fax : (65) 62870590

CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type	Singapore NRIC
Owner ID	6640G

Vehicle Details

Vehicle No.	SFU9751A
Vehicle to be Exported	No
Intended De-registration Date	06 Dec 2017
Vehicle Make	NISSAN
Vehicle Model	SUNNY 1.6EXM
Primary Colour	Gold
Manufacturing Year	2005
Engine No.	QG16373356
Chassis No.	JN1CFAN16Z0509977
Maximum Power Output	81.0 kW (108 bhp)
Open Market Value	\$11,789.00
Original Registration Date	20 May 2005
First Registration Date	20 May 2005
Transfer Count	0
Actual ARF Paid	\$12,968.00

Intended PARF Rebate Details

PARF Eligibility	Forfeited
PARF Eligibility Expiry Date	-
PARF Rebate Amount	\$0.00

Intended COE Rebate Details

COE Expiry Date	30 Apr 2020
COE Category	A - Car (1600cc & below)
COE Period(Years)	5
PQP Paid	\$31,361.00
COE Rebate Amount	\$15,053.00
Total Rebate Amount	\$15,053.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 06 Dec 2017

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62898126 Fax :62870590

Company Reg No:200704370C GST Reg No ::200704370C

DATE : 5/12/2017

M/S MSIG Insurance Ltd

DEAR SIR / MADAM

ESTIMATE REPAIR COST FOR SFU9751A

- | | | |
|-----|-------|---|
| 01) | 1 PC | REAR BUMPER |
| 02) | 1 SET | REAR BUMPER CLIPS |
| 03) | 1 PC | REAR BUMPER MOULDING |
| 04) | 1 PC | REAR BUMPER SIDE RETAINER |
| 05) | 1 PC | REAR BUMPER RH BRACKET |
| 06) | 1 PC | REAR LAMP |
| 07) | 1 PC | TAILLAMP LOWER RETAINER |
| 08) | 1 PC | SPRAY PAINTING |
| 09) | 1 PC | TUFF COAT |
| 10) | 1 PC | TO REMOVE AND REFIX SENSOR |
| 11) | 2 PCS | CHECK WIRING |
| 12) | 1 PC | LABOUR CHARGE TO REMOVE AND RENEW PARTS |

NETT ITEM

10	\$	452.50	✓
11	\$	40.00	✓
12	\$	175.20	✓
13	\$	30.70	✓
14	\$	86.60	✓
15	\$	360.20	✓
16	\$	33.30	✓
	\$	1,178.50	
Less 10%	\$	(117.85)	
	\$	1,060.65	
	\$	750.00	400
17	\$	80.00	✓
	\$	100.00	50
	\$	25.00	20
	\$	380.00	250
	\$	2,395.65	

1058.6

952.74
1672.74

Not Admit
1/5 \$1300/2
2 dy.

Why to other rep -
6/12/17

Consultants hence notify
of the following:
Before/after spray painting
The damaged part(s) during resurvey
The survey is on a "Without Prejudice" basis
The repair work is allowed
The item(s) must be resurveyed and
subject to final approval from Insurance Company

Witnessed by Repairer
Signature:

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG17023089/UTBN2

Date: 22/12/2017

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	P28997667DMV
Claimant Vehicle No :	SFU9751A	Insured Vehicle No :	SJS2286K
Date of Loss:	03/12/2017	Nature of Claim:	TP
		Claim No:	539350

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SFU9751A	Engine No:	QG16373356
Make & Model:	NISSAN SUNNY, 1.6 EX (M)	Chassis No:	JN1CFAN16Z0509977
Reg. Date:	20/05/2005 (Man. Year: 2005)	Odometer:	223872 km
Colour:	Gold		
Engine Capacity:	1597 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/65R15	Rear Tyre Size:	185/65R15
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	1,060.65	952.74	107.91	10.17
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,335.00	720.00	615.00	46.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	2,395.65	1,672.74	722.91	30.18
Approved Total (Overridden) (S\$)		1,300.00		
(S\$)	2,395.65	1,300.00	1,095.65	45.73
+ GST 7.00/7.00% (S\$)	167.70	91.00	76.70	45.74
Nett Amount (S\$)	2,563.35	1,391.00	1,172.35	45.74

INSPECTION

Date of Assignment: 05/12/2017

Date Inspected: 06/12/2017 Inspected At:

Jin Auto Services Pte Ltd (Defu)
Blk 14 Defu Lane 10, #01-410/412
Singapore 539195

Estimated Period of Repair: 2.0 days

Adjuster: MARCUS CHUA

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 22 Dec 2017)
Parts:	143	NISSAN SUNNY 1.6 EX (M) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SFU9751A)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented	452.50 FL	*452.50 FL
2	1		*SET REAR BUMPER CLIPS	Necessary	40.00 FL	*40.00 FL
3	1		*REAR BUMPER MOULDING	Bent	175.20 FL	*175.20 FL
4	1		*REAR BUMPER SIDE RETAINER	Bent	30.70 FL	*30.70 FL
5	1		*REAR BUMPER RH BRACKET	Not Necessary	86.60 FL	*- FL
6	1		*REAR LAMP	Cracked	360.20 FL	*360.20 FL
7	1		*TAILLAMP LOWER RETAINER	Not Necessary	33.30 FL	*- FL
					Sub Total (S\$)	1,178.50
					- List Item Discount on L Items 10.00/10.00% (S\$)	117.85
					Total Parts (S\$)	1,060.65
						952.74

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items**There are no new miscellaneous items selected.****Recommended Labour**

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	SPRAY PAINTING	New	750.00	400.00
2	TUFF COAT	New	80.00	-
3	TO REMOVE AND REFIX SENSOR	New	100.00	50.00
4	CHECK WIRING	New	25.00	20.00
5	LABOUR CHARGE TO REMOVE AND RENEW PARTS	New	380.00	250.00
Gross Labour Cost (S\$)			1,335.00	720.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >