

Jin Auto Services Pte Ltd

Blk 14 Defu Lane 10 #01-412

Singapore 539195

Tel:62898126 Fax :62870590

Company Reg No:200704370C GST Reg No ::200704370C

5/12/2017

M/S AIG

ESTIMATE REPAIR COST FOR SGE 7435Z

Not AIG
N/A
1/5 \$ 2050/2
To be paid. After repair
3 days
6/12/17

S/N	QTY	DESCRIPTION
1	1 PC	REAR BUMPER
2	1 PC	REAR BUMPER CLIPS
3	1 PC	REAR BUMPER RETAINER
4	1 PC	REAR RH LAMP
5	1 PC	REAR RH DOOR
6		REAR RH RIM
7		SPRAY PAINT
8		TRANSFER OF REVERSE SENSOR
9		WHEEL ALIGNMENT
10		TUFF KOTE
11		LABOUR CHARGE
12		WIRING CHECK

DD	\$	470.70	✓
re	\$	30.00	✓
st	\$	57.10	✓
sin	\$	472.60	✓
DD/Rep	\$	1,122.80	✓
	\$	2,153.20	
LESS 25%	\$	(538.30)	
	\$	1,614.90	
n	\$	424.80	X
	\$	400.00	✓
	\$	120.00	50
	\$	120.00	60
	\$	80.00	30
	\$	680.00	400
	\$	25.00	20
	\$	3,464.70	

2574.9

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: