

DING AUTO PTE LTD

Blk 10, #01-20

Sin Ming Industrial Est. Sec C

Singapore 575645

Tel: 6452 1208

Fax: 6452 0614

Vehicle:	XE872P
Model:	TGS 35.360 8X4 BB
Chassis:	WMA37SZZ6FM669819

NO	DESCRIPTION	QTY	LIST	DISC	PRICE	SURVEYORS MARKING
1	MUDGUARDS STEPPWELL LEFT GRAY <i>CPA</i>	1	\$ 1,133.34	10%	\$ 1,020.01	✓
2	STEAL BUMPER <i>Not part</i>	1	\$ 1,437.50	10%	\$ 1,293.75	✓
3	OVAL-HEAD SELF-TAPING SCREW <i>Sm</i>	8	\$ 8.40	10%	\$ 60.48	X
4	FLASHER FRONT	1	\$ 250.10	10%	\$ 225.09	?
5	HEADLAMP LEFT SIDE	1	\$ 769.70	10%	\$ 692.73	?
6	REAR BUMPER END PANEL BRACKET LEFT	1	\$ 124.20	10%	\$ 111.78	?
7	STEP PANEL METAL PLATE	2	\$ 256.70	10%	\$ 462.06	X
TOTAL:					\$ 3,865.90	

	LABOUR	PRICE	SURVEYOR MARKING
8	STRAIGHTEN & PANEL BEAT ACCIDENT AREAS	\$ 1,200.00	500
9	R & R FRONT BUMPER	\$ 400.00	?
10	R & R ELECTRICAL WIRINGS, CHECK LIGHTING AND RESET HEADLAMP FOCUSING	\$ 100.00	201
11	RESPRAY FRONT BUMPER & MUDGUARD STEPPWELL <i>nn</i>	\$ 500.00	X
TOTAL:		\$ 2,200.00	

PARTS	\$ 3,865.90
LABOUR	\$ 2,200.00
TOTAL	\$ 6,065.90
GST 7%	\$ 424.61
FINAL TOTAL	\$ 6,490.51

*Not withered
1.2.1
Respray B4 paint
3 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: