

RECEIVED 08 MAY 2018

THIRD PARTY CLAIM

Date: 03 May 2018

Name & Address Of Claimant:

Tay Kim Huan

C/O: KAN FOOK SING MOTOR WORKSHOP 61 DEFU LANE 12 SINGAPORE 539147

Name & Address Of Third Party Insured:

FWD Singapore Pte Ltd

6 Temasek Boulevard #18-01 Suntec Tower 4 Singapore 038986

Dear Sir/Madam,

Accident involving vehicles

SLB 3660Y

&

SKTH214M

on

1/12/2017

along/ at

along mce towards kpe

I am the owner of vehicle registration no:

SLB 3660Y

which was involved in the

above mentioned vehicle registration no:

SKTH214M

which I understand is insured

with you.

The accident was clearly caused by your insured's negligence and I am therefore claiming compensation from you for all financial losses as itemized below:-

1 Repair Costs		S\$ <u>33,748.44</u>
2 Miscellaneous Items		S\$ <u>—</u>
3 Surveyor Fee		S\$ <u>—</u>
4 LTA/GIA Search Fee		S\$ <u>—</u>
5 Loss of Use /		
Rental for	<u>62</u> days @ S\$ <u>107.00</u> per day	S\$ <u>6,634.00</u>
6 Excess		S\$ <u>—</u>
7 Medical Fee **		S\$ <u>TBA</u>
TOTAL:		S\$ <u>40,382.44</u>

I enclosed the relevant copies of documents in support of my claims. Your prompt settlement of my claim would be much appreciated. If you require any other information, please contact my workshop at **KAN FOOK SING MOTOR WORKSHOP**, 61 Defu Lane 12 Singapore (539147), Tel: 6747 9560 Fax: 6748 1006. I have authorized the said workshop to deal with my repairs & accept payment in relation to the claim for repairs/loss of use & execute documents on my behalf for the purpose of my convenience.

\*\* Strictly without prejudice to bodily injury claim.

Thank you.

Your faithfully



AUTHORISATION FORM

TO:-

KAN FOOK SING MOTOR WORKSHOP  
61 DEFU LANE 12  
SINGAPORE 539147

FROM:-

NAME: Tay Kim Hwat  
NRIC NO: S77248214

Dear Sir/Madam

Accident on 1/12/2017 involving vehicles SLB3660Y & SRT 421HM  
along/at along Ave. towards KPE

I/We Tay Kim Hwat the owner of  
vehicle registration no. SLB3660Y hereby do authorize you, Kan Fook Sing Motor  
Workshop to commence repairs to my above mentioned vehicle.


I/ We confirm that Kan Fook Sing Motor Workshop is hereby authorized to handle the repairs of my/ our  
vehicle and/ or to negotiate and settle any claims relating to the above accident which I/ We may have  
against other third party/ parties or insurers and/ or to instruct lawyers on my/ our behalf to facilitate the  
third party claim for me/ us.

Kan Fook Sing Motor Workshop is hereby authorized to execute and /or sign my documents/ discharge  
vouchers/ discharge agreements regarding my/ our claim to facilitate my convenience. **ALL PAYMENT  
WILL BE MADE TO KAN FOOK SING MOTOR WORKSHOP.**

*\*\* strictly without prejudice to bodily injury claim.*

Thank you.

Yours faithfully



RELEASE

Claim Reference:	1201700008458
Surveyor's Reference:	CC4/FWD17023104/Gea3
TP Reference:	SLB 3660Y

We, KAN FOOK SING MOTOR WORKSHOP ("Workshop") hereby agree and confirm that we are authorized by the owner ("Claimant") of motor vehicle SLB 3660Y ("Vehicle") to accept the sum of \$35,674.44, being the amount claimed for \$33,748.44 (repair costs), \$1,926.00 (loss of rental/ use), \$ - (loss of income), \$ - (search fees) as compensation for the loss of or damage to the Vehicle, as a result of an accident ("Accident") which occurred on 01/12/2017 (date of accident) at / along MCE TWDS KPE (location) involving vehicle no/s. SLB 3660Y and SKT 4214M.

This is pursuant to the inspection conducted on 05/12/2017 (date) at the Workshop.

We confirm that this acceptance is in full and final settlement of all claims arising from the damage to the Vehicle (whether now or hereafter to become manifest), to the intent that FWD Singapore Pte. Ltd. and all other persons, in particular the driver of SKT 4214M be absolutely and finally exonerated and discharged from all claims of every nature and kind whatsoever which have been made or which may be made in respect of this Accident.

We also declare that we are authorized by the Claimant to receive the above compensation and we have full authority to make the claim as set out above and to settle the matter on behalf of the Claimant in any manner we deem fit.

This settlement is reached on a without prejudice and without admission of liability basis. As such, this Release is not to be construed as an admission of liability on the part of FWD Singapore Pte Ltd, their policyholder and / or authorised driver and shall not be used as evidence in any claims and / or action which may be lodged by any of them.

Dated this 3 day of Jul 2018

CLAIMANT



[Signed by the "Workshop" with Co. Stamp]

For and on behalf of the "Claimant"



XGQ

[FWD's appointed surveyor with Co. Stamp]

For and on behalf of FWD Singapore Pte. Ltd.



# 簡福星噴漆工廠 KAN FOOK SING MOTOR WORKSHOP

Headquarter: 61 Defu Lane 12, Singapore 539147  
Tel: (65) 6747 9560, 6858 2126, 6858 4361 • Fax: (65) 6748 1006, 6281 8428  
E-mail: ryan@kanfs.net/patricia@kanfs.net • Website: www.kanfs.com.sg  
Branch: 1 Kaki Bukit Avenue 6 #01-108 / #01-13 / #01-14, Singapore 417883  
Tel: (65) 6743 5344, 6481 5150, 6481 5152 • Fax: (65) 6481 8683

## TAX INVOICE

Business Reg. No. 221468-00E  
GST Reg. No. M9-0005333-E

FWD SINGAPORE PTE LTD  
6 TEMASEK BOULEVARD  
#18-01 SUNTEC TOWER 4  
SINGAPORE 038986  
VEHICLE NO. : SLB3660Y  
ACCIDENT DATE : 01-12-2017 17:53  
THIRD PARTY REF. : SKT4214M

INVOICE NO : 44987  
DATE : 03-05-2018

ATTN: FWD SINGAPORE PTE LTD

INVOICE COST OF REPAIRS TO VEHICLE SLB3660Y MERCEDES BENZ GLA 180

QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	REAR BOOT COVER	1767.00
1	REAR BUMPER	1570.00
1	REAR BUMPER TOP CHROME	148.00
5	REAR BUMPER TOP GARNISH CLIP@\$9.00	45.00
1	REAR BUMPER TOW COVER	55.00
1	REAR BUMPER REINFORCEMENT	545.00
2	REAR BUMPER SIDE RETAINER@\$20.00	40.00
1	REAR BUMPER SIDE GARNISH RH	29.00
1	REAR BUMPER LOWER GARNISH RH	92.00
1	REAR BUMPER LOWER	663.00
1	REAR BUMPER LOWER COVER	525.00
2	REAR BUMPER LOWER GARNISH BRACKET @\$90.00	180.00
1	REAR UNDERCOVER	740.00
1	REAR EXHAUST MUFFLER	1111.00
1	REAR EXHAUST HEAT SHIELD CENTRE	126.00
2	REAR EXHAUST CHROME PIPE@\$256.00	512.00
2	REAR EXHAUST MOUNTING@\$38.00	76.00
1	FRONT BONNET	1398.00
1	FRONT BONNET SEAL	34.00
2	FRONT BONNET HINGES@\$82.00	164.00
2	FRONT BONNET ACTUATOR@\$175.00	350.00
2	FRONT BONNET STOPPER@\$19.00	38.00
1	FRONT GRILLE BASE	285.00
1	FRONT GRILLE EMBLEM	255.00
1	FRONT GRILLE CHROME	145.00

IN PANEL-BEATING & BODY-WORK, OUR WORKSHOP IS WELL-EQUIPPED WITH THE LATEST TECHNOLOGY --- CELETTE BENCH PULLER SYSTEM WHICH ENABLE US TO MEASURE CORRECTLY & REPAIR MANY DIFFERENT KINDS OF DAMAGES, SERIOUS DAMAGES TO THE FLOOR-BOARD CHASSIS & WHEEL-HOUSING CAN BE RESTORED BACK TO THE ACCORDING MEASUREMENT. WE ARE ABLE TO REPAIR & RESTORE ANY BADLY DAMAGED VEHICLE BACK TO ITS ORIGINAL SPECIFICATIONS TO ENSURE SAFETY WHILE DRIVING.

在钣金修理業，本廠有最精良，先進的機械，來準確測量及修理，在規格尺寸圖內，本公司有能力回復原來相符的程度。



# 簡福星摩多工廠 KAN FOOK SING MOTOR WORKSHOP

Headquarter: 61 Defu Lane 12, Singapore 539147  
Tel: (65) 6747 9560, 6858 2126, 6858 4361 • Fax: (65) 6748 1006, 6281 8428  
E-mail: ryan@kanfs.net/patricia@kanfs.net • Website: www.kanfs.com.sg  
Branch: 1 Kaki Bukit Avenue 6 #01-108 / #01-13 / #01-14, Singapore 417883  
Tel: (65) 6743 5344, 6481 5150, 6481 5152 • Fax: (65) 6481 8683

## TAX INVOICE

Business Reg. No. 221468-00E  
GST Reg. No. M9-0005333-E

VEHICLE NO. : SLB3660Y  
ACCIDENT DATE : 01-12-2017 17:53  
THIRD PARTY REF. : SKT4214M

QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
4	FRONT GRILLE CHROME FIN@\$63.00	252.00
1	FRONT HEADLAMP RH	2360.00
1	FRONT SUPPORT PANEL	608.00
1	FRONT FENDER RH	705.00
10	FRONT FENDER SHIELD CLIP@\$9.00	90.00
1	FRONT FENDER GARNISH RH	108.00
8	FRONT FENDER GARNISH CLIP@\$9.00	72.00
1	FRONT BUMPER	1645.00
1	FRONT BUMPER FOAM	130.00
1	FRONT BUMPER TOP FRAME	120.00
1	FRONT BUMPER REINFORCEMENT	305.00
1	FRONT BUMPER REINFORCEMENT BRACKET RH	110.00
2	FRONT BUMPER SIDE RETAINER@\$9.00	18.00
1	FRONT BUMPER TOW COVER	67.00
1	FRONT BUMPER SENSOR	185.00
2	FRONT BUMPER SENSOR RING @\$12.00	24.00
1	FRONT BUMPER SENSOR WIRE	114.00
1	FRONT BUMPER WIPER NOZZLE COVER RH	52.00
1	FRONT BUMPER WIPER COVER SPRING RH	20.00
1	FRONT BUMPER FOGLAMP COVER RH	45.00
1	FRONT BUMPER EMBLEM	60.00
10	FRONT BUMPER CLIP@\$9.00	90.00
1	AIR CON CONDENSER	1078.00
1	RADIATOR ASSY	840.00
1	RADIATOR FAN ASSY	428.00

IN PANEL-BEATING & BODY-WORK, OUR WORKSHOP IS WELL-EQUIPPED WITH THE LATEST TECHNOLOGY --- CELETTE BENCH PULLER SYSTEM WHICH ENABLE US TO MEASURE CORRECTLY & REPAIR MANY DIFFERENT KINDS OF DAMAGES, SERIOUS DAMAGES TO THE FLOOR-BOARD CHASSIS & WHEEL-HOUSING CAN BE RESTORED BACK TO THE ACCORDING MEASUREMENT. WE ARE ABLE TO REPAIR & RESTORE ANY BADLY DAMAGED VEHICLE BACK TO ITS ORIGINAL SPECIFICATIONS TO ENSURE SAFETY WHILE DRIVING.

在鈹金修理業，本廠有最精良，先進的機械，來準確測量及修理，在規格尺寸圖內，本公司有能力回復原來相符的程度。



簡福星摩多工廠  
KAN FOOK SING MOTOR WORKSHOP

Headquarter: 61 Defu Lane 12, Singapore 539147  
Tel: (65) 6747 9560, 6858 2126, 6858 4361 • Fax: (65) 6748 1006, 6281 8428  
E-mail: ryan@kanfs.net/patricia@kanfs.net • Website: www.kanfs.com.sg  
Branch: 1 Kaki Bukit Avenue 6 #01-108 / #01-13 / #01-14, Singapore 417883  
Tel: (65) 6743 5344, 6481 5150, 6481 5152 • Fax: (65) 6481 8683

TAX INVOICE

Business Reg. No. 221468-00E  
GST Reg. No. M9-0005333-E

VEHICLE NO. : SLB3660Y  
ACCIDENT DATE : 01-12-2017 17:53  
THIRD PARTY REF. : SKT4214M

QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
1	RADIATOR SPARE TANK	155.00
1	SPARE TANK BREATHING PIPE	88.00
1	INTERCOOLER PIPE RH	190.00
1	INTERCOOLER PIPE LH	230.00
1	FRONT FENDER SHIELD RH	170.00
1	FRONT HEADLAMP ADJUSTOR CONTROL	277.00
40	RIVET @\$9.00	360.00
1	FRONT BONNET LOCK COVER	70.00
1	AIR DUCT	105.00
1	ENGINE TOP COVER	365.00
1	FRONT SUPPORT SIDE BRACKET RH	24.00
1	TURBO ASSY	6760.00
1	TURBO PIPE	95.00
1	INTAKE MANIFOLD PIPE	210.00
1	MANIFOLD JOINT PIPE	130.00
1	WATER PUMP	650.00
1	WATER PUMP PIPE	155.00
1	AIR CON SIDE GARNISH RH	22.00
1	RADITOR SIDE GARNISH TOP RH	38.00
1	RADIATOR SIDE GARNISH LOWER RH	38.00
1	ENGINE MOUNTING RH	370.00
1	FRONT NUMBER PLATE GARNISH	164.00
2	ROOF MOULDING CLIP @\$12.00	24.00
1	REAR BUMPER TOW COVER TRIM	15.00
1	REAR FENDER SIDE GARNISH RH	210.00

IN PANEL-BEATING & BODY-WORK, OUR WORKSHOP IS WELL-EQUIPPED WITH THE LATEST TECHNOLOGY --- CELETTE BENCH PULLER SYSTEM WHICH ENABLE US TO MEASURE CORRECTLY & REPAIR MANY DIFFERENT KINDS OF DAMAGES, SERIOUS DAMAGES TO THE FLOOR-BOARD CHASSIS & WHEEL-HOUSING CAN BE RESTORED BACK TO THE ACCORDING MEASUREMENT. WE ARE ABLE TO REPAIR & RESTORE ANY BADLY DAMAGED VEHICLE BACK TO ITS ORIGINAL SPECIFICATIONS TO ENSURE SAFETY WHILE DRIVING.

在钣金修理業，本廠有最精良，先進的機械，來準確測量及修理，在規格尺寸圖內，本公司有能力回復原來相符的程度。



簡 福 星 嘑 嘑 工 廠  
KAN FOOK SING MOTOR WORKSHOP

Headquarter: 61 Defu Lane 12, Singapore 539147  
Tel: (65) 6747 9560, 6858 2126, 6858 4361 • Fax: (65) 6748 1006, 6281 8428  
E-mail: ryan@kanfs.net/patricia@kanfs.net • Website: www.kanfs.com.sg  
Branch: 1 Kaki Bukit Avenue 6 #01-108 / #01-13 / #01-14, Singapore 417883  
Tel: (65) 6743 5344, 6481 5150, 6481 5152 • Fax: (65) 6481 8683

TAX INVOICE

Business Reg. No. 221468-00E  
GST Reg. No. M9-0005333-E

VEHICLE NO. : SLB3660Y  
ACCIDENT DATE : 01-12-2017 17:53  
THIRD PARTY REF. : SKT4214M

QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
		31,334.00
	LESS 10 %	3,133.40
	TOTAL ( A )	28,200.60

SPECIAL NETT ITEMS

1	REAR WINDSCREEN GUM	40.00
1	FRONT NUMBER PLATE	30.00
1	COOLANT	50.00
	TOTAL ( C )	120.00

LABOUR CHARGES

1	TO CHECK WIRING SYSTEM, RE-PROGRAM/RESET MEMORY	100.00
1	TO REMOVE/REFIT/REFILL AIR CON GAS	80.00
1	TO REMOVE/REFIT EXHAUST SYSTEM	80.00
1	TO REMOVE/REFIT REAR FENDER INNER GARNISH AND ETC	60.00
1	TO REMOVE/REFIT REAR WINDSCREEN GLASS	100.00
1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS (REAR)	500.00
1	TO REMOVE ALL NECESSARY AFFECTED PARTS WELD CUT PANEL BEAT AND FITTING NEW PARTS (FRONT)	1100.00
1	SPRAYPAINTING CHARGES (FRONT & REAR )	1200.00

IN PANEL-BEATING & BODY-WORK, OUR WORKSHOP IS WELL-EQUIPPED WITH THE LATEST TECHNOLOGY --- CELETTE BENCH PULLER SYSTEM WHICH ENABLE US TO MEASURE CORRECTLY & REPAIR MANY DIFFERENT KINDS OF DAMAGES, SERIOUS DAMAGES TO THE FLOOR-BOARD CHASSIS & WHEEL-HOUSING CAN BE RESTORED BACK TO THE ACCORDING MEASUREMENT. WE ARE ABLE TO REPAIR & RESTORE ANY BADLY DAMAGED VEHICLE BACK TO ITS ORIGINAL SPECIFICATIONS TO ENSURE SAFETY WHILE DRIVING.

在鈹金修理業，本廠有最精良，先進的機械，來準確測量及修理，在規格尺寸圖內，本公司有能力回復原來相符的程度。



簡 福 星 嘜 工 廠  
KAN FOOK SING MOTOR WORKSHOP

Headquarter: 61 Defu Lane 12, Singapore 539147  
Tel: (65) 6747 9560, 6858 2126, 6858 4361 • Fax: (65) 6748 1006, 6281 8428  
E-mail: ryan@kanfs.net/patricia@kanfs.net • Website: www.kanfs.com.sg  
Branch: 1 Kaki Bukit Avenue 6 #01-108 / #01-13 / #01-14, Singapore 417853  
Tel: (65) 6743 5344, 6481 5150, 6481 5152 • Fax: (65) 6481 8683

TAX INVOICE

Business Reg. No. 221468-00E  
GST Reg. No. M9-0005333-E

VEHICLE NO. : SLB3660Y  
ACCIDENT DATE : 01-12-2017 17:53  
THIRD PARTY REF. : SKT4214M

QTY	PARTS DESCRIPTION	AMOUNT (SG\$)
	TOTAL ( D )	3,220.00
	TOTAL REPAIR COST :	31,540.60
	G S T % :	2,207.84
	INVOICE AMOUNT :	33,748.44



IN PANEL-BEATING & BODY-WORK, OUR WORKSHOP IS WELL-EQUIPPED WITH THE LATEST TECHNOLOGY --- CELETTE BENCH PULLER SYSTEM WHICH ENABLE US TO MEASURE CORRECTLY & REPAIR MANY DIFFERENT KINDS OF DAMAGES, SERIOUS DAMAGES TO THE FLOOR-BOARD CHASSIS & WHEEL-HOUSING CAN BE RESTORED BACK TO THE ACCORDING MEASUREMENT. WE ARE ABLE TO REPAIR & RESTORE ANY BADLY DAMAGED VEHICLE BACK TO ITS ORIGINAL SPECIFICATIONS TO ENSURE SAFETY WHILE DRIVING.

在鈑金修理業，本廠有最精良，先進的機械，來準確測量及修理，在規格尺寸圖內，本公司有能力回復原來相符的程度。





# KAN CAR RENTAL

61 Defu Lane 12, Singapore 539147

Tel: (65) 6747 9560 • Fax: (65) 6748 1006






Co. Reg. No.: 52908213J • GST Reg. No.: 52-908213-J

## TAX INVOICE

COMPREHENSIVE/THIRD PARTY COVERAGE

RENTAL AGREEMENT NO. RA 5171

SLB 3660 Y  
TIP

Vehicle Reg. No. <u>S4J438-P</u> Engine Capacity:		Date Out: <u>2/12/2017</u> Date In: <u>2/2/18</u>
Make / Model: <u>T. Altis</u>		Time Out: <u>10/5 am</u> Time In: <u>@ 1205h.</u>
COMPANY NAME:		Mileage Out:
Address:		Mileage In:
Tel:		Estimated Date / Time Return:
Person in Charge:		Form of Payment:
Designation:		6 Days @ S\$ 100 per Day # 6,200
Tel:		Weeks @ S\$ per Week
Fax:		Months @ S\$ per Month
Contact No.		Additional @ S\$ per Hours
DRIVER NAME: <u>Tay Kim Huet</u>		TOTAL # 6,200
Address: <u>5 Lorong 106</u> Tel (R):		GOODS & SERVICES TAX (GST) 7% # 434
<u>Chensi (S) H26467</u> Tel (O):		TOTAL CHARGE DUE # 6,634
<u>H/p No.: 97421646</u>		DEPOSIT BY RENTER
NRIC/Passport #: <u>S4704821H</u> Country of Issue:		BALANCE DUE FROM RENTER
Date of Birth: <u>14/9/1977</u> Nationality:		 Right Side  Top  Left Side  Front  Rear
Driving Licence #: Country of Issue:		
Expiry Date: Years of Driving:		
FUEL GAUGE		
ADDITIONAL DRIVER:		
Address:		
Tel (R):		
Tel (O):		
H/p No.:		
NRIC/Passport #:		
Date of Birth:		
Driving Licence #:		
Expiry Date:		
RENTER'S Liability for Vehicle Damage shall NOT Exceed S\$ per Accident / Damage		
Remarks:		
<b>For Singapore Use Only</b>		
Own Damage Excess S\$1,500.0		
All damages borne by hirer for Third Party Coverage vehicle		
Agreement Prepared By	Checked Out By:	Checked In By:
		RENTER'S I/D

### RENTER'S DECLARATION:

I/We agreed to the terms & conditions of the above & declared that all informations given is true and correct in all respect. My/Our driving licence(s) is/are current and not disqualified from driving. I/We hereby authorized KAN CAR RENTAL to charge all amount due to this rental to my/our account.

  
RENTER'S SIGNATURE & CO'S STAMP

  
AUTHORIZED SIGNATURE (KAN CAR RENTAL)