

REPAIR ESTIMATE*

VEHICLE NO : SHC 2964U

AIG

DATE 5/12/2017 10:51

MAKE :

DOT: 04.12.17

MODEL : HYUNDAI SONATA

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Front Fender (RH) ✓			\$ 593.00	
	Front Fender Shield (RH) ✕			\$ 86.00	
	Front Fender Retainer ✕			\$ 9.20	
	Fender Lamp (RH) ✓				
	SUB TOTAL			\$ 688.20	
	LESS 20%			\$ 137.64	
	DISCOUNTED TOTAL			\$ 550.56	
	Front Fender Advertisement Logo (RH) ✓			\$ 100.00	Nett
				\$ 100.00	
	Labour Charge			200	
	Panel Beating			\$ 560.00	
	Spray Painting Charge			\$ 200.00	180
	Tuff Kote			\$ 50.00	✕
	TOTAL LABOUR			\$ 810.00	
	ESTIMATE TOTAL			\$ 1,460.56	
Larry Ng Kalvi 10/11/17 5/12/17 1120hrs. 2043. 4/3 After Repair p/Lt KK Auto Consultants hence notify the Repairer of the following: - To resurvey before/after spray painting - To display damaged part(s) during resurvey - Parts prices are subject to confirmation - Third party survey is on a "Without Prejudice" basis - No illegal modification(s) is allowed - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:					
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					