

ASS. REC. BY:

REF: CS/FCI17023137 / Wqber Special Instruction:

SUBMITTER:

CWs

Wilson

ASSIGNMENT (Office)

From (Person):

Lurene jaw

of

FCI

Date/Time: 6.17pm @ 5/12/17

Estimated Cost:

Bill to:

OD ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLF 313Z

Insured:

SHB 3508C

at Workshop m/s

Kah Motor

Tel:

81006306

of

15 ubi Road 4

Policy No:

Claim No:

D17009998 MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 24/10/2017

7/12/17 @ 10am owner waiting

CA / REV / REP. / REV 24 HRS

wop

H.O.D. Endorsement:

Date/Time:

9:24am @

Person Contacted:

Any chua

Vehicle IN ~~OUT~~

Date/Time	Action/Instruction (✓) Estimate
	SLF 313Z - CC4/AXA17019393/Uka3 - D.O.A. 5/10/2017
	SHB 3508C - *
08/11/17 @ 3.17pm	revised to Lurene by email.
03/12/17 @ 3.50pm	Tracez (wop) informed that the owner claims OD (LIB)
03/12/17	Submit Prelim. report

27/7/18 content sent by \$1139.50 note Any. 3/18.
 Used \$2195.07, 667.07

29/7/18

Re-open ref. for submit final report.

01/08/18

1st closed date = 14/05/2018, Reopen by km
 becoz has to submit final report. (Previously
 submitted Prelim report).

30/7/18

REF: FCI

ASSIGNMENT

From

Date 7/12/17

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLF 313Z

at Workshop m/s Kah Motor

of 15 ubi Road 4

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh:

Any

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 3 days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS Wp

Date: Person Contacted:

Vehicle: IN / OUT

Veh No:

SLF 313Z Yr Regn: 22/7/2016

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Odyssey D.O. 2356

Colour: Silver A/C Insured / Std / NI / NA

Sp. Reading: 035765 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JHMRC 1890GC 205262

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: NIF / S/Rim / STD A/Rim or

Tyre Size F: 215 / 55 R17

R: 215 / 55 R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Dunlop

Front

Rear

R/Bal. 3 mm R/Bal. 3 mm

L/Bal. 3 mm L/Bal. 3 mm

D.O.A. 24/12/2017 D.O.I. 7/12/2017

Survey held at: As Above

Des. of Damages: (Frt) Rear / O/S / N/S / U/C / Rooftop or

Left Frt

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

RECEIVED 17 DEC 2018

Date/Time: File Pass to?

☒ : Preli. Report

11/03/18 to 11/03/18

☐ : Final Report

Date/Time: File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$) :

Days Of Repair: 3

Resurvey No. of Trip:

Add Fee: ☐ Site Insp. (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Survey Fee:

Transportation

) S - RS (\$)

) Photos

) Other

TOTAL

130
50
11
191



KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer : FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877
Registration No : SLF313Z
Chassis No : JHMRC1890GC205262
Model : ODYSSEY 2.4 EXV-S 16YM
Owner's Name : LOW KAH HOE
Ins Policy No. : SD16V09529/VPC2/R00
Date of Accident : 24/10/2017

Document No. : SQT17004953
Date : 5. Dec 2017
Customer No. : WZF002
Svc Advisor : ARY CHUA WAI NGEE
Engine No : K24W72012372
Date | Time : 5. Dec 2017 3:10:49 PM
Surveyor Name :
Survey Date :
Authorisation Date :
DID : +65 6846 5673
HP : +65 8100 6306
Email : arychua@honda.com.sg

Page 1

68411972 07 DEC 2017 @ 10.00am

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount incl GST
	TP DIRECT SETTLEMENT (J/NO: OWNER: LOW KAH HOE OWNER INSURER: LIBERTY INSURANCE PTE LTD ACC DATE: 24/10/2017@10:25AM SURVEYED BY: 4 WORKING DAY TO COMPLETED REF NO TP INSURER: FIRST CAPITAL INSURANCE LTD TP VEH: SHB3508C (HYUNDAI I40/YELLOW CAB)						
04711-T6A-900ZZ	FACEFR BUMPER ✓ 2 R	1	686.30	25	514.72	36.03	550.75
71130-T6A-310ZZ	BEAM COMP. FR. BUMPER 11	1	291.80	25	218.85	15.32	234.17
91505-TM8-003	CLIPBUMPER ✓ NEC	13	2.00	25	21.00	1.47	22.47
					Sum Item	754.57	52.82
							807.39
BOSUN	SUNDRIES	1	10.00	✓	10.00	0.70	10.70
BML01I	INSPECT FR LIGHTING MECHANISMS & FOCUS	1	100.00	✓	100.00	7.00	107.00
BKBH12S	STRAIGHTEN ALIGN FR R BULKHEAD WHEELHOUSE & 1	1	1120.00	56.0	1120.00	78.40	1198.40
BP03R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (3P)	1	1350.00	45.0	1350.00	94.50	1444.50
					Sum Labor	2580.00	180.60
							2,760.60

Survey By

Date & Time

Excess

Status

Signature

E-mail

Part 3 by Part

3 Working Day Repair

Printed on 5/12/2017 3:26:59 PM

This is a computer generated invoice. No signature is required

Part prices are subjected to change without notice

The above estimated cost of repair do not include any unforeseen damages

GST Amount is calculated from individual line(s)

Total Amount 3,334.57 233.42 3,567.99

Total (Inclusive of GST) 3,567.99

LIK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No legal notification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

Authorized by Repairer

Signature:

Date:

4/12/17



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651, Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937, Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WZF002 / FIRST CAPITAL
Chassis No: JHMRC1890GC205262
License No: SLF313Z
Mileage: 52842
Engine No: K24W72012372

Document No: SVO18038619
Printed By: ARYCHUA
Order Date: 5. July 2018
Order Time: 3:10:49 PM
Service Advisor: ARY CHUA WAI NGEN

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	7% GST Amount	incld GST
	TP DIRECT SETTLEMENT (J/NO: 70798) OWNER: LOW KAH HOE OWNER INSURER: LIBERTY INSURANCE PTE LTD ACC DATE: 24/10/2017@10:25AM SURVEYED BY: WILSON/MARCUS CHUA LKK-AUTO DATE: 07/12/2017@10.30AM REF NO: D1809998MFSH-LJ TP INSURER: FIRST CAPITAL INSURANCE LTD TP VEH: SHB3508C (HYUNDAI/140/YELLOW CAB)						
91505-TM8-003	CLIPBUMPER	13	2.00	25	19.50	1.37	20.87
	SUM PARTS:				19.50	1.37	20.87
BOSUN	0672 SUNDRIES	1	10.00		10.00	0.70	10.70
BML011	0760 INSPECT FR LIGHTING MECHANISMS & FOCUS HEADLIGHTS.(N)	1	100.00		100.00	7.00	107.00
BP01R	EXT-YBH SPRAY PAINT ON REPAIRED/REPLACED AREAS.(1Px\$450)	1	450.00		450.00	31.50	481.50
BKBH12S	0760 STRAIGHTEN ALIGN FR R BULKHEAD WHEELHOUSE & RENEW DAMAGE PARTS.	1	560.00		560.00	39.20	599.20
	SUM LABOUR:				1,120.00	78.40	1,198.40
	TOTAL SGD				1,139.50	79.77	1,219.27
	Total Payable (SGD)						1,219.27

GST Amount is calculated from individual line(s)

1139.50



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLF 313Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	FACEFR.BUMPER (SN)	TO REPAIR SEE LABOUR	514.72	-
1	BEAM COMP,FR.BUMPER (SN)	NOT NECESSARY	218.85	-
14	CLIPBUMPER (SN)	NECESSARY-3PCS ONLY	21.00	19.50
1	SUNDRIES (SN)	NECESSARY	10.00	10.00
			764.57	29.50
LABOUR				
	INSPECT FR LIGHTING MECHANISMS & FOCUS.		100.00	100.00
	STRAIGHTEN ALIGN FR R BULKHEAD WHEELHOUSE & INCLUSIVE OF THE REPAIR OF FACEFR.BUMPER.		1,120.00	560.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS (3P)		1,350.00	450.00
			2,570.00	1,110.00
GRAND TOTAL			3,334.57	1,139.50
RECOMMENDED COST OF REPAIRS				1,139.50

Report Ref No. CS/FCI17023137/Wqbe2

WILSON TEO CHENG MING

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.