

ASS. REC. BY:

REF: CS/FCJ17023141/R1rbn2

Special Instruction:

SUPERVISOR:

Rasul

ASSIGNMENT (Office)

CWS

From (Person):

Serene Ter

of

FCI

Date/Time: 9:32am @ 6/12/17

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLF 4247E

Insured:

SHA 4839X

at Workshop m/s

Cycle & Curnage Automotive
209 Pandan Gardens

Tel:

65684501

Policy No:

Claim No:

D1701182 MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A. 2/12/17

(Client's Record)

CA / REV / REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time: 10:01am @ 6/12/17

Person Contacted:

Tayjian Ye

Vehicle IN OUT

Date/Time

Action/Instruction (✓) Estimate

SLF 4247E - X

SHA 4839X - CC3/EQ17016315/K1pb3q2

D.O.A: 20/08/2017

Confirm L/S \$14K @ 16 days

Red: \$9866, 41%.

From

4557K


ASSIGNMENT

From: _____ Date: **6/12/17**
 Estimated Cost: _____
 OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To Inspect Vehicle No: **SLF 4247E**
 at Workshop no: **Cycle & Carriage Automotive**
 of: **209 Pandan Gardens**
 Insured: _____
 Policy No: _____
 Claims No: _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Tay jian ye

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: **64K**
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle IN / OUT

Veh No: **SLF 4247E** / Page: **2016** **AKH**
 Type: ☒ Car / ☐ M.Cycle / ☐ Bus / ☐ Van / ☐ Lorry / ☐ Taxi / ☐ Prime Mover /
 Truck / Trailer or
 Make: **MITSUBISHI ATTACHE 1.2** cc: **1193**
 Colour: **RED** A/C: _____ Insured / Std / NI / NA
 Sp Reading: **123122** T-Radio: Insured / Std / NI / NA
 Eng No: _____
 C.No: **MMB5TA13AHH001133**
 Gen. Cond: Good / ☒ Fair / ☐ Poor / ☐ Burnt
 Steering: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or
 Brake: ☒ In order / ☐ Jammed / ☐ Leaked / ☐ Burnt or
 Mod: Nil / ☒ S/Rim / ☐ STD A/Rim or
 Tyre Size: F: **185/55R15**
 R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or **ROADSTONE**

Front	Rear
R/Bal: 5 mm	R/Bal: 5 mm
L/Bal: 5 mm	L/Bal: 5 mm
D.O.A: 02/12/17	D.O.A: 06/12/17
Survey held at: C&C CPA	

Des. of Damages: Fnt / Rear / O/S / N/S / U/C / Rooftop or

N/S FRT & N/S REAR

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

07/12/17 Email to Jian Ye regarding this veh. repair limit is 14K. He noted, will inform again to confirm

RECEIVED 30 MAY 2018

Date/Time File Pass to?

☐ : Preli. Report
☒ : Final Report

Days Of Repair: **16**

Resurvey No. of Trip: **1**

Survey Fee

Transportation

Add Fee:

☐ Site Insp \$
☐ Interview \$
☐ Tech Insp \$
☐ Weekend \$

13x15=195

170+195

50

50

149

614

Report Format:

Lump Sum / 14K

TP
14K

50
50
149
614



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17023141/R1rb	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 06-12-2017	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 4839X	Veh. Inspected	SLF 4247E	
Policy No.		Coverage (\$)	0.00	
Claim No.	D17011182MFSH	Excess (\$)	0.00	
Assign From	CWS (SERENE LER)	Assign Date	06/12/2017	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	02/12/2017	Inspection Date	06/12/2017	
Survey held at	CYCLE & CARRIAGE AUTOMOTIVE PTE LTD 209 PANDAN GARDENS SINGAPORE 609339			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	04-12-2017	Our Ref No. D17011182MFSH
Accident Date	02-12-2017	Claim Type. Third Party
Insured Vehicle	SHA4839X	Third Party Vehicle. SLF4247E
Survey Location	209 PANDAN GARDENS	
Contact Person.	TAY JIAN YE	
Contact No.	65684501/ 0	Fax No. 65651240
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	CYCLE & CARRIAGE AUTOMOTIVE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	SERENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/231421)



PRI Documents



Close



PRI Header Details

Claim No	D17011182MFSH	Policy No	D-15072701MFSH	Claimant S.No & Name	1 & CYCLE & C LTD
Workshop Name	CYCLE & CARRIAGE AUTOMOTIVE PTE LTD (Contact Person : TAY JIAN YE)	Survey Location & Contact Details	209 PANDAN GARDENS Mobile: 0 , Phone: 65684501 , Fax: 65651240 EmailId: JIANYE.TAY@CYCLECARRIAGE.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHA4839X	TP Vehicle No	SLF4247E
PRI Recieved Date	05-12-2017 05:00:55 PM	Surveyor Appointed Date	06-12-2017 09:31:36 AM	Surveyor Accept Date	06-12-2017 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	06-12-2017	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S1182584B



PANG KOK KIANG
冯国强
CHINESE
Date of Birth: 20-12-1956 Sex: M
Country of Birth: SINGAPORE

0982641

FOR C&C USE ONLY

REPUBLIC OF SINGAPORE DRIVING LICENCE

Licence Number: S1182584B
Name: PANG KOK KIANG
Birth Date: 20 Dec 1956
Issue Date: 09 May 2003




000463463C

FOR C&C USE ONLY

0982641




NRIC No: S1182584B
Blood Group: A+ Date of issue: 25-05-1993
Address: APT BLK 10 EUNOS CRESCENT #15-2733
SINGAPORE 400010
NRIC No: S1182584B Date: 14-02-2000 No: 8355915


FOR C&C USE ONLY

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASS(IES)

Class	Description	PASS DATE
Class 2B	Motorcycles not exceeding 200 cc	26 Jul 1977
Class 2A	Motorcycles between 201 cc and 400 cc	26 Jul 1977
Class 2	Motorcycles exceeding 400 cc	26 Jul 1977
Class 3	Motor Cars and Motor Tractors the weight of which unladen does not exceed 2500 kilograms	07 Jun 1978


FOR C&C USE ONLY

Licence No: S1182584B



NP 420A

I WAS TRAVELING AT CHANGI BUSINESS PARK CENTRE 2 TO CHANGI BUSINESS PARK CENTRE 1
SUDDENLY I FELT AN IMPACT ON MY RH AND MY VEHICLE LOSS CONTROL AND MOUNT ON CURB AND
HIT THE RAILING ON MY RH FRT SIDE OF MY VEHICLE SO I CAME DOWN AND TOOK A LOOK I SAW
THE TAXI SHA4839X COME OUT FROM THE SLIP ROAD AND HIT MY REAR OF MY VEHICLE AND COST
MY VEHICLE TO LOSS CONTROL



Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Company
Owner ID	4597K
Vehicle Details	
Vehicle No.	SLF4247E
Vehicle to be Exported	No
Intended De-registration Date	07 Dec 2017
Vehicle Make	MITSUBISHI
Vehicle Model	ATTRAGE 1.2 CVT
Primary Colour	Red
Manufacturing Year	2016
Engine No.	3A92UDG8152
Chassis No.	MMBSTA13AHH001133
Maximum Power Output	57.0 kW (76 bhp)
Open Market Value	\$14,648.00
Original Registration Date	26 Aug 2016
First Registration Date	26 Aug 2016
Transfer Count	1
Actual ARF Paid	\$5,000.00
Intended PARF Rebate Details	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	25 Aug 2026
PARF Rebate Amount	\$3,750.00
Intended COE Rebate Details	
COE Expiry Date	25 Aug 2026
COE Category	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years)	10
QP Paid	\$52,503.00
COE Rebate Amount	\$45,756.00
Total Rebate Amount	\$49,506.00

The information contained herein is correct as at 07 Dec 2017

OK

64,000
49,506
14,494



Please read through the [Privacy Statement](#), [Terms of Use](#), and [Disclaimer](#).

Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 10 and above, Chrome, Firefox, and Safari.

Copyright 2017 LTA [Privacy Statement](#) [Terms of Use](#) [Disclaimer](#) [Rate the Website](#) [Rate this e-Service](#)

Last updated on 19 Nov 2017 at 12:12 AM



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
Lion City Rentals Pte Ltd 60 Anson Road #11-01 Mapletree Anson Singapore 079914 Contact No Mobile: 67420984	Cust No/Name	/Lion City Rentals Pte Ltd
	Reg No/Reg Date	SLF4247E / 26/08/201
	Date In/Mileage	/ 0
	Chassis No	MMBSTA13AHH001133
	Engine No	3A92UDG8152
	Make/Model	MIT/17MY ATTRAGE 1.2 CVT
	Colour/Trim	P01 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00041	Cash	06/12/2017/ 17:03		465 / Tay Jian Ye	17805		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000							2200 2750.00
TO RENEW REAR BUMPER, WELD AND CUT REAR LH FENDER,							X 177 240.00
E PNT88000							150 200.00
TO REMOVE AND REFIT REAR WINDSCREEN							840 1260.00
E PNT88000							X 177 150? 200.00
TO REMOVE AND REFIT REAR SEAT AND TRIM TO FACILITATE REPAIR							X 177 60 80.00
E PNT98000							2200 2750.00
PAINT WORK SPRAY REAR BUMPER , REAR LH FENDER							X 177 240 240.00
A 34900099							X 177 150 300.00
TO REMOVE AND REFIT RH REAR U/CARRIAGE							2100 2520.00
E PNT88000							150 300.00
TO TRANSFER REAR RH TYRE TO NEW RIM AND BALANCING							X 177 60 80.00
E PNT88000							120.00
TO RENEW FRT BUMPER, FRT LH FENDER, WELD AND CUT FRT LH A PILLAR							30 50.00
REPAIR LH SILL MEMBER AND FRT LH DOOR							200.00
E PNT88000							
TO REMOVE AND REFIT FRT WINDSCREEN							
E PNT88000							
TO REMOVE AND REFIT FRT CONSOLE							
E PNT98000							
PAINT WORK SPRAY FRT BUMPER , FRT LH FENDER, FRT LH A PILLAR ,							
FRT LH DOOR, SILL LH MEMBER							
A 33900099							
TO REMOVE AND REFIT LH FRT U/CARRIAGE							
E PNT88000							
TO TRANSFER FRT LH TYRE TO NEW RIM AND BALANCING							
A WHEELALIGNMENTBP							
To Conduct Computerize Full Wheel Alignment							
A 54900099							
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM							
A 10028901							
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST							
USING HI-SCAN PRO TEST							

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info	
Lion City Rentals Pte Ltd 60 Anson Road #11-01 Mapletree Anson Singapore 079914 Contact No Mobile: 67420984	Cust No/Name	/Lion City Rentals Pte Ltd
	Reg No/Reg Date	SLF4247E / 26/08/201
	Date In/Mileage	/ 0
	Chassis No	MMBSTA13AHH001133
	Engine No	3A92UDG8152
	Make/Model	MIT/17MY ATTRAGE 1.2 CVT
	Colour/Trim	P01 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00041	Cash	06/12/2017/ 17:03		465 / Tay Jian Ye	17805		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
M SUNDRY							XN 178120 160.00
TO APPLY FRT AND REAR WINDSCREEN SEALANT							80 150.00
M SUNDRY							200.00
TO APPLY ANTI COROSSION ON AFFECTED PORTION							
M SUNDRY							XN 150 300.00
TO APPLY BODY SEALANT ON AFFECTED PORTION							
A 30000001							AN X 50.00
TO REMOVE AND REFIT FUEL TANK							
M SUNDRY							
SUNDRIES				1.00	27.00	00.00	new 27.00
M BRACKET,RR BUMPER,LH				10.00	3.00	00.00	new 30.00
M CLIP,FR BUMPER				1.00	740.00	00.00	DE 740.00
M FACE,RR BUMPER				1.00	748.00	00.00	R 748.00
M PANEL,QTR,OTR LH				2.00	3.00	00.00	new 6.00
M STOPPER,WINDSHIELD GLASS				3.00	9.00	00.00	new 27.00
M SPACER,RR WINDOW				1.00	40.00	00.00	new 40.00
M SHIELD,RR WHEELHOUSE,LH				1.00	743.00	00.00	sch 743.00
M WHEEL,DISC RR LH				1.00	193.00	00.00	XN 193.00
M SHOCK ABSORBER,RR LH SUSP				1.00	49.00	00.00	new 49.00
M MARK,THREE-DIA				1.00	548.00	00.00	sch 548.00
M GRILLE,RADIATOR				1.00	696.00	00.00	TOR 696.00
M FACE,FR BUMPER				10.00	3.00	00.00	new 30.00
P CLIP,FR BUMPER				1.00	163.00	00.00	DE 163.00
M GRILLE,FR UNDER				1.00	62.00	00.00	sch X 62.00
M COVER,HEADLAMP SUPT PANEL				1.00	13.00	00.00	new 13.00
M BRACKET,FR BUMPER,LH				1.00	126.00	00.00	sch 126.00
M GARNISH,FR BUMPER,LH				1.00	286.00	00.00	XN 286.00
M LAMP ASSY,FOG,FR LH				1.00	136.00	00.00	sch 136.00
M REINFORCEMENT,FR BUMPER				1.00	654.00	00.00	sch 654.00
M HEADLAMP ASSY,LH				1.00	458.00	00.00	sch 458.00
M FENDER,FR LH				1.00	97.00	00.00	sch 97.00
M SHIELD,FR WHEELHOUSE,LH				10.00	3.00	00.00	rep 30.00
M CLIP,FR BUMPER							

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 1977014696

Invoice Name & Address	Owner Name & Vehicle Info
Lion City Rentals Pte Ltd	Cust No/Name /Lion City Rentals Pte Ltd
60 Anson Road	Reg No/Reg Date SLF4247E / 26/08/201
#11-01 Mapletree Anson	Date In/Mileage / 0
Singapore 079914	Chassis No MMBSTA13AHH001133
Contact No Mobile: 67420984	Engine No 3A92UDG8152
	Make/Model MIT/17MY ATTRAGE 1.2 CVT
	Colour/Trim PO1 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00041	Cash	06/12/2017/ 17:03		465 / Tay Jian Ye	17805

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M PILLAR,FR OTR LH	1.00	992.00	00.00	992.00
M STOPPER,WINDSHIELD GLASS	2.00	3.00	00.00	6.00
M SPACER,WINDSHIELD	2.00	3.00	00.00	6.00
M WHEEL,DISC FRT LH	1.00	743.00	00.00	743.00
M SHAFT AS,FR AXLE DRIVE,LH	1.00	1133.00	00.00	1133.00
M KNUCKLE,LH	1.00	344.00	00.00	344.00
M BEARING,FR WHEEL HUB LH	1.00	119.00	00.00	119.00
M SNAP RING,FR WHEEL HUB LH	1.00	8.00	00.00	8.00
M HUB ASSY,FR WHEEL LH	1.00	203.00	00.00	203.00
M CROSSMEMBER,FR AXLE,NO.1	1.00	815.00	00.00	815.00
M ARM ASSY,FR SUSP,LWR LH	1.00	318.00	00.00	318.00
M STRUT,FR SUSP RH	1.00	447.00	00.00	447.00
M INSULATOR,FR SUSP STRUT LH	1.00	92.00	00.00	92.00
M INSULATOR,FR SUSP STRUT LH	1.00	79.00	00.00	79.00
M SEAT,FR SUSP SPRING,UPR LH	1.00	35.00	00.00	35.00
M BOX ASSY,RELAY	1.00	131.00	00.00	131.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

SURVEYOR NAME: *Rajan - Hp 9001 0068*
SURVEYOR SIGNATURE: *[Signature]*
DATE: *06/12/17 @ 1625*
REMARKS: *15-16 days*

Resurvey b4 paint
NOTE: TO CHECK M/C

Confirm & accepted by

23866
Nett 23,523.00
7% GST on 23523.00 1646.61
Total Payable 25,169.61

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

SUPPLEMENTARY

INSURANCE CO : FIRST CAPITAL INSURANCE LIMITED

REGISTRATION NO : SLF4247E

S/N	Description	Qty	Unit Price	Disc%	Amount
<u>PARTS</u>					
1	COVER, FR BRAKE DISC	1.00	25.00	0.00	25.00 <i>RF ✓</i>
2	STOPPER, FR SUSP STRUT	1.00	27.00	0.00	27.00 <i>RF ✓</i>
3	BEARING, FR SUSP STRUT	1.00	9.00	0.00	9.00 <i>RF ✓</i>
					<u>61.00</u>
<u>LABOUR</u>					
1	ACCIDENT TOWING @ MIDNIGHT FROM CBP TO PG	1.00	102.00	0.00	102.00 ✓
2	SUPPLY LH FRONT TIRE	1.00	180.00	0.00	180.00 ✓
				Total	<u>343.00</u>
				7 % GST	24.01
				Grand Total	<u><u>367.01</u></u>

Thank You.

Yours faithfully

CYCLE & CARRIAGE AUTOMOTIVE PTE LTD



JoJo Cheng
Customer Service
Cycle & Carriage
Pandan Gardens
Tel. # 6568 4554

No: SLF 4247E WIP 17803

WIP 17805

ADDITIONAL PARTS CHANGE

[illegible]

TAKEN BY

DATE _____

PHOTO BEFORE PAINT

PHOTO AFTER PAINT

PHOTO OF DAMAGED PARTS (DPS)

PHOTO OF CELLETE BENCH

REMOVE & INSTALL ENGINE

REMOVE & INSTALL DASHBOARD

PHOTO B4 SUSP & U/C REMOVE

Model:

Net Address

Surveyor:

~~Final~~ Revised (LKK)

VEHICLE NO : SLF4247E
MODEL : MIT/17MY ATTRAGE 1.2 CVT
WIP : 17805

Material	:	\$	<u>8,964.00</u>
Labour	:	\$	<u>8,672.00</u>
Sub-Total	:	\$	<u>17,636.00</u>
Repair Limit	:	\$	<u>14,000.00</u>
Less Excess	:	\$	<u>-</u>
Total	:	\$	<u>14,000.00</u>
GST 7%	:	\$	<u>980.00</u>
Grand Total	:	\$	<u>14,980.00</u>
Finalise By/Date	:	<u>JoJo / 07/05/2018</u>	

☒ REVERT BACK WITHIN 7 DAYS,
OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

REPAIR TOOK 16 WORKING DAYS + 6 Days (3) Weekends
+ Days () Public Holiday
TOTAL DAYS REPAIR TOOK = 22


☐ TP claim 1st Capital - SHA4839X

☐ Claim GIA / LTA fee \$ -

☐ Claim Loss ☐ Use ☐ Rental

☐ Claim Medical Fee / Others \$ -

☐ Third Party Report \$ -



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE****THIS IS NOT AN OFFICIAL TAX INVOICE**

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info	
Lion City Rentals Pte Ltd 60 Anson Road #11-01 Mapletree Anson Singapore 079914 Contact No Mobile: 67420984 11/12/	Cust No/Name	/Lion City Rentals Pte Ltd
	Reg No/Reg Date	SLF4247E / 26/08/2016
	Date In/Mileage	12/12/2017/ 123122
	Chassis/Package	MMBSTA13AHH001133
	Engine No	3A92UDG8152
	Make/Model	MIT/17MY ATTRAGE 1.2 CVT
	Colour/Trim	P01 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
CSM00041	Cash	03/05/2018/ 08:53	TLT	881 / Jojo Cheng	17805
Description of Goods / Services					Qty Unit Price Disc% Amount
E PNT88000					✓2200.00
TO RENEW REAR BUMPER, WELD AND CUT REAR LH FENDER,					✓150.00
E PNT88000					✓840.00
TO REMOVE AND REFIT REAR SEAT AND TRIM TO FACILIATE REPAIR					
E PNT98000					✓2200.00
SPRAY PAINT REAR BUMPER , REAR LH FENDER					
E PNT88000					✓2100.00
TO RENEW FRONT BUMPER, FRONT LH FENDER, WELD AND CUT FRONT LH A PILLAR					
REPAIR LH SILL MEMBER AND FRONT LH DOOR					
E PNT98000					✓150.00
SPRAY PAINT FRONT BUMPER , FRONT LH FENDER, FRONT LH A PILLAR ,					
FRONT LH DOOR, SILL LH MEMBER					
A 33900099					✓120.00
TO REMOVE AND REFIT LH FRONT U/CARRIAGE					
A WHEELALIGNMENTBP					✓30.00
TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT					
A 54900099					✓200.00
CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM					
A 10028901					✓80.00
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST					
USING HI-SCAN PRO TEST					
M SUNDRY					✓200.00
TO APPLY ANTI COROSSION ON AFFECTED PORTION					
M SUNDRY					✓102.00
TO APPLY BODY SEALANT ON AFFECTED PORTION					
S SPECIALISTJOB					180.00
WO: T140471 ACCIDENT TOWING @MIDNIGHT FROM CHANGI BUSINESS PARK TO PG -supp					
S TYRESALES1					✓60.00
SUPPLY LH FRONT TIRE -supp					
S SPECIALISTJOB					✓60.00
REPLACE LH FRONT SPORTS RIM, REPLACE TIRE VALVE, CONDUCT WHEEL					
BALANCING					
M SUNDRY					



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

**PRO-FORMA INVOICE****THIS IS NOT AN OFFICIAL TAX INVOICE**

GST Reg No : MR-8500111-X

Co Reg No : 1977014696

Invoice Name & Address	Owner Name & Vehicle Info	
Lion City Rentals Pte Ltd 60 Anson Road #11-01 Mapletree Anson Singapore 079914 Contact No Mobile: 67420984 11/12/	Cust No/Name	/Lion City Rentals Pte Ltd
	Reg No/Reg Date	SLF4247E / 26/08/2016
	Date In/Mileage	12/12/2017/ 123122
	Chassis/Package	MMBSTA13AHH001133
	Engine No	3A92UDG8152
	Make/Model	MIT/17MY ATTRAGE 1.2 CVT
	Colour/Trim	PO1 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
CSM00041	Cash	03/05/2018/ 08:53	TLT	881 / Jojo Cheng	17805			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
REPLACE LH REAR SPORTS RIM, REPLACE TIRE VALVE, CONDUCT WHEEL BALANCING								
X	BRACKET,RR BUMPER,LH				1.00	27.00	00.00	✓27.00
X	CLIP,FR BUMPER				10.00	3.00	00.00	✓30.00
X	FACE,RR BUMPER				1.00	740.00	00.00	✓740.00
X	SHIELD,RR WHEELHOUSE,LH				1.00	40.00	00.00	✓40.00
X	WHEEL,DISC RR LH				1.00	743.00	00.00	✓743.00
X	MARK,THREE-DIA				1.00	49.00	00.00	✓49.00
X	GRILLE,RADIATOR				1.00	548.00	00.00	✓548.00
X	FACE,FR BUMPER				1.00	696.00	00.00	✓696.00
X	CLIP,FR BUMPER				10.00	3.00	00.00	✓30.00
X	GRILLE,FR UNDER				1.00	163.00	00.00	✓163.00
X	BRACKET,FR BUMPER,LH				1.00	13.00	00.00	✓13.00
X	GARNISH,FR BUMPER,LH				1.00	126.00	00.00	✓126.00
X	REINFORCEMENT,FR BUMPER				1.00	136.00	00.00	✓136.00
X	HEADLAMP ASSY,LH				1.00	654.00	00.00	✓654.00
X	FENDER,FR LH				1.00	458.00	00.00	✓458.00
X	SHIELD,FR WHEELHOUSE,LH				1.00	97.00	00.00	✓97.00
X	WHEEL,DISC FRT LH				1.00	743.00	00.00	✓743.00
X	SHAFT AS,FR AXLE DRIVE,LH				1.00	1133.00	00.00	✓1133.00
X	KNUCKLE,LH				1.00	344.00	00.00	? 344.00
X	BEARING,FR WHEEL HUB LH				1.00	119.00	00.00	? 119.00
X	SNAP RING,FR WHEEL HUB LH				1.00	8.00	00.00	? 8.00
X	HUB ASSY,FR WHEEL LH				1.00	203.00	00.00	? 203.00
X	CROSSMEMBER,FR AXLE,NO.1				1.00	815.00	00.00	? 815.00
X	ARM ASSY,FR SUSP,LWR LH				1.00	318.00	00.00	? 318.00
X	STRUT,FR SUSP RH				1.00	447.00	00.00	? 447.00
X	INSULATOR,FR SUSP STRUT LH				1.00	92.00	00.00	? 92.00
X	BOX ASSY,RELAY				1.00	131.00	00.00	✓131.00
X	COVER,FR BRAKE DISC				1.00	25.00	00.00	25.00
X	STOPPER,FR SUSP STRUT				1.00	27.00	00.00	27.00
X	BEARING,FR SUSP STRUT				1.00	9.00	00.00	9.00
Z TEXT								



CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056



PRO-FORMA INVOICE

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Co Reg No : 197701469G

Invoice Name & Address	Owner Name & Vehicle Info	
Lion City Rentals Pte Ltd	Cust No/Name	/Lion City Rentals Pte Ltd
60 Anson Road	Reg No/Reg Date	SLF4247E / 26/08/2016
#11-01 Mapletree Anson	Date In/Mileage	12/12/2017/ 123122
Singapore 079914	Chassis/Package	MMBSTA13AH001133
Contact No Mobile: 67420984	Engine No	3A92UDG8152
11/12/	Make/Model	MIT/17MY ATTRAGE 1.2 CVT
	Colour/Trim	PO1 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
CSM00041	Cash	03/05/2018/ 08:53	TLT	881 / Jojo Cheng	17805		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount

TP FIRST CAP
DOA: 02.12.2017
SURVEYOR RASUL LKK 06.12.2017

Pro Forma

"Guarantee your warranty, maintain with Cycle & Carriage."

Parts	8,964.00		Nett	17,636.00
Labour	7,990.00	7% GST on	17636.00	1234.52
Standard Menu	0.00			
Specialist Job	342.00		Total Payable	18,870.52
Diagnostics Job	0.00			
Sundry/Others	340.00			
Total(w/o GST)	17,636.00			

Customer

Vehicle ident no.

Repair order no.
R000071Technician
SAM 114Date
16.12.17License plate no.
SLF 4247 E

First reg. date

Model

Mitsubishi : Mirage/Attrage : 2012- (Including G4)

Odometer reading: km/miles

123122

Complaints or reason for alignment check

			Before	Target Data		Actual
Rear axle	Camber	left	-0°11' *	-1°00'	+/-0°45'	-0°10' *
		right	-1°53' *			-1°53' *
		cross	1°42' *	0°00'	+/-0°30'	1°43' *
	Toe	left	0°03'	0°06'	+/-0°07'	0°03'
		right	0°13'			0°13'
		total	0°15'	0°12'	+/-0°14'	0°15'
	Geometrical driving axis		-0°05'	0°00'		-0°05'
Front axle	Camber	left	0°33'	0°05'	+/-0°45'	0°34'
		right	-1°13' *			-1°14' *
		cross	1°46' *	0°00'	+/-0°30'	1°48' *
	Caster	left	3°37'	4°00'	+/-0°45'	3°37'
		right	4°05'			4°05'
		cross	-0°28'	0°00'	+/-0°30'	-0°28'
	SAI	left	12°49'	11°35'	+/-1°30'	12°47'
		right	12°05'			12°05'
		cross	0°44'	0°00'		0°42'
	Track differential angle		left			
			right			
	Toe	left	0°01'	0°00'	+/-0°07'	0°00'
		right	0°03'			0°00'
		total	0°04'	0°00'	+/-0°14'	0°00'
Setback			0°00'			
Max steering lock	left steer	left				
		right				
	right steer	left				
		right				

* This value is not within specification. Tire wear, handling and safety problems may result.

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17023141/R1rbn2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 01-06-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 4839X	Veh. Inspected	SLF 4247E	
Policy No.	D-15072701MFSH	Coverage (\$)	0.00	
Claim No.	D17011182MFSH	Excess (\$)	0.00	
Assign From	SERENE	Assign Date	06/12/2017	
2. Vehicle Particulars & Condition				
Make & Model	MITSUBISHI ATTRAGE 1.2	c.c	1193	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	MMBSTA13AHH001133	Colour	RED	
Odometer	123122	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/55 R15	ROADSTONE	5 mm	
L/H Front Tyre	185/55 R15	ROADSTONE	5 mm	
R/H Rear Tyre	185/55 R15	ROADSTONE	5 mm	
L/H Rear Tyre	185/55 R15	ROADSTONE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT AND N/S REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/12/2017	Inspection Date	06/12/2017	
Survey held at	CYCLE & CARRIAGE AUTOMOTIVE PTE LTD 209 PANDAN GARDENS SINGAPORE 609339			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		16 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 3

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLF 4247E

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	BRACKET,RR BUMPER,LH (SN)	NECESSARY	27.00	27.00
10	CLIP,FR BUMPER (SN)	NECESSARY	30.00	30.00
1	FACE,RR BUMPER (SN)	DEFORMED	740.00	740.00
1	PANEL,QTR,OTR LH (SN)	TO REPAIR SEE LABOUR	748.00	-
2	STOPPER,WINDSHIELD GLASS (SN)	NOT NECESSARY	6.00	-
3	SPACER,RR WINDOW (SN)	NOT NECESSARY	27.00	-
1	SHIELD,RR WHEELHOUSE,LH (SN)	NECESSARY	40.00	40.00
1	WHEEL,DISC RR LH (SN)	SCRATCHED	743.00	743.00
1	SHOCK ABSORBER,RR LH SUSP (SN)	SERVICEABLE	193.00	-
1	MARK,THREE-DIA (SN)	NECESSARY	49.00	49.00
1	GRILLE,RADIATOR (SN)	SCRATCHED	548.00	548.00
1	FACE,FR BUMPER (SN)	TORN	696.00	696.00
10	CLIP,FR BUMPER (SN)	NECESSARY	30.00	30.00
1	GRILLE,FR UNDER (SN)	DEFORMED	163.00	163.00
1	COVER,HEADLAMP SUPT PANEL (SN)	SERVICEABLE	62.00	-
1	BRACKET,FR BUMPER,LH (SN)	NECESSARY	13.00	13.00
1	GARNISH,FR BUMPER,LH (SN)	SCRATCHED	126.00	126.00
1	LAMP ASSY,FOG,FR LH (SN)	SERVICEABLE	286.00	-
1	REINFORCEMENT,FR BUMPER (SN)	BENT	136.00	136.00
1	HEADLAMP ASSY,LH (SN)	BROKEN	654.00	654.00
1	FENDER,FR LH (SN)	BUCKLED	458.00	458.00
1	SHIELD,FR WHEELHOUSE,LH (SN)	CUT	97.00	97.00
10	CLIP,FR BUMPER (SN)	REPEATED	30.00	-
1	PILLAR,FR OTR LH (SN)	SERVICEABLE	992.00	-
2	STOPPER,WINDSHIELD GLASS (SN)	NOT NECESSARY	6.00	-
2	SPACER,WINDSHIELD (SN)	NOT NECESSARY	6.00	-
1	WHEEL,DISC FRT LH (SN)	SCRATCHED	743.00	743.00
1	SHAFT AS,FR AXLE DRIVE,LH (SN)	DISTORTED	1,133.00	1,133.00
1	KNUCKLE,LH (SN)	BENT	344.00	344.00
1	BEARING,FR WHEEL HUB LH (SN)	NECESSARY	119.00	119.00

Report Ref No. CS/FC117023141/R1rbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SNAP RING,FR WHEEL HUB LH (SN)	NECESSARY	8.00	8.00
1	HUB ASSY,FR WHEEL LH (SN)	BENT	203.00	203.00
1	CROSSMEMBER,FR AXLE,NO.1 (SN)	BENT	815.00	815.00
1	ARM ASSY,FR SUSP,LWR LH (SN)	BENT	318.00	318.00
1	STRUT,FR SUSP RH (SN)	BENT	447.00	447.00
1	INSULATOR,FR SUSP STRUT LH (SN)	NECESSARY	92.00	92.00
1	INSULATOR,FR SUSP STRUT LH (SN)	NECESSARY	79.00	79.00
1	SEAT,FR SUSP SPRING,UPR LH (SN)	NECESSARY	35.00	35.00
1	BOX,ASSY,RELAY (SN)	CRACKED	131.00	131.00
1	COVER,FR BRAKE DISC (ADDITIONAL)(SN)	BENT	25.00	25.00
1	STOPPER,FR SUSP STRUT (ADDITIONAL)(SN)	NECESSARY	27.00	27.00
1	BEARING,FR SUSP STRUT (ADDITIONAL)(SN)	NECESSARY	9.00	9.00
1	SUNDRIES (SN)	NOT NECESSARY	50.00	-
			11,484.00	9,078.00
	LABOUR			
	ACCIDENT TOWING.MIDNIGHT FROM CBP TO PG (ADDITIONAL).		102.00	102.00
	SUPPLY LH FRONT TIRE (ADDITIONAL).		180.00	180.00
	TO RENEW REAR BUMPER,WELD AND CUT REAR LH FENDER.INCLUSIVE OF THE REPAIR OF PANEL,QTR,OTR LH.		2,750.00	2,200.00
	TO REMOVE AND REFIT REAR WINDSCREEN.	NOT NECESSARY	240.00	-
	TO REMOVE AND REFIT REAR SEAT AND TRIM TO FACILITATE REPAIR.		200.00	150.00
	PAINT WORK SPRAY REAR BUMPER,REAR LH FENDER.		1,260.00	840.00
	TO REMOVE AND REFIT RH REAR U/CARRIAGE.	NOT NECESSARY	200.00	-
	TO TRANSFER REAR RH TYRE TO NEW RIM AND BALANCING.	NOT NECESSARY	80.00	-
	TO RENEW FRT BUMPER,FRT LH FENDER,WELD AND CUT FRT LH A PILLAR.REPAIR LH SILL MEMBER AND FRT LH DOOR.		2,750.00	2,200.00
	TO REMOVE AND REFIT FRT WINDSCREEN.	NOT NECESSARY	240.00	-
	TO REMOVE AND REFIT FRT CONSOLE.	NOT NECESSARY	300.00	-
	PAINT WORK SPRAY FRT BUMPER,FRT LH FENDER,FRT LH A PILLAR,FRT LH DOOR,SILL LH MEMBER.		2,520.00	2,100.00

Report Ref No. CS/FCI17023141/R1rbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE AND REFIT LH FRT U/CARRIAGE.	NOT NECESSARY	300.00	150.00
	TO TRANSFER FRT LH TYRE TO NEW RIM AND BALANCING.		80.00	-
	TO CONDUCT COMPUTERIZE FULL WHEEL ALIGNMENT.		120.00	120.00
	CHECK WIRING AND CHASSIS ELECTRICAL SYSTEM.		50.00	30.00
	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST.	NOT NECESSARY	200.00	200.00
	TO APPLY FRT AND REAR WINDSCREEN SEALANT.		160.00	-
	TO APPLY ANTI COROSSION ON AFFECTED PORTION.		150.00	80.00
	TO APPLY BODY SEALANT ON AFFECTED PORTION.		200.00	200.00
	TO REMOVE AND REFIT FUEL TANK.	NOT NECESSARY	300.00	-
			12,382.00	8,552.00
GRAND TOTAL			23,866.00	17,630.00
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				14,000.00

Report Ref No. CS/FCI17023141/R1rbn2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.