



Messrs Grab Rentals Pte Ltd

Estimate To Repair

Vehicle No :

Chassis No :

Mazda 3 Sedan 1.5 AT EU6

SLN9128R

JM6BN22A8H0153425

Third Party Insurer :

Insured's Veh No :

Date of accident :

III

SHD6524A

02.12.2017

Date : 02.12.2017

Pages : 1 of 2

S/No	Quantity	Description	Unit price	Amount
LIST ITEMS				
1	1 pc	bootlid <i>Beut/suc</i>	\$ 958.00	\$ 958.00
2	1 pc	bootlid Mazda 3 badge <i>nee</i>	\$ 54.00	\$ 54.00
3	1 pc	bootlid Skyativ badge <i>nee</i>	\$ 64.00	\$ 64.00
4	1 pc	bootlid centre emblem <i>nee</i>	\$ 75.00	\$ 75.00
5	2 pc	bootlid reflector <i>11</i>	\$ 265.00	\$ 530.00
	1 pc	bootlid inner trim <i>11</i>	\$ 121.00	\$ 121.00
7	5 pc	bootlid inner trim clips <i>11</i>	\$ 5.00	\$ 25.00
8	1-2 pc	bootlid lock <i>11</i>	\$ 153.00	\$ 306.00
9	1 pc	bootlid lock stricker <i>11</i>	\$ 35.00	\$ 35.00
10	1 pc	bootlid weatherstirp <i>11</i>	\$ 130.00	\$ 130.00
11	1 pc	bootlid keyless sensor <i>11</i>	\$ 78.00	\$ 78.00
12	2 pc	bootlid licence plate lamp <i>11</i>	\$ 72.00	\$ 144.00
13	1 pc	rear end panel <i>Body</i>	\$ 506.00	\$ 506.00
14	1 pc	rear end panel inner trim <i>11</i>	\$ 86.00	\$ 86.00
15	1 pc	rear end panel inner trim clips <i>11</i>	\$ 5.00	\$ 5.00
16	1 pc	rear luggage floor compartment foam <i>11</i>	\$ 166.00	\$ 166.00
17	1 pc	rear luggage floor trimboard <i>11</i>	\$ 350.00	\$ 350.00
18	2 pc	rear lamp <i>one</i>	\$ 509.00	\$ 1,018.00
19	4 pc	rear lamp clips holder <i>nee</i>	\$ 8.00	\$ 32.00
20	1 pc	rear bumper <i>Dis</i>	\$ 1,075.00	\$ 1,075.00
21	2 pc	rear bumper reflector <i>11</i>	\$ 51.00	\$ 102.00
	2 pc	rear bumper end splashshield cover <i>11</i>	\$ 80.00	\$ 160.00
23	10 pc	rear bumper clips <i>nee</i>	\$ 5.00	\$ 50.00
24	1 pc	rear bumper reinforcement <i>nee</i>	\$ 538.00	\$ 538.00
25	2 pc	rear bumper side retainer <i>nee</i>	\$ 46.00	\$ 92.00
26	2 pc	rear bumper side holder <i>nee</i>	\$ 37.00	\$ 74.00
27	4 pc	rear bumper side holder rivets <i>nee</i>	\$ 5.00	\$ 20.00
28	2 pc	rear bumper tow cover <i>nee</i>	\$ 17.00	\$ 34.00
Less 20%				\$ 6,828.00
				\$ 1,365.60
				\$ 5,462.40
Balance C/F				\$ 5,462.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Please conduct the survey at

Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216

Enail on 02.12.2017
@ 172hrs.

Confirmed
on 06/12/17

Not Admit
note
6/14/17
1/5 # 4800

take place After repair
5 day

req: LKK marcus

06.12.2017 @ 0930hrs

Messrs Grab Rentals Pte Ltd

Date : 02.12.2017

Estimate To Repair : Mazda 3 Sedan 1.5 AT EU6
Vehicle No : SLN9128R
Chassis No : JM6BN22A8H0153425

Pages : 2 of 2

S/No	Quantity	Description	Unit price	Amount
		Balance B/F		\$ 5,462.40
		<u>SPECIAL NETT ITEMS</u>		
29		rear licence plate	\$ 80.00	\$ 80.00 X
30		rear bumper parking sensor 2005.11 shift	\$ 450.00	\$ 450.00
				\$ 530.00
		<u>LABOUR & MISC. CHARGES</u>		
1		To check electrical lighting concerned.	30	\$ 60.00
2		To rust-proofing of the affected areas.	60	\$ 180.00
3		To remove and refit interior fittings, trimmings, garnish and other, to enable repair.	80	\$ 150.00
4		To reinstall of rear bumper parking sensor.	50	\$ 120.00
5		To repair and realign rear exhaust box.	11 X	\$ 120.00
6		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.		\$ 850.00 ✓
7		Putty and spray painting of the affected portion.		\$ 850.00 ✓
			2/20	\$ 2,330.00
			601F.4	
		Grand Total		\$ 8,322.40

Please conduct the survey at

Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216