



BAN HOCK HIN
Co., Pte Ltd

Co.Reg.No: 19700288K

MOTORCYCLE ACCESSORIES | SERVICE CENTRE
MODIFICATIONS | SPRAY PAINTING AND BODY WORK | METAL
WORKS | LEASING & RENTALS | FLEET SALES | INSURANCE SALES

QUOTATION

Customer :

NO. : 32189

AIG ASIA PACIFIC INSURANCE PTE LTD
CHARTIS BUILDING
78 SHENTON WAY
#07-16
SINGAPORE 079120
MOTOR CLAIMS DEPT

DATE : 30/11/2017
CLAIM NO. : 11067
POLICY NO. : AVFMSB0000621700
FROM : RAYMOND

VEHICLE NO. : FBK6113L
MAKE/MODEL : YAM / YBR125

*Not Arthur
here
To highlight other items
2/1/17
4/1/17 6/1/17*

(Page 1 of 3)

S/N	Description	Action	Qty	Unit Price	Amount
1	BAR HANDLE P/N: 42062	REPLACE	1.00	\$68.00	68.00
2	BRACKET UNDER FORK P/N: 27458	REPLACE	1.00	\$180.00	180.00
3	CLIP TUBE INNER FORK P/N: 35796	REPLACE	2.00	\$5.00	10.00
4	COVER TAIL LH (BLACK) P/N: 50952	REPLACE	1.00	\$85.00	85.00
5	COVER TANK SIDE LH (BLACK) P/N: 54458	REPLACE	1.00	\$98.00	98.00
6	CRASH BAR P/N: 35878	REPLACE	1.00	\$195.00	195.00
7	FOOT REST 1 P/N: 50005	REPLACE	1.00	\$55.00	55.00
8	GUIDE AIR LH P/N: 48403	REPLACE	1.00	\$23.00	23.00
9	HANDLE SEAT P/N: 42567	REPLACE	1.00	\$98.00	98.00
10	HEADLIGHT ASSY P/N: 50950	REPLACE	1.00	\$320.00	320.00
11	LABOUR P/N: 06766 - FOR DISMANTLING AND ASSEMBLING OF PARTS QUOTED.	Supply/Install	8.00	\$35.00	280.00
12	LAMP SIGNAL FRONT RH P/N: 42003	REPLACE	1.00	\$55.00	55.00
13	LAMP SIGNAL REAR LH P/N: 44858	REPLACE	1.00	\$63.00	63.00



S/N	Description	Action	Qty	Unit Price	Amount
14	LEVER CLUTCH P/N: 49946	REPLACE	1.00	\$18.00	18.00
15	MIRROR LH P/N: 49947	REPLACE	1.00	\$80.00	80.00
16	MIRROR RH P/N: 54029	REPLACE	1.00	\$80.00	80.00
17	MUDGUARD FRONT (BLACK) P/N: 45203	REPLACE	1.00	\$85.00	85.00
18	OIL FORK (UNICORN) MR-10 P/N: 54320	REPLACE	0.36	\$10.00	3.60
19	PIPE EXHAUST ASSY P/N: 50025	REPLACE	1.00	\$1,655.00	1,655.00
20	PLATE NUMBER REAR (6.5 INCH X 9 INCH) P/N: 26951	REPLACE	1.00	\$21.00	21.00
21	RUBBER FOOTREST FRONT P/N: 26136	REPLACE	2.00	\$14.00	28.00
22	SEAL DUST FORK P/N: 26833	REPLACE	2.00	\$7.00	14.00
23	SEAL OIL (30X41X10) FORK P/N: 13451	REPLACE	2.00	\$24.00	48.00
24	STEERING CONE SET P/N: 41793	REPLACE	1.00	\$66.00	66.00
25	STICKER (MCDONALDS) SIDE COVER V2 P/N: 56222	REPLACE	2.00	\$16.00	32.00
26	STICKER (MCDONALDS) WINDSHIELD V2 P/N: 56223	REPLACE	1.00	\$16.00	16.00
27	STICKER NUMBER PLATE FRONT (BLACK) STRAIGHT P/N: 32921	REPLACE	1.00	\$12.00	12.00
28	TRANSPORT CHARGES P/N: 07169 - TOW BACK BIKE FOR ACCIDENT REPAIRS. - DELIVER BIKE BACK TO OUTLET.		1.00	\$35.00	35.00
29	TUBE INNER FORK P/N: 27114	REPLACE	2.00	\$96.00	192.00
30	VISOR P/N: 43130	REPLACE	1.00	\$29.00	29.00

SUB TOTAL

\$3,944.60

GST @ 7 %

\$276.12

GRAND TOTAL

\$4,220.72

Validity: 30 days

For & on Behalf of
BAN HOCK HIN CO PTE LTD



LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Acknowledge & Accepted By



<u>S/N</u>	<u>Description</u>	<u>Action</u>	<u>Qty</u>	<u>Unit Price</u>	<u>Amount</u>
	 RAYMOND				

This quotation is sent via email / LAN-Fax and will bear a computer generated signature.

