



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
INDIA INTERNATIONAL INSURANCE PL		Ref : CC6/III17023151/Uua3	
64 CECIL STREET #05-02 IOB BUILDING SINGAPORE 049711		Date : 06-12-2017	
		Code : III2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHD 4824Y	Veh. Inspected	SKG 3572D
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	06/12/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	02/12/2017	Inspection Date	06/12/2017
Survey held at	QUAN DE MOTOR TRADING BLK 1 KAKI BUKIT AVENUE 6 #01-67 AUTOBAY SINGAPORE 417883		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

2263W U

not allowed
 r/r
 2/5 @ 3300
 4 day.
 take photo after rep
 Attn: Mr. Marcus

QUAN DE MOTOR TRADING

1 KAKI BUKIT AVENUE 6, #01-67
 AUTOBAY, SINGAPORE 417883
 HP: 96709191 FAX: 66840767
 email: quanv3@yahoo.com.sg

India International Insurance Pte Ltd
 64 Cecil Street
 #04/#05 IOB Building
 Singapore 049711
 Attn: Motor Claims Department

Date: 5 December 2017

**Accident on 02/12/2017 Involving vehicles SKG3572D & SHD4824Y
 along Selegie Road**

Estimate cost of repair to vehicle SKG3572D Subaru Impreza

1 pc.	bootlid	R	\$ 654.00	a
1 pc.	bootlid weatherstrip	tw	\$ 86.30	✓
1 pc.	rear end panel	Body	\$ 576.60	✓
1 pc.	rear end panel top garnish	tw	\$ 118.00	✓
1 pc.	taillamp	cre	\$ 412.30	✓
1 pc.	rear floor panel top board	tin	\$ 125.00	✓
1 pc.	rear fender inner trim	tin	\$ 166.20	✓
			\$ 2,138.40	1484.4
		20% Less 10%	\$ 213.84	1187.52
			\$ 1,924.56	

S. Nett Items:

1 pc.	rear bumper sport	CR	\$ 1,500.00	1100
1 set	rear bumper clips	ru	\$ 50.00	✓
1 set	rear bumper reverse sensor	shk	\$ 280.00	200
1 pc.	rear licence plate w/holder	bat	\$ 50.00	40

Labour Charges:

To check wiring	\$ 50.00	30
To remove & refix reverse sensor	\$ 100.00	50
To transfer bootlid mechanism	\$ 100.00	x
To remove & refix interior upholstery	\$ 100.00	60
To spray rust-proofing	\$ 100.00	30
Labour for panel beating, welding & renew parts	\$ 900.00	680
Spray painting	\$ 950.00	800

Total: \$ 6,104.56 4227.52

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

View Received Message

This mail is associated with :

*SKG3572D (MCT17120060)
[SHD4824Y]
TP
REPUBLIC CAR PTE. LTD.
Dec 2 2017 4:00PM
[-]
Quan De Motor Trading

Reply Reply All Mark as Unread Print Message Delete Message Forward

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 06/08/2018 11:45 AM.
To LAK_HQ
Subject Alert - Adj Mandate Approved (\$90.00) - SKG3572D - Claim Handler: NATALIE LEE

Approved: 0.00: We have uploaded the video of the accident, the damages to our insured vehicle and the damages to TP does not seem to match. Please comment on the same

DOCUMENTS SUMMARY

There are no documents.

according to OI video footage can see clearly tp vehicle rear bumper is No Damage
After OI hit on tp vehicle. reporting photo show OI took ~~photo~~ some photo
at the scene can clearly show tp vehicle rear bumper had been cracked and damaged.
~~because~~ TP vehicle rear bumper is custom made and is made from (fibre)
base on the video footage & scene photo & inspection assessment
Damage is consistent.

View Received Message

This mail is associated with :

***SKG3572D (MCT17120060)**
[SHD4824Y]
 TP
 REPUBLIC CAR, PTE. LTD.
 Dec 2 2017 4:00PM
 [-]
 Quan De Motor Trading

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 24/08/2018 09:25 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$3665.35) - SKG3572D - Claim Handler: NATALIE LEE

Approved:3665.35.

DOCUMENTS SUMMARY
 There are no documents.

Print Received Message

This mail is associated with :

***SKG3572D (MCT17120060)
[SHD4824Y]**

TP

REPUBLIC CAR PTE. LTD.

Dec 2 2017 4:00PM

[COMFORT TRANSPORTATION PTE LTD]

Quan De Motor Trading

From India International Insurance Pte Ltd (HQ) (III_SG), sent on 01/07/2019 11:04 AM.
To LKK_HQ
Subject Alert - Adj Mandate Approved (S\$3665.35) - SKG3572D - Claim Handler: Pooi Chin Han Daniel

Approved:3665.35.

QUAN DE MOTOR TRADING

1 KAKI BUKIT AVENUE 6, #01-67

AUTOBAY, SINGAPORE 417883

HP: 96709191 FAX: 65096584

India International Insurance Pte Ltd
64 Cecil Street
#04/#05 IOB Building
Singapore 049711
Attn: Motor Claims Department

Date: 18 January 2018

**Accident on 02/12/2017 involving vehicles SKG3572D & SHD4824Y
along Selegie Road**

With regards to the above, we are writing on behalf of the registered owner of vehicle SKG3572D which was involved in the abovementioned accident.

We are informed that the accident was caused solely by the negligence of your insured vehicle SHD4824Y. As a result of the accident, our client's vehicle was damaged and our client has been put to great loss and expenses, particulars of which are as follows:

1) Cost of Repairs	\$3,300.00
2) Loss Of Rental (6 days x @\$100.00)	\$600.00
3) LTA search fee	\$5.35
Total:	<u><u>\$3,905.35</u></u>

We hereby enclosed herewith the following documents for your confirmation of the above claim.

- | | |
|-----------------------------|--|
| a) Original Invoice | b) GIA Accident Report |
| c) Certificate of Insurance | d) Owner/Driver NRIC & Driving License |
| e) Letter of Authorisation | f) LTA search invoice |

Kindly acknowledge receipt of the above documents and your favourable reply is much appreciated.

Yours sincerely,

QUAN DE MOTOR TRADING


email: quanv3@yahoo.com.sg

Date: 06/12/2017

To: India International Insurance Pk. Ltd.

RE: ACCIDENT INVOLVING VEHICLES SKG 3572 D & SHD 4824 Y

ALONG SELEGIE ROAD

ON 02/12/2017

I/We, Republic Car Pk. Ltd. of (NRIC/ROC No.) 201712263W

of _____

owner of vehicle no. SKG 3572 D in consideration of M/s. Quan De Motor Trading

repairing my/our vehicle SKG 3572 D at my/our instruction and hereby authorise

M/s. Quan De Motor Trading to demand claim settle receive whatever amount settled/payable

by the Insurance Company and/or third party or to commence legal proceedings, if necessary,

under my name, for cost of repairs, car rental and/or loss of use, etc. and to their appointing

solicitor to act for me/us in respect of the said accident/claim and all claimed and/or settled shall

belong to them absolutely.

I further agree and undertake to indemnify them against the abovementioned claims costs which may arisen therewith.

Signature of Owner: _____



Name of Owner : REPUBLIC CAR PTE LTD



INDIA INTERNATIONAL INSURANCE PTE LTD
 Co Reg No: 196701792R | GST Reg No: M2-0070006-X
 54 Cecil Street | #04 | #05 | #06-02 - Raffles Building | Singapore 040711
 Office: 65 63476100 Email: insurance@iia.com.sg
 Fax: 65 62244174 Website: www.iia.com.sg

EXPRESS SETTLEMENT

DISCHARGE VOUCHER III-Direct Settlement (PODS)

India Ref: MCT17120060
 Claimant Ref: SKG 3572D

We/I, Quan De Motor Trading ("the workshop") hereby confirm that we/I have reached an agreement with the appointed Surveyor of India International Insurance Pte Ltd LKK Auto Consultants Pte Ltd (name of Surveyor) with respect to the amount claimed for S\$ 3,300.00 (repair cost), S\$ 360.00 (loss of use ~~cost~~), S\$ 5.35 (search fee), vehicle no. SKG 3572D that was damaged pursuant to the accident which occurred on 02/12/2017 (date) at SELEGIE ROAD (location) involving vehicle no. SHD4824Y (insured vehicle). This is pursuant to the inspection conducted on 06/12/2017 (date) at "the workshop".

We/I confirm that we/I are/am authorized by the owner REPUBLIC CAR PTE LTD ("the third party claimant") of vehicle no. SKG 3572D to make the claim as set out in the above paragraph and we/I have full authority to settle the matter on his/her behalf in a manner that we/I deem fit. We/I enclose herein the letter of authority given by "the third party claimant".

We/I further confirm that we/I will indemnify India International Insurance Pte Ltd for all damages, loss and/or expense that they will or have already incurred in the event that "the third party claimant" after the above said agreement lodges a further claim against the former for any loss and expenses suffered pertaining to cost of repairs and/or rental and/or loss of use pursuant to the damage to SKG 3572D (vehicle no.) as a result of the accident.

We/I confirm that the agreement reached above is in full and final settlement of all claims of "the third party claimant" pursuant to the accident and that further this settlement is reached on a without prejudice and without admission of liability basis.

This agreement is subject to the application of Singapore law and the Singapore Courts have exclusive jurisdiction over any dispute arising out of the same.

We/I authorize you to pay the total amount of S\$ 3,665.35 to Quan De Motor Trading

Dated this 16 day of July 20 19

CLAIMANT: **QUAN DE MOTOR TRADING**
 1 Kaki Bukit Avenue 6
 Signature: #01-67 Autobay, Singapore 417883
 Signed by the workshop (workshop)
 Name: _____
 NRIC: _____
 Address: _____
 Nationality: _____
 Occupation: _____

WITNESS: 
 Signature: [Signature]
 Signed by appointed Surveyor
 Name: LKK Auto Consultants Pte Ltd
 NRIC: 199607198R
 Address: Blk 51, Paya Ubi Industrial Park
Ubi Avenue 1, #02-25 | S(408933)
 Nationality: -
 Occupation: -

QUAN DE MOTOR TRADING

1 KAKI BUKIT AVENUE 6, #01-67
AUTOBAY, SINGAPORE 417883
HP: 96709191 FAX: 66840767
Email: quanv3@yahoo.com.sg

India International Insurance Pte Ltd
64 Cecil Street
#04/#05 IOB Building
Singapore 049711
Attn: Motor Claims Department

Date: 18 January 2018

Accident on 02/12/2017 involving vehicles SKG3572D & SHD4824Y
along Selegie Road
Invoice for cost of repair to vehicle SKG3572D Subaru Impreza

To supply spare parts, labour for panel
beating, welding & renew parts,
including spray painting.

Lump sum: \$ 3,300.00

(S.DLS: THREE THOUSAND THREE HUNDRED ONLY)





Land Transport Authority
 10 Sin Ming Drive
 Singapore 575701
 GST Registration No. : M4-0006529-2

Print Date/Time : 05 Dec 2017 / 15:32:12

Receipt Date/Time : 05 Dec 2017 / 15:32:12

Tax Invoice/Receipt

Receipt No. : ITNET-00000-171205-001432

Previous Receipt No. :

S/N	Item Description/ Business Transaction Reference No.	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SHD4824Y As at 02 Dec 2017/16:30:00 Insurance Co: INDIA INT'L INS PTE LTD				
1	Insurance Enquiry - SHD4824Y Enquiry Fee 20171205153057119171	5.00	0.35	5.35
Sub-Total		5.00	0.35	5.35
Total Before Rounding		5.00	0.35	5.35
Rounding Difference				0.00
Total Amount Payable				5.35
Paid By				
	xxxxxxxxxxxx9696		Credit Card: Visa/MasterCard	5.35
Total				5.35
Cash Change				0.00
Tendered Amount				5.35
Excess Refundable Amount				0.00

THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.

Enquire PARF/COE Rebate for Registered Vehicle

1597

Vehicle Owner Particulars

Owner ID Type	Company
Owner ID	2263W

Vehicle Details

Vehicle No.	SKG3572D
Vehicle to be Exported	No
Intended De-registration Date	31 Dec 2017
Vehicle Make	SUBARU
Vehicle Model	IMPREZA 4AT
Primary Colour	White
Manufacturing Year	2007
Engine No.	EJ16D134220
Chassis No.	JF1GD5KR57G072039
Maximum Power Output	70.0 kW (93 bhp)
Open Market Value	\$10,994.00
Original Registration Date	18 Apr 2008
First Registration Date	18 Apr 2008
Transfer Count	5
Actual ARF Paid	\$12,094.00

Intended PARF Rebate Details

PARF Eligibility	Yes
PARF Eligibility Expiry Date	17 Apr 2018
PARF Rebate Amount	\$6,047.00

Intended COE Rebate Details

COE Expiry Date	17 Apr 2018
COE Category	A - Car (1600cc & below)
COE Period(Years)	10
QP Paid	\$16,839.00
COE Rebate Amount	\$500.00
Total Rebate Amount	\$6,547.00

The information contained herein is correct as at 05 Dec 2017

OK

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Dec 2017 Edit Reg		06 Dec 2017 00:00 Edit Adj Rpt	S\$3,300.00 Edit Estimates	S\$3,300.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by adjuster]									
Insured:	COMFORT TRANSPORTATION PTE LTD , Co. Reg. No.: 199303821R								
Main Claimant:	REPUBLIC CAR PTE. LTD. , Co. Reg. No.: 201712263W								
Vehicle Reg. No.:	SKG3572D	Date of Loss:	02/12/2017 16:00 - :59 [115 Months and 14 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / MCT17120060	Policy/Cover Note No.:	MCOM0016						
Vehicle Reg. No. (Insured):	SHD4824Y	Policy No. (Claimant):	5091129051(PREMIUM)						
		Excess:							
Repairer:	Quan De Motor Trading () BLK 1 KAKI BUKIT AVENUE 6 #01-67 AUTOBAY SINGAPORE 417883, 417883 Kaki Bukit - Tel:								
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Pool Chin Han Daniel]								
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MARCUS CHUA] ... [Final Rpt due 15/12/2017]								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
<ul style="list-style-type: none"> • III_SG (01/07/2019): Alert - Adj Mandate Approved (S\$3665.35) - SKG3572D - Claim Handler: Pool Chin H... • III_SG (24/08/2018): Alert - Adj Mandate Approved (S\$3665.35) - SKG3572D - Claim Handler: NATALIE LEE • III_SG (06/08/2018): Alert - Adj Mandate Approved (S\$0.00) - SKG3572D - Claim Handler: NATALIE LEE • III_SG (13/12/2017): Alert - Adj Mandate Approved (S\$0.00) - SKG3572D - Claim Handler: NATALIE LEE 									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SKG3572D (MCT17120060)
[SHD4824Y]
TP
REPUBLIC CAR PTE. LTD.
Dec 2 2017 4:00PM
[COMFORT TRANSPORTATION PTE LTD]
Quan De Motor Trading

Upload Documents			Upload Photos			Compose New Letter			View	View in Browser
Video									1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)		Thumbnail	Print					
1	06/08/18 11:42	Video - Accident		Load MP4	<input type="checkbox"/>					
2	06/08/18 11:53	Video - Accident		Load MP4	<input type="checkbox"/>					
Photos/Images									3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	06/12/17 14:41	Chassis Number		Load JPG	<input checked="" type="checkbox"/>					
2	06/12/17 14:41	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>					
3	06/12/17 14:41	General View		Load JPG	<input checked="" type="checkbox"/>					
4	06/12/17 14:41	General View		Load JPG	<input checked="" type="checkbox"/>					
5	06/12/17 14:41	General View		Load JPG	<input checked="" type="checkbox"/>					
6	06/12/17 14:41	General View		Load JPG	<input checked="" type="checkbox"/>					
7	06/12/17 14:41	General View		Load JPG	<input checked="" type="checkbox"/>					
8	06/12/17 14:41	General View		Load JPG	<input checked="" type="checkbox"/>					
9	06/12/17 14:41	General View		Load JPG	<input checked="" type="checkbox"/>					
10	06/12/17 14:41	General View		Load JPG	<input checked="" type="checkbox"/>					
11	06/12/17 14:41	General View		Load JPG	<input checked="" type="checkbox"/>					
12	06/12/17 14:41	General View		Load JPG	<input checked="" type="checkbox"/>					
13	06/12/17 14:41	General View		Load JPG	<input checked="" type="checkbox"/>					
14	06/12/17 14:41	General View		Load JPG	<input checked="" type="checkbox"/>					
15	06/12/17 14:41	General View		Load JPG	<input checked="" type="checkbox"/>					
16	06/12/17 14:41	General View		Load JPG	<input checked="" type="checkbox"/>					
17	06/12/17 14:41	General View		Load JPG	<input checked="" type="checkbox"/>					
18	06/12/17 14:41	General View		Load JPG	<input checked="" type="checkbox"/>					
19	06/12/17 14:41	General View		Load JPG	<input checked="" type="checkbox"/>					
20	06/12/17 14:41	General View		Load JPG	<input checked="" type="checkbox"/>					
21	06/12/17 14:41	General View		Load JPG	<input checked="" type="checkbox"/>					
22	06/12/17 14:41	General View		Load JPG	<input checked="" type="checkbox"/>					
23	06/12/17 14:41	General View		Load JPG	<input checked="" type="checkbox"/>					
24	06/12/17 14:41	General View		Load JPG	<input checked="" type="checkbox"/>					
25	06/12/17 14:41	General View		Load JPG	<input checked="" type="checkbox"/>					
26	06/12/17 14:41	General View		Load JPG	<input checked="" type="checkbox"/>					
27	06/12/17 14:41	General View		Load JPG	<input checked="" type="checkbox"/>					
28	06/12/17 14:41	General View		Load JPG	<input checked="" type="checkbox"/>					
29	06/12/17 14:41	General View		Load JPG	<input checked="" type="checkbox"/>					
30	06/12/17 14:41	General View		Load JPG	<input checked="" type="checkbox"/>					
31	06/12/17 14:41	General View		Load JPG	<input checked="" type="checkbox"/>					
32	06/12/17 14:41	General View		Load JPG	<input checked="" type="checkbox"/>					
33	06/12/17 14:41	General View		Load JPG	<input checked="" type="checkbox"/>					

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
34	06/12/17 14:41	General View	 Load JPG	<input checked="" type="checkbox"/>
35	06/12/17 14:41	General View	 Load JPG	<input checked="" type="checkbox"/>
36	06/12/17 14:41	General View	 Load JPG	<input checked="" type="checkbox"/>
37	06/12/17 14:41	General View	 Load JPG	<input checked="" type="checkbox"/>
38	06/12/17 18:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	06/12/17 18:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	06/12/17 18:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	06/12/17 18:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	06/12/17 18:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	06/12/17 18:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	06/12/17 18:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	06/12/17 18:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	06/12/17 18:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	06/12/17 18:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	06/12/17 18:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	06/12/17 18:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	06/12/17 18:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	06/12/17 18:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	06/12/17 18:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	06/12/17 18:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	06/12/17 18:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	06/12/17 18:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	06/12/17 18:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	06/12/17 18:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	06/12/17 18:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	06/12/17 18:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	06/12/17 18:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	06/12/17 18:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	06/12/17 18:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	06/12/17 18:11	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	07/12/17 15:55	TP GIA REPORT	 Load PDF	
2	23/01/18 10:10	TP ESTIMATE - MARKED	 Load PDF	
3	27/07/18 11:12	WORKSHOP INVOICE	 Load PDF	
4	27/07/18 11:12	LTA SEARCH	 Load PDF	
5	27/07/18 11:12	LOD	 Load PDF	
6	17/07/19 11:07	DISCHARGE VOUCHER	 Load PDF	
7	17/07/19 11:07	AUTHORISATION TO ACT FORM	 Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	07/12/17 08:42	Singapore Accident Statement	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)			

Show Remarks To: Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III17023151/UHA3Q2

Date: 17/07/2019

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No: MCOM0016
Claimant Vehicle No : SKG3572D	Insured Vehicle No : SHD4824Y
Date of Loss: 02/12/2017	Nature of Claim: TP Claim No: MCT17120060

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKG3572D	Engine No: EJ16D134220
Make & Model: SUBARU IMPREZA, 1.6 (A)	Chassis No: JF1GD5KR57G072039
Reg. Date: 18/04/2008 (Man. Year: 2007)	Odometer: 242045 km
Colour: White	
Engine Capacity: 1597 cc	
Market Value/New Car Price: N/A	
Sum Insured (S\$): Market Value/New Car Price	

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/45Z R17	Rear Tyre Size:	215/45Z R17
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,804.56	2,577.52	1,227.04	32.25
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,300.00	1,650.00	650.00	28.26
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,104.56	4,227.52	1,877.04	30.75
Approved Total (Overridden) (S\$)		3,300.00		
Nett Amount (S\$)	6,104.56	3,300.00	2,804.56	45.94
+ Loss of Use (6.0 x S\$60.00/day) (S\$)		360.00		
+ Doc/Search Fee (S\$)		5.35		
Nett Liability (S\$)		3,665.35		

INSPECTION

Date of Assignment: 06/12/2017
Date Inspected: 06/12/2017 Inspected At:

Quan De Motor Trading
BLK 1 KAKI BUKIT AVENUE 6 #01-67
AUTOBAY SINGAPORE 417883
Singapore 417883

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 27 Jul 2018)
Parts: 143	SUBARU IMPREZA 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SKG3572D)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BOOTLID	Repair	654.00 FL	*- FL
2	1		*BOOTLID WEATHERSTRIP	Twisted	86.30 FL	*86.30 FL
3	1		*REAR END PANEL	Badly Dented	576.60 FL	*576.60 FL
4	1		*REAR END PANEL TOP GARNISH	Twisted	118.00 FL	*118.00 FL
5	1		*TAILLAMP	Cracked	412.30 FL	*412.30 FL
6	1		*REAR FLOOR PANEL TOP BOARD	Torn	125.00 FL	*125.00 FL
7	1		*REAR FENDER INNER TRIM	Torn	166.20 FL	*166.20 FL
8	1		*REAR BUMPER SPORT	Cracked	1,500.00 FS	*1,100.00 FS
9	1		*SET REAR BUMPER CLIPS	Necessary	50.00 FS	*50.00 FS
10	1		*SET REAR BUMPER REVERSE SENSOR	Shorted	280.00 FS	*200.00 FS
11	1		*REAR LICENCE PLATE W/HOLDER	Bent	50.00 FS	*40.00 FS
Sub Total (\$\$)					4,018.40	2,874.40
- List Item Discount on L Items 10.00/20.00% (\$\$)					213.84	296.88
Total Parts (\$\$)					3,804.56	2,577.52

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO CHECK WIRING	New	50.00	30.00
2	TO REMOVE & REFIX REVERSE SENSOR	New	100.00	50.00
3	TO TRANSFER BOOTLID MECHANISM	New	100.00	0.00
4	TO REMOVE & REFIX INTERIOR UPHOLSTERY	New	100.00	60.00
5	TO SPRAY RUST-PROOFING	New	100.00	30.00
6	LABOUR FOR PANEL BEATING ,WELDING & RENEW PARTS	New	900.00	680.00
7	SPRAY PAINTING	New	950.00	800.00
Gross Labour Cost (S\$)			2,300.00	1,650.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >