

INS. CASE OWNER

Kwee May | CC 4 / AXA170 23157, MUA3

LKK:  
IDAC:

Surveyor:

MA CP

DOI:

ASSIGNMENT

7/12/17

Date / Time:

Registered in Meriment:

5/12/17  
5/12/17

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHC 5843R

Name of Insured:

TRANS-CAB SERVICE P/L

Insured Tel No.:

HP:

Excess Sec II :SS

5,000.00

D.O.A.:

30/11/17

Is driver the owner?

( YES NO )

Nature of Accident:

If NO, Driver Name / Age:

Seah Keng Soon

Driver Tel No.:

92308428

(V/L: YES / NO)

Claim No.:

Policy No.:

Make / Model:

Place of Accident:

PI680520

Perakut Latitude

Tanjung Pagar Road

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability: % Final ? Yes / No

STE 8915M



INSRS:

WSP:

Tel:

Liability:

RMKS:

Hui Yang



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

12/12  
THSTE 8915M - X;  
SHC 5843R - NA (MUA 5012849 / 01) ; D.O.A. 29/10/15

12/12/17

OI rear-ended to TP. Send email to OI

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

THW RyEnail  
12/12

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD:

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE Date/Time:

8/12

Sent By:

LSP

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost

S\$

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with:

Email

Call

Final Liability:

%

100 - (Agreed / Assessed) BOLA S/N No. : 27

Repair Cost

S\$

2675.00

Loss of Rental (LOR):

S\$

642.00 ( 5 days) x 120 + GST

Loss of Use (LOU):

S\$

( \$ x days)

Loss of Income (LOI):

S\$

( \$ x days)

LOR only ☐ LOU only ☐LOR + LOU ☐ LOR + LOI ☐ [Tick only one]

GIA/LTA Search

S\$

Medical:

S\$

Disbursement:

S\$

(e.g. Tow/ Independent)

Legal Cost

S\$

Total:

S\$

3317.00

Global Sum S\$:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

S\$

3317.00

Name 1:

HUI YANG MOTOR PTE LTD

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

11/11/18

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

3) Survey fee:

Surrey

REF:

Kun3

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No: \_\_\_\_\_

Claims No: \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: S8E891SM- Yr Regn MAY 2008

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: HONDA STREAM. C.C. 1799

Colour: Brown. A/C: Insured / Std / NI / NA

Sp. Reading: 152689. T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: RN61055815.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55/16

R: \_\_\_\_\_

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or TOYO.

Front Rear

R/Bal. 7 mm R/Bal. 7 mm

L/Bal. 7 mm L/Bal. 7 mm

D.O.A. 30/4/2017 D.O.I. 04/12/2017

Survey held at \_\_\_\_\_

Des. of Damages: Frt Rear O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

L/S - \$2500+ (Red: \$ 1650.99 / 40%)

Date/Time: File Pass to?

☐

: Prel. Report

1)

☐

: Final Report

Date/Time: File Return to?

2)

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Survey Fee: \_\_\_\_\_

Transportation: \_\_\_\_\_

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech Invs (\$)☐ Weekend (\$)

) \$ - RS. \$

) Photo

) Other

TOTAL

Report Format: \_\_\_\_\_

Lump Sum / I.B.I: (\$ \_\_\_\_\_)



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AXA INSURANCE PTE LTD			Ref : CC4/AXA17023157/M1ua3	
8 SHENTON WAY #24-01 AXA TOWERSINGAPORE 068811			Date : 06-12-2017	
			Code : AXA2	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHC 5843R	Veh. Inspected	SJE 8915M	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	06/12/2017	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date	30/11/2017	Inspection Date	07/12/2017	
Survey held at	HUI YANG MOTOR SERVICE BLOCK 176 SIN MING DRIVE #04-02/03 SIN MING AUTOCARE SINGAPORE 575721			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

06/12 Wed  
after 11am

# 輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721  
Tel: 64515752 (2 Lines) . Fax: 64514658  
Reg No. 201629438M

30/11/2017

Owner: HYMS CAR LEASING PTE LTD

## ESTIMATE TO REPAIR HONDA STREAM 1.8L - SJE8915M

1pc	rear tailgate	\$ 903.20	bt
1pc	rear tailgate stream emble	\$ 31.60	h2
1pc	rear tailgate glass moulding	\$ 75.20	h2
1pc	rear tailgate inner lock	\$ 109.20	bt
1pc	rear tailgate inner rubber	\$ 121.64	h2
1pc	rear end panel	x\$ 458.50	h2
1pc	rear end panel inner garnish	x\$ 116.70	ov
1pc	rear bumper	\$ 588.90	df
2ps	rear bumper side retainer @ \$29.40	\$ 58.80	dis

less 20%

\$ 2,463.74  
\$ 492.75  
\$ 1,970.99

1 set reverse sensor  
sealant

1510  
1640  
Jute s.nett \$ 280.00 220  
New s.nett \$ 60.00

remove & refix rear windscreen  
tuffkote  
wiring  
spray painting  
labour charges  
Total

3150  
23 20%  
152500  
\$ 120.00 100  
\$ 60.00 30  
\$ 60.00 30  
\$ 800.00 600  
\$ 800.00 600  
\$ 4,150.99

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:



WAS Anthony  
H/S Repur  
A/P...  
LKK Auto  
4wldays  
7/12/2017

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AXA Insurance Pte Ltd  
8 Shenton Way #24-01  
AXA Tower  
Singapore 068811

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Tan Kwee May

Date: 08 Dec 2017

**Preliminary Advice**

Insured Vehicle No	: SHC5843R	Accident Date	: 30/11/2017
TP Vehicle No	: SJE8915M	Assignment Date	: 05/12/2017
Make	: HONDA STREAM	Est. Duration of Repair	: 4/Days
Date of Inspection	: 07/12/2017		
Inspection At	: HUI YANG MOTOR SERVICE		

**Point of Impact / General Description of Damages**

The vehicle sustained impact / damages ...Rear.... portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	4,150.99
Revised Amount	:S\$	3,150.83
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,150.83

Lump Sum Repair :S\$

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( x ) Other comments :We have not authorized repairs.

# 輝陽汽車有限公司

## HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

Date: 01/01/2018

AXA Insurance Singapore Pte Ltd  
Motor Claims Department  
8 Shenton Way  
#27-01 AXA Tower  
Singapore 068811

**RE: ACCIDENT INVOLVING SJE8915M & SHC5843R ON 30-11-2017  
ALONG 165 TANJONG PAGAR ROAD**

**SETTLEMENT OF OUR CLAIM FOR SJE8915M**

Lump sum repair cost as recommended by surveyor ( TP0251 )	\$ 2,675.00
05 days Loss of Rental @ \$128.40 per day ( 4 repair days + 1 Sunday )	\$ 642.00
Total	<u>\$ 3,317.00</u>

*\*The above claim applies only to vehicle damage and expressly exclude all personal injuries and other consequential loss.*

*Please let us have your reply soonest possible, thank you.*

Best Regards,  
Marco Neo  
HUI YANG MOTOR PTE LTD  
DID: 64515752  
Fax: 64514658  
email: hui\_yang\_motor@hotmail.com

## Thin Thin (LKKAUTO)

---

**From:** Thin Thin (LKKAUTO)  
**Sent:** Tuesday, 12 December 2017 2:24 PM  
**To:** claims@transcab.com.sg  
**Cc:** CS A Team; carrisalee@ava-ins.com; icewong@ava-ins.com; ireneng@ava-ins.com; foonghon@ava-ins.com  
**Subject:** ACCIDENT INVOLVING SHC 5843R AND SJE 8915M ALONG TANJONG PAGAR ROAD ON 30/11/2017

12 DECEMBER 2017

Transcab Taxi  
Singapore

Dear Sir/Mdm,

OUR REF : CC4/AXA17023157/M1ua3  
YOUR REF : SHC 5843R

### ACCIDENT INVOLVING SHC 5843R AND SJE 8915M ALONG TANJONG PAGAR ROAD ON 30/11/2017

We refer to the above subject matter. We write to inform you that we are the loss adjuster appointed by your motor insurer, AXA Insurance Pte Ltd to deal with the third party claim against your policy.

We have received a claim from **Hui Yang Motor Pte Ltd** acting on behalf of the owner of SJE 8915M against your motor insurance policy.

Basing on the circumstances of the accident reported by both parties, we are of the opinion that we cannot be absolved from liability.

We also wish to advise that there is an excess of S\$5,000.00 attached with Third Party Claims. Please be informed that you shall be liable for the excess following any settlement of the third party claim. The applicability of the excess is as follows:

- (1) Any settlement equal to or above the excess, you shall be liable to make the payment of S\$5,000.00; or
- (2) Any settlement below the excess, you shall be liable for the amount settled.

AXA shall keep you informed of the third party claim settlement and thereafter kindly let AXA have the excess payment in your cheque payable to "AXA Insurance Pte Ltd". Please indicate your vehicle registration number and the date of accident on the back of the cheque.

Notwithstanding the excess being applied and/or received by AXA for the above subject matter, AXA expressly reserves all their rights under the policy to refund the excess payment in the event that there arises any known policy breach and or exclusion material to coverage.

We shall proceed to deal with the claim(s) subject to the merits of the case and according to the rights afforded under the policy. Should you not be seeking the protection of your policy and seek to take conduct of third party claim(s) arising from this incident, at your own cost and defence, please reply to us within 7 days from the date of this letter. Your intent must be formally expressed to us and acknowledged by us.

Your full co-operation in the handling of the claim is required and kindly submit the following to [thinthin@lkkauto.com](mailto:thinthin@lkkauto.com) within 7 days from the date of this letter if not provided at our reporting centre. The list below is not all inclusive and further document may be required:

- Police report, Police Investigation result, appeal against the Traffic Police offence and status (if any)
- Driver's driving license or foreign driving license (if any)
- Coloured photographs of accident scene (if any)
- Coloured photographs of damage to all vehicles involved (If any)
- Video footage of accident (if any)
- Statement and/or police report from independent witness(es) (if any)

If you or your passenger(s) are filing a claim against any of the involved Third Party(s), you are to keep us informed of your legal representative(s) and the status of the claim.

To protect your interest(s) in the handling of this claim, please do not discuss liability with any of the Third Party(s) and/or their legal representatives, or make any compromise or settlement without AXA's prior knowledge and consent. If you receive any correspondence or legal document such as a Writ of Summons in connection with this accident, please forward it to AXA immediately. You may email it to [cst@axa.com.sg](mailto:cst@axa.com.sg) or deliver it by hand to AXA's Customer Care Centre.

This letter should not be regarded as a waiver by AXA of their rights to repudiate any claim because of any breach of policy terms and conditions you and/or your authorised driver may have committed.

In the event of receiving and handling of any third party injury claim(s), AXA shall keep you informed of the final indemnity upon conclusion of the matter(s).

If you need any clarification, please do not hesitate to contact us at 6841 2360 or email us at [thinthin@lkkauto.com](mailto:thinthin@lkkauto.com). Please quote our claim reference when you contact us that we can assist you more effectively.

Yours sincerely,

THIN THIN HLAING  
LKK Auto Consultants Pte Ltd  
DID: 6841 2360  
FAX: 6741 4108  
Email: [thinthin@lkkauto.com](mailto:thinthin@lkkauto.com)

This is a computer generated letter and no signature is required.

Cc Motor Claims Department  
AXA Insurance Pte Ltd




## AUTHORIZATION LETTER

TO WHOM IT MAY CONCERN

I/We, Hymc car Leasing pte Ltd hereby declare and agree to use the address of **Hui Yang Motor Pte Ltd**, that is at Blk 176 Sin Ming Drive, #04-02 Sin Ming Autocare Singapore 575721 in all my/our correspondences with any party in connection with my/our claim arising from an accident involving my/our motor vehicle registration number SJE8A15M and other vehicles registration number SHL5843R along 165 Tanjong Pagar Road on 20/11/2017

I/We, further grant authority to Messrs **Hui Yang Motor Pte Ltd** or any of their representatives to open all my/our letters and to negotiate my/our claim on my/our behalf.

I/We wish to inform you that you could issue the cheque payment in favour of my/our repairer Messrs **Hui Yang Motor Pte Ltd**.

  
.....  
Signature of registered owner



redefining / insurance

CLAIM REF :  
INSURED : TRANS-CAB SERVICES PTE LTD

**DISCHARGE VOUCHER**

We/I [HYMS CAR LEASING PTE LTD, 201320561K] hereby agree to accept the sum of dollars Three Thousand Three Hundred and Seventeen Only (\$3,317.00) paid to us/me by AXA INSURANCE PTE LTD as full and final settlement of all claims of whatever kind including damages for personal injuries and damages to property that we/I may have against the said AXA INSURANCE PTE LTD or their Insured or the driver of motor vehicle no. SHC 5843R as a result of an accident along TANJONG PAGAR ROAD on 30/11/2017 of which we/I were/was the driver/ owner/ hirer/ passenger/rider/pillion/ insurer of motor vehicle no. SJE 8915M.

We/I hereby declare that the said insurer or owner and/or driver of insured vehicle shall not be liable for any further claim(s) whatsoever and whosoever present or future that we/I may have against the said Insurer, owner and/or driver of vehicle no. SHC 5843R in connection directly or indirectly with the said accident and give our/my full and final discharge.

We/I hereby declare that we/I are/am the person(s) entitled to receive the above settlement and hereby undertake to indemnify AXA INSURANCE PTE LTD against any claim made or to be made in respect of this settlement.

It is understood and agreed that payment herein is made without admission of liability whatsoever on the part of the said insurer, owner and/or driver of vehicle no. SHC 5843R.

Dated this 08 day of January, 2018

Claimant's Signature : 

NRIC no./ Company Stamp : 201320561K

Occupation/ Business : Car Rental Company

Address : 176 Sin Ming Drive, #04-02, S(575721)

Telephone No. : 6451 5752

Witness's Name : Boi

Witness's Signature : 

Witness's NRIC No. : S8206720E

# HUI YANG MOTOR PTE LTD

**Bill To:**

AXA Insurance Singapore Pte Ltd  
Motor Claims Department  
8 Shenton Way  
#27-01 AXA Tower  
Singapore 068811

**TAX INVOICE**

TP Claim Invoice No: **TP0251**  
Bill Date: **01/01/2018**

	Description	Amount
	Date of Accident : 30/11/2017 Owner : HYMS CAR LEASING PTE LTD Vehicle No : <u>SJE8915M</u> Make & Model : <u>HONDA STREAM 1.8X A</u>	
	<u>Lump Sum repair cost as recommended by surveyor</u>	\$ 2,500.00
	Sub-Total :	\$ 2,500.00
	Add 7% GST :	\$ 175.00
	Total Amount SGD :	<b>\$ 2,675.00</b>

Reg No.:201629438M

GST No:201629438M

**HUI YANG MOTOR PTE LTD**

\_\_\_\_\_  
Authorised Signature

**Hui Yang Motor Pte Ltd**

Sin Ming Autocare Blk 176 Sin Ming Drive

#04-02 Singapore 575721

Email: hui\_yang\_motor@hotmail.com

H/P: 98625891 Office: 64515752 Fax : 64514658

# RENT RECEIPT

No.: 2617-34

Date: 18/12/17

Received from 益收到  
Hanyang motor Pte Ltd

the sum of Dollars 支付大銀  
\$4,200.00 (Four thousand and two hundred only)

being the rent of 为租金  
\$11117 (1110 x 5 days) + 7% GST 11/6/17 to 25

due for the period from 日期从  
06/12/17 to 11/12/17

\$ 642.00

Cash / Cheque No.:

Important: No subletting of the above premise or any part thereof, or assigning the tenancy of the premise is allowed without the written consent of the landlord.



Signature of Landlord





# HYMS CAR LEASING PTE LTD

Blk 176 Sin Ming Drive #04-02 Sin Ming AutoCare Singapore 575721

Hp: 8333 6725 Fax 6451 4658

## RENTAL TERMS AND CONDITIONS

No.: 13475

NAME HUI YANER MOTOR PTE LTD			REG. NO. SLR 2115T	CAR MAKE TOYOTA CAMRY		
ADDRESS BLK 176 SIN MING DRIVE #04-02			KM OUT	DATE & TIME OUT 6/12/19 2.30PM		
SIN MING AUTOCARE 575721			KM IN	DATE & TIME IN 11/12/19 4.00PM		
TEL HP 93654094			KM DRIVEN	TIME USED		
NAMED DRIVER MUHAMMAD HAMAFI BIN ABUL RAZAK						
DRIVING LICENCE NO. 58141399C	DATE OF EXPIRY	PLACE OF ISSUE	HOURS	@\$		
PASSPORT NO.	DATE OF ISSUE	PLACE OF ISSUE	5 DAYS	@\$ 120	\$ 600	
ADD NAMED DRIVER			WEEKS	@\$		
DRIVING LICENCE NO.	DATE OF EXPIRY	PLACE OF ISSUE	MONTHS	@\$		
PASSPORT NO.	DATE OF ISSUE	PLACE OF ISSUE	BY INITIALING, RENTER AGREES TO PAY ADD FEE FOR COLLISION DAMAGES WAIVER (C.D.W.)			
REMARKS  			SUB-TOTAL			
			TOTAL RENTAL		\$ 600.00	
			DELIVERY FEE			
			COLLECTION FEE			
THIS VEHICLE IS USE WITHIN SINGAPORE ONLY OUR INSURANCE DOES NOT COVER IN MALAYSIA			X PER DAY \$ PER WEEK \$ PER MONTH \$ BY INITIALING, RENTER AGREES TO PAY ADD FEE FOR PERSONAL ACCIDENT INSURANCE (P.A.I.)			
Vehicle Number	Date From	Date To	Remarks	X PER DAY \$ PER WEEK \$ PER MONTH \$		
			Replacement			
			Replacement			
1st Party Excess \$2500/-				PREPAYMENT TOTAL CHARGE \$ 600.00		
3rd Party Excess \$2500/-				CHECK DEPOSIT		
				CASH		
				RECEIPT NO. NETT CHARGE		
FORM OF PAYMENT IN ADVANCE CASH BILL CHARGE CLUB CHEQUE NO.			AMOUNT DUE/ REFUND			
I HAVE READ THE TERMS AND CONDITIONS ON BOTH SIDES OF THIS RENTAL AGREEMENT AND AGREE THEREOF. I UNDERTAKE NOT TO USE OR LET OTHERS USE THE VEHICLE TO CARRYOUT ANY ILLEGAL OR CRIMINAL ACTS INCLUDING CARRYING OF DUTY UNPAID GOODS ESPECIALLY CIGARETTES.						
SIGNED BY THE PARTIES HERETO ON THE			DAY OF			
						
X			X			
OWNER			RENTER'S/DRIVER'S SIGNATURE			

# HYMS CAR LEASING PTE LTD

BLK 176 SIN MING DRIVE  
#04-02 AUTOCARE  
SINGAPORE 575721  
HP : 8333 6725 FAX : 6451 4658  
REG NO : 201320561K  
GST REGISTER NO: 201320561K

## TAX INVOICE

**BILL TO:** HUIYANG MOTOR PTE LTD  
BLK 176 SIN MING DRIVE  
#04-02 SIN MING AUTOCARE  
SINGAPORE 525721

**TAX INVOICE NO :** LT122017-021  
**DATE :** 18/12/2017  
**REFERENCE NO :** SJE8915M

NO.	DESCRIPTION	AMOUNT
	AGREEMENT NO : 13475 HIRER'S NAME : MUHAMMAD HAMAFFI BIN ABDUL RAZAK REGISTRATION NO : SLP2113T MAKE : TOYOTA CAMRY DURATION : 06/12/17 - 11/12/17 PER DAY \$120X5DAYS	\$600.00
	SUB TOTAL	\$600.00
	7% GST	\$42.00
	TOTAL AMOUNT	\$642.00

### Payment:

- A. For Cheque Payment, Please Crossed And Issue to "HYMS CAR LEASING PTE LTD".  
Please Indicate Vehicle Number On The Back Of The Cheque And Mail The Cheque To:  
**HYMS CAR LEASING PTE LTD**  
Blk 176 Sin Ming Drive  
#04-02 Sin Ming AutoCare  
Singapore 575721
- B. For Internet Banking Transfer, Please Indicate Vehicle Number And Transfer To:  
**Bank OCBC Current Account 531-756864-001**



## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Dec 2017		05 Dec 2017 16:02 <a href="#">Edit Adj Rpt</a>	<b>S\$2,500.00</b> <a href="#">Edit Estimates</a>	<b>S\$2,500.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

<b>Main</b>	<b>Reference</b>	<b>Claim Details</b>	<b>Documents</b>	<a href="#">Show All</a>
-------------	------------------	----------------------	------------------	--------------------------

#### CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K		
Main Claimant:	HYMS CAR LEASING PTE LTD, Co. Reg. No.: 201320561K		
Vehicle Reg. No.:	SJE8915M	Date of Loss:	30/11/2017 00:00 - :59
Claim Type:	TP	Policy/Cover Note No.:	P1680520 (Third Party Only)
Vehicle Reg. No. (Insured):	SHC5843R	Policy No. (Claimant):	5082577969-01
		Excess:	S\$5,000.00
Repairer:	Hui Yang Motor Pte Ltd (HQ) 176 Sin Ming Drive #04-02, Sin Ming AutoCare, 575721 Sin Ming - Tel: 64515752		
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Tan Kwee May]		
Claimant's Insurer:	NTUC Income Insurance Co-operative Ltd (HQ) - Tel:		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MA CHIN FOOK] ... [Final Rpt due 14/12/2017]		
Adj Asg. Remarks:	ARC - YES		

#### ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

- AXA\_SG (05/12/2017): New TP Assignment - /P1680520

#### ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Claim Documents

\*SJE8915M  
[SHC5843R]  
TP  
HYMS CAR LEASING PTE LTD  
Nov 30 2017 12:00AM  
[TRANS-CAB SERVICES PTE LTD]  
Hui Yang Motor Pte Ltd

Upload Documents

Upload Photos






Compose New Letter

View

View in Browser

Letters/Correspondences			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown		Edit
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/12/17 11:19	Adjuster Immediate Advice		Load HTM
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/12/17 14:05	General View		Load JPG
2	12/12/17 14:05	General View		Load JPG
3	12/12/17 14:05	General View		Load JPG
4	12/12/17 14:05	General View		Load JPG
5	12/12/17 14:05	General View		Load JPG
6	12/12/17 14:05	General View		Load JPG
7	12/12/17 14:05	General View		Load JPG
8	12/12/17 14:05	General View		Load JPG
9	12/12/17 14:05	General View		Load JPG
10	12/12/17 14:05	General View		Load JPG
11	12/12/17 14:05	General View		Load JPG
12	12/12/17 14:05	General View		Load JPG
13	12/12/17 14:05	General View		Load JPG
14	12/12/17 14:05	General View		Load JPG
15	12/12/17 14:05	Odometer Reading		Load JPG
16	12/12/17 14:05	General View		Load JPG
17	12/12/17 14:05	Chassis Number		Load JPG
18	08/01/18 13:40	Reinspection Photo		Load JPG
19	08/01/18 13:40	Reinspection Photo		Load JPG
20	08/01/18 13:40	Reinspection Photo		Load JPG
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	AXA Insurance Pte Ltd (HQ)	Thumbnail	Print
1	05/12/17 10:50	GIA SHC5843R INSD		Load PDF
2	05/12/17 10:50	ESTIMATE & GIA SJE8915M TP		Load PDF
3	05/12/17 10:50	EMAIL		Load PDF
4	05/12/17 15:59	PH GIA		Load PDF
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	08/12/17 12:14	TP ESTIMATE- MARKED		Load PDF
2	16/01/18 17:26	WORKSHOP INVOICE		Load PDF



3	16/01/18 17:26	<b>AUTHORISATION TO ACT FORM</b>		Load PDF	
4	16/01/18 17:26	<b>DISCHARGE VOUCHER</b>		Load PDF	
5	16/01/18 17:26	<b>RENTAL RECEIPT</b>		Load PDF	
6	16/01/18 17:26	<b>LOD</b>		Load PDF	
7	16/01/18 17:26	<b>LETTER TO OI</b>		Load PDF	

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	<a href="#">Reset</a>	<a href="#">Save</a>	<a href="#">Print</a>
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SHC5843R (Insd veh)	Model:	HONDA STREAM 1.8 X (A)
	SJE8915M (TP veh)		
Date of Accident:	30/11/2017		

Global Sum Settlement	:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No
Repair Estimate	:	\$	4,441.56
Final Repair Cost	:	\$	2,675.00
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	642.00 5 days
LTA / GIA Search Fee	:	\$	0.00
Others:	:	\$	0.00
	:	\$	
Final Settlement Sum	:	\$	3,317.00

Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)

A) For Non GIA Registered Workshop: Agreed Liability \_\_\_\_ 100 \_\_\_\_ (%)

B) For GIA Registered Workshop: BOLA Applicable: Yes/ No BOLA Scenario No: \_\_\_\_

BOLA Liability: \_\_\_\_ (%) Assessed Liability (\*): \_\_\_\_ (%)

\* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.

Remarks \_\_\_\_\_

Payment Instruction: Payee's Breakdown			
1)	Hui Yang Motor Pte Ltd	:	\$ 3,317.00
2)		:	\$

JOANNE LEE KHANG MIN

16 Jan  
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

# LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AXA17023157/M1UA3Q2

Date: 16/01/2018

### REFERENCE

Handling Insurer: AXA Insurance Pte Ltd

Policy No:

P1680520

Claimant Vehicle No: SJE8915M

Insured Vehicle No:

SHC5843R

Date of Loss: 30/11/2017

Nature of Claim:

TP

Claim No:

N/A

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SJE8915M

Make &amp; Model: HONDA STREAM, 1.8 X (A)

Engine No: R18A1762463

Reg. Date: 12/05/2008 (Man. Year: 2008)

Chassis No: RN61055815

Colour: Brown

Odometer: 152689 km

Engine Capacity: 1799 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 205/55 R16 Rear Tyre Size: 205/55 R16

Front Left Side: Toyo 7 mm Rear Left Side: Toyo 7 mm

Front Right Side: Toyo 7 mm Rear Right Side: Toyo 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,310.99	1,790.83	520.16	22.51
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,840.00	1,360.00	480.00	26.09
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>4,150.99</b>	<b>3,150.83</b>	<b>1,000.16</b>	<b>24.09</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>2,500.00</b>		
<b>(S\$)</b>	<b>4,150.99</b>	<b>2,500.00</b>	<b>1,650.99</b>	<b>39.77</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>290.57</b>	<b>175.00</b>	<b>115.57</b>	<b>39.77</b>
<b>Nett Amount (S\$)</b>	<b>4,441.56</b>	<b>2,675.00</b>	<b>1,766.56</b>	<b>39.77</b>
<b>+ Car Rental (5.0 x S\$120.00/day + 7.00% GST) (S\$)</b>		<b>642.00</b>		
<b>Nett Liability (S\$)</b>		<b>3,317.00</b>		

### INSPECTION

Date of Assignment: 05/12/2017

Date Inspected: 07/12/2017 Inspected At:

Hui Yang Motor Pte Ltd (HQ)  
176 Sin Ming Drive #04-02, Sin Ming  
AutoCare  
Singapore 575721

Estimated Period of Repair: 4.0 days

---

**Adjuster:** MA CHIN FOOK

**Manager:** THIN THIN HLAING

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 16 Jan 2018)	
<b>Parts:</b> M1-MPV	HONDA STREAM 1.8 X (A) (Catalogue:Merimen Singapore 1.0)	
<b>Labour:</b> Repairer's	(Price-denominated Standard List)	
<b>Print Code:</b>	(Unsubmitted, no print-code for SJE8915M)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR TAILGATE (CONSISTENT)	Bent	903.20 FL	*903.20 FL
2	1		*REAR TAILGATE STREAM EMBLE (CONSISTENT)	Necessary	31.60 FL	*31.60 FL
3	1		*REAR TAILGATE GLASS MOULDING (CONSISTENT)	Necessary	75.20 FL	*75.20 FL
4	1		*REAR TAILGATE INNER LOCK (CONSISTENT)	Bent	109.20 FL	*109.20 FL
5	1		*REAR TAILGATE INNE RUBBER (CONSISTENT)	Necessary	121.64 FL	*121.64 FL
6	1		*REAR END PANEL (CONSISTENT)	Repair	458.50 FL	*- FL
7	1		*REAR END PANEL INNER GARNISH (CONSISTENT)	Serviceable	116.70 FL	*- FL
8	1		*REAR BUMPER (CONSISTENT)	Deformed	588.90 FL	*588.90 FL
9	2		*REAR BUMPER SIDE RETAINER (CONSISTENT)	Distorted	58.80 FL	*58.80 FL
10	1		*SET REVERSE SENSOR (CONSISTENT)	Shorted	280.00 FS	*220.00 FS
11	1		*SEALANT (CONSISTENT)	Necessary	60.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (S\$)</b>	<b>2,803.74</b>	<b>2,168.54</b>
<b>- List Item Discount on L Items 20.00/20.00% (S\$)</b>	<b>492.75</b>	<b>377.71</b>
<b>Total Parts (S\$)</b>	<b>2,310.99</b>	<b>1,790.83</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	REMOVE & REFIX REAR WINDSCREEN	New	120.00	100.00
2	TUFFKOTE	New	60.00	30.00
3	WIRING	New	60.00	30.00
4	SPRAY PAINTING	New	800.00	600.00
5	LABOUR CHARGES	New	800.00	600.00
Gross Labour Cost (S\$)			<b>1,840.00</b>	<b>1,360.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >