

AXA
06/12 Wed
after Nam.

輝陽汽車有限公司 HUI YANG MOTOR PTE. LTD.

Contact Add : SIN MING AUTOCARE Blk 176 Sin Ming Drive #04-02 Singapore 575721

Tel: 64515752 (2 Lines) . Fax: 64514658

Reg No. 201629438M

30/11/2017

Owner: HYMS CAR LEASING PTE LTD

ESTIMATE TO REPAIR HONDA STREAM 1.8L - SJE8915M

1pc rear tailgate
1pc rear tailgate stream emble
1pc rear tailgate glass moulding
1pc rear tailgate inner lock
1pc rear tailgate inner rubber
1pc rear end panel
1pc rear end panel inner garnish
1pc rear bumper
2ps rear bumper side retainer @ \$29.40

\$ 903.20
\$ 31.60
\$ 75.20
\$ 109.20
\$ 121.64
x\$ 458.50
x\$ 116.70
\$ 588.90
\$ 58.80

\$ 2,463.74

less 20%

\$ 492.75

\$ 1,970.99

1set reverse sensor
sealant

s.nett \$ 280.00
s.nett \$ 60.00

remove & refix rear windscreen
tuffkote
wiring
spray painting
labour charges
Total

\$ 120.00
\$ 60.00
\$ 60.00
\$ 800.00
\$ 800.00
\$ 4,150.99

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Handwritten notes and signatures:
1510
1640
3150
20%
2500
Signature: [Signature]
H/S Repm
Aftersales Dept
LKK Auto
4w/day
7/12/2017