

CITY CAB PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 978D

DATE 4/12/2017 16:15

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper ✓			\$ 603.60	
	Rear Bumper Reinforcement ?			\$ 504.35	
	Rear Bumper Reinforcement Bracket (LH/RH)?		\$ 180.00	\$ 360.00	
	Rear Bumper Side Bracket ?			\$ 49.00	
	Rear Bumper Clips ✓			\$ 22.00	
	Rear Bumper Sponge ?			\$ 143.40	
	Rear Bumper Under Cover ✓			\$ 225.00	
	Rear Bumper Reflector Lamp (RH) XAC			\$ 32.00	
	SUB TOTAL			\$ 1,939.35	
	LESS 20%			\$ 387.87	
	DISCOUNTED TOTAL			\$ 1,551.48	
	Rear Bumper Reverse Sensor ✓			\$ 135.70	Nett
	Rear Bumper i40 Plate ✓			\$ 50.00	Nett
				\$ 185.70	
	Labour Charge			200	
	Panel Beating			\$ 380.00	
	Spray Painting Charge			\$ 200.00	186
	Wiring Charge			\$ 50.00	X
	R/Refix Reverse Sensor			\$ 120.00	20
	TOTAL LABOUR			\$ 750.00	
	ESTIMATE TOTAL			\$ 2,487.18	
<p>Kaluaricki</p> <p>6/12/17 1425hrs.</p> <p>2 days.</p> <p>PIP</p> <p>Before Part photo</p>					
<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer</p> <p>Signature:</p> <p>Date:</p>					
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					