

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHC 2289K

DATE 4/12/2017 16:19

MAKE :

MODEL : HYUNDAI SONATA

DOA: 01.12.17

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Boot Lid ✕			\$ 1,349.50	
	Boot Lid Rubber ✕			\$ 110.90	
	Boot Lid Lock Upper ✕			\$ 132.10	
	Boot Lid Lock Lower ✕			\$ 30.30	
	Boot Lid Sonata Plate ✕			\$ 43.60	
	Boot Lid Hyundai Plate ✕			\$ 24.20	
	Boot Lid 'H' Emblem ✕			\$ 26.10	
	Boot Lid CRDI Plate ✓			\$ 22.70	
	Rear Bumper ✓			\$ 578.40	
	Rear Bumper Reinforcement ?			\$ 483.30	
	Rear Bumper Clip ✓			\$ 22.00	
	Rear Bumper Sponge ?			\$ 137.40	
	Rear Bumper Under Cover ?			\$ 185.80	
	Rear Bumper Protector (LH/RH) ✕ repair		\$ 38.00	\$ 76.00	
	Rear Panel ✕ repair			\$ 391.80	
	Rear Panel Garnish ?			\$ 95.80	
	SUB TOTAL			\$ 3,709.90	
	LESS 20%			\$ 741.98	
	DISCOUNTED TOTAL			\$ 2,967.92	
	Boot Lid Comfort Logo & Tel No. Sticker ✕			\$ 30.00	Nett
	Rear Bumper Reverse Sensor ✓			\$ 135.70	Nett
	Rear Bumper Rubber Mat ✓			\$ 50.00	Nett
				\$ 215.70	
	Labour Charge				
	Panel Beating			\$ 850.00	600
	Spray Painting Charge			\$ 600.00	360
	Wiring Charge			\$ 50.00	✕
	Tuff Kote			\$ 50.00	✕
	Remove/Refix Reverse Sensor			\$ 120.00	20
	TOTAL LABOUR			\$ 1,670.00	
	ESTIMATE TOTAL			\$ 4,853.62	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.					

LKK Auto Consultants hence notify the Reparer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Reparer

Signature:

Date:

Kahar 16/12/17

5/12/17 1630hrs.

3 Days

4/5

After Repair photo

Larry Ng