

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 6 #01-01 Auto Bay @ Kaki Bukit Singapore 417883

ROB No: 532917933 Tel: 6741-1730 / 731 Fax: 6744-5746 Email: liusbros@gmail.com

Invoice/Ref No: GBC1468M171118

**Estimate****Customer**

Name: EQ Insurance Company Limited

Address: Motor Claims Department

5 Maxwell Road #17-00

Tower Block MND Complex Singapore 069110

Date: 05-12-17

Vehicle No: GBC1468M

Model/Make: Nissan Urvan 3.0

5MT ABS AB 5DR LWB Panel

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	<b>Rear Fender</b> 30% Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc To putty & spray painting & including touch up paint on accident affected areas	\$ 2,110.80 \$ 800.00 \$ 600.00	600 400

Total Parts &amp; Labour of estimate for damaged vehicle

\$ 3,510.80

Total amount in Part By Part / Lump Sum Basis for repaired vehicle

\$ -

SDLS:



M/s Liu's Brother Auto Engrg Ws

not Authorized  
H/L

p/p \$ 1000

3 dy.

who pre. After repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: