

ASS. REC. BY:

REF: CS/FCU7023168/Adp012 Special Instruction:

Surveyor:

Adrian.

ASSIGNMENT (Office)

WS

From (Person):

Lurene Jaw

of

FCI

Date/Time: 6.08pm @ 5/12/17

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SLA 7803G

Insured:

SHB 2699R

at Workshop m/s

Kah Motor

Tel:

68465671

of

15 Ubi Road 4

Policy No:

D1507270MFSH

Claim No:

D17011204MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 2/12/17

4pm owner waiting

CA / REV / REP. / REV 24 HRS

'Ds'

H.O.D. Endorsement:

Date/Time:

9.45am @ 6/12/17

Person Contacted:

Steven

Vehicle IN OUT

Date/Time

Action/Instruction (✓) Estimate

SLA 7803G - X

SHB 2699R - X

07/12/17 @ 4.31pm revised to Lurene Jaw by email.

26/11/18 @ 5.40pm confirmed with Steven final trig @ \$275.82, 5 days.

Cred @ 2344.42, 31%

REF: FCL

ASSIGNMENT

From: Date: 06122017

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLA 7803G

at Workshop/mis: Kah motor

of: 15 Ubi Rd 4

Insured:

Policy No:

Claims No:

Sum Insured: Excess:

(Client's Record)

Make of Veh: Steven

(Policy Condition)

4pm

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR. Seen: Consistent? : Yes or No

Est. Repairs: 05 hrs days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS 05'

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SLA 7803G Yr Regn: 2016 March

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Honda Mobilio. o/c 1497

Colour: Grey. A/C Insured / Std / NI / NA

Sp. Reading: 23995. T/Radio: Insured / Std / NI / NA

Eng/No:

O/No: MRHDD48706 P000037.

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orMod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 185/65R15

R: 185/65R15.

BS / CUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 06 mm

R/Bal. 06 mm

L/Bal. 06 mm

L/Bal. 06 mm

D.O.A.

D.O.I. 06/12/17.

Survey held at: Kah Motor.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

77 / 1st Cap.

RECEIVED 29 JAN 2018

Date/Time: File Pass to?

☐

: Prel. Report

29/1/17

☐

: Final Report

Date/Time: File Return to?

2)

Days Of Repair: 5

Resurvey No. of Trip: 1

Survey Fee

Transportation

S - RS S

Photo

Other

TOTAL

Add Fee:

☐

Site Insp. S

☐

Interview S

☐

Tech Invs S

☐

Weekend S

Report Format:

Lump Sum / I.B.I. S

7P

5775.82

150

50

50

33

283



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI17023168/Aqb	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 06-12-2017	
		Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHB 2699R	Veh. Inspected	SLA 7803G
Policy No.		Coverage (\$)	0.00
Claim No.	D17011204MFSH	Excess (\$)	0.00
Assign From	CWS (LURENE JAW)	Assign Date	05/12/2017
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	02/12/2017	Inspection Date	06/12/2017
Survey held at	KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D17011204MFSH

Date: 07 December 2017

Our Ref: CS/FCI17023168/Aqb

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SLA 7803G

Please be informed that we had conducted the inspection of the abovementioned vehicle on 06/12/2017 at the premises of M/s KAH MOTOR, and have the following to report:-

Workshop Estimate Amount	: S\$ 7,609.22 .
Revised Estimate Amount	: S\$ 5,286.17 .
"Check" Items Amount	: S\$ - .
Market Value	: S\$ - .
LTA Reimbursement Value	: S\$ - .
Nett Value	: S\$ - .

Description of Damage:

The vehicle sustained damages
at the rear portion.



Yours faithfully

ADRIAN LING WAI PING
B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI
Licensed Appraiser

Survey Department Check List (Case Handler)

Reference No.: Cy/FCI/7023168/Ag/b
 Policy Type: OD / (TP) TP RES / TL / EVA

SLA 7803G

Case Handler

Typist

Admin (Cath): Case handler to make sure all information created by the assignment team are **ACCURATE**.

(1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

Surveyor (Adrian): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

✓		
---	--	--

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

✓		
✓		
✓		

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

✓		
---	--	--

Check By:

Adrian 26/1/18

Case Handler

Date

First Capital Insurance Limited

A FAIRFAX Company

Company Reg. No. 195000106C
GST Reg. No. M2-0001676-9

MOTOR SURVEY ASSIGNMENT

Date	05-12-2017	Our Ref No. D17011204MFSH
Accident Date	02-12-2017	Claim Type. Third Party
Insured Vehicle	SHB2699R	Third Party Vehicle. SLA7803G
Survey Location	15 UBI ROAD 4	
Contact Person.	STEVEN CHUI	
Contact No.	68465671/ 81006303	Fax No. 0
Survey Type	DIRECT SETTLEMENT:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	KAH MOTOR CO SDN BHD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	LURENE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/231448)



PRI Documents



Close



PRI Header Details

Claim No	D17011204MFSH	Policy No	D-15072702MFSH	Claimant S.No & Name	1 & KAH MOTC
Workshop Name	KAH MOTOR CO SDN BHD (Contact Person : STEVEN CHUI)	Survey Location & Contact Details	15 UBI ROAD 4 Mobile: 81006303 , Phone: 68465671 , Fax: 0 EmailId: STEVENCHUI@HONDA.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	DIRECT SETTLEMENT:		
Insured Name	CITYCAB PTE LTD	Insured Vehicle No	SHB2699R	TP Vehicle No	SLA7803G
PRI Recieved Date	05-12-2017 03:08:48 PM	Surveyor Appointed Date	05-12-2017 06:07:29 PM	Surveyor Accept Date	06-12-2017 1

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	06-12-2017	Upload Survey Report *:	Choose File
-----------------------------	--	----------------------	------------	-------------------------	--

Vehicle Particulars

Make	Please Select Make ▼	Model	Please Select Model ▼	Year	Select Year ▼
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

Upload Multiple Documents	
File Name	Action

Surveyor Job Remarks

Remarks		Save
---------	----------------------	-------------------------------------

Shiau Chan (LKKAuto)

From: Shiau Chan (LKKAuto)
Sent: Friday, 26 January 2018 5:40 PM
To: 'Steven Chui'; SUR
Subject: RE: SLA7803G final bills

Dear Steven,

Confirm final fig \$5,275.82 before GST and 5 repair days.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: sjewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Steven Chui [mailto:stevenchui@honda.com.sg]
Sent: Thursday, 28 December 2017 8:52 AM
To: SUR <sur@lkkauto.com>
Subject: SLA7803G final bills

Dear Sir/Mdm,

Attached final bills for SLA7803G, kindly close it as soon as possible.

Total repair bill \$5,645.13

LOU 5 days

Kindly email me if the case is close.

Steven Chui
Kah Motor Sdn Bhd
Service Advisor



Confidential Note: The information contained in this email is intended only for the use of the individual or entity named above and may contain information that is privileged, confidential and exempt from disclosure under applicable law. If the reader of this message is not the intended recipient, you are hereby notified that any dissemination, distribution or copying of this communication is strictly prohibited. If you have received this message in error, please immediately notify the sender and delete the mail. Thank you.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Thursday, 7 December, 2017 4:31 PM
To: 'Claim Workflow System'; assignments
Cc: LURENEJAW@FIRST-INSURANCE.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D17011204MFSH/1
Attachments: CSFCI17023168Aqb.pdf

Dear Lurene,

Enclosed herewith preliminary advice of SLA 7803G.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Wednesday, 6 December, 2017 9:47 AM
To: 'Claim Workflow System' <cwsmotorclaims@first-insurance.com.sg>; assignments <assignments@lkkauto.com>
Cc: LURENEJAW@FIRST-INSURANCE.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D17011204MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@first-insurance.com.sg>]
Sent: Tuesday, 5 December, 2017 6:07 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@FIRST-INSURANCE.COM.SG; LURENEJAW@FIRST-INSURANCE.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D17011204MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S8441198A



Name

TEO EU LIANG NICHOLAS
(ZHAO YOU LIANG NICHOLAS)

趙宥量

Race

CHINESE

Date of birth

20-12-1984

Sex

M

S8441198A

Country/Place of birth

SINGAPORE

REPUBLIC OF SINGAPORE DRIVING LICENCE




Licence Number S8441198A

TEO EU LIANG NICHOLAS
(ZHAO YOU LIANG NICHOLAS)

Birth Date: 20 Dec 1984

Issue Date: 30 Nov 2009




001808317H

5286192



NRIC No. S8441198A



Date of issue
27-03-2014


Address

APT BLK 313A SUMANG LINK
#14-109
SINGAPORE 821313

YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

PASS DATE

Class 2B	Motorcycles <= 200 cc	10 Nov 2005
Class 2A	Motorcycles between 201 cc and 400 cc	27 Feb 2007
Class 2	Motorcycles > 400 cc	11 Nov 2008
Class 3	Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver; and other motor vehicles <= 2500kg	30 Nov 2009



Licence No: S8441198A

NP 428A



KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : FIRST CAPITAL INSURANCE LTD
 36 ROBINSON ROAD
 #16-01 CITY HOUSE
 SINGAPORE 068877

Registration No : SLA7803G

Chassis No : MRHDD4870GP000037

Model : MOBILIO YM 2016

Owner's Name : TEO EU LIANG NICHOLAS

Ins Policy No. :

Date of Accident : 3/12/2017

Document No. : SQT17004928

Date : 4. Dec 2017

Customer No. : WZF002

Svc Advisor :

Engine No : L15Z12870743

Date | Time : 4. Dec 2017 1:53:18 PM

Surveyor Name :

Survey Date :

Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: TEO EU LIANG NICHOLAS OWNER INSURER: LIBERTY INS- ACC DATE: 03/12/2017 SURVEYED BY: DATE: REF NO: TP INSURER: FIRST CAP TP VEH: SHB2699R						
68100-TRD-K10ZZ	TAILGATE COMP <i>Distorted</i>	1	1056.00	25	792.00	55.44	847.44
73225-TE7-K00	RUBBER A/WINDSHIELD DAMPER <i>nee</i>	1	17.70	25	13.27	0.93	14.20
73525-SYY-000	RUBBERRR QTR W/SHIELD <i>not Nee</i>	3	9.50	25	21.37	1.50	22.87
91501-S70-003	FASTENER BW/SHIELD <i>nee</i>	4	3.20	25	9.60	0.67	10.27
91502-S70-003	FASTENER B <i>nee</i>	2	4.90	25	7.35	0.51	7.86
91536-SS0-J01	FASTENER AW/SHIELD <i>nee</i>	4	3.50	25	10.50	0.74	11.24
75722-TE8-K00	EMBLEM SETRR.MOBILIO <i>nee</i>	1	17.90	25	13.42	0.94	14.36
75725-TRD-T00	EMBLEMRR.I VTEC <i>nee</i>	1	11.60	25	8.70	0.61	9.31
75723-TE7-K90	EMBLEMRR.RS <i>nee</i>	1	16.90	25	12.67	0.89	13.56
75701-TE7-K00	EMBLEM H <i>not Nee</i>	1	17.40	25	13.05	0.91	13.96
71501-TE7-K90ZZ	FACERR.BUMPER <i>del</i>	1	463.70	25	347.77	24.34	372.11
71502-TE7-K90	MOLDINGRR.BUMPER <i>not</i>	1	106.70	25	80.02	5.60	85.62
71593-TE7-K01	SPACERR.RR.BUMPER SIDE <i>nee</i>	1	27.00	25	20.25	1.42	21.67
71598-TE7-K01	SPACERL.RR.BUMPER SIDE	1	27.00	25	20.25	1.42	21.67
91505-TG1-T01	CLIP ABUMPER <i>nee</i>	2	6.00	25	9.00	0.63	9.63
BO-WS-SEALANT	WINDSCREEN SEALANT (N) <i>nee</i>	1	60.00		60.00	4.20	64.20
Sum Item					1439.22	100.75	1,539.97
BOSUN	SUNDRIES <i>nee</i>		100.00				
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00		250.00	17.50	267.50
BG02D	REMOVE & INSTALL RR. WINDSCREEN.(N)	1	280.00		280.00	19.60	299.60

**KAH MOTOR CO. SDN. BHD.**

(A Member of the Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg No.: M200050223

Company Ref. No.: S60FC1380G

Customer : FIRST CAPITAL INSURANCE LTD
36 ROBINSON ROAD
#16-01 CITY HOUSE
SINGAPORE 068877
Registration No : SLA7803G
Chassis No : MRHDD4870GP000037
Model : MOBILIO YM 2016
Owner's Name : TEO EU LIANG NICHOLAS
Ins Policy No. :
Date of Accident : 3/12/2017

Document No. : SQT17004928
Date : 4. Dec 2017
Customer No. : WZF002
Svc Advisor :
Engine No : L15Z12870743
Date | Time : 4. Dec 2017 1:53:18 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	GST Amt	Amount incld GST
BKTG02R	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST &	3	100.00		✓ 300.00	21.00	321.00
BA01R	REMOVE & RENEW REVERSE SENSORS-2 PCS (N)	1	180.00		✓ 180.00	12.60	192.60
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	60.00		✓ 60.00	4.20	64.20
BKRP02S	STRAIGHTEN ALIGN RR PANEL & RENEW DAMAGE PARTS.	1	2400.00	1680	2400.00	168.00	2568.00
BP05R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (5P)--	1	2700.00	1350	2700.00	189.00	2889.00
Sum Labor					6170.00	431.90	6.601.90

Survey By

Date & Time

Excess

Status

Signature

Total Amount 7,609.22 532.65 8,141.87

Total (Inclusive of GST) 7,609.22 8,141.87

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Printed on 5/12/2017 10:24:29 AM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s)



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WZF002 / FIRST CAPITAL
Chassis No: MRHDD4870GP000037
License No: SLA7803G
Mileage: 22794
Engine No: L15Z12870743

Document No: SVO17078750
Printed By: FSCHUI
Order Date: 18. December 2017
Order Time: 10:14:43 AM
Service Advisor: STEVEN CHUI FOOK SENG

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	GST Amt	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:69616 OWNER:TEO EU LIANG NICHOLAS OWNER INSURER:LIBERTY INS- ACC DATE:03/12/2017 SURVEYED BY:06/12/2017 DATE: REF NO: TP INSURER:FIRST CAP TP VEH:SHB2699R						
68100-TRD-K10ZZ	TAILGATE COMP	1	1,056.00	25	792.00	55.44	847.44
73225-TE7-K00	RUBBER A WINDSHIELD DAMPER	1	17.70	25	13.27	0.93	14.20
91501-S70-003	FASTENER BW/SHIELD	4	3.20	25	9.60	0.67	10.27
91502-S70-003	FASTENER B	2	4.90	25	7.35	0.51	7.86
91536-SS0-J01	FASTENER AW/SHIELD	4	3.50	25	10.50	0.74	11.24
75722-TE8-K00	EMBLEM SETRR.MOBILIO	1	17.90	25	13.42	0.94	14.36
75725-TRD-T00	EMBLEMRR.I VTEC	1	11.60	25	8.70	0.61	9.31
75723-TE7-K90	EMBLEMRR.RS	1	16.90	25	12.67	0.89	13.56
71501-TE7-K90ZZ	FACERR.BUMPER	1	463.70	25	347.77	24.34	372.11
71502-TE7-K90	MOLDINGRR.BUMPER	1	106.70	25	80.02	5.60	85.62
71593-TE7-K01	SPACERR.RR.BUMPER SIDE	1	27.00	25	20.25	1.42	21.67
71598-TE7-K01	SPACERL.RR.BUMPER SIDE	1	27.00	25	20.25	1.42	21.67
91505-TG1-T01	CLIP ABUMPER	2	6.00	25	9.00	0.63	9.63
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
33505-TE7-T11	REFLECTOR ASSY (LEFT REAR) <i>cancelled</i>	1	14.70	25	11.02	0.77	11.79 <i>ing</i>
	SUM PARTS:				1,415.82	99.11	1,514.93
BOSUN	0626	1	10.00		10.00	0.70	10.70
BG02D	SUNDRIES	1	280.00		280.00	19.60	299.60
BKTG02R	EXT-YJ REMOVE & INSTALL RR. WINDSCREEN. (N)	1	300.00		300.00	21.00	321.00
BA01R	EXT-YJ REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)	1	180.00		180.00	12.60	192.60
BML02I	EXT-YJ REMOVE & RENEW REVERSE SENSORS-2 PCS (N)	1	60.00		60.00	4.20	64.20
BKRP02S	EXT-YJ INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)	1	1,680.00		1,680.00	117.60	1,797.60
BP05R	EXT-YBH STRAIGHTEN ALIGN RR PANEL & RENEW DAMAGE PARTS.	1	1,350.00		1,350.00	94.50	1,444.50
	EXT-YBH SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(5P)						
	SUM LABOUR:				3,860.00	270.20	4,130.20
	TOTAL SGD				5,275.82	369.31	5,645.13

Total Payable (SGD)

5,645.13



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI17023168/Aqbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 31-01-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 2699R	Veh. Inspected	SLA 7803G	
Policy No.	D-15072702MFSH	Coverage (\$)	0.00	
Claim No.	D17011204MFSH	Excess (\$)	0.00	
Assign From	LURENE	Assign Date	05/12/2017	
2. Vehicle Particulars & Condition				
Make & Model	HONDA MOBILIO	c.c	1497	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	MRHDD4870GP000037	Colour	GREY	
Odometer	23995	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/65 R15	DUNLOP	6 mm	
L/H Front Tyre	185/65 R15	DUNLOP	6 mm	
R/H Rear Tyre	185/65 R15	DUNLOP	6 mm	
L/H Rear Tyre	185/65 R15	DUNLOP	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	02/12/2017	Inspection Date	06/12/2017	
Survey held at	KAH MOTOR CO SDN BERHAD 15 UBI ROAD 4 SINGAPORE 408610			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLA 7803G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	TAILGATE COMP (SN)	DISTORTED	792.00	792.00
1	RUBBER A/WINDSHIELD DAMPER (SN)	NECESSARY	13.27	13.27
3	RUBBERRR QTR W/SHIELD (SN)	NOT NECESSARY	21.37	-
4	FASTENER BW/SHIELD (SN)	NECESSARY	9.60	9.60
2	FASTENER B (SN)	NECESSARY	7.35	7.35
4	FASTENER AW/SHIELD (SN)	NECESSARY	10.50	10.50
1	EMBLEM SETRR MOBILIO (SN)	NECESSARY	13.42	13.42
1	EMBLEMRR I-VTEC (SN)	NECESSARY	8.70	8.70
1	EMBLEMRR RS (SN)	NECESSARY	12.67	12.67
1	EMBLEM H (SN)	NOT NECESSARY	13.05	-
1	FACERR BUMPER (SN)	DEFORMED	347.77	347.77
1	MOLDINGRR BUMPER (SN)	CUT	80.02	80.02
1	SPACERR RR BUMPER SIDE (SN)	NECESSARY	20.25	20.25
1	SPACERL RR BUMPER SIDE (SN)	NECESSARY	20.25	20.25
2	CLIP ABUMPER (SN)	NECESSARY	9.00	9.00
1	WINDSCREEN SEALANT (SN)	NECESSARY	60.00	60.00
1	SUNDRIES (SN)	NECESSARY	100.00	10.00
1	REFLECTOR ASSY (LEFT REAR)(ADDITIONAL)(SN)	CRACKED	11.02	11.02
			1,550.24	1,425.82
LABOUR				
	APPLY BODY UNDERSIDE COATING.	NOT NECESSARY	250.00	-
	REMOVE & INSTALL RR WINDSCREEN.		280.00	280.00
	REMOVE & TRANSFER ITEMS TO NEW TAILGATE ADJUST.		300.00	300.00
	REMOVE & RENEW REVERSE SENSOR-2PCS.		180.00	180.00
	INSPECT RR LIGHTING MECHANISMS.PERFORM WATER.		60.00	60.00
	STRAIGHTEN ALIGN RR PANEL & RENEW DAMAGE PARTS.		2,400.00	1,680.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.		2,700.00	1,350.00
			6,170.00	3,850.00

Report Ref No. CS/FC117023168/Aqbn2



GRAND TOTAL		7,720.24	5,275.82
RECOMMENDED COST OF REPAIRS			5,275.82

Report Ref No. CS/FCI17023168/Aqbn2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.