



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer: WZF002 / FIRST CAPITAL
Chassis No: MRHDD4870GP000037
License No: SLA7803G
Mileage: 22794
Engine No: L15Z12870743

Document No: SVO17078750
Printed By: FSCHUI
Order Date: 18. December 2017
Order Time: 10:14:43 AM
Service Advisor: STEVEN CHUI FOOK SENG

ITEM	DESCRIPTION	QTY	UNIT	DISC %	AMOUNT	GST Amt	Amount incl GST
	TP DIRECT SETTLEMENT (J/NO:69616 OWNER:TEO EU LIANG NICHOLAS OWNER INSURER:LIBERTY INS- ACC DATE:03/12/2017 SURVEYED BY:06/12/2017 DATE: REF NO: TP INSURER:FIRST CAP TP VEH:SHB2699R						
68100-TRD-K10ZZ	TAILGATE COMP	1	1,056.00	25	792.00	55.44	847.44
73225-TE7-K00	RUBBER A WINDSHIELD DAMPER	1	17.70	25	13.27	0.93	14.20
91501-S70-003	FASTENER BW/SHIELD	4	3.20	25	9.60	0.67	10.27
91502-S70-003	FASTENER B	2	4.90	25	7.35	0.51	7.86
91536-SS0-J01	FASTENER AW/SHIELD	4	3.50	25	10.50	0.74	11.24
75722-TE8-K00	EMBLEM SETRR.MOBILIO	1	17.90	25	13.42	0.94	14.36
75725-TRD-T00	EMBLEMRR.I VTEC	1	11.60	25	8.70	0.61	9.31
75723-TE7-K90	EMBLEMRR.RS	1	16.90	25	12.67	0.89	13.56
71501-TE7-K90ZZ	FACERR.BUMPER	1	463.70	25	347.77	24.34	372.11
71502-TE7-K90	MOLDINGRR.BUMPER	1	106.70	25	80.02	5.60	85.62
71593-TE7-K01	SPACERR.RR.BUMPER SIDE	1	27.00	25	20.25	1.42	21.67
71598-TE7-K01	SPACERL.RR.BUMPER SIDE	1	27.00	25	20.25	1.42	21.67
91505-TG1-T01	CLIP ABUMPER	2	6.00	25	9.00	0.63	9.63
BO-WS-SEALANT	WINDSCREEN SEALANT (N)	1	60.00		60.00	4.20	64.20
33505-TE7-T11	REFLECTOR ASSY (LEFT REAR) <i>cracked.</i>	1	14.70	25	11.02	0.77	11.79 <i>LM</i>
	SUM PARTS:				1,415.82	99.11	1,514.93
BOSUN	0626	1	10.00		10.00	0.70	10.70
	SUNDRIES						
BG02D	EXT-YJ	1	280.00		280.00	19.60	299.60
	REMOVE & INSTALL RR. WINDSCREEN. (N)						
BKTG02R	EXT-YJ	1	300.00		300.00	21.00	321.00
	REMOVE & TRANSFER ITEMS TO NEW TAILGATE. ADJUST & ALIGN TAILGATE.(N)						
BA01R	EXT-YJ	1	180.00		180.00	12.60	192.60
	REMOVE & RENEW REVERSE SENSORS-2 PCS (N)						
BML02I	EXT-YJ	1	60.00		60.00	4.20	64.20
	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)						
BKRP02S	EXT-YJ	1	1,680.00		1,680.00	117.60	1,797.60
	STRAIGHTEN ALIGN RR PANEL & RENEW DAMAGE PARTS.						
BP05R	EXT-YBH	1	1,350.00		1,350.00	94.50	1,444.50
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(5P)						
	SUM LABOUR:				3,860.00	270.20	4,130.20
	TOTAL SGD				5,275.82	369.31	5,645.13

Total Payable (SGD)

5,645.13