

Veron Chen (LKKAUTO)


From: Perry HE (SPF) <Perry_HE@spf.gov.sg>
Sent: Thursday, 14 December, 2017 3:05 PM
To: Veron Chen (LKKAUTO)
Cc: Wei Yea LIM (SPF); Kwee Huat TAN (SPF); Kim Pang CHAY (SPF); Guo Qiang (LKKAUTO); SUR
Subject: RE: Appraisal Services for SPF vehicle at INDECO - HOMSPFETQ16000399 - QX329A

Hi Veron,

Sure, pls amend the report accordingly.



Perry He Junyun
Contract Management Engineer
Automotive Engineering & Management Division
Police Logistics Department
[Singapore Police Force](#)
DID: (65) 6478 4869 | HP: (65) 9191 5725



WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Veron Chen (LKKAUTO) [mailto:veronchen@lkkauto.com]
Sent: Thursday, 14 December, 2017 2:50 PM
To: Perry HE (SPF) <Perry_HE@spf.gov.sg>
Cc: Wei Yea LIM (SPF) <LIM_Wei_Yea@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>; Guo Qiang (LKKAUTO) <GuoQiang@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: Appraisal Services for SPF vehicle at INDECO - HOMSPFETQ16000399 - QX329A

Dear Perry,

According to surveyor, due to chassis member badly damaged. It's unsafe to repair the vehicle.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Wednesday, 13 December, 2017 3:12 PM
To: Perry HE (SPF) <Perry_HE@spf.gov.sg>
Cc: Wei Yea LIM (SPF) <LIM_Wei_Yea@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>; Guo Qiang (LKKAUTO) <GuoQiang@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: Appraisal Services for SPF vehicle at INDECO - HOMSPFETQ16000399 - QX329A

Dear Perry,

Will check and revert.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Perry HE (SPF) [mailto:Perry_HE@spf.gov.sg]
Sent: Wednesday, 13 December, 2017 3:08 PM
To: Veron Chen (LKKAUTO) <veronchen@lkkauto.com>
Cc: Wei Yea LIM (SPF) <LIM_Wei_Yea@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>
Subject: RE: Appraisal Services for SPF vehicle at INDECO - HOMSPFETQ16000399 - QX329A

Hi Veron,

Pls provide assessment on the following parts as this concerns whether should we proceed on with the repair.

1.122	CHASSIS INNER SIDE MEMBER RH 57411A
1.123	CHASSIS INNER SIDE MEMBER LH 57412A
1.124	CHASSIS INNER SUB MEMBER RH 57601
1.125	CHASSIS INNER SUB MEMBER LH 57602
1.126	CHASSIS OUTER SUB MEMBER RH 57615A
1.127	CHASSIS OUTER SUB MEMBER LH 57616A

Thank you.



Perry He Junyun
Contract Management Engineer
Automotive Engineering & Management Division
Police Logistics Department
[Singapore Police Force](#)
DID: (65) 6478 4869 | HP: (65) 9191 5725



TOGETHER WE KEEP OUR HOME SAFE AND SECURE

WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."

From: Veron Chen (LKKAUTO) [<mailto:veronchen@lkkauto.com>]

Sent: Monday, 11 December, 2017 3:26 PM

To: Perry HE (SPF) <Perry_HE@spf.gov.sg>

Cc: Wei Yea LIM (SPF) <LIM_Wei_Yea@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>

Subject: RE: Appraisal Services for SPF vehicle at INDECO - HOMSPFETQ16000399 - QX329A

Dear Perry,

Kindly refer attached.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Perry HE (SPF) [mailto:Perry_HE@spf.gov.sg]

Sent: Tuesday, 5 December, 2017 4:56 PM

To: assignments <assignments@lkkauto.com>

Cc: Wei Yea LIM (SPF) <LIM_Wei_Yea@spf.gov.sg>; Kwee Huat TAN (SPF) <TAN_Kwee_Huat@spf.gov.sg>; Kim Pang CHAY (SPF) <CHAY_Kim_Pang@spf.gov.sg>; Ai Phing (LKKAUTO) <aiphing@lkkauto.com>; Shiau Chan (LKKAUTO) <siewsc@lkkauto.com>

Subject: Appraisal Services for SPF vehicle at INDECO - HOMSPFETQ16000399 - QX329A

Hi Catherine and Ashley,

Please provide Appraisal Service for the following SPF vehicle at INDECO Engineers.

1) QX329A

Parts:

BONNET
BONNET HINGE RH
BONNET HINGE LH
BONNET LOCK
HEADLAMP RH
HEADLAMP LH
FRT BUMPER
FRT BUMPER RETAINER RH
FRT BUMPER RETAINER LH
FRT BUMPER REINFORCEMENT
FRT BUMPER CLIPS
FRT BUMPER LOWER GRILLE
FRT NUMBER PLATE
FRT BUMPER TOP RUBBER STRIP
FOGLAMP COVER LH
TOYOTA LOGO
FRT SUPPORT PANEL ASSY
CONDENSER
RADIATOR
RADIATOR FAN BLADE
RADIATOR FAN MOTOR
RADIATOR FAN COWLING
ENGINE UNDER COVER RH
ENGINE UNDER COVER LH
ENGINE MOUNTING FRT
ENGINE MOUNTING LH
FRT WINDSCREEN
FRT WINDSCREEN MOULDING
SEALANT
INNER SEAL TAPE
IU STICKER
DASHBOARD

DASHBOARD AIRBAG
STEERING AIRBAG
AIRBAG ECU
SEATBELT RH
SEATBELT LH
LHF DOOR
LHF DOOR HINGE TOP
LHF DOOR HINGE BOTTOM
LHF DOOR BLACK STICKER
LHR DOOR
LHR DOOR HINGE TOP
LHR DOOR HINGE BOTTOM
LHR DOOR BLACK STICKER
LH ROCKER PANEL GARNISH
LHR FENDER
LHR FENDER INNER SHIELD
LHR WHEEL HOUSE
LHR WHEEL HOUSE AIR DUCT
LHR FENDER INNER TRIM
PETROL TANK COVER
PETROL TANK COVER LOCK
PETROL TANK
REAR WINDSCREEN MOULDING
SEALANT
INNER SEAL TAPE
SPEAKER BOARD
SPEAKER BOARD PANEL
PETROL TANK COVER LOCK CABLE
RHF DOOR
RHF DOOR HINGE TOP
RHF DOOR HINGE BOTTOM
RHF DOOR BLACK STICKER
RHR DOOR

RHR DOOR HINGE TOP
RHR DOOR HINGE BOTTOM
RHR DOOR BLACK STICKER
RH ROCKER PANEL GARNISH
RHR FENDER
RHR FENDER INNER SHIELD
RHR WHEEL HOUSE
RHR WHEEL HOUSE AIR DUCT
RHR FENDER INNER TRIM
RHF DOOR PROTECTOR W CHROME
RHR DOOR PROTECTOR W CHROME
RHR DOOR LOCK
RHR DOOR LOCK CATCH
BOOT LID
BOOT HINGE RH
BOOT HINGE LH
LOGO ALTIS
LOGO 1.6
LOGO COROLLA
EMBLEM TOYOTA
BOOT CHROME MOULDING
BOOT REFLECTOR RH
BOOT REFLECTOR LH
BOOT REFLECTOR BACK COVER RH
BOOT REFLECTOR BACK COVER LH
BOOT LOCK
BOOT LOCK CATCH
TAILLAMP RH
TAILLAMP LH
TAILLAMP PANEL RH
TAILLAMP PANEL LH
TAILLAMP LOWER BEAM RH
TAILLAMP LOWER BEAM LH

REAR NUMBER PLATE
REAR NUMBER PLATE LAMP
BOOT OUTER LOCK
BOOT INSULATOR
REAR BUMPER
REAR BUMPER REFLECTOR RH
REAR BUMPER REFLECTOR LH
REAR BUMPER CLIP
REVERSE SENSOR
REAR BUMPER CLIP
REAR BUMPER RETAINER RH (LONG)
REAR BUMPER RETAINER LH (LONG)
REAR BUMPER RETAINER RH (SHORT)
REAR BUMPER RETAINER LH (SHORT)
REAR BUMPER REINFORCEMENT
REAR BUMPER REINFORCEMENT BRACKET RH
REAR BUMPER REINFORCEMENT BRACKET LH
REAR BUMPER SPONGE
REAR END PANEL
REAR END PANEL GARNISH
BOOT WEATHER STRIP
EXHAUST MUFFLER
EXHAUST MUFFLER MOUNTING
CHASSIS INNER SIDE MEMBER RH 57411A
CHASSIS INNER SIDE MEMBER LH 57412A
CHASSIS INNER SUB MEMBER RH 57601
CHASSIS INNER SUB MEMBER LH 57602
CHASSIS OUTER SUB MEMBER RH 57615A
CHASSIS OUTER SUB MEMBER LH 57616A
TRANSPORT HOOK RH 51967E
TRANSPORT HOOK LH 51963D
SUB MEMBER 57605B
SUB MEMBER 57606C

REAR SEAT FRAME LH 71015
REAR SEAT PAD LH 71652S
REAR SEAT SIDE PAD LH 71550A
REAR AXLE ASSY
RHR WHEEL BEARING
LHR WHEEL BEARING
RHR S.ABSORBER
LHR S.SBSORBER
RHR TYRE 195/65/15
LHR TYRE 195/65/15
WHEEL ALIGNMENT

Labour:


TO ALIGN,REPLACE AND RESPRAY BONNET,HINGES
TO REPLACE AND REPSRAY FRT BUMPER
TO REPAIR AND RESPRAY RHF FENDER
TO REPAIR AND RESPRAY LHF FENDER
TO REPLACE AND RESPRAY SUPPORT PANEL
TO REPLACE,CONDENSER,RADIATOR AND TOP UP AC GAS
TO REPLACE AND RESPRAY REINFORCEMENT
TO REPLACE AND RESPRAY LHF DOOR
TO REPLACE AND RESPRAY LHR DOOR
TO REPLACE AND RESPRAY LH ROCKER PANEL GARNISH
TO ALIGN,REPAIR AND RESPRAY LH DOORS FRAME
TO REPLACE AND RESPRAY LHR FENDER
TO REPLACE AND RESPRAY LHF WHEEL HOUSE
TO REPLACE AND RESPRAY BOOT LID
TO REPLACE AND RESPRAY REAR BUMPER
TO REPLACE AND RESPRAY REAR END PANEL
TO ALIGN, REPLACE AND RESPRAY REAR CHASSIS,SUB MEMBERS
TO REPLACE AND RESPRAY RHR WHEEL HOUSE
TO REPLACE AND RESPRAY RHR FENDER
TO REPLACE AND RESPRAY RHR DOOR

TO REPLACE AND RESPRAY RH F DOOR
TO REPLACE AND RESPRAY RH ROCKER PANEL GARNISH
TO REPAIR AND RESPRAY RH DOORS FRAME
TO REMOVE AND REFIX FRT WINDSCREEN
TO REMOVE AND REFIX REAR WINDSCREEN
TO REPLACE REAR AXLE AND UNDERCARRIAGE
TO REMOVE AND REPLACE REAR SEAT FRAME,PAD,COVER
TO REMOVE AND REPLACE PETROL TANK
TO REMOVE AND REFIX ROOF LINING TO ASSIST WORK
TO REMOVE AND REFIX UPHOISTERY TO ASSIST WORK
TO REMOVE AND REFIX ENGINE PARTS IN COMPARTMENT TO ASSIST WORK
TO PERFORM 4 WHEEL ALIGNMENT

Thank you.



Perry He Junyun
Contract Management Engineer
Automotive Engineering & Management Division
Police Logistics Department
[Singapore Police Force](#)
DID: (65) 6478 4869 | HP: (65) 9191 5725



WARNING: "Privileged/Confidential information may be contained in this message. If you are not the intended addressee, you must not copy, distribute or take any action in reliance thereon. Communication of any information in this email to any unauthorized person is an offence under the Official Secrets Act (Cap 213). Please notify the sender immediately if you receive this in error."