

22/03/2002

ASS. REC. BY:

REF: CS3/SM017023176 / W bet

range & days.

Special Instruction:

Surveyor: WilsonASSIGNMENT (Office)

From (Person):

Sheng Wong

of

SMO

Date/Time:

3:15pm @ 6/12/17

Estimated Cost:

Bill to:

OD TP WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

PC 4232 R

Insured:

FBF 6977D

at Workshop m/s

Sheng Li Lai

Tel:

911 19222

of

No. 2 Kaki Bukit Ave 2 #01-36 417921 Autohub

Policy No:

Claim No:

CMTD1704281 / NSW

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

6/12/17

CA / REV / REP. / REV 24 HRS

(wp)15.12.2017 @ morning

H.O.D. Endorsement:

Date/Time:

3:48pm @ 6/12/17

Person Contacted:

Mr. LawVehicle IN / OUT

Date/Time

Action/Instruction

(X)

Estimate

PC4232R-XFBF6977D-XDismantle Part: 15.12.201720.01.18 12:29pm Email to Sheng Wong

PPS
Wilson REF. 3M0

ASSIGNMENT

From: Date 15/12/17

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect vehicle No: PC 4232 R /

at Workshop no: Sheng Li Tei

of No: 2 kaki bukit ave 2 #01-36 autohub

Insured

Policy No

Claims No.

Sum Insured

Excess

(Client's Record)

Make of Veh:

Morning

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Ball or Market Value

IDAC Accident Report Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res: Yes or No

Lump Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS 'cap'

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: PC 4232 R

Type: M.Cat / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover

Truck / Trailer or

Make: Toyota Hiace

Colour: Silver A/C Insured / Std / Nil / NA

Se Reading: 56473 T Radio: Insured / Std / Nil / NA

Eng No:

C No: JTF ST22PX 03022715

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size F: 195 R15 C
R: 195 R15 C

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or JK Tyre

Front

Rear

R.Bal: 3 mm R.Bal: 4 mm

L.Bal: 3 mm L.Bal: 4 mm

D.O.A: D.O.A: 15/12/2017

Survey held at: As Above @ 12pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Right Fnt

The U/C / Chassis frame / Body Structure affected due to collision

Date Time Action Instruction

No Accident Report Given.

Range \$4500 - \$5600

4 Days Repair. 15/12/17

RECEIVED

Date Time File Pass to

☐ : Preli. Report

Days Of Repair:

☐ : Final Report

Resurvey No. of Trip:

Survey Fee

Date Time File Return to

Transporter

Add Fee: ☐ Ste Insc S

☐ Interfer S

☐ Tech Insc S

☐ Clean end S

Report Format: PPS

Lump Sum / L.B. / S





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Fédération Internationale Des Experts En Automobile

SOMPO INSURANCE SINGAPORE PL

Ref : CS3/SMO17023176/Wb

50 RAFFLES PLACE

#05-01/06

SINGAPORE LAND TOWERS SINGAPORE 048623

Date : 06-12-2017



Code : SMO

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	FBF 6977D	Veh. Inspected	PC 4232R
Policy No.		Coverage (\$)	0.00
Claim No.	CMTD1704281/NSW	Excess (\$)	0.00
Assign From	SHERY WONG	Assign Date	06/12/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	06/12/2017	Inspection Date	15/12/2017
Survey held at	SHENG LI LAI 2 KAKI BUKIT AVE 2 #01-36 KAKI BUKIT AUTOHUB SINGAPORE 417921		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

Nivitha (LKK Auto)

From: Wong, Shi Yi Shery <Shery.Wong@sompo.com.sg>
Sent: Wednesday, 6 December, 2017 3:15 PM
To: 'Yvonne'; 'assignments'
Cc: Henry, Irene James; Ngo, Sau Wei Shawn; 'Nivitha (LKK Auto)'
Subject: RE: PRI : Sompo Insured FBF6977D [EAL.2017.5335.EA.MK.ya - PC4232R]

Our Reference: CMTD1704281/NSW

Your Reference: 2017.5335.EA.MK.ya – PC4232R

Date: 06TH December 2017

Without Prejudice

BY EMAIL ONLY

Attention:

M/S CATHERINE LIM LLC

Accident involving FBF6977D and PC4232R on 06/12/2017

Dear Sirs,

We refer to your email reply dated 06/12/2017.

We do not agree to your list of surveyors.

As such, we will be appointing our motor surveyor, **LKK AUTO** to conduct the pre-repair survey of your client's vehicle.

The pre-repair survey will include a survey of the vehicle when its damaged parts are being dismantled prior to the commencement of repairs.

We would like our motor surveyor to conduct a post repair inspection once your client's vehicle has been repaired.

The survey is conducted on a without Prejudice basis and without any admission of liability.

Aside to **LKK AUO**,

Kindly assign your motor surveyor to conduct motor survey of the mentioned (PC4232R).

Thank you.

Best Regards
Shery Wong
Claims Division
T: 6461 6555 | F: 6221 3147

2017/12/31
VNI
No need call

**Sompo Insurance Singapore Pte. Ltd.**

50 Raffles Place, #05-01/06 Singapore Land Tower, Singapore 048623

Website: www.sompo.com.sg | **Facebook:** www.facebook.com/SompoSG

Disclaimer: This e-mail, including attachments, is intended for the person(s) or company named and may contain confidential and/or legally privileged information. Unauthorised disclosure, copying or use of this information may be unlawful and is prohibited. If you are not the intended recipient, please delete this message.

Privacy Policy Notice: Sompo Insurance Singapore Pte. Ltd. may collect, use and disclose your personal data for the purposes stated in our Privacy Policy. This may include disclosure to holding and associated companies, credit bureau, parties to whom disclosure is permitted/required by laws, our third party service providers and agents (acting on our behalf). Please click [here](#) for our Privacy Policy.

From: Yvonne [mailto:yvonne@ealc.com.sg]**Sent:** Wednesday, December 06, 2017 11:33 AM**To:** Wong, Shi Yi Shery**Cc:** Henry, Irene James; Ngo, Sau Wei Shawn**Subject:** PRI : Sompo Insured FBF6977D [EAL.2017.5335.EA.MK.ya - PC4232R]

Our ref : 2017.5335.EA.MK.ya - PC4232R

Your ref : FBF6997D

PLEASE REPLY VIA EMAIL (yvonne@ealc.com.sg)

Sompo Insurance Pte. Ltd
No. 50 Raffles Place
#05-01/06 Singapore Land Tower
Singapore 048623
Attn: Motor Claims Department
2 DAYS' PRE-REPAIR NOTICE

Surveyor from M/s Sompo Insurance Pte. Ltd
Vehicle **PC4232R** inspected as follows by Name:

Before repair	Parts removed	After repair
_____ Signature Date/ Time:	_____ Signature Date/ Time:	_____ Signature Date/ Time:

Dear Sir/Madam,

NOTICE TO THIRD PARTY INSURERS FOR PRE-REPAIR NOTICE**CLAIMANT: SILVERAY PTE LTD****ACCIDENT INVOLVING PC4232R & FBF6997D ON 27 NOVEMBER 2017 ALONG TAMPINES AVENUE 9 TOWARDS TAMPINES AVE 12 AT ABOUT 0800 HOURS**

We refer to the above matter wherein we are instructed to act for **SILVERAY PTE LTD**, the owner of vehicle no. **PC4232R**.

There is no agreement to the surveyors proposed by parties.

Our client's vehicle **PC4232R** is available as follows, please call prior appointment for the pre-repair inspection:

M/s Sheng Li Lai
No. 2 Kaki Bukit Ave 2,
#01-36 Autohub Kaki Bukit,
Singapore 417921.
Tel: 91119222 (Mr Low)

Please arrange for the pre-repair inspection on the damaged vehicle within 2 working days from the time of notification, excluding Saturdays, Sundays and public holidays.

Regards,
Yvonne Ang

East Asia Law Corporation

No. 133 New Bridge Road, #10-02 Chinatown Point, Singapore 059413
Tel: 63232565 Fax: 63232373

Confidentiality Notice: This e-mail is confidential. It may also be legally privileged.

If you are not the addressee or to whom it is intended, you may not copy, forward, disclose or use any part of it.

If you have received this message in error, please delete the message and all copies from your system and notify the sender immediately by return e-mail.

Survey Department Check List (Case Handler)

Reference No. :

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin () : Case handler to make sure all information created by the assignment team are ACCURATE.

(1) Office Assignment Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

Surveyor () : Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

(2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

✓			
---	--	--	--

(3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

(4) System - (Views/Merimen)

- C Resurvey photo Uploaded

--	--	--	--

Check By:

--	--

Case Handler

Date

*C: Critical *N: Non-Critical

Catherine Chong (LKK Auto)

From: Catherine Chong (LKK Auto) <admin-d@lkkauto.com>
Sent: Saturday, 20 January, 2018 12:29 PM
To: 'Wong, Shi Yi Shery'; 'assignments'
Cc: 'Henry, Irene James'; 'Ngo, Sau Wei Shawn'
Subject: RE: PRI : Sompo Insured FBF6977D [EAL.2017.5335.EA.MK.ya - PC4232R]

Dear Shery,

Refer to your assignment on 06.12.2017 at 3.15PM.

Please be informed that we have inspected the vehicle PC 4232R on 15.12.2017 at 12PM.

At the time of inspection the repairer did not present their estimation to the damaged vehicle.

We will submit our report accordingly.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Nivitha (LKK Auto) [mailto:admin-d@lkkauto.com]
Sent: Wednesday, 6 December, 2017 3:51 PM
To: 'Wong, Shi Yi Shery' <Shery.Wong@sompo.com.sg>; 'assignments' <assignments@lkkauto.com>
Cc: 'Henry, Irene James' <irene.henry@sompo.com.sg>; 'Ngo, Sau Wei Shawn' <Shawn.Ngo@sompo.com.sg>;
sur@lkkauto.com
Subject: RE: PRI : Sompo Insured FBF6977D [EAL.2017.5335.EA.MK.ya - PC4232R]

Dear Sir/Mdm,

Thank you for the assignment.

Please be informed vehicle not in workshop, repairer will arrange.

Best Regards,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Wong, Shi Yi Shery [mailto:Shery.Wong@sompo.com.sg]
Sent: Wednesday, 6 December, 2017 3:15 PM
To: 'Yvonne'; 'assignments'
Cc: Henry, Irene James; Ngo, Sau Wei Shawn; 'Nivitha (LKK Auto)'
Subject: RE: PRI : Sompo Insured FBF6977D [EAL.2017.5335.EA.MK.ya - PC4232R]

Our Reference: CMTD1704281/NSW

Your Reference: 2017.5335.EA.MK.ya – PC4232R



**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
SOMPO INSURANCE SINGAPORE PL		Ref: CS3/SMO17023176/Wbe2		
50 RAFFLES PLACE #05-01/06 SINGAPORE LAND		Date: 05-04-2018		
TOWERSINGAPORE 048623		Code: SMO		
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	FBF 6977D	Veh. Inspected	PC 4232R	
Policy No.		Coverage (\$)	0.00	
Claim No.	CMTD1704281/NSW	Excess (\$)	0.00	
Assign From	SHERY WONG	Assign Date	06/12/2017	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA HIACE	c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.	JTFST22PX00022715	Colour	SILVER	
Odometer	56473 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195 R15C	JK TYRE	3 mm	
L/H Front Tyre	195 R15C	JK TYRE	3 mm	
R/H Rear Tyre	195 R15C	JK TYRE	4 mm	
L/H Rear Tyre	195 R15C	JK TYRE	4 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION.				
5. General Information				
Accident Date	06/12/2017	Inspect Date / Time	15/12/2017 (12:00 PM)	
Survey held at	SHENG LI LAI 2 KAKI BUKIT AVE 2 #01-36 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,600-\$5,600				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		

Report Ref No. CS3/SMO17023176/Wbe2

Inspected By



WILSON TEO CHENG MING

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE, MInstAEE, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.