

Surveyor *marcuf*

CS/TP 17023180/Uvbn2

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No: *SLM 6885M*

at Workshop m/s *3m/*

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: *4* days Res.: Yes or No

Lum Sum: *15* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: *SLM 6885M*

Yr Regn: *5.12*

Type: *M.Car* / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or *CA* /

Make: *Mer Benz* *E200* c.c. *1796*

Colour: *Black* A/C: Insured / Std / NI / NA

Sp. Reading: *132304* T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *WDD2120482A595794*

Gen. Cond: *Good* / Fair / Poor / Burnt

Steering: *Inorder* / Jammed / Leaked / Burnt or

Brake: *Inorder* / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: _____

R: *245/40R18*

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or *continental*

Front

Rear

R/Bal. *6* mm

R/Bal. *6* mm

L/Bal. *6* mm

L/Bal. *6* mm

D.O.A. *5/12/17*

D.O.I. *8/12/17*

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction *L7A 70428*

26/12/17 *Mc Apex* *45 4200* *(Red 2661.76, 38%)*

RECEIVED 20 DEC 2017

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) *26/12 typist*

Report Format: *TP*

Lump Sum / I.B.I: (\$) *4200h*

Days Of Repair: *4*

Resurvey No. of Trip: *1*

Add Fee:

☐

: Site Insp (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

Survey Fee:

Transportation:

\$ + RS \$

Photos:

Others:

TOTAL

145
50
50
68
80
393

Ref. No : <u>CS/TP17023180/UVB⁷²</u>	Res. Date: <u>6/12/17</u>	Date Received:
Veh. No : <u>SKM 6885M</u>	SP:	WKSP: <u>BW</u>
C/No :		
Action/Instruction:		
1. File	2. Submit Photo? YES / NO	
3. Indicate Res. Date On Photo Page?	YES / NO	Message:
If No, due to	a) No authorisation b) Days of repair	
others:		
Final Re-inspection or Progress Photos		Inspected By:

Survey Department Check List (Case Handler)

Reference No.: CS/TP17023180/UV6

Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are ACCURATE.

(1) Office Assign Form

		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)				
C	D.O.A	✓			
C	Policy No				
C	Claim No				
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form

C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount				
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON

Case Handler

23/12/17

Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
BLUWEL AUTOMOTIVE SERVICE PTE LTD			Ref : CS/TP17023180/Uvb	
BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE)SINGAPORE 417883			Date : 06-12-2017	
			Code : TP149	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	Veh. Inspected		SLM 6885M	
Policy No.	Coverage (\$)		0.00	
Claim No.	Excess (\$)		0.00	
Assign From	Assign Date		06/12/2017	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No. HIDDEN	Year of Reg.			
Chassis No.	Colour			
Odometer -	Steering			
Brakes	Modification			
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	05/12/2017	Inspection Date	06/12/2017	
Survey held at	BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE) SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars	
Owner ID Type	Singapore NRIC
Owner ID	4522Z
Vehicle Details	
Vehicle No.	SLM6885M
Vehicle to be Exported	No
Intended De-registration Date	06 Dec 2017
Vehicle Make	MERCEDES BENZ
Vehicle Model	E 200
Primary Colour	Black
Manufacturing Year	2012
Engine No.	27186030444917
Chassis No.	WDD2120482A595794
Maximum Power Output	135.0 kW (181 bhp)
Open Market Value	\$50,734.00
Original Registration Date	02 May 2012
First Registration Date	02 May 2012
Transfer Count	2
Actual ARF Paid	\$50,734.00
Intended PARF Rebate Details	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	01 May 2022
PARF Rebate Amount	\$35,513.00
Intended COE Rebate Details	
COE Expiry Date	01 May 2022
COE Category	B - Car (1601cc & above)
COE Period(Years)	10
QP Paid	\$79,304.00
COE Rebate Amount	\$34,915.00
Total Rebate Amount	\$70,428.00

The information contained herein is correct as at 06 Dec 2017

OK

MYT217160137 / Yew Tee Automobile Tech Pte Ltd - Kaki Bukit
ENTRY DATE & TIME: 05/12/2017 11:42

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and in copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report 05/12/2017 11:42
Date Of Accident 05/12/2017 08:45
Exact Location Of Accident JUNCTION OF HENDERSON ROAD AND REPOT ROAD
Country/State of Loss SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number SLM6885M
Insured/Policyholder
Name Of Registered Owner WONG YUN XUAN SHERLYN
NRIC No S8734522Z
Email Address NOEMAIL
Mobile Phone No (LOCAL) +65-81829540
Alternative Phone No OFFICE-81829540
Vehicle Particulars
Manufacturer MERCEDES-BENZ
Model E200-2.0 (A)
Exact Purpose for which vehicle was being used at time of accident
Are you claiming under your own insurance policy for repair to your vehicle? NO
If No, Please state action to be taken THIRD PARTY
Vehicle Category PRIVATE CAR
Insurance Company
Name of Insurance Company NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage COMPREHENSIVE
Fleet Policy NO
Policy Number 5093033576
Cover Note Number
Driver
Name of Driver WONG YUN XUAN SHERLYN
NRIC No S8734522Z
Date Of Birth 27/10/1987
Occupation INDOOR
Date Of Driving Pass 16/11/2007
Driving Experience 10 YEARS AND 0 MONTHS
Gender FEMALE
Mobile Number (LOCAL) +65-81829540
Fax Number
Contact Number OFFICE-81829540
Email Address NOEMAIL

Address

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle

Insurance Company of Driver's Own Vehicle

General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR

Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO

Was any body injured in the Accident? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 2

Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

Circumstances of Accident

REFER TO ATTACHMENT

Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number S8312CD

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver

NRIC/Passport Number

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)


Details of Witness

Name

Phone Number

Email Address

Sketch Plan #2



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 05/12/17 at about 8:55am, I was driving
 on Henderson Road on the left lane. My vehicle was stationary. ^{traffic light was red so}
 Suddenly vehicle B which was behind me started to
 move and hit the rear of my vehicle A.

DECLARATION

(We declare the foregoing particulars are true in every respect.)

Policyholder's Signature
 Date & Time:

Driver's Signature
 (If driver is not the policyholder)
 Date & Time: 5/12/17, 11:55am

Reporting Centre Personnel's Signature
 Name:
 NRBC/FIN No.:

GLADMAC Sketch Plan Form V3



BLUWEL AUTOMOTIVE SERVICE PTE LTD

Workshop: 1 Kaki Bukit Ave 6 (Unit B) #01-28
 (Unit C) #01-51/53/55 Singapore 417883
 Hp: 9755 2088 Tel: 6745 2088 Fax: 6841 2088
 Website: www.bluwel.com.sg Email: bluwel2088@yahoo.com.sg
 Co. Reg. No.: 200704951N
 GST Reg. No.: 200704951N

52m6885m

	Rear bumper	no/pc	1561.32	✓
	Rear bumper chrome moulding centre	pc	191.22	✓
2ps	Rear bumper chrome moulding sides @ 166.11	pc	332.22	✓
2ps	Rear bumper reverse sensors @ 215.00	shotels	430.00	✓
	Rear bumper reinforcement	buf	715.00	✓
	Rear bumper inner reinforcement plastic	twi	189.00	✓
2ps	Rear bumper brackets @ 60.00	twi	120.00	✓
	Rear end panel	pc	1018.00	X
	Tail lamp	10% cm	695.00	✓
			5251.76	4233.76

To check wiring	50.00	-	20
To dismantle & replacing reverse sensor	80.00	-	50
To dismantle & refix seat cushion upholstery	120.00	-	60
Labour for panel heating & replacing parts	680.00	-	480
To putty & spray painting	680.00	-	550
	TOTAL	\$	6861.76

4970.38

Lkh Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

BLUWEL AUTOMOTIVE SERVICE PTE LTD

Ref : CS/TP17023180/Uvbn2

BLK 1 KAKI BUKIT AVE 6
#01-28/51/53/55(MAIN OFFICE)SINGAPORE
417883

Date : 28-12-2017



ON BEHALF OF WONG YUN XUAN SHERLYN

Code : TP149

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	Veh. Inspected	SLM 6885M
Policy No.	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From	Assign Date	06/12/2017

2. Vehicle Particulars & Condition

Make & Model	MERCEDES BENZ E 200 (A)	c.c	1796
Engine No.	HIDDEN	Year of Reg.	2012
Chassis No.	WDD2120482A595794	Colour	BLACK
Odometer	132304	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	245/40 R18	CONTINENTAL	6 mm
L/H Front Tyre	245/40 R18	CONTINENTAL	6 mm
R/H Rear Tyre	245/40 R18	CONTINENTAL	6 mm
L/H Rear Tyre	245/40 R18	CONTINENTAL	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.
--

5. General Information

Accident Date	05/12/2017	Inspection Date	06/12/2017
Survey held at	BLUWEL AUTOMOTIVE SERVICE PTE LTD BLK 1 KAKI BUKIT AVE 6 #01-28/51/53/55(MAIN OFFICE) SINGAPORE 417883		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLM 6885M

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	REAR BUMPER	DENTED / DEFORMED	1,561.32	1,561.32
1	REAR BUMPER CHROME MOULDING CENTRE	NECESSARY	191.22	191.22
2	REAR BUMPER CHROME MOULDING SIDES @\$166.11	NECESSARY	332.22	332.22
2	REAR BUMPER REVERSE SENSORS @\$215.00	SHORTED	430.00	430.00
1	REAR BUMPER REINFORCEMENT	BENT	715.00	715.00
1	REAR BUMPER INNER REINFORCEMENT PLASTIC	TWISTED	189.00	189.00
2	REAR BUMPER BRACKETS @\$60.00	TWISTED	120.00	120.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	1,018.00	-
1	TAILLAMP	CRACKED	695.00	695.00
	LESS 10% DISCOUNT		-	-423.38
			5,251.76	3,810.38
<u>LABOUR</u>				
	TO CHECK WIRING.		50.00	20.00
	TO DISMANTLE & REPLACING REVERSE SENSOR.		80.00	50.00
	TO DISMANTLE & REFIX SEAT, CUSHION UPHOLSTERY.		120.00	60.00
	LABOUR FOR PANEL BEATING & REPLACING PARTS. INCLUSIVE OF THE REPAIR OF REAR END PANEL.		680.00	480.00
	TO PUTTY & SPRAY PAINTING.		680.00	550.00
			1,610.00	1,160.00
GRAND TOTAL			6,861.76	4,970.38
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				4,200.00

Report Ref No. CS/TP17023180/Uvbn2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.