

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5628X -**AAD1712-033***Not Authoised*
1/1 Sep 8

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHC5628X - JHOW

VF1ABL15AUC279627

RENAULT

LATITUDE

04.12.2017

III**PART****LIST**

1	1	BUMPER COVER FRT	\$	<i>Br</i> 1,259.42	—
2	1	BUMPER SPOILER FRT	\$	<i>SL</i> 181.75	X
3	1	BUMPER ABSORBER FRT	\$	<i>SL</i> 394.68	X
4	1	BUMPER RETAINER FRT LH	\$	<i>Dr</i> 151.41	—
5	1	BUMPER SUPPORT FRT	\$	<i>SL</i> 123.88	}
6	1	BUMPER RETAINER FRT RH	\$	<i>SL</i> 150.77	
7	1	BUMPER SUPPORT FRT	\$	<i>SL</i> 123.88	
8	1	BUMPER UNDERTRAY FRT	\$	<i>SL</i> 472.83	
9	1	BUMPER GRILLE LOWER FRT	\$	<i>SL</i> 266.80	
10	1	BUMPER FOG LAMP GRILLE LH	\$	<i>SL</i> 207.21	
11	1	BUMPER FOG LAMP GRILLE RH	\$	<i>SL</i> 207.21	
12	1	BUMPER BEAM FRT	\$	<i>R</i> 914.08	
13	1	TOW COVER FRT	\$	<i>SL</i> 28.61	
14	1	RADAIOR GRILLE	\$	<i>SL</i> 1,707.78	
15	1	RADIATOR GRILLE BADGE 'RENAULT'	\$	<i>SL</i> 225.36	}
16	1	RADAIOR GRILLE FRAME	\$	<i>SL</i> 1,353.75	
17	1	FRAME FULL SUPPORT PANEL	\$	<i>R</i> 615.90	
18	1	FRAME FULL SUPPORT BRACKET	\$	<i>R</i> 89.79	
19	1	FRONT BRACE PANEL	\$	<i>R</i> 177.22	
20	1	HORN	\$	<i>SL</i> 314.17	
21	1	HORN BRACKET	\$	<i>R</i> 40.45	
22	1	HEADLAMP LH	\$	<i>SL</i> 1,184.43	—
23	1	HEADLAMP RH	\$	<i>SL</i> 1,184.43	X
24	1	HEADLAMP PANEL FRT LH	\$	<i>R</i> 152.15	X
25	1	HEADLAMP PANEL FRT RH	\$	<i>R</i> 152.15	X
26	1	BONNET	\$	<i>R</i> 1,941.63	X
27	1	BONNET INSULATOR	\$	<i>SL</i> 405.73	X
28	1	BONNET STRUT LH	\$	<i>SL</i> 88.61	X
29	1	BONNET STRUT RH	\$	<i>SL</i> 88.61	X
30	1	BONNET HINGE LH	\$	<i>R</i> 348.31	X
31	1	BONNET HINGE RH	\$	<i>R</i> 348.31	X
32	1	BONNET LOCK	\$	<i>R</i> 305.48	X
33	1	BONNET CABLE	\$	<i>SL</i> 119.19	X
34	1	BONNET CABLE COVER	\$	<i>SL</i> 161.03	X

TRANS-CAB AUTO SERVICES PTE LTD

AAD1712-033

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5628X -

35	1	BONNET SEAL OUTER	\$	Su	92.36	
36	1	FENDER PANEL FRT LH	\$	R	783.83	
37	1	FENDER PANEL FRT RH	\$	R	783.83	
38	1	WHEELARCH FRT LH	\$	Su	278.84	
39	1	WHEELARCH FRT RH	\$	Su	278.84	
40	1	FENDER BRACKET LOWER LH	\$	Su	15.79	
41	1	FENDER BRACKET LOWER RH	\$	Su	15.79	
42	1	FENDER INSULATOR LH	\$	Su	130.84	
43	1	FENDER INSULATOR RH	\$	Su	130.84	
44	1	AIR CLEANER LOWER	\$	Su	271.26	
45	1	AIR CLEANER HOSE	\$	Su	76.14	
46	1	AUTO COMPUTER	\$	Su	5,032.17	
47	1	STEERING PUMP ELECTRIC	\$	Su	2,306.90	
48	1	A/C CONDENSER	\$	Su	2,020.37	
49	1	A/C CONDENSER GARNISH LH UPPER	\$	Su	39.67	
50	1	A/C CONDENSER GARNISH RH UPPER	\$	Su	39.67	
51	1	A/C CONDENSER GARNISH LH	\$	Su	58.81	
52	1	A/C CONDENSER GARNISH RH	\$	Su	59.60	
53	1	A/C PIPE CONDENSER TO COMPRESSOR	\$	Su	208.39	
54	1	A/C PIPE CONDENSER TO EXPENSION VALV	\$	Su	658.72	
55	1	A/C PIPE COMPRESSOR	\$	Su	334.29	
56	1	A/C PIPE	\$	Su	658.72	
57	1	A/C COMRPRESSOR	\$	Su	2,684.61	
58	1	AIR COOLER	\$	Su	792.60	
59	1	AIR INTERCOOLER HOSE (LONG)	\$	Su	1,014.13	
60	1	AIR INTERCOOLER HOSE (Short)	\$	Su	375.14	
61	1	TRANSMISSION COOLER	\$	Su	1,219.30	
62	1	TRANSMISSION COOLER PAD	\$	Su	17.96	
63	1	RADIATOR	\$	Su	1,202.20	
64	2	RADIATOR STUD UPPER	\$	Su	14.41	
65	2	RADIATOR BUSH UPPER	\$	Su	50.12	
66	2	RADIATOR MTG LOWER	\$	Su	55.85	
67	1	RADAITOR FAN COWLING	\$	Su	820.54	
68	1	RADIATOR FAN MOTOR LH	\$	Su	967.36	
69	1	RADIATOR FAN MOTOR RH	\$	Su	1,479.46	
70	1	RADIATOR TANK	\$	Su	324.62	
71	1	RADIATOR HOSE UPPER	\$	Su	240.56	
72	1	RADIATOR HOSE LOWER	\$	Su	491.18	
73	1	RADIATOR TANK HOSE	\$	Su	61.18	
74	1	BUMPER COVER REAR	\$	B	1,108.46	✓
75	1	BUMPER LOWER REAR	\$	B	768.84	✓
76	1	BUMPER BRACKET CTR REAR	\$	D	113.47	✓

TRANS-CAB AUTO SERVICES PTE LTD

AAD1712-033

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5628X -

77	1	BUMEPR BRACKET SIDE LH REAR	\$	D's	135.97	✓
78	1	BUMEPR BRACKET CTR LH REAR	\$	D's	44.99	✓
79	1	BUMEPR BRACKET SIDE RH REAR	\$	Sn	135.97	✓
80	1	BUMEPR BRACKET CTR RH REAR	\$	Sn	44.99	X
81	1	BUMPER BEAM REAR	\$	Ry	777.52	✓
82	1	BUMPER BEAM BRACKET LH REAR	\$	Ry	225.95	✓
83	1	BUMPER BEAM BRACKET RH REAR	\$	R	225.95	X
84	1	BUMPER REFLECTOR LH	\$	CRM	43.61	✓
85	1	BUMPER REFLECTOR RH	\$	Sn	43.61	X
86	1	BOOT REAR	\$	Ry	2,872.68	✓
87	2	BOOT RUBBER PLUG	\$	Sn	221.81	X
88	1	BOOT FINISHER	\$	Sn	470.06	X
89	1	BOOT SWITCH	\$	Sn	168.13	X
90	1	BOOT TRIM BOARD	\$	Reform	914.87	✓
91	1	BOOT LOCK	\$	M	202.67	✓
92	1	BOOT LOCK CATCH	\$	R	74.40	X
93	1	BOOT LOCK LINKAGE	\$	Sn	34.53	X
94	1	BOOT LOCK LINKAGE HOLDER	\$	Sn	154.52	X
95	1	BOOT LOCK CATCH TRIM BOARD	\$	Sn	249.24	X
96	1	BOOT WHEATERSTRIP	\$	Red/Lot	323.05	✓
97	1	BOOT REFLECTOR LAMP LH	\$	CRM	493.35	✓
98	1	BOOT REFLECTOR LAMP RH	\$	CRM	493.35	✓
99	1	BOOT BADGE 'RENAULT'	\$	Ree	225.36	✓
100	1	BOOT BADGE	\$	Ree	225.36	✓
101	1	BOOT STRUT LH	\$	Sn	276.08	X
102	1	BOOT STRUT RH	\$	Sn	276.08	X
103	1	BOOT HINGE LH	\$	R	367.84	X
104	1	BOOT HINGE RH	\$	R	367.84	X
105	2	LICENCE PLATE LAMP	\$	Sn	50.52	X
106	1	WINDSCREEN REAR	\$	Sn	1,463.28	X
107	1	WINDSCREEN GARNISH INNER LH	\$	Sn	263.74	X
108	1	WINDSCREEN GARNISH INNER RH	\$	Sn	263.74	X
109	1	TAILLAMP LH	\$	CRM	552.55	✓
110	1	TAILLAMP PANEL LH	\$	Ry	986.70	✓
111	1	TAILLAMP RH	\$	Sn	552.55	X
112	1	TAILLAMP PANEL RH	\$	R	986.70	X
113	1	CHASSIS PANEL REAR LH	\$	Ry	3,766.43	✓
114	1	FENDER PANEL REAR LH	\$	Bu	3,299.13	✓
115	1	FENDER PANEL REAR RH	\$	R	3,299.13	X
116	1	WHEELARCH REAR LH	\$	Sn	543.47	X
117	1	WHEELARCH REAR RH	\$	Sn	543.47	X
118	1	FENDER PANEL INNER TRIM REAR RH	\$	Sn	671.45	X

TRANS-CAB AUTO SERVICES PTE LTD

AAD1712-033

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5628X -

119	1	FENDER PANEL INNER TRIM REAR LH	\$
120	1	FENDER WHEEL HOUSE PANEL REAR LH	\$
121	1	FENDER WHEEL HOUSE PANEL REAR RH	\$
122	1	LOWER ARM REAR LH	\$
123	1	KUCKLE ARM REAR LH	\$
124	1	ABSORBER REAR LH	\$
125	1	ABSORBER BOLT REAR LH	\$
126	1	ABSORBER DUST COVER REAR LH	\$
127	1	AIR VENT RH	\$
128	1	REAR AXLE	\$
129	1	AXLE ARM ROD	\$
130	1	AXLE ARM LH	\$
131	1	AXLE ARM RH	\$
132	1	AXLE ARM SHIELD LH	\$
133	1	AXLE ARM SHIELD RH	\$
134	1	AXLE SPRING ARM LH	\$
135	1	AXLE SPRING ARM RH	\$
136	1	STABILIZER BAR REAR	\$
137	1	STABILIZER LINK REAR LH	\$
138	1	STABILIZER LINK REAR RH	\$
139	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$
140	1	SPARE WHEEL PANEL TRIM (Luggage Floor F	\$
141	1	SPARE WHEEL PANEL BRACKET LH	\$
142	1	SPARE WHEEL PANEL BRACKET RH	\$
143	1	OUTER PANEL REAR (End Panel)	\$
144	1	OUTER PANEL REAR (End Panel)TRIM	\$
145	1	EXHAUST REAR	\$
146	1	EXHAUST CAP REAR	\$
147	1	EXHAUST MOUNTING REAR	\$
148	1	EXHAUST BRACKET REAR	\$
149	1	EXHAUST HEAT SHIELD REAR	\$
150	1	SHIELD - HEAT - TUNNEL	\$
151	1	FUEL FLAP	\$
152	1	FUEL TANK NECK	\$
153	1	FUEL CAP	\$
154	1	DOOR PANEL REAR LH	\$
155	1	DOOR SEAL REAR LH	\$
156	1	DOOR PANEL REAR RH	\$
157	1	DOOR SEAL REAR RH	\$

Reform 671.45 ✓

R 3,039.04 X

R 3,039.04 X

Sm 905.99 X

Sm 736.67 X

Sm 389.75

Sm 52.10

Sm 92.16

Sm 97.28

Sm 4,167.03

Sm 117.22

Sm 117.22

Sm 117.22

Sm 9.08

Sm 9.08

Sm 376.92

Sm 376.92

Sm 604.65

Sm 92.36

Sm 92.36

Br/Bu 2,189.88 ✓

Reform 612.21 ✓

R 123.73 ✓

R 121.36 X

R 1,471.77 ✓

CR 401.02 ✓

R 7,489.05

R 230.49

Sm 31.97

R 39.86

R 99.06

Sm 225.16

Sm 343.57

Sm 684.77

Sm 233.02

R 2,844.66

Sm 187.08

R 2,844.66

Sm 162.02

TOTAL	\$	106,336.20
10%	\$	10,633.62
	\$	95,702.58

TRANS-CAB AUTO SERVICES PTE LTD**AAD1712-033**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5628X -**Specical Nett**

1	1SET	RADAITOR GRILLE FRAME CLIP	\$	nn	52.00	X
2	1SET	BUMPER CLIP FRT	\$	nn	66.00	✓
3	1	BUMPER BRACKET CLIP FRT LH	\$	nn	12.00	} X
4	1	BUMPER SUPPORT CLIP FRT LH	\$	nn	10.50	
5	1	BUMPER BRACKET CLIP FRT RH	\$	nn	12.00	
6	1	BUMPER SUPPORT CLIP FRT RH	\$	nn	10.50	
7	1	TOW COVER FRT	\$	sn	14.50	
8	1SET	RADAITOR GRILLE SCREW	\$	nn	16.00	
9	1SET	BUMPER GRILLE LOWER CLIP	\$	nn	69.00	
10	1SET	FRAME FULL SUPPORT PANEL CLIP	\$	nn	70.00	
11	2	FRAME FULL SUPPORT PANEL NUT	\$	nn	20.00	
12	2	FRAME FULL SUPPORT PANEL STUD	\$	nn	30.00	
13	1SET	WHEELARCH CLIP FRT LH	\$	nn	30.50	} X
14	1SET	WHEELARCH CLIP FRT RH	\$	nn	29.40	
15	1	CAP HUB LH FRT	\$	sn	35.00	
16	1	RIM LH FRT	\$	sn	385.00	
17	1	TYRE LH FRT	\$	sn	330.00	
18	1	CAP HUB RH FRT	\$	sn	35.00	
19	1	RIM RH FRT	\$	sn	385.00	
20	1	TYRE RH FRT	\$	sn	330.00	
21	1SET	BUMPER RR CLIP	\$	nn	66.00	✓
22	1SET	BUMPER BEAM BOLT	\$	sn	22.22	X
23	1SET	PARKING AID	\$	short	600.00	✓
24	1	BUMPER BRACKET CLIP CTR REAR	\$	nn	15.00	} X
25	1	BUMEPR BRACKET SIDE CLIP LH REAR	\$	nn	12.00	
26	1	BUMEPR RETAINER CLIP LH REAR	\$	nn	10.40	
27	1	BUMEPR BRACKET SIDE CLIP RH REAR	\$	nn	12.00	
28	1	BUMEPR RETAINER CLIP RH REAR	\$	nn	10.40	
29	1	CAP HUB LH RR	\$	sn	35.00	
30	1	RIM LH RR	\$	sn	385.00	
31	1	TYRE LH RR	\$	sn	330.00	
32	1	CAP HUB RH RR	\$	sn	35.00	
33	1	RIM RH RR	\$	sn	385.00	
34	1	TYRE RH RR	\$	sn	330.00	
35	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	sn	385.00	
36	1	SPARE TYRE	\$	sn	330.00	
37	1SET	BOOT FINISHER CLIP	\$	nn	25.10	
38	1	Rear boots sticker "trans-cab"	\$	nn	30.00	✓
39	1	Rear boots sticker "6555-3333"	\$	nn	30.00	✓
40	1	FENDER PANEL INNER TRIM CLIP REAR RH	\$	nn	22.00	X
41	1	FENDER PANEL INNER TRIM CLIP REAR LH	\$	nn	22.00	X

TRANS-CAB AUTO SERVICES PTE LTD**AAD1712-033**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5628X -

42	1SET	WHEELARCH CLIP LH RR	\$	nn	32.34	X
43	1SET	WHEELARCH CLIP RH RR	\$	nn	32.34	X
44	2	Rear windscreen sealant	\$	nn	80.00	4000
45	1	Windscreen moulding	\$	nn	100.00	✓
46	1	Rear Windscreen Inner Sponge Seal	\$	nn	100.00	3000
47	1	EXHAUST MOUNTING REAR	\$	nn	65.50	X
48	1	EXHAUST BRACKET REAR	\$	nn	22.22	X
49	1SET	Front licence plate with holder	\$	nn	80.00	X
50	1SET	Rear licence plate with holder	\$	nn	80.00	X
51	1	DOOR STICKER "6555-3333" LH	\$	nn	80.00	X
52	1	DOOR STICKER "6555-3333" RH	\$	nn	80.00	X

TOTAL	\$	5,786.92
TOTAL PARTS	\$	101,489.50

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$	8,400.00	2200
Towing Fees.	\$	120.00	500
To apply paint protection system (PPS) maintain and enhancement	\$	nn 380.00	X
Putty and spray painting of the affected	\$	9,000.00	1500
To rust-proofing of the affected areas.	\$	170.00	1200
To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.	\$	380.00	1000
To check steering geometry and computer wheel alignment	\$	220.00	600
To transfer of tire, rim and on wheel	\$	nn 170.00	X
To Check Electrical Lighting Concerned.	\$	170.00	200
To pull and jack out chassis frame and correct it to symmetrical position with the aid of hydraulic pneumatic jack.	\$	380.00	} 2500
Labour charge to mount and dismount vehicle on jig bench, to facilitate repair.	\$	380.00	

TRANS-CAB AUTO SERVICES PTE LTD**AAD1712-033**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5628X -

To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	<i>Repair</i>	170.00	X
To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.	\$	<i>✓</i>	170.00	X
To supply and re-do rear luggage floor panel insulation padding.	\$		380.00	<i>Bo</i>
To transfer of bootlid fittings, attachments and perform water seepage test.	\$		170.00	<i>Bo</i>
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	<i>Repair</i>	380.00	X
To transfer of tailgate fittings and conduct water seepage test.	\$		170.00	<i>Bo</i>
To transfer of rear windscreen fittings, attachments and perform water seepage test.	\$		380.00	<i>120</i>
To reinstall rear bumper parking sensor.	\$		170.00	<i>Bo</i>
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$		280.00	} <i>Bo</i>
To repair and realign rear exhaust pipe.	\$		170.00	
To dismantle and refit rear undercarriage parts, final checking and testing.	\$	<i>nn</i>	380.00	X
To dismantle and refit rear axle housing assy, remove and renewal of parts, final checking and testing.	\$	<i>nn</i>	380.00	X
To drop rear axle assy, remove and renewal of the necessary parts	\$	<i>nn</i>	380.00	X
To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	<i>nn</i>	440.00	X
To drop diesel tank, pipes, hoses to facilitate bodywork repair, final checking and testing.	\$		380.00	<i>Bo</i>

TRANS-CAB AUTO SERVICES PTE LTD**AAD1712-033**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHC5628X -

To remove and renew power steering pump, oil cooler pipe and final checking and testing.	\$	<i>nn</i> 440.00 <i>X</i>
To vacuum, replace, refix and recharge air condenser	\$	<i>nn</i> 380.00 <i>X</i>
To replace, refix and top up coolant for	\$	<i>nn</i> 170.00 <i>X</i>
To vacuum, replace, refix and recharge Air Intercooler	\$	<i>nn</i> 170.00 <i>X</i>
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	<i>nn</i> 170.00 <i>X</i>

TOTAL	\$	22,970.00
Over All Total	\$	124,459.50

< parts by parts > Repair Days

~~30 DAYS~~*18 days*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: