

ASS. REC. BY:

REF:

CB/EGLI7033193 / Amber

Special Instruction:

Surveyor: Adrian.

ASSIGNMENT (Office)

From (Person): Yee Pei Li

of

EGL

Date/Time: 06/22/07 2:13pm

Estimated Cost:

Bill to:

OD / ~~TP~~ / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBE 7088

1702E

Insured:

GBD 17408

at Workshop m/s

Ho Bang

Tel:

9271 2214

of

Blk 3020A Ubi Rd 1 #01-33

Policy No:

Claim No:

GBD17408 / RH / pi

Sum Insured:

Excess:

Make of Veh:

D.O.A. 04/22/07

(Client's Record)

CA / REV / REP. / REV 24 HRS 'WP'

H.O.D. Endorsement:

Date/Time: 06-12-2017 2:48pm

Person Contacted:

Chris

Vehicle: ~~IN~~ / OUT

Date/Time	Action/Instruction (✓) Estimate
	GBE 7088 X
	GBD 17408 X
7/10/17	Email Pei Li informed pending est from repairer
25/1/18	Adrian confirmed LS \$ 19,300 (Real 13,279.20, 5690)
26/1/18	Email preli revised to Pei Li

ASSIGNMENT

From _____ Date _____
 Estimated Cost: _____
OD / TP / WS / TP RES / OD RES / EVA / INV / MV
 To inspect Vehicle No: _____
 at Workshop no: _____
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
 repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____
 IDAC Accident Rpt: _____ Consistent? : Yes or No
 GIA / PR Seen: _____ Consistent? : Yes or No
 Est. Repairs: _____ days Res.: Yes or No
 Lum Sum: _____ % 3 Val: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____ Vehicle: IN / OUT

Veh No. **GBE708S** Yr Regn: **2015 August**
 Type: M/Car / M/Cycle / Bus / Van Lorry / Taxi / Prime Mover /
 Truck / Trailer or

Make: **Isuzu NHR** No. **2999**
 Colour: **White** A.O. Insured / Std / NI / NA
 So Reading: **80784** T Radio: Insured / Std / NI / NA

Eng No: _____
 O/No: **JAA NHR 85 EF 7100755**

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: **185R15 ohtsu.**R: **165R13C Nifly.**

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PR / SUMI /

TOYO / YOKO or

Front		Rear	
R/Bal. 06	mm	R/Bal. 06	mm
L/Bal. 06	mm	L/Bal. 06	mm
D.O.A.		D.O.I.	06/12/17

Survey held at **Ho Bong.**Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

TP Ergo.

RECEIVED 2018

Data/Time: File Pass to? ☐ : Preli. Reportto ☐ : Final Report

Data/Time: File Return to?

1/2- typist

Report Format:

Lump Sum / I.B.I. \$

TP
10,300kDays Of Repair: **13**Resurvey No. of Trip: **2**Add Fee: ☐ Site Insp. \$☐ Inter. Exp. \$☐ Tech. Ins. \$☐ Weekend \$

Survey Fee:

Transportation

___ \$ - P# ___ \$

Photos

Other

TOTAL

390

390

Survey Department Check List (Case Handler)

Reference No.: (S) EGI 17023193 / Avb
Policy Type: OD / TP / TP RES / TL / EVA

Case Handler

Typist

Admin (): Case handler to make sure all Information created by the assignment team are **ACCURATE**.

(1) Office Assign Form		Y-Date	N-Date	Y-Date	N-Date
C	Reference No.	✓			
C	Customer Code				
N	Assign From				
C	Assign Date	✓			
C	Veh No (Inspected)	✓			
C	Veh No (Insured)	✓			
C	D.O.A	✓			
C	Policy No				
C	Claim No	✓			
C	Insurance Authorisation (CA /REV/REP)				
C	Report Type	✓			
C	Weekend Charges				
N	Survey held at/Repairer	✓			
C	Excess				

Surveyor (): Case handler to make sure the surveyor completed all required information.

(1) Assignment Form		Y-Date	N-Date	Y-Date	N-Date
C	Vehicle No	✓			
C	Regn Month/Year	✓			
N	Vehicle Type	✓			
N	Make & Model	✓			
C	Engine Capacity. (C.C)	✓			
N	Colour	✓			
C	Odometer. (Sp.Reading)	✓			
C	Chassis No	✓			
N	General Condition	✓			
N	Steering	✓			
N	Brake	✓			
N	Modification (Modi)	✓			
C	Tyre Size	✓			
N	Tyre Make	✓			
C	Tyre Balance	✓			
C	Date of Inspection	✓			
N	Survey held	✓			
N	Des.of Damages	✓			

(2) System - (Views/Merimen)

C	Damaged Vehicle Photographs Uploaded	✓			
---	--------------------------------------	---	--	--	--

(3) Workshop Estimate/Assignment Form

N	ALL Parts condition	✓			
C	Market Value for OD cases				
C	Estimate Repair Cost for PRI (RSI, TMI, MSIG)				
C	Days of repair	✓			
C	Finalised Amount	✓			
C	Re-inspection Cases to Finalize within 5 Days				

(4) System - (Views/Merimen)

C	Resurvey photo Uploaded	✓			
---	-------------------------	---	--	--	--

Check By: VERON 12/18
Case Handler Date

*C: Critical *N: Non-Critical

21/05/2014



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EGI17023193/Avb

5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985

Date : 06-12-2017



Code : EGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBD 1790B	Veh. Inspected	GBE 708S
Policy No.		Coverage (\$)	0.00
Claim No.	GBD1790B/RH/pl	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	06/12/2017

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer		Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	04/12/2017	Inspection Date	06/12/2017
Survey held at	HO BENG TRADING BLK 3020A, UBI ROAD 1 #01-33 SINGAPORE 408714		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 26 January 2018 6:02 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'
Cc: SUR
Subject: RE: GBD1790B / TP : GBE708S/LKK / DOA : 04/12/2017
Attachments: GBE 708S PRELI REVISED.pdf

Dear Pei Li,

Enclosed preliminary revised of vehicle GBE 708S
Date of survey: 6/12/2017
Number of days:13 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Veron Chen (LKKAUTO)
Sent: Thursday, 7 December 2017 9:57 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>
Cc: SUR <sur@lkkauto.com>
Subject: RE: GBD1790B / TP : GBE708S/LKK / DOA : 04/12/2017

Dear Pei Li,

Please be informed that we have inspected the vehicle GBE 708S on 6/12/2017.

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 6 December, 2017 2:48 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>
Cc: assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: GBD1790B / TP : GBE708S/LKK / DOA : 04/12/2017

Dear Pei Li,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]
Sent: Wednesday, 6 December, 2017 2:13 PM
To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>
Subject: OI : GBD1790B / TP : GBE708S/LKK / DOA : 04/12/2017

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **HO BENG TRADING**

ADDRESS : BLK 3020A UBI ROAD 1
#01-33

PERSON TO CONTACT : CHRIS CHAN @ 9271 2214

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are our insured's and TP's SAS (note: reports not to be released to any Third Party). No estimates was provided.

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194

Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: GBD1790B/RH/pl

Our ref: CS/EG117023193/Avb

Date : 26/1/2018

The Motor Claims Department
M/s: ERGO Insurance Pte Ltd

Without Prejudice

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. GBE 708S


We thank you for your instruction on 6/12/2017

Please be informed that we had conducted the inspection of the above mentioned vehicle on 6/12/2017 at the premises of M/s HO BENG TRADING

Workshop Estimate Amount	: S\$23,579.20
Revised Estimate Amount	: S\$10,300.00 (LUMP SUM)
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the front portion.



Comments/Present Status:

Damages Consistent

Yours faithfully,

ADRIAN LING WAI PING

B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI

Licensed Appraiser

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 7 December, 2017 9:57 AM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)'
Cc: SUR
Subject: RE: GBD1790B / TP : GBE708S/LKK / DOA : 04/12/2017

Dear Pei Li,

Please be informed that we have inspected the vehicle GBE 708S on 6/12/2017.

We are pending estimate from repairer.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Wednesday, 6 December, 2017 2:48 PM
To: 'Survey Report (ERGO Insurance Pte. Ltd.)' <Survey.Report@ergo.com.sg>
Cc: assignments <assignments@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: RE: GBD1790B / TP : GBE708S/LKK / DOA : 04/12/2017

Dear Pei Li,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Survey Report (ERGO Insurance Pte. Ltd.) [<mailto:Survey.Report@ergo.com.sg>]
Sent: Wednesday, 6 December, 2017 2:13 PM
To: 'admin-d@lkkauto.com' <admin-d@lkkauto.com>
Subject: OI : GBD1790B / TP : GBE708S/LKK / DOA : 04/12/2017

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **HO BENG TRADING**

ADDRESS : BLK 3020A UBI ROAD 1
#01-33

PERSON TO CONTACT : CHRIS CHAN @ 9271 2214

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are our insured's and TP's SAS (**note: reports not to be released to any Third Party**). No estimates was provided.

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers.

Catherine Chong (LKK Auto)

From: Survey Report (ERGO Insurance Pte. Ltd.) <Survey.Report@ergo.com.sg>
Sent: Wednesday, 6 December, 2017 2:13 PM
To: 'admin-d@lkkauto.com'
Subject: OI : GBD1790B / TP : GBE708S/LKK / DOA : 04/12/2017
Attachments: GBD1790B - SAS.pdf; GBE708S - SAS.pdf; GBE708S - PRS FORM.pdf

Dear Catherine,

In compliance with "State Courts Practice Directions Amendment No.1 of 2016" in regards to the Pre Repair Survey, both TP repairer and ERGO Insurance Pte Ltd have agreed on your company **LKK AUTO CONSULTANTS PTE LTD** to be the "Single Joint Expert".

Please conduct this survey request from **HO BENG TRADING**

ADDRESS : BLK 3020A UBI ROAD 1
#01-33

PERSON TO CONTACT : CHRIS CHAN @ 9271 2214

ERGO OFFICER-IN-CHARGE : STEVE LIM

Note: To survey on without prejudice basis. Obtain estimate and advise the consistency of damages to third party vehicle that you are require to conduct a re-survey before vehicle is returned to claimant. They are to contact your office directly. Please do keep us in the loop.

Please fill up the necessary on ERGO PRS Form from workshop and return to us together on your update of the survey status via Survey.Report@ergo.com.sg.

Attached are our insured's and TP's SAS (note: reports not to be released to any Third Party). No estimates was provided.

Kindly acknowledge receipt of this email.

Thank you.

Yee Pei Li

Claims Assistant (Motor)
ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985
Tel.: 65 6829 9199 DID: 65 6829 9194
Website: www.ergo.com.sg

ERGO is one of the major insurance groups in Germany and Europe. Worldwide, ERGO is represented in more than 30 countries and concentrates on Europe and Asia. ERGO is part of Munich Re (Group), one of the world's leading risk carriers

ERGO

Date: 06.12.2017
Our Reference: GBD 1790B/RH/pl
Your Reference: GBE 708S

To: HO BENG TRADING

Sent via Fax

6829 9247

or

Email

chris_chanbebe@hotmail.com

Pre-Repair Survey (PRS) Acknowledgement

Vehicle For Inspection: GBE 708S
Insured's Vehicle: GBD 1790B
Date Of Accident: 04.12.2017


We acknowledge receipt of your request for PRS on: 05.12.2017

In compliance with "State Courts Practice Directions Amendment No.1 of 2016", do select an assessor from the list below and indicate your selection in the box marked *.

* LKK

IAS	Infiniti Appraisal Service		
LBS	L.B.S Auto Consultants Pte Ltd		
LKK	LKK Auto Consultants Pte Ltd		

- ☒ Your request for inspection does not have your client's cost of repair estimate, kindly forward a copy.
☐ Your request for inspection does not have your client's complete GIA report, kindly forward a copy.
☐ We acknowledge your interest for direct settlement, we will assess & revert soon upon receipt of estimate.
☐ Our insured's driver has not reported the accident to us today.
☒ Others: OFFICER-IN-CHARGE - ROHAINI

Prepared by:		Per Li	6829 9194	claims@ergo.com.sg
Signature:				FAX : 6829 9247

Assessor use only:

Assignment Date: _____
Assignment Time: _____

Remarks:

Workshop use only:

Assessor attended workshop on:

Date: _____
Time: _____
Inspector: _____

☐ Vehicle not available at the appointed date and time.

Kindly acknowledge our Assessor presence for the above job.

Workshop Acknowledgement & Stamp.

Note: Our inspection is on a without admission to liability basis.

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Business
Owner ID: 1702E

Vehicle Details

Vehicle No.: GBE708S
Vehicle to be Exported: No
Intended De-registration Date: 01 Feb 2018
Vehicle Make: ISUZU
Vehicle Model: NHR85AUE4AA
Primary Colour: White
Manufacturing Year: 2015
Engine No.: 4JJ11X9731
Chassis No.: JAANHR85EF7100155
Maximum Power Output: -
Open Market Value: \$22,515.00
Original Registration Date: 27 Aug 2015
First Registration Date: 27 Aug 2015
Transfer Count: 1
Actual ARF Paid: \$1,126.00

Intended PARF Rebate Details

PARF Eligibility: No
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 26 Aug 2025
COE Category: C - Goods Vehicle & Bus

COE Period(Years):	10
PQP Paid:	\$5,337.00
COE Rebate Amount:	\$4,038.00
Total Rebate Amount:	\$4,038.00

The information contained herein is correct as at 01 Feb 2018

OK

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	05/12/2017 15:34
Date Of Accident	04/12/2017 15:30
Exact Location Of Accident	PIE (CHANGI) EXIT TO BKE
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBE708S
Insured/Policyholder	
Name Of Registered Owner	SIN YI SENG TRADING
Co Reg No	53156232L (12025)
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-90909629
Vehicle Particulars	
Manufacturer	ISUZU
Model	NHR85AUE4AA
Exact Purpose for which vehicle was being used at time of accident	WORK USE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	GOODS VEHICLE
Insurance Company	
Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	5068101892-03
Cover Note Number	
Driver	
Name of Driver	ONG WEI KEAN
NRIC No	G7295392X
Date Of Birth	23/08/1983
Occupation	OUTDOOR
Date Of Driving Pass	07/07/2008
Driving Experience	9 YEARS AND 4 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93853919
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address
Postcode
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle -
Vehicle -
Insurance Company of Driver's Own Vehicle -
-

General Information of the Accident

Type Of Accident COLLISION - CHANGE/CROSS LANE
Weather Conditions RAINING
Road Surface WET

Other Information

Was any foreign vehicle involved in this accident? NO
Was any body injured in the Accident? YES
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 1

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

I WAS TRAVELLING ALONG PIE EXIT TO BKE AT LANE 3. SUDDENLY VEHICLE B (GBD1790B) SPIN FROM LANE 1 INTO MY LANE. I COULD NOT STOP IN TIME AND HIT HIS FRONT RIGHT SIDE OF HIS VEHICLE.

Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? NO
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBD1790B
Vehicle Make/Model/Colour
Details Of Properties
Name of Driver
NRIC/Passport Number
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage
No. Of Passenger (Including Driver)

Details of Witness

Name
Phone Number
Email Address

DETAILS OF INJURED PERSON 1

Name ONG WEI KEAN

Approximate Age

Injuries Sustain

Injured person in which vehicle?

GBE708S

Were seat belts worn?

YES

Was injured conveyed to hospital by ambulance?

NO

Address

Postcode

Sketch Plan Pg. 1

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claim process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.

Singapore Police
UEN NO. 53156232
4008 DEPOT LANE #01-90
SINGAPORE 109792
HP: 9090 9624

Policyholder's Signature

Date & Time: 5/12/17
15:00pm


Driver's Signature
(If driver is not the policyholder)
Date & Time: 5/12/17
15:00pm

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:



Sketch Plan Pg. 2

SKETCH PLAN



A : GBE708S

B : GBD1790B

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

I was travelling along PIE exit to BKE at lane 3. suddenly

vehicle B (GBD1790B) spin from lane 1 into my lane.

I could not stop in time and hit his front right side of

his vehicle.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

4008 DEPT LINE MOTORS
SINGAPORE 108752
HP: 9090 9824

Policyholder's Signature

Date & Time: 5/12/17
15.00pm

Driver's Signature

(If driver is not the policyholder)

Date & Time: 5/12/17
15.00pm



Reporting Centre Personnel's Signature

Name:

NRIC/FIN No.:

Sheet1

HO BENG TRADING

Block 3020A Ubi Road 1 # 01-33 Singapore 408714

Tel : (65) 69664526 HP: 92712214 Fax: (65) 69664526

Email : chris_chanbebe@hotmail.com

SIN YI SENG TRADING
BLOCK 3020A UBI ROAD 1
01-33
Singapore 408714

TP Erygo.
Veron

06th December 2017

JAA NHR85ER7100155

Accident date: 04.12.2017

Estimated repair cost for vehicle no: GBE708S ISUZU NHR85U

S/n	Qty	Items	U/price	Amount
1	1	Front panel Distorted		\$850.00 ✓
2	2	Front corner panel Cracked	\$190	\$380.00 ✓
3	1	front isuzu emble New		\$120.00 ✓
4	1	front grille clips -set New		\$25.00 ✓
5	1	Front grille Cracked		\$628.00 ✓
6	2	Front headlamp Cracked	\$765.90	\$1,531.80 ✓
7	2	Front signal lamp New	\$188.00	\$376.00 x
8	2	front wiper Nozzle Cracked	\$122.00	\$244.00 170 ✓
9	2	Front bumper bracket Best	\$256.20	\$512.40 ✓
10	2	front wiper arm Best	\$285.00	\$570.00 120 ✓
11	2	front wiper blade Lt	\$45.00	\$90.00 ✓
12	1	front wiper linkage Best		\$266.00 ✓
13	1	front cross member New		\$850.00 x
14	1	torsion bar Best		\$630.00 ✓
15	1	air cond liquid pipe Best		\$188.20 ✓
16	1	air cond section pipe Best		\$215.20 ✓
17	1	air cond discharge pipe Best		\$255.30 ✓
18	3	brake pipe Best	\$147.60	\$442.80 ✓
19	1	front dashboard outer garnish Deformed		\$228.60 ✓
20	1	front dashboard Deformed		\$1,258.00 ✓
21	1	front dashboard frame New		\$795.00 x
22	1	air cond evaporator Cracked		\$898.00 ✓
23	1	air cond blower Cracked		\$959.00 ✓
24	1	front brake booster { New		\$1,205.20 x
25	2	front brake master pump { New		\$2,233.30 x

Subtotal :- \$15,276.80 15,801.80

S/n	Qty	Items/SNett	U/price	Amount
1	1	Front bumper <i>dist</i>		\$765.00 ✓
2	2	front bumper side cover <i>win</i>	\$56.00	\$112.00 X
3	2	head lamp lower rubber <i>at</i>	\$102.20	\$204.40 40 (SN)
4	1	head lamp lower rubber clips <i>m</i>		\$50.00 20 (SN)
5	1	NH sticker <i>win</i>		\$50.00 ✓ (SN)
6	1	front windscreen <i>shattered</i>		\$1,080.00 ✓
7	1	front windscreen moulding <i>new</i>		\$180.00 ✓
8	1	front windscreen sealant <i>m</i>		\$150.00 60 (SN)
9	1	EPR Bracket <i>new</i>		\$26.00 ✓ (SN)
10	1	brake fluid <i>new</i>		\$80.00 50 (SN)
11	1	Front bumper number plate <i>best</i>		\$50.00 30 (SN)

1184330

S-N: 276

1006680

Subtotal :- \$2,747.40

Labour charges

To underseal

~~\$150.00~~ 60

Remove & refix front dashboard

~~\$450.00~~ 220

to remove & Refix front windscreen

~~\$180.00~~ 120

To remove & re-fix air-con evaporator ,air cond pipe blower & top up gas

~~\$400.00~~ 200

WHEEL alignment (computer)

\$120.00 X

To remove & Refix front brake pump , booster & brake fluid

~~\$450.00~~ 120

To Check Wiring System

2550

~~\$80.00~~ 30

Panel beating

~~\$1,800.00~~ 1000

Spray painting

~~\$1,400.00~~ 800

subtotal:- \$5,030.00

Total:- \$23,054.20 23,579.20

Total: 12892.80

h/s: 10.3K

13 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts during resurvey
- Parts provided subject to information
- Third party survey is on an "without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

ERGO INSURANCE PTE LTD

Ref : CS/EGI17023193/Avbe2

5 TEMASEK BOULEVARD
#04-01 SUNTEC TOWER FIVE
SINGAPORE 038985

Date : 08-02-2018



Code : EGI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBD 1790B	Veh. Inspected	GBE 708S
Policy No.		Coverage (\$)	0.00
Claim No.	GBD1790B/RH/pl	Excess (\$)	0.00
Assign From	YEE PEI LI	Assign Date	06/12/2017

2. Vehicle Particulars & Condition

Make & Model	ISUZU NHR	c.c	2999
Engine No.	HIDDEN	Year of Reg.	2015
Chassis No.	JAANHR85EF7100155	Colour	WHITE
Odometer	80784	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195 R15	OHTSU	6 mm
L/H Front Tyre	195 R15	OHTSU	6 mm
R/H Rear Tyre	165 R13C	HIFLY	6 mm
L/H Rear Tyre	165 R13C	HIFLY	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.

5. General Information

Accident Date	04/12/2017	Inspection Date	06/12/2017
Survey held at	HO BENG TRADING BLK 3020A, UBI ROAD 1 #01-33 SINGAPORE 408714		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	13 Working Days
-------------------------------------	-----------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBE 708S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<u>REPLACEMENT OF PARTS</u>			
1	FRONT PANEL	DISTORTED	850.00	850.00
2	FRONT CORNER PANEL @\$190.00	CRACKED	380.00	380.00
1	FRONT ISUZU EMBLE	NECESSARY	120.00	120.00
1	SET FRONT GRILLE CLIPS	NECESSARY	25.00	25.00
1	FRONT GRILLE	CRACKED	628.00	628.00
2	FRONT HEADLAMP @\$765.90	CRACKED	1,531.80	1,531.80
2	FRONT SIGNAL LAMP @\$188.00	NOT NECESSARY	376.00	-
2	FRONT WIPER NOZZLE @\$122.00	CRACKED	244.00	170.00
2	FRONT BUMPER BRACKET @\$256.20	BENT	512.40	512.40
2	FRONT WIPER ARM @\$285.00	BENT	570.00	120.00
2	FRONT WIPER BLADE @\$45.00	CUT	90.00	90.00
1	FRONT WIPER LEAKAGE	BENT	266.00	266.00
1	FRONT CROSS MEMBER	NOT NECESSARY	850.00	-
1	TORSION BAR	BENT	680.00	680.00
1	AIR COND LIQUID PIPE	BENT	188.20	188.20
1	AIR COND SECTION PIPE	BENT	215.20	215.20
1	AIR COND DISCHARGE PIPE	BENT	255.30	255.30
3	BRAKE PIPE @\$147.60	BENT	442.80	442.80
1	FRONT DASHBOARD OUTER GARNISH	DEFORMED	228.60	228.60
1	FRONT DASHBOARD	DEFORMED	1,258.00	1,258.00
1	FRONT DASHBOARD FRAME	NOT NECESSARY	795.00	-
1	AIR COND EVAPORATOR	CRACKED	898.00	898.00
1	AIR COND BLOWER	CRACKED	959.00	959.00
1	FRONT BRAKE BOOSTER	NOT NECESSARY	1,205.20	-
2	FRONT BRAKE MASTER PUMP	NOT NECESSARY	2,233.30	-
1	FRONT BUMPER	DISTORTED	765.00	765.00
2	FRONT BUMPER SIDE COVER @\$56.00 (SN)	NOT NECESSARY	112.00	-
1	FRONT WINDSCREEN	SHATTERED	1,080.00	1,080.00
1	FRONT WINDSCREEN MOULDING	NECESSARY	180.00	180.00

Report Ref No. CS/EGI17023193/Avbe2

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 15% DISCOUNT		-	-1,776.49
			17,938.80	10,066.81
	<u>SPECIAL NETT ITEMS</u>			
2	HEAD LAMP LOWER RUBBER @\$102.20 (SN)	CUT	204.40	40.00
1	HEAD LAMP LOWER RUBBER CLIPS (SN)	NECESSARY	50.00	20.00
1	NH STICKER (SN)	NECESSARY	50.00	50.00
1	FRONT WINDSCREEN SEALANT (SN)	NECESSARY	150.00	60.00
1	EPR BRACKET (SN)	NECESSARY	26.00	26.00
1	BRAKE FLUID (SN)	NECESSARY	80.00	50.00
1	FRONT BUMPER NUMBER PLATE (SN)	BENT	50.00	30.00
			610.40	276.00
	<u>LABOUR</u>			
	TO UNDERSEAL.		150.00	60.00
	REMOVE & REFIX FRONT DASHBOARD.		450.00	220.00
	TO REMOVE & REFIX FRONT WINDSCREEN.		180.00	120.00
	TO REMOVE & RE-FIX AIR-CON EVAPORATOR, AIR COND PIPE BLOWER & TOP UP GAS.		400.00	200.00
	WHEEL ALIGNMENT (COMPUTER)	NOT NECESSARY	120.00	-
	TO REMOVE & REFIX FRONT BRAKE PUMP, BOOSTER & BRAKE FLUID.		450.00	120.00
	TO CHECK WIRING SYSTEM.		80.00	30.00
	PANEL BEATING.		1,800.00	1,000.00
	SPRAY PAINTING.		1,400.00	800.00
			5,030.00	2,550.00
	GRAND TOTAL		23,579.20	12,892.81
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				10,300.00

Report Ref No. CS/EG117023193/Avbe2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.