



# CHARN'S CUSTOMCRAFT

Lkk

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,  
 Spray-Painting, Mechanical Repair And Customizing of Cars  
 BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724  
 BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723  
 TEL: 62717054, 62733304 FAX: 62736676 EMAIL: [charns@singnet.com.sg](mailto:charns@singnet.com.sg)  
 Bus. Reg. No. 251513/00M

DA/III(SHC8031Y)  
 DOA: 29/11/2017@2200

INDIA INTERNATIONAL INSURANCE PTE LTD  
 ATTN: THE MOTOR CLAIMS DEPT

THIRD PARTY CLAIM  
 ESTIMATE COST OF REPAIR FOR VEHICLE NO:  
 EX 978 T - VOLVO XC60 T5 R-DESIGN  
 CHASSIS NO: YV1DZ47HBD2437498 (2013)

LKK Auto Consultants hence notify  
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts to be resurveyed to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

1 pc	Front door protector LH	<i>RAME</i>	\$ 365.80	<i>scr</i>
1 pc	Front door LH		\$ 2,984.60	<i>R</i>
1 pc	Front door frame rubber LH	<i>Hp 9001218</i>	\$ 288.20	<i>X</i>
1 pc	Rear door LH		\$ 2,995.10	<i>PA</i>
1 pc	Rear door top hinge LH	<i>8 days</i>	\$ 222.30	<i>X</i>
1 pc	Rear door lwr hinge LH		\$ 222.30	<i>X</i>
1 pc	Rear door protector LH	<i>P/P</i>	\$ 375.40	<i>scr</i>
1 pc	Rear door rubber LH	<i>12/12/17 @ 1300</i>	\$ 145.20	<i>scr</i>
1 pc	Rear door frame rubber LH		\$ 294.70	<i>X</i>
1 pc	Rocker panel garnish LH (Sliver)	<i>Resurvey by paint</i>	\$ 1,120.10	<i>scr</i>
1 pc	Rear bumper		\$ 1,985.80	<i>ME</i>
1 pc	Rear bumper retainer LH		\$ 88.60	<i>ME</i>
1 pc	Rear bumper lower garnish		\$ 1,741.50	<i>scr</i>
			\$ 12,829.60	
	LESS 5%		\$ 641.48	
			\$ 12,188.12	
	Alignment			
	Repair, putty and respray rear rim LH		\$ <del>100.00</del>	<i>50</i>
	Remove and reinstall front door glass LH		\$ 80.00	<i>X</i>
	Remove and reinstall rear door glass LH		\$ <del>80.00</del>	<i>60</i>
	Remove necessary parts; jacking, panel beating, repair and straighten front door LH, rear door LH, rear fender and rear bumper.		\$ <del>900.00</del>	<i>800</i>
	Putty and respray front door LH, rear door LH, rear fender LH and rear bumper.		\$ <del>1,000.00</del>	<i>200</i>
			\$ 14,348.12	
	ADD 7% GST		\$ 1,004.37	
			\$ 15,352.49	

Note: The above is an estimate only. IF other parts requested during the course of repair, we will inform you accordingly.

All parts are subject to availability.

CHARN'S CUSTOMCRAFT