



創 CHARN'S CUSTOMCRAFT

Accident Claim Repair, Corrosion Welding, Body Dent Repairs,
Spray-Painting, Mechanical Repair And Customizing of Cars

BLOCK 1010, BUKIT MERAH LANE 3, #01-105, SINGAPORE 159724
BLOCK 1009, BUKIT MERAH LANE 3, #01-82, SINGAPORE 159723
TEL: 62717054, 62733304 FAX: 62736676 EMAIL: charns@singnet.com.sg
Bus. Reg. No. 251513/00M

DA/III(SHC8031Y)

DOA: 29/11/2017@2200

INDIA INTERNATIONAL INSURANCE PTE LTD

6/12/2017

ATTN: THE MOTOR CLAIMS DEPT

THIRD PARTY CLAIM

ESTIMATE COST OF REPAIR FOR VEHICLE NO:

EX 978 T - VOLVO XC60 T5 R-DESIGN

CHASSIS NO: YV1DZ47HBD2437498 (2013)

1 pc	Front door protector LH	\$ 365.80
1 pc	Front door LH	\$ 2,984.60
1 pc	Front door frame rubber LH	\$ 288.20
1 pc	Rear door LH	\$ 2,995.10
1 pc	Rear door top hinge LH	\$ 222.30
1 pc	Rear door lwr hinge LH	\$ 222.30
1 pc	Rear door protector LH	\$ 375.40
1 pc	Rear door rubber LH	\$ 145.20
1 pc	Rear door frame rubber LH	\$ 294.70
1 pc	Rocker panel garnish LH (Sliver)	\$ 1,120.10
1 pc	Rear bumper	\$ 1,985.80
1 pc	Rear bumper retainer LH	\$ 88.60
1 pc	Rear bumper lower garnish	\$ 1,741.50
		<u>\$ 12,829.60</u>
	LESS 5%	\$ 641.48
		<u>\$ 12,188.12</u>
	Alignment	
	Repair, putty and respray rear rim LH	\$ 100.00
	Remove and reinstall front door glass LH	\$ 80.00
	Remove and reinstall rear door glass LH	\$ 80.00
	Remove necessary parts; jacking, panel beating, repair and straighten front door LH, rear door LH, rear fender and rear bumper.	\$ 900.00
	Putty and respray front door LH, rear door LH, rear fender LH and rear bumper.	\$ 1,000.00
		<u>\$ 14,348.12</u>
	ADD 7% GST	\$ 1,004.37
		<u>\$ 15,352.49</u>

Note: The above is an estimate only. IF other parts requested during the course of repair, we will inform you accordingly.

All parts are subject to availability.

CHARN'S CUSTOMCRAFT