

|   |    |    |
|---|----|----|
| 6 | 12 | 12 |
|---|----|----|

| Insured Liability :                 | % | Final ? Yes / No |
|-------------------------------------|---|------------------|
| 1. General Liability                |   |                  |
| 2. Professional Liability           |   |                  |
| 3. Directors and Officers Liability |   |                  |
| 4. Employment Practices Liability   |   |                  |
| 5. Fidelity and Bonding             |   |                  |
| 6. Commercial Automobile            |   |                  |
| 7. Aircraft and Helicopter          |   |                  |
| 8. Watercraft                       |   |                  |
| 9. Umbrella                         |   |                  |
| 10. Other                           |   |                  |



RMKS:

|                               |          |                     |                          |                          |
|-------------------------------|----------|---------------------|--------------------------|--------------------------|
| PRELIMINARY ADVICE Date/Time: | Sent By: | Post-Repair Photos: | <input type="checkbox"/> | <input type="checkbox"/> |
|                               |          | Others:             | <input type="checkbox"/> | <input type="checkbox"/> |

SINCE

REF: ALG

h

42806

## ASSIGNMENT

From: Date 05012018

Estimated Cost:

OD / ☒ TS / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SLK 7657J

at Workshop m/s

Performane

of

303 Alexandra Rd

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Hun

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bel. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 8 days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLK 7657J Yr Reg: 2017 JMN

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: B.N.W XI SDRIVE 181A cc 1499

Colour: Grey A/C Insured / Std / NI / NA

Sp. Reading: 25496 T. Radio: Insured / Std / NI / NA

Eng/No:

C/No: WBAH 5120 305 FO 3606

Gen. Cond: Good / ☒ Fair / Poor / BurntSteering: In order / ☒ Jammed / Leaked / Burnt orBrake: In order / ☒ Jammed / Leaked / Burnt orModi: Nil / ☒ S/Brim / STD A/Rim or

Tyre Size: F: 225/50R18

R:

DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal: 6 mm R/Bal: 6 mm

L/Bal: 6 mm L/Bal: 6 mm

D.O.A. 06/12/17 D.O.I. 05/01/18

Survey held at: Performane

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / instruction

Plp: \$18,098.65

(Net: \$4,206.15 / 19%)

Date/Time File Pass to?

☐

: Preli. Report

Days Of Repair:

1)

☐

: Final Report

Resurvey No. of Trip:

Survey Fee

Date/Time File Return to?

Transporter

2)

Add Fee:

☐

Site Insp \$

☐

Interview \$

☐

Tech. Insp \$

☐

Weekend \$

\$4.95

Phone

Chart

Report Format :

Lump Sum / I.B. : \$

TOTAL



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile  |  |                           |            |   |
|--|--|---------------------------|------------|---|
| AIG ASIA PACIFIC INSURANCE PTE LTD   |  | Ref : CC3/AIG17023201/hb3 |            |   |
| 78 SHENTON WAY #08-16<br>CHARTIS BUILDING<br>SINGAPORE 079120  |  | Date : 06-12-2017         |            |  |
|  |  | Code : AIG                |            |   |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>  |  |                           |            |   |
| Insured Veh.   | SKH 7719S  | Veh. Inspected            | SLK 7657J  |   |
| Policy No.   |  | Coverage (\$)             | 0.00       |   |
| Claim No.  |  | Excess (\$)               | 0.00       |   |
| Assign From  |  | Assign Date               | 06/12/2017 |   |
| <b>2. Vehicle Particulars &amp; Condition</b>  |  |                           |            |   |
| Make & Model   |  | c.c                       | 0          |   |
| Engine No.   | HIDDEN   | Year of Reg.              |            |   |
| Chassis No.  |  | Colour                    |            |   |
| Odometer   | -  | Steering                  |            |   |
| Brakes   |  | Modification              |            |   |
| General  |  |                           |            |   |
| <b>3. Conditions of Tyres</b>  |  |                           |            |   |
|  | Size   | Make                      | Balance    |   |
| R/H Front Tyre   |  |                           | mm         |   |
| L/H Front Tyre   |  |                           | mm         |   |
| R/H Rear Tyre  |  |                           | mm         |   |
| L/H Rear Tyre  |  |                           | mm         |   |
| <b>4. Description of Damages</b>   |  |                           |            |   |
|  |  |                           |            |   |
| <b>5. General Information</b>  |  |                           |            |   |
| Accident Date  | 06/12/2017   | Inspection Date           |            |   |
| Survey held at   | PERFORMANCE MOTORS LTD<br>303 ALEXANDRA ROAD<br>SINGAPORE 159941 |                           |            |   |
| <b>5a. Remarks</b>   |  |                           |            |   |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |  |                           |            |   |

BMW Dealer

# Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559M GST Reg. No M2-0020081-X

303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/538 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

## ESTIMATE

06 DEC 2017

Estimate No. : b1 45072  
Date Estimated : 06/12/2017  
Prepared By : Han Kwan Yong

Page No. : 1 of 2

- ESTIMATE REPAIR FOR -  
Peh Chee Beng (Bai Zhiming)  
58 Punggol Walk  
#03-18

Singapore 828779

- ACCOUNT - 40000  
Cash Sales - Service  
Singapore

| REGN. NO. | CHASSIS NO. | REGN. DATE | MODEL        | MILEAGE |
|-----------|-------------|------------|--------------|---------|
| SLK7657J  | 5F03606     | 25/01/2017 | X1 sDrive18i | 0       |

### DESCRIPTION

END

### VALUE

2915 To replace rear bumper & attachments, boot lid, tail panel including to pull & straighten tail panel before cutting and to knock out dented area caused by the accident

2975 5,950.00  
5,100

2123 (A) TO MAKE GOOD THE REAR LH/RH FENDER, TRUNK FLOOR PLATE TO PULL STRAIGHTEN ON ACCIDENT AREA.  
To respray rear bumper, boot lid, tail panel, rear left fender, rear right fender and boot compartment

2474 5,640.00  
5,076

To remove and install boot compartment carpet and garnish to facilitate repairs.

231 271.00

To replace bootlid smart opener top and bottom sensor lines including program and conduct checks for proper function.

XAN 561? 661.00

To transfer lock mechanism from old to new bootlid including conduct checks on new bootlid central locking system for proper function.

451 531.00

To remove and install rear windscreen glass including conduct water leak tests.

649.00

To remove and install fuse box at the rear section to facilitate repairs.

XAN 451? 531.00

To reconnect electrical components and wirings at the rear section including conduct checks for proper function.

150 354.00  
301

Sundries.

150 150.00

Total Labour 1: 14,737.00

### DESCRIPTION

| QTY | PRIC     |
|-----|----------|
| 1   | 1,171.20 |
| 1   | 315.65   |
| 1   | 401.75   |

### VALUE

BOOTLID  
INTERIOR TAIL TRIM  
TAIL PANEL

XAN 1,171.20  
315.65  
401.75

## Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559M GST Reg. No M2-0020081-X



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Estimate No. : b1 45072  
Date Estimated : 06/12/2017  
Prepared By : Han Kwan Yong

Page No. : 2 of 2

| REGN. NO. | CHASSIS NO. | REGN. DATE | MODEL        | MILEAGE |
|-----------|-------------|------------|--------------|---------|
| SLK7657J  | 5F03606     | 25/01/2017 | X1 sDrive18i | 0       |

| DESCRIPTION                            | QTY | PRIC   | VALUE  |
|--|-----|--------|--------|
| REAR LH BUMPER MOUNT                   | 1   | 141.65 | 141.65 |
| REAR RH BUMPER MOUNT                   | 1   | 141.65 | 141.65 |
| RR BUMPER CARRIER                      | 1   | 445.75 | 445.75 |
| MOUNTING SMART OPENER                  | 1   | 35.70  | 35.70  |
| REAR TRIM UNDERRIDE PROTECTION (X L    | 1   | 97.40  | 97.40  |
| RR BUMPER LH CORNER MOUNTING           | 1   | 141.65 | 141.65 |
| RR BUMPER RH CORNER MOUNTING           | 1   | 141.65 | 141.65 |
| # REAR BUMPER PANEL PRIMED             | 1   | 705.80 | 705.80 |
| # REAR BUMPER MIDDLE TRIM PANE         | 1   | 222.35 | 222.35 |
| REAR BUMPER TRIM BOTTOM (LINES)        | 1   | 211.75 | 211.75 |
| EMBLEM GROMMET                         | 2   | 0.80   | 1.60   |
| BMW PLAQUE WITH ADHESIVE FILM          | 1   | 67.80  | 67.80  |
| LETTERING X1                           | 1   | 61.05  | 61.05  |
| REAR BUMPER TOWING EYE COVER           | 1   | 29.20  | 29.20  |
| REAR BUMPER HEAT INSULATION            | 1   | 66.20  | 66.20  |
| BOOTLID SEALING                        | 1   | 119.20 | 119.20 |
| SENSOR WIRE FOR SMART OPENER TOP       | 1   | 42.10  | 42.10  |
| SENSOR WIRE FOR SMART OPENER BOTTOM    | 1   | 40.50  | 40.50  |
| REAR LH REFLECTOR                      | 1   | 35.40  | 35.40  |
| REAR RH REFLECTOR                      | 1   | 35.40  | 35.40  |
| ULTRASONIC SENSOR BLACK                | 21  | 242.65 | 485.30 |
| DECOUPING RING PDC TORQUE CONVERTER    | 21  | 4.95   | 9.90   |
| (DG) CLEANER R1 (100ML)                | 1   | 23.85  | 23.85  |
| (DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) | 2   | 131.55 | 263.10 |
| (DG/SL) GLASS PRIMER 30ML (VP206)      | 1   | 27.85  | 27.85  |
| (S/L) SEAM SEAL 300ML                  | 3   | 33.80  | 101.40 |

Total Parts : 5,583.80

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. \_\_\_\_\_ Claim No. \_\_\_\_\_

Date&amp;Time 05/01/18 P1155 Excess \$5

Surveyor's Name Rame Sign \_\_\_\_\_

Surveyor's Tel 90066668 Authorised Yes / No

Authorised Date \_\_\_\_\_ Time \_\_\_\_\_

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail \_\_\_\_\_

No. of Working Days Recommend 5-6 days

8

## LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

20333/10

## Acknowledged by Repairer

Signature Labour 1 : 14,737.00

Date: Parts : 5,583.80

Labour 2 : 0.00

Excess : 0.00

Total GST @ 7% : 1,422.46

Grand Total : 21,743.26

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

22304.80

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## SUPPLEMENTARY

Estimate No. : b1 45072  
Date Estimated : 06/12/2017  
Prepared By : Han Kwan Yong

Page No. :

REPAIR FOR -  
Peh Chee Beng (Bai Zhiming)  
58 Punggol Walk  
#03-18

Singapore 828779

- ACCOUNT - 121  
AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way  
#08-16 Chartis Building  
Singapore 079120

| REGN NO  | CHASSIS NO | REGN DATE  | MODEL        | MILEAGE |
|----------|------------|------------|--------------|---------|
| SLK7657J | 5F03606    | 25/01/2017 | X1 sDrive18i | 0       |

| DESCRIPTION   | ORIGINAL PRICE | DISC. % | NETT     |
|---|----------------|---------|----------|
| # To carry out body cavity preservation (Per panel)   | 100.00         |         | 100.00 ✓ |
| # To carry out body cavity preservation (For cut panel)   | 451.00         |         | 451.00 ✓ |
| # To remove old PDC assembly, replace damaged parts and reconnect to new bumper include conducting checks for proper function | 150.00         |         | 150.00 ✓ |
| # To mount vehicle on speed bench to facilitate re-alignment of body/chassis in accordance with BMW specifications            | 564.00         |         | 564.00 ✓ |

| DESCRIPTION                                      | UNIT PRICE | QTY   | DISC. % | NETT     |
|--|------------|-------|---------|----------|
| # BLIND RIVET NUT M6 *                           | 2.60       | 1.00  |         | 2.60 ✓   |
| # RIVET *  | 0.50       | 10.00 |         | 5.00 ✓   |
| # EXPANDING NUT *                                | 1.00       | 2.00  |         | 2.00 ✓   |
| # EXPANDING NUT *                                | 1.00       | 1.00  |         | 1.00 ✓   |
| # EXPANDING NUT *                                | 1.00       | 1.00  |         | 1.00 ✓   |
| # REAR BUMPER MIDDLE TRIM PANEL (PDC) * - REPAIR | 222.35     | 1.00  |         | 222.35 X |
| # EXPANDING RIVET *                              | 1.35       | 20.00 |         | 27.00 ✓  |
| # BLIND RIVET AVIBVLB *                          | 0.55       | 20.00 |         | 11.00 ✓  |
| # (DG/SL) BODY ADHESIVE K5B (195ML) *            | 281.55     | 1.00  |         | 281.55 ✓ |
| # PUNCH RIVET N4 *                               | 0.55       | 20.00 |         | 11.00 ✓  |
| # (DG) BODYWORK ADHESIVE K5A (50ML) *            | 118.35     | 1.00  |         | 118.35 ✓ |
| # (DG) CLEANER R1 (100ML) *                      | 23.85      | 1.00  |         | 23.85 ✓  |

|                        |          |
|------------------------|----------|
| Total Labour :         | 1,265.00 |
| Total Parts :          | 706.70   |
| Total Labour & Parts : | 1,971.70 |





## FINAL REPORT

Estimate No. : b1 45072  
Date Estimated : 06/12/2017  
Prepared By : Han Kwan Yong

Page No. :

**REPAIR FOR -**  
Peh Chee Beng (Bai Zhiming)  
58 Punggol Walk  
#03-18

**- ACCOUNT - 121**  
AIG Asia Pacific Insurance Pte. Ltd.  
78 Shenton Way  
#08-16 Chartis Building  
Singapore 079120

Singapore 828779

| REGN NO   | CHASSIS NO     | REGN DATE  | MODEL        | MILEAGE |
|---|----------------|------------|--------------|---------|
| SLK7657J  | 5F03606        | 25/01/2017 | X1 sDrive18i | 0       |
| DESCRIPTION   | ORIGINAL PRICE | DISC. %    | NETT         |         |
| To replace rear bumper and attachments, boot lid and attachments, tail end panel include making good the rear LH/RH fender, trunk floor plate, to pull and straighten on accident areas and knocking out dents caused by the accident | 5100.00        |            | 5,100.00     |         |
| To respray rear bumper, boot lid, tail end panel, rear LH fender, rear RH fender and trunk floor plate  | 5076.00        |            | 5,076.00     |         |
| To remove and install boot compartment carpet and garnish to facilitate repairs   | 231.00         |            | 231.00       |         |
| To transfer lock mechanism from old to new boot lid include conducting checks on new boot lid central locking system for proper function  | 451.00         |            | 451.00       |         |
| To remove and install rear windscreen glass to facilitate repairs include conducting water leak tests   | 649.00         |            | 649.00       |         |
| * To reconnect electrical components and wirings at the rear section include conducting checks for proper function (For cut panel)  | 301.00         |            | 301.00       |         |
| # To carry out body cavity preservation (Per panel)   | 100.00         |            | 100.00       |         |
| # To carry out body cavity preservation (For cut panel)   | 451.00         |            | 451.00       |         |
| # To remove old PDC assembly, replace damaged parts and reconnect to new bumper include conducting checks for proper function   | 150.00         |            | 150.00       |         |
| # To mount vehicle on speed bench to facilitate re-alignment of body/chassis in accordance with BMW specifications  | 564.00         |            | 564.00       |         |
| Sundries  | 150.00         |            | 150.00       |         |



## FINAL REPORT

| DESCRIPTION                             | UNIT PRICE | QTY   | DISC. % | NETT     |
|---|------------|-------|---------|----------|
| # BLIND RIVET NUT M6 *                  | 2.60       | 1.00  |         | 2.60     |
| BOOTLID                                 | 1,171.20   | 1.00  |         | 1,171.20 |
| TAIL PANEL                              | 401.75     | 1.00  |         | 401.75   |
| # RIVET *                               | 0.50       | 10.00 |         | 5.00     |
| # EXPANDING NUT *                       | 1.00       | 2.00  |         | 2.00     |
| # EXPANDING NUT *                       | 1.00       | 1.00  |         | 1.00     |
| # EXPANDING NUT *                       | 1.00       | 1.00  |         | 1.00     |
| RR BUMPER CARRIER                       | 445.75     | 1.00  |         | 445.75   |
| REAR TRIM UNDERRIDE PROTECTION (X L     | 97.40      | 1.00  |         | 97.40    |
| RR BUMPER LH CORNER MOUNTING            | 141.65     | 1.00  |         | 141.65   |
| RR BUMPER RH CORNER MOUNTING            | 141.65     | 1.00  |         | 141.65   |
| REAR BUMPER PANEL PRIMED                | 705.80     | 1.00  |         | 705.80   |
| # REAR BUMPER MIDDLE TRIM PANEL (PDC) * | 222.35     | 1.00  |         | 222.35   |
| REAR BUMPER TRIM BOTTOM (LINES)         | 211.75     | 1.00  |         | 211.75   |
| EMBLEM GROMMET                          | 0.80       | 2.00  |         | 1.60     |
| BMW PLAQUE WITH ADHESIVE FILM           | 67.80      | 1.00  |         | 67.80    |
| LETTERING X1                            | 61.05      | 1.00  |         | 61.05    |
| BOOTLID SEALING                         | 119.20     | 1.00  |         | 119.20   |
| # EXPANDING RIVET *                     | 1.35       | 20.00 |         | 27.00    |
| ULTRASONIC SENSOR BLACK                 | 248.70     | 1.00  |         | 248.70   |
| DECOUPING RING PDC TORQUE CONVERTER     | 5.05       | 1.00  |         | 5.05     |
| # BLIND RIVET AVIBVLB *                 | 0.55       | 20.00 |         | 11.00    |
| # (DG/SL) BODY ADHESIVE K5B (195ML) *   | 281.55     | 1.00  |         | 281.55   |
| # PUNCH RIVET N4 *                      | 0.55       | 20.00 |         | 11.00    |
| # (DG) BODYWORK ADHESIVE K5A (50ML) *   | 118.35     | 1.00  |         | 118.35   |
| # (DG) CLEANER R1 (100ML) *             | 23.85      | 1.00  |         | 23.85    |
| (DG) CLEANER R1 (100ML)                 | 23.85      | 1.00  |         | 23.85    |
| (DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)  | 131.55     | 2.00  |         | 263.10   |
| (DG/SL) GLASS PRIMER 30ML (VP206)       | 27.85      | 1.00  |         | 27.85    |
| (S/L) SEAM SEAL 300ML                   | 33.80      | 1.00  |         | 33.80    |

### # SUPPLEMENTARY ITEMS

|                                 |           |
|---------------------------------|-----------|
| Total Labour :                  | 13,223.00 |
| Total Parts :                   | 4,875.65  |
| Total Labour & Parts :          | 18,098.65 |
| Deduction for Excess :          | 0.00      |
| Total Repair Costs less Excess: | 18,098.65 |
| GST @7%:                        | 1,266.91  |
| Grand Total :                   | 19,365.56 |



## Vic (LKKAuto)

---

**From:** PBSP <pml-pbsp@simedarby.com.sg>  
**Sent:** Friday, 26 January, 2018 5:09 PM  
**To:** Rasul (LKKAuto); Vic (LKKAuto)  
**Subject:** FINAL REPORT / SLK7657J  
**Attachments:** Final Report SLK7657J.pdf, Final Report SLK7657J\_2.pdf

Dear Rasul and Vic

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 13,223.00  
Total Parts : 4,875.65  
Total Labour & Parts : 18,098.65

Repair days: 8

Thank you.

Regards,  
Caroline  
C/o Performance Motors Limited - Body and Paint  
303 Alexandra Road Singapore 159941  
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

## Vic (LKKAUTO)

---

**From:** Vic (LKKAUTO)  
**Sent:** Friday, 8 December, 2017 3:34 PM  
**To:** PBSP  
**Cc:** Admin A; Asher Sng (LKKAUTO); Vic (LKKAUTO)  
**Subject:** RE: REQ FOR DIRECT SETTLEMENT - SLK7657J AND SKH7719S ON 06/12/2017  
\*\*\*LKK REF:CC3/AIG17023201/hb3

Your Ref: SLK 7657J  
Our Ref: CC3/AIG17023201/hb3

"WITHOUT PREJUDICE"

Dear Caroline,

### ACCIDENT INVOLVING VEHICLES SKH 7719S AND SLK 7657J ON 06/12/2017

We refer to the above matter.

Please be informed that basing on the accident statements submitted by both party, the liability is clear subject to the BOLA guideline settlement.

Please note that this e-mail is on without prejudice basis which does not amount to an authorisation of repair to your client's vehicle and admission of any liability to our Insured's part. The final repair cost is subjected to the consistency of the damages according to the nature of the accident. And the days of LOU/ LOR will be based on the number of days of repair as recommended by our surveyor.

Kindly forward the LOD and all supporting documents to us if available to proceed with the settlement.

Thank you.


Best Regards,

**Vic Alpeh** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2096 | email: [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

---

**From:** PBSP [mailto:[pml-pbsp@simedarby.com.sg](mailto:pml-pbsp@simedarby.com.sg)]  
**Sent:** Friday, 8 December, 2017 9:33 AM  
**To:** Shu Pei (LKKAUTO); Vic (LKKAUTO)  
**Cc:** Admin A; CS A Team  
**Subject:** Re: REQ FOR DIRECT SETTLEMENT - SLK7657J AND SKH7719S ON 06/12/2017 \*\*\*LKK  
REF:CC3/AIG17023201/hb3

Dear Vic,

Please let us have your reply on liability.

Thank you.

Regards,  
Caroline  
C/o Performance Motors Limited - Body and Paint  
303 Alexandra Road Singapore 159941  
DID: 6319 0174 Fax: 6479 4601

---

**From:** Shu Pei (LKKAUTO) <shupeil@lkkauto.com>  
**Sent:** Wednesday, 6 December 2017 5:54 PM  
**To:** PBSP  
**Cc:** 甯瑒 ©; CS A Team  
**Subject:** RE: REQ FOR DIRECT SETTLEMENT - SLK7657J AND SKH7719S ON 06/12/2017 \*\*\*LKK  
REF:CC3/AIG17023201/hb3

Dear Caroline,

We refer to your email below.

Please be informed that we are currently **pending for our insured's GIA report.**

Kindly note that for liability, claim negotiation and settlement, please contact Vic at 6841 2096.

Our respective case handler will look into the matter and revert to you in due course.

Thank you

***To check availability of the case handler , you may contact the undersigned.***

Best Regards,  
Shu Pei | Admin  
LKK Auto Consultants Pte Ltd  
Phone: 6366-0055 | email: [shupeil@lkkauto.com](mailto:shupeil@lkkauto.com) | fax: 6741-4108  
Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** PBSP [<mailto:pml-pbsp@simedarby.com.sg>]  
**Sent:** Wednesday, 6 December, 2017 1:11 PM  
**To:** Admin A <[admin-a@lkkauto.com](mailto:admin-a@lkkauto.com)>; CS A Team <[cs-a@lkkauto.com](mailto:cs-a@lkkauto.com)>  
**Subject:** REQ FOR DIRECT SETTLEMENT - SLK7657J AND SKH7719S ON 06/12/2017

Dear Sirs,

We refer to the above matter.

We have instructions from our client to seek repair cost and loss of use/car rental from you through Direct Settlement.

Attached is the estimates and supporting documents for your consideration.

Please let us have your confirmation that you agree that liability is clear and we may proceed with Direct Settlement.

If Direct Settlement is approved, kindly let us have your offer for LOU / rental.

Thank you.

Regards,

Caroline

C/o Performance Motors Limited - Body and Paint

303 Alexandra Road Singapore 159941

DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

## Vic (LKKAuto)

---

**From:** Vic (LKKAuto)  
**Sent:** Monday, 3 September, 2018 3:04 PM  
**To:** PBSP  
**Cc:** Admin A; Vic (LKKAuto)  
**Subject:** RE: REQ FOR DIRECT SETTLEMENT - SLK7657J AND SKH7719S ON 06/12/2017  
\*\*\*LKK REF:CC3/AIG17023201/R1hb3

Without Prejudice

Dear Caroline,

We refer to the above matter.

Purely for an amicable settlement on a without prejudice basis and without admission of liability to our Insured's part, we have our principal's mandate and we confirmed acceptance of your offer of **\$20,123.56** (all in) to settle your client's claim.

Thank you.

*"Please note that our above offer and any settlement arising from the above offer are made on a without prejudice basis, and should not be construed as an admission of liability on our part or on the part of our Insured Driver. Terms of such settlement should also not be disclosed in any other related matter(s) in respect of the accident. Our offer made in respect of this present matter is made solely to resolve this matter only. No reference shall be made to this offer or any settlement arising from this offer in any other related matters."*


Best Regards,

**Vic Alpeh** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6841-2096 | email: [vicalpeh@lkkauto.com](mailto:vicalpeh@lkkauto.com) | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Auto  
Consultants  
Pte Ltd

*Save the Earth. Print only when necessary.*

This e-mail contain confidential and privileged material, and are for the sole use of the intended recipient. Use or distribution by an unintended recipient is prohibited, and may be a violation of law. If you believe that you received this e-mail in error, please do not read this e-mail or any attached items. Please delete the e-mail and all attachments, including any copies thereof, and inform the sender that you have deleted the e-mail, all attachments and any copies thereof. Thank you.

---

**From:** PBSP [mailto:[pml-pbsp@simedarby.com.sg](mailto:pml-pbsp@simedarby.com.sg)]  
**Sent:** Thursday, 16 August, 2018 6:31 PM  
**To:** Vic (LKKAuto)  
**Cc:** Admin A; Asher Sng (LKKAuto)  
**Subject:** Re: REQ FOR DIRECT SETTLEMENT - SLK7657J AND SKH7719S ON 06/12/2017 \*\*\*LKK  
REF:CC3/AIG17023201/hb3

Dear Vic

We understand that AIG Insurance is using Benchmark 2016.

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

## CLAIM SUBFOLDER TRACKING

| Case | Notified                                | Est Submitted | Adj Assigned   | Adj Rpt   | Adj Submitted                                   | Ins Auth'd | Status  |
|------|---|---------------|--|---|---|------------|---|
| Main | 06 Dec 2017<br><a href="#">Edit Reg</a> |               | 05 Jan 2018<br>00:00<br><a href="#">Edit Adj Rpt</a> | <b>S\$18,098.65</b><br><a href="#">Edit Estimates</a> | <b>S\$18,098.65</b><br><a href="#">View Rpt</a> |            | <b>Pending for Survey Report</b><br><a href="#">Cancel Case</a> |

Main

Reference

Claim Details

Documents

[Show All](#)

## CLAIM SUBFOLDER DETAILS

[Created by adjuster]

|                             |  |                        |  |
|-----------------------------|--|------------------------|--|
| Insured:                    | <b>KARAN SOOD</b> , ID: G5386595Q, Tel: +6597831789  |                        |  |
| Main Claimant:              | <b>PEH CHEE BENG</b> , ID: S7614280G   |                        |  |
| Vehicle Reg. No.:           | <b>SLK7657J</b>  | Date of Loss:          | 06/12/2017 09:00 - :59<br>[10 Months and 11 Days From LTA Reg Date (Man Yr)] |
| Claim Type:                 | <b>TP / 9130398394SG</b>   | Policy/Cover Note No.: | 2100426009   |
| Vehicle Reg. No. (Insured): | <b>SKH7719S</b>  | Policy No. (Claimant): | SD17V02300   |
|                             |  | Excess:                |  |
| Repairer:                   | <b>Performance Motors Limited (Alexandra)</b> 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174 |                        |  |
| Handling Insurer:           | <b>AIG Asia Pacific Insurance Pte. Ltd. (Express)</b> - Tel: 65-6419-3000 ... [Handled by <b>Lee, Ming-Yao</b> ] MingYao.Lee@aig.com       |                        |  |
| Claimant's Insurer:         | <b>Liberty Insurance Pte Ltd (HQ)</b> - Tel: 6221 8611   |                        |  |
| Adjuster:                   | <b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD RASUL</b> ] ... [Final Rpt due 15/12/2017]               |                        |  |
| Driver/Custodian (Insured): | KANGAN (), NRIC: G5386600Q   |                        |  |

## ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG\_SG\_EXPRESS (03/09/2018): **Alert - Adj Mandate Approved (S\$20123.56) - SLK7657J - Claim Handler: Lee, Ming-...**
- AIG\_SG\_EXPRESS (01/06/2018): **Alert - Adj Mandate Approved (S\$19943.56) - SLK7657J - Claim Handler: Lee, Ming-...**

## ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|----------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
|----------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|

No results.





## Claim Documents

**\*SLK7657J (9130398394SG)**  
**[SKH7719S]**  
**TP**  
**PEH CHEE BENG**  
**Dec 6 2017 9:00AM**  
**[KARAN SOOD]**  
**Performance Motors Limited**

|                         |                 |   |               |  |  |                    |  |  |              |  |  |              |  |  |            |                                     |                                     |                 |  |  |
|-------------------------|-----------------|---|---------------|--|--|--------------------|--|--|--------------|--|--|--------------|--|--|------------|-------------------------------------|-------------------------------------|-----------------|--|--|
| Upload Documents        |                 |   | Upload Photos |  |  | Compose New Letter |  |  | Upload Video |  |  | Upload Audio |  |  | View       |                                     |                                     | View in Browser |  |  |
| Letters/Correspondences |                 |   |               |  |  |                    |  |  |              |  |  |              |  |  | 1 per page |                                     | <input checked="" type="checkbox"/> |                 |  |  |
| No                      | Finalized On    | LKK Auto Consultants Pte Ltd (HQ)                                       |               |  |  |                    |  |  |              |  |  |              |  |  | Thumbnail  | Print                               |                                     |                 |  |  |
| 1                       | (Draft)         | Third Party Express Settlement – Payment Breakdown                      |               |  |  |                    |  |  |              |  |  |              |  |  | Edit       |                                     |                                     |                 |  |  |
| Assessment Reports      |                 |   |               |  |  |                    |  |  |              |  |  |              |  |  | 1 per page |                                     | <input checked="" type="checkbox"/> |                 |  |  |
| No                      | Finalized On    | AIG Asia Pacific Insurance Pte. Ltd. (SG)                               |               |  |  |                    |  |  |              |  |  |              |  |  | Thumbnail  | Print                               |                                     |                 |  |  |
| 1                       | 07/12/17 10:06  | Accident Statement<br>From:SC - Reg. No: SKH7719S, Claimant: KARAN SOOD |               |  |  |                    |  |  |              |  |  |              |  |  | Load HTM   |                                     |                                     |                 |  |  |
| Photos/Images           |                 |   |               |  |  |                    |  |  |              |  |  |              |  |  | 3 per page |                                     | <input checked="" type="checkbox"/> |                 |  |  |
| No                      | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ)                                       |               |  |  |                    |  |  |              |  |  |              |  |  | Thumbnail  | Print                               |                                     |                 |  |  |
| 1                       | 14/03/18 10:27  | Odometer Reading  |               |  |  |                    |  |  |              |  |  |              |  |  | Load JPG   | <input checked="" type="checkbox"/> |                                     |                 |  |  |
| 2                       | 14/03/18 10:27  | Chassis Number  |               |  |  |                    |  |  |              |  |  |              |  |  | Load JPG   | <input checked="" type="checkbox"/> |                                     |                 |  |  |
| 3                       | 14/03/18 10:27  | General View  |               |  |  |                    |  |  |              |  |  |              |  |  | Load JPG   | <input checked="" type="checkbox"/> |                                     |                 |  |  |
| 4                       | 14/03/18 10:27  | General View  |               |  |  |                    |  |  |              |  |  |              |  |  | Load JPG   | <input checked="" type="checkbox"/> |                                     |                 |  |  |
| 5                       | 14/03/18 10:27  | General View  |               |  |  |                    |  |  |              |  |  |              |  |  | Load JPG   | <input checked="" type="checkbox"/> |                                     |                 |  |  |
| 6                       | 14/03/18 10:27  | General View  |               |  |  |                    |  |  |              |  |  |              |  |  | Load JPG   | <input checked="" type="checkbox"/> |                                     |                 |  |  |
| 7                       | 14/03/18 10:27  | General View  |               |  |  |                    |  |  |              |  |  |              |  |  | Load JPG   | <input checked="" type="checkbox"/> |                                     |                 |  |  |
| 8                       | 14/03/18 10:27  | General View  |               |  |  |                    |  |  |              |  |  |              |  |  | Load JPG   | <input checked="" type="checkbox"/> |                                     |                 |  |  |
| 9                       | 14/03/18 10:27  | General View  |               |  |  |                    |  |  |              |  |  |              |  |  | Load JPG   | <input checked="" type="checkbox"/> |                                     |                 |  |  |
| 10                      | 14/03/18 10:27  | General View  |               |  |  |                    |  |  |              |  |  |              |  |  | Load JPG   | <input checked="" type="checkbox"/> |                                     |                 |  |  |
| 11                      | 14/03/18 10:27  | General View  |               |  |  |                    |  |  |              |  |  |              |  |  | Load JPG   | <input checked="" type="checkbox"/> |                                     |                 |  |  |
| 12                      | 14/03/18 10:27  | General View  |               |  |  |                    |  |  |              |  |  |              |  |  | Load JPG   | <input checked="" type="checkbox"/> |                                     |                 |  |  |
| 13                      | 14/03/18 10:28  | General View  |               |  |  |                    |  |  |              |  |  |              |  |  | Load JPG   | <input checked="" type="checkbox"/> |                                     |                 |  |  |
| 14                      | 14/03/18 10:28  | General View  |               |  |  |                    |  |  |              |  |  |              |  |  | Load JPG   | <input checked="" type="checkbox"/> |                                     |                 |  |  |
| 15                      | 14/03/18 10:28  | General View  |               |  |  |                    |  |  |              |  |  |              |  |  | Load JPG   | <input checked="" type="checkbox"/> |                                     |                 |  |  |
| 16                      | 14/03/18 10:28  | General View  |               |  |  |                    |  |  |              |  |  |              |  |  | Load JPG   | <input checked="" type="checkbox"/> |                                     |                 |  |  |
| 17                      | 14/03/18 10:28  | General View  |               |  |  |                    |  |  |              |  |  |              |  |  | Load JPG   | <input checked="" type="checkbox"/> |                                     |                 |  |  |
| 18                      | 14/03/18 10:28  | General View  |               |  |  |                    |  |  |              |  |  |              |  |  | Load JPG   | <input checked="" type="checkbox"/> |                                     |                 |  |  |
| 19                      | 14/03/18 10:28  | General View  |               |  |  |                    |  |  |              |  |  |              |  |  | Load JPG   | <input checked="" type="checkbox"/> |                                     |                 |  |  |
| 20                      | 14/03/18 10:28  | General View  |               |  |  |                    |  |  |              |  |  |              |  |  | Load JPG   | <input checked="" type="checkbox"/> |                                     |                 |  |  |
| 21                      | 14/03/18 10:28  | General View  |               |  |  |                    |  |  |              |  |  |              |  |  | Load JPG   | <input checked="" type="checkbox"/> |                                     |                 |  |  |
| 22                      | 14/03/18 10:28  | General View  |               |  |  |                    |  |  |              |  |  |              |  |  | Load JPG   | <input checked="" type="checkbox"/> |                                     |                 |  |  |
| 23                      | 14/03/18 10:28  | General View  |               |  |  |                    |  |  |              |  |  |              |  |  | Load JPG   | <input checked="" type="checkbox"/> |                                     |                 |  |  |
| 24                      | 14/03/18 10:28  | General View  |               |  |  |                    |  |  |              |  |  |              |  |  | Load JPG   | <input checked="" type="checkbox"/> |                                     |                 |  |  |
| 25                      | 14/03/18 10:28  | General View  |               |  |  |                    |  |  |              |  |  |              |  |  | Load JPG   | <input checked="" type="checkbox"/> |                                     |                 |  |  |
| 26                      | 14/03/18 10:28  | General View  |               |  |  |                    |  |  |              |  |  |              |  |  | Load JPG   | <input checked="" type="checkbox"/> |                                     |                 |  |  |
| 27                      | 14/03/18 10:28  | General View  |               |  |  |                    |  |  |              |  |  |              |  |  | Load JPG   | <input checked="" type="checkbox"/> |                                     |                 |  |  |
| 28                      | 14/03/18 10:28  | General View  |               |  |  |                    |  |  |              |  |  |              |  |  | Load JPG   | <input checked="" type="checkbox"/> |                                     |                 |  |  |

| Letters/Correspondences |                |                                   | 1 per page ▼ |       |
|-------------------------|----------------|-----------------------------------|--------------|-------|
| No                      | Finalized On   | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail    | Print |
| 29                      | 14/03/18 10:28 | General View                      | Load JPG     |       |
| 30                      | 14/03/18 10:28 | General View                      | Load JPG     |       |
| 31                      | 14/03/18 10:28 | General View                      | Load JPG     |       |
| 32                      | 14/03/18 10:28 | General View                      | Load JPG     |       |
| 33                      | 14/03/18 10:28 | General View                      | Load JPG     |       |
| 34                      | 14/03/18 10:28 | General View                      | Load JPG     |       |
| 35                      | 14/03/18 10:28 | General View                      | Load JPG     |       |
| 36                      | 14/03/18 10:28 | General View                      | Load JPG     |       |
| 37                      | 14/03/18 10:28 | General View                      | Load JPG     |       |
| 38                      | 14/03/18 10:28 | General View                      | Load JPG     |       |
| 39                      | 14/03/18 10:28 | General View                      | Load JPG     |       |
| 40                      | 14/03/18 10:28 | General View                      | Load JPG     |       |
| 41                      | 14/03/18 10:28 | Reinspection Photo                | Load JPG     |       |
| 42                      | 14/03/18 10:28 | Reinspection Photo                | Load JPG     |       |
| 43                      | 14/03/18 10:28 | Reinspection Photo                | Load JPG     |       |
| 44                      | 14/03/18 10:28 | Reinspection Photo                | Load JPG     |       |
| 45                      | 14/03/18 10:28 | Reinspection Photo                | Load JPG     |       |
| 46                      | 14/03/18 10:28 | Reinspection Photo                | Load JPG     |       |
| 47                      | 14/03/18 10:28 | Reinspection Photo                | Load JPG     |       |
| 48                      | 14/03/18 10:28 | Reinspection Photo                | Load JPG     |       |
| 49                      | 14/03/18 10:28 | Reinspection Photo                | Load JPG     |       |
| 50                      | 14/03/18 10:28 | Reinspection Photo                | Load JPG     |       |
| 51                      | 14/03/18 10:28 | Reinspection Photo                | Load JPG     |       |
| 52                      | 14/03/18 10:28 | Reinspection Photo                | Load JPG     |       |
| 53                      | 14/03/18 10:28 | Reinspection Photo                | Load JPG     |       |
| 54                      | 14/03/18 10:28 | Reinspection Photo                | Load JPG     |       |
| 55                      | 14/03/18 10:28 | Reinspection Photo                | Load JPG     |       |
| 56                      | 14/03/18 10:28 | Reinspection Photo                | Load JPG     |       |
| 57                      | 14/03/18 10:28 | Reinspection Photo                | Load JPG     |       |
| 58                      | 14/03/18 10:28 | Reinspection Photo                | Load JPG     |       |
| 59                      | 14/03/18 10:28 | Reinspection Photo                | Load JPG     |       |
| 60                      | 14/03/18 10:28 | Reinspection Photo                | Load JPG     |       |
| 61                      | 14/03/18 10:28 | Reinspection Photo                | Load JPG     |       |
| 62                      | 14/03/18 10:28 | Reinspection Photo                | Load JPG     |       |
| 63                      | 14/03/18 10:28 | Reinspection Photo                | Load JPG     |       |
| 64                      | 14/03/18 10:28 | Reinspection Photo                | Load JPG     |       |
| 65                      | 14/03/18 10:28 | Reinspection Photo                | Load JPG     |       |
| 66                      | 14/03/18 10:28 | Reinspection Photo                | Load JPG     |       |
| 67                      | 14/03/18 10:28 | Reinspection Photo                | Load JPG     |       |
| 68                      | 14/03/18 10:28 | Reinspection Photo                | Load JPG     |       |
| 69                      | 14/03/18 10:28 | Reinspection Photo                | Load JPG     |       |
| 70                      | 14/03/18 10:28 | Reinspection Photo                | Load JPG     |       |
| 71                      | 14/03/18 10:28 | Reinspection Photo                | Load JPG     |       |
| 72                      | 14/03/18 10:28 | Reinspection Photo                | Load JPG     |       |
| 73                      | 14/03/18 10:28 | Reinspection Photo                | Load JPG     |       |
| 74                      | 14/03/18 10:28 | Reinspection Photo                | Load JPG     |       |
| 75                      | 14/03/18 10:28 | Reinspection Photo                | Load JPG     |       |

| Letters/Correspondences |                 |                                   | 1 per page ▼ | ✓     |
|-------------------------|-----------------|-----------------------------------|--------------|-------|
| No                      | Finalized On    | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail    | Print |
| Documentation           |                 |                                   | 1 per page ▼ | ✓     |
| No                      | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail    | Print |
| 1                       | 06/12/17 17:33  | TP ESTIMATE                       | Load TIF     |       |
| 2                       | 06/12/17 17:33  | TP GIA REPORT                     | Load PDF     |       |
| 3                       | 08/12/17 15:51  | LETTER TO OI                      | Load PDF     |       |
| 4                       | 08/12/17 15:51  | EMAIL TO OI                       | Load PDF     |       |
| 5                       | 09/01/18 18:00  | TP ESTIMATE- MARKED               | Load PDF     |       |
| 6                       | 26/04/18 17:30  | GIA SEARCH                        | Load PDF     |       |
| 7                       | 26/04/18 17:30  | MEDICAL FEE                       | Load PDF     |       |
| 8                       | 26/04/18 17:30  | RENTAL RECEIPT                    | Load PDF     |       |
| 9                       | 03/09/18 15:00  | CLAIMANT'S NRIC                   | Load PDF     |       |
| 10                      | 04/09/18 11:59  | AUTHORISATION TO ACT              | Load PDF     |       |
| 11                      | 04/09/18 11:59  | RELEASE VOUCHER                   | Load PDF     |       |
| 12                      | 04/09/18 11:59  | WORKSHOP INVOICE                  | Load PDF     |       |

## Documents Checklist

| DOCUMENTS CHECKLIST                          | Reset | Save | Print |
|--|-------|------|-------|
| There are no document checklists configured. |       |      |       |

### Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM \_\_\_\_\_

### THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

|                   |                     |        |                           |
|-------------------|---------------------|--------|---------------------------|
| Vehicle No:       | SKH7719S (Insd veh) | Model: | BMW X1 1.5 SDRIVE 18i (A) |
|                   | SLK7657J (TP veh)   |        |                           |
| Date of Accident: | 06/12/2017          |        |                           |

|   |      |   |  |
|---|------|---|--|
| Global Sum Settlement   | :    | <input type="checkbox"/> Yes                                    | <input checked="" type="checkbox"/> No |
| Repair Estimate   | : \$ | 23,866.14   |  |
| Final Repair Cost   | : \$ | 19,365.56   |  |
| Loss of Use   | : \$ | 720.00  | 9.00 days at \$80.00 per day           |
| Rental (if any)   | : \$ |   | days                                   |
| LTA / GIA Search Fee  | : \$ | 2.00  |  |
| Medical Fee:  | : \$ | 36.00   |  |
|   | : \$ |   |  |
| Final Settlement Sum  | : \$ | 20,123.56   |  |
| Is Third Party Workshop GIA Registered? <input checked="" type="checkbox"/> YES <input type="checkbox"/> NO (Kindly indicate below) |      |   |  |
| A) For <u>Non GIA Registered Workshop</u> :   |      | Agreed Liability _____ (%)                                      |  |
| B) For <u>GIA Registered Workshop</u> :   |      | BOLA Applicable: Yes/ <del>No</del> BOLA Scenario No: <u>27</u> |  |
| BOLA Liability: <u>100</u> (%)  |      | Assessed Liability (*): _____ (%)                               |  |
| * Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.                                |      |   |  |
| Remarks _____   |      |   |  |

#### Payment Instruction: Payee's Breakdown

|    |                             |      |           |
|----|-----------------------------|------|-----------|
| 1) | Performance Motors Limited  | : \$ | 20,087.56 |
| 2) | PEH CHEE BENG (BAI ZHIMING) | : \$ | 36.00     |
| 3) |                             | : \$ |           |
| 4) |                             | : \$ |           |

NUR SHAQILAH BTE ABDOL WAHAB

04 Sep  
2018

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG17023201/R1HB3S2

Date: 04/09/2018

## REFERENCE

|                       |                                      |                      |              |
|-----------------------|--------------------------------------|----------------------|--------------|
| Handling Insurer:     | AIG Asia Pacific Insurance Pte. Ltd. | Policy No:           | 2100426009   |
| Claimant Vehicle No : | SLK7657J                             | Insured Vehicle No : | SKH7719S     |
| Date of Loss:         | 06/12/2017                           | Nature of Claim:     | TP           |
|                       |                                      | Claim No:            | 9130398394SG |

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

|                             |                              |             |                   |
|-----------------------------|------------------------------|-------------|-------------------|
| Reg No:                     | SLK7657J                     | Engine No:  | F868H370B38A15A   |
| Make & Model:               | BMW X1, 1.5 SDRIVE 18i (A)   | Chassis No: | WBAHS120305F03606 |
| Reg. Date:                  | 25/01/2017 (Man. Year: 2016) | Odometer:   | 25496 km          |
| Colour:                     | Grey                         |             |                   |
| Engine Capacity:            | 1499 cc                      |             |                   |
| Market Value/New Car Price: | N/A                          |             |                   |
| Sum Insured (S\$):          | Market Value/New Car Price   |             |                   |

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

|                          |      |                         |     |                          |     |
|--------------------------|------|-------------------------|-----|--------------------------|-----|
| General Condition:       | Fair | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes  | Engine Modification:    | No  | Pre-accident Condition:  |     |

## CONDITION OF TYRES

|                   |                  |                  |                  |
|-------------------|------------------|------------------|------------------|
| Front Tyre Size:  | 225/50R18        | Rear Tyre Size:  | 225/50R18        |
| Front Left Side:  | Bridgestone 6 mm | Rear Left Side:  | Bridgestone 6 mm |
| Front Right Side: | Bridgestone 6 mm | Rear Right Side: | Bridgestone 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS                                  | Repairer's       | Adjuster's       | Difference      | Diff %       |
|---|------------------|------------------|-----------------|--------------|
| Parts   | 6,452.80         | 5,025.65         | 1,427.15        | 22.12        |
| Miscellaneous Items                             | 0.00             | 0.00             | 0.00            |              |
| Labour  | 15,852.00        | 13,073.00        | 2,779.00        | 17.53        |
| Paintwork Labour                                | 0.00             | 0.00             | 0.00            |              |
| Towing  | 0.00             | 0.00             | 0.00            |              |
| <b>Gross Total (S\$)</b>                        | <b>22,304.80</b> | <b>18,098.65</b> | <b>4,206.15</b> | <b>18.86</b> |
| <b>+ GST 7.00/7.00% (S\$)</b>                   | <b>1,561.34</b>  | <b>1,266.91</b>  | <b>294.43</b>   | <b>18.86</b> |
| <b>Nett Amount (S\$)</b>                        | <b>23,866.14</b> | <b>19,365.56</b> | <b>4,500.58</b> | <b>18.86</b> |
| <b>+ Loss of Use (9.0 x S\$80.00/day) (S\$)</b> |                  | 720.00           |                 |              |
| <b>+ Doc/Search Fee (S\$)</b>                   |                  | 2.00             |                 |              |
| <b>+ Other Costs (S\$)</b>                      |                  | 36.00            |                 |              |
| <b>Nett Liability (S\$)</b>                     |                  | <b>20,123.56</b> |                 |              |

## INSPECTION

|                             |                          |   |
|-----------------------------|--------------------------|---|
| Date of Assignment:         | 05/01/2018               | Performance Motors Limited (Alexandra)            |
| Date Inspected:             | 05/01/2018 Inspected At: | 303 Alexandra Road, Sime Darby Performance Centre |
| Estimated Period of Repair: | 8.0 days                 | Singapore 159941                                  |



9/4/2018

Adjuster Report

**Adjuster:** MOHD RASUL

**Manager:** VIC ALPEH

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

# REPAIR DETAILS

## Recommended Parts

| No. | Qty | Part No. | Particulars                                  | Condition          | Repairer's  | Amount       |
|-----|-----|----------|--|--------------------|-------------|--------------|
| 1   | 1   |          | *BOOTLID                                     | Buckled            | 1,171.20 FS | *1,171.20 FS |
| 2   | 1   |          | *INTERIOR TAIL TRIM                          | Serviceable        | 315.65 FS   | *- FS        |
| 3   | 1   |          | *TAIL PANEL                                  | Bent               | 401.75 FS   | *401.75 FS   |
| 4   | 1   |          | *REAR LH BUMPER MOUNT                        | Serviceable        | 141.65 FS   | *- FS        |
| 5   | 1   |          | *REAR RH BUMPER MOUNT                        | Serviceable        | 141.65 FS   | *- FS        |
| 6   | 1   |          | *RR BUMPER CARRIER                           | Bent               | 445.75 FS   | *445.75 FS   |
| 7   | 1   |          | *MOUNTING SMART OPENER                       | Serviceable        | 35.70 FS    | *- FS        |
| 8   | 1   |          | *REAR TRIM UNDERRIDE PROTECTION (XL          | Scratched          | 97.40 FS    | *97.40 FS    |
| 9   | 1   |          | *RR BUMPER LH CORNER MOUNTING                | Cracked            | 141.65 FS   | *141.65 FS   |
| 10  | 1   |          | *RR BUMPER RH CORNER MOUNTING                | Cracked            | 141.65 FS   | *141.65 FS   |
| 11  | 1   |          | *REAR BUMPER PANEL PRIMED                    | Deformed           | 705.80 FS   | *705.80 FS   |
| 12  | 1   |          | *REAR BUMPER MIDDLE TRIM PANE                | Scratched          | 222.35 FS   | *222.35 FS   |
| 13  | 1   |          | *REAR BUMPER TRIM BOTTOM (LINES)             | Scratched          | 211.75 FS   | *211.75 FS   |
| 14  | 2   |          | *EMBLEM GROMMET                              | Necessary          | 1.60 FS     | *1.60 FS     |
| 15  | 1   |          | *BMW PLAQUE WITH ADHESIVE FILM               | Necessary          | 67.80 FS    | *67.80 FS    |
| 16  | 1   |          | *LETTERING X1                                | Necessary          | 61.05 FS    | *61.05 FS    |
| 17  | 1   |          | *REAR BUMPER TOWING EYE COVER                | Serviceable        | 29.20 FS    | *- FS        |
| 18  | 1   |          | *REAR BUMPER HEAT INSULATION                 | Serviceable        | 66.20 FS    | *- FS        |
| 19  | 1   |          | *BOOTLID SEALING                             | Necessary          | 119.20 FS   | *119.20 FS   |
| 20  | 1   |          | *SENSOR WIRE FOR SMART OPENER TOP            | Serviceable        | 42.10 FS    | *- FS        |
| 21  | 1   |          | *SENSOR WIRE FOR SMART OPENER BOTTOM         | Serviceable        | 40.50 FS    | *- FS        |
| 22  | 1   |          | *REAR LH REFLECTOR                           | Serviceable        | 35.40 FS    | *- FS        |
| 23  | 1   |          | *REAR RH REFLECTOR                           | Serviceable        | 35.40 FS    | *- FS        |
| 24  | 2   |          | *ULTRASONIC SENSOR BLACK                     | Missing 1pc Only   | 497.40 FS   | *248.70 FS   |
| 25  | 1   |          | *DECOUPING RING PDC TORQUE CONVERTER<br>2pcs | Necessary 1pc Only | 10.10 FS    | *5.05 FS     |
| 26  | 1   |          | *{(DG) CLEANER R1 (100ML)                    | Necessary          | 23.85 FS    | *23.85 FS    |
| 27  | 2   |          | *{(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)     | Necessary          | 263.10 FS   | *263.10 FS   |
| 28  | 1   |          | *{(DG/SL) GLASS PRIMER 30ML (VP206)          | Necessary          | 27.85 FS    | *27.85 FS    |
| 29  | 1   |          | *{(S/L) SEAM SEAL 300ML<br>3pcs              | Necessary          | 101.40 FS   | *33.80 FS    |
| 30  | 1   |          | *SUNDRIES                                    | Necessary          | 150.00 FS   | *150.00 FS   |
| 31  | 1   |          | *BLIND RIVET NUT M6                          | Necessary          | 2.60 FS     | *2.60 FS     |
| 32  | 10  |          | *RIVET                                       | Necessary          | 5.00 FS     | *5.00 FS     |
| 33  | 2   |          | *EXPANDING NUT                               | Necessary          | 2.00 FS     | *2.00 FS     |
| 34  | 1   |          | *EXPANDING NUT                               | Necessary          | 1.00 FS     | *1.00 FS     |
| 35  | 1   |          | *EXPANDING NUT                               | Necessary          | 1.00 FS     | *1.00 FS     |
| 36  | 20  |          | *EXPANDING RIVET                             | Necessary          | 27.00 FS    | *27.00 FS    |
| 37  | 20  |          | *BLIND RIVET AVIBVLB                         | Necessary          | 11.00 FS    | *11.00 FS    |
| 38  | 1   |          | *{(DG/SL) BODY ADHESIVE K5B (195ML)          | Necessary          | 281.55 FS   | *281.55 FS   |
| 39  | 20  |          | *PUNCH RIVET N4                              | Necessary          | 11.00 FS    | *11.00 FS    |
| 40  | 1   |          | *{(DG) BODYWORK ADHESIVE K5A (50ML)          | Necessary          | 118.35 FS   | *118.35 FS   |
| 41  | 1   |          | *{(DG) CLEANER R1 (100ML)                    | Necessary          | 23.85 FS    | *23.85 FS    |
| 42  | 1   |          | *REAR BUMPER MIDDLE TRIM PANEL (PDC)         | Repeated           | 222.35 FS   | *- FS        |

F=Franchise part. S=SpcNett.

**Total Parts (\$\$)**      **6,452.80**      **5,025.65**

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

| No                              | Particulars   | Lab.Type | Repairer's       | Amount           |
|---------------------------------|---|----------|------------------|------------------|
| <b>Labour Items</b>             |   |          |                  |                  |
| 1                               | TO REPLACE REAR BUMPER, & ATTACHMENTS, BOOT LID, TAIL END PANEL AND TO KNOCK OUT DENTED AREA CAUSED BY THE ACCIDENT. TO MAKE GOOD THE REAR LH/RH FENDER, TRUNK FLOOR PLATE TO PULL STRAIGHTEN ON ACCIDENT AREA. | New      | 5,950.00         | 5,100.00         |
| 2                               | TO RESPRAY REAR BUMPER, BOOT LID, TAIL PANEL, REAR LEFT FENDER, REAR RIGHT FENDER AND BOOT COMPARTMENT.   | New      | 5,640.00         | 5,076.00         |
| 3                               | TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS.  | New      | 271.00           | 231.00           |
| 4                               | TO REPLACE BOOTLID SMART OPENER TOP AND BOTTOM SENSOR LINES INCLUDING PROGRAM AND CONDUCT CHECKS FOR PROPER FUNCTION.   | New      | 661.00           | 0.00             |
| 5                               | TO TRANSFER LOCK MECHANISM FROM OLD TO NEW BOOTLID INCLUDING CONDUCT CHECKS ON NEW BOOTLID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION.  | New      | 531.00           | 451.00           |
| 6                               | TO REMOVE AND INSTALL REAR WINDSCREEN GLASS INCLUDING CONDUCT WATER LEAK TESTS.   | New      | 649.00           | 649.00           |
| 7                               | TO REMOVE AND INSTALL FUSE BOX AT THE REAR SECTION TO FACILITATE REPAIRS.   | New      | 531.00           | 0.00             |
| 8                               | TO RECONNECT ELECTRICAL COMPONENTS AND WIRINGS AT THE REAR SECTION INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION.  | New      | 354.00           | 301.00           |
| 9                               | TO CARRY OUT BODY CAVITY PRESERVATION. (PER PANEL)  | New      | 100.00           | 100.00           |
| 10                              | TO CARRY OUT BODY CAVITY PRESERVATION. (FOR CUT PANEL)  | New      | 451.00           | 451.00           |
| 11                              | TO REMOVE OLD PDC ASSEMBLY, REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDE CONDUCTING CHECKS FOR PROPER FUNCTION.  | New      | 150.00           | 150.00           |
| 12                              | TO MOUNT VEHICLE ON SPEED BENCH TO FACILITATE RE-ALIGNMENT OF BODY / CHASSIS IN ACCORDANCE WITH BMW SPECIFICATIONS.   | New      | 564.00           | 564.00           |
| <b>Gross Labour Cost (\$\$)</b> |   |          | <b>15,852.00</b> | <b>13,073.00</b> |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >