

**LIU'S BROTHER AUTO ENGINEERING WORKSHOP**

No. 1 Kaki Bukit Avenue 5 #01-01, Auto Bay @ Kaki Bukit Singapore 417982

ROB No: 55291793 / Tel: 6741-3720 / 731 / Fax: 6741-5746 Email: liubro@jglobal.com

Invoice/Ref No: YN8457T171122

Estimate

Customer:

Name: AIG Asia Pacific Insurance Pte Ltd

Address: Motor Claims Department

78 Shenton Way #07-16

AIG Building Singapore 079120

Date: 06-12-17

Vehicle No: YN8457T

Model/Make: Mitsubishi Canter

FEB21ER4SDEB (CBU)

Item No.	Descriptions Of Parts	Original Quotation / Estimation	Revised Quotation / Cost Of Repair
1	Rear Rh Tailgate Outer Fibers Panel	\$ 600.00	SN
2	Pillar Outer Fibers	\$ 400.00	SN
3	Tail Lamp	\$ 245.00	X
	Remove and refix rear tailgate components & wiper mechanism	\$ 120.00	X
	To check all wiring & electrical component for proper function	\$ 30.00	20
	Labor for Panel Beating, Cut, Weld, Straighten & Replacing Parts Etc	\$ 800.00	600
	To putty & spray painting & including touch up paint on accident affected areas	\$ 600.00	400

Total Parts & Labour of estimate for damaged vehicle

\$ 2,795.00

Total amount in Lump Sum Basis for repaired vehicle

\$ -

SDLS:

not Agent
rule

M/s Liu's Brother Auto Engrg Wks

Lump Sum \$ 1600

3 day.

when 2nd after rep

8/12/17

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: