

PLEASE ARRANGE TO SURVEY
VEHICLE AT 22 TAMPINES ST 92 (S
528876)

Jimmy Goh K1
CLAIM DEPARTMENT
DID : 66547618
FAX :

Date : 06/12/2017
To : FWD SINGAPORE PTE. LTD.

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ANUJIT PRASAD
DIRECT ASIA INSURANCE(SINGAPORE) PTE LTD
Certificate No : MT/00193776/03 Accident Date : 01/12/2017
Vehicle No : SJG-5013-A Make & Model : CHEVROLET AVEO 1.5S FL 1498 cc

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
<u>List Item</u>			
1	BOOTLID 1220	1,382.00	✓
1	BOOTLID HINGE RH	85.00	X
1	BOOTLID HINGE LH	85.00	X
1	BOOTLID INSULATOR	306.00	X
10	BOOTLID INSULATOR CLIPS	65.00	X
1	BOOTLID WEATHER STRIP	89.00	✓
1	BOOTLID LOCK	304.00	✓
1	BOOTLID LOGO	95.00	✓
1	BOOTLID EMBLEM "CHEVROLET"	69.00	✓

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Date : 06/12/2017
To : FWD SINGAPORE PTE. LTD.

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ANUJIT PRASAD
: DIRECT ASIA INSURANCE(SINGAPORE) PTE LTD
Certificate No : MT/00193776/03 Accident Date : 01/12/2017
Vehicle No : SJG-5013-A Make & Model : CHEVROLET AVEO 1.5S FL 1498 cc

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	BOOTLID EMBLEM "AVEO"	62.00	
1	TAIL LAMP ASSY (RH)	495.00	
1	TAIL LAMP INNER PANEL (RH)	RESTORE	
1	REAR BUMPER ASSY 1080	1,254.00	
10	REAR BUMPER CLIPS	45.00	
1	REAR END PANEL	668.00	
1	REAR END PANEL TOP GARNISH	94.00	
1	REAR FENDER (RH)	RESTORE	
1	REAR FENDER INNER SHIELD (RH)	38.00	
10	REAR FENDER INNER SHIELD CLIPS	45.00	

Date : 06/12/2017
To : FWD SINGAPORE PTE. LTD.

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ANUJIT PRASAD
: DIRECT ASIA INSURANCE(SINGAPORE) PTE LTD
Certificate No : MT/00193776/03 Accident Date : 01/12/2017
Vehicle No : SJG-5013-A Make & Model : CHEVROLET AVEO 1.5S FL 1498 cc

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
1	REAR MUD FLAP (R/H)	29.00	✓
	Sub Total	5210.00	
	Discount 10% On Parts	(521.00)	
	Special Nett Item		
1	REAR END PANEL SEALANT	60.00	SD SW
1	REAR NUMBER PLATE & HOLDER	45.00	X
1	REVERSE SENSOR	220.00	2.2K ✓
	Sub Total	325.00	
	Labour & Misc		
	LABOUR TO FACILITATE REPAIR	800.00	600

Date : 06/12/2017
To : FWD SINGAPORE PTE. LTD.

ESTIMATION

Attn : Motor Claim Department

FAX :

Owner : ANUJIT PRASAD
: DIRECT ASIA INSURANCE(SINGAPORE) PTE LTD
Certificate No : MT/00193776/03 Accident Date : 01/12/2017
Vehicle No : SJG-5013-A Make & Model : CHEVROLET AVEO 1.5S FL 1498 cc

ESTIMATED REPAIR COST DETAILS

Excess : 0.00 Add Excess : 0.00

QTY	DESCRIPTION	REPAIRER AMT (\$)	SURVEYOR APP.
	TO REMOVE & INSTALL ALL REAR BOOT LID COMPONENT TO FACILITATE REPAIRS	80.00	60
	TO DETACH & RENEW REVERSE SENSOR	40.00	✓
	TO REMOVE & INSTALL SPARE TYRE BOARD & TRIMS TO FACILITATE REPAIR	80.00	60
	TO RUST PROOF AFFECTED AREA	80.00	60
	TO CHECK AND RECONNECT ALL NECESSARY WIRINGS	40.00	20
	TO SPRAY PAINT ON AFFECTED AREAS	900.00	800
	Sub Total	2020.00	1890
		7,034.00	

Remarks:

Not Approved

SUB TOTAL

GST 7.0 % 492.38

TOTAL 7,526.38

Surveyor's name: *Marcus Loke* L/S *S*

Principal's name: ANUJIT PRASAD

Survey Date & Time: *7/12/17* 5pm