

Third Party Insurer : AXA
Insured's Veh No : GX8441X
Date of accident : 05.12.2017

Messrs Grab Rentals Pte Ltd

Date of accident : 05.12.2017

Estimate To Repair Honda Vezel 1.5 Hybrid
Vehicle No : SLR2603K
Chassis No : RU31223559

Pages : 1 of 1

S/No	Quantity	Description	Unit price	Amount
<u>LIST ITEMS</u>				
1	1 pc	front bumper	\$ 927.50	\$ 927.50
2	1 pc	front bumper reinforcement	\$ 321.00	\$ 321.00
3	1 pc	n/s front bumper side retainer	\$ 23.00	\$ 23.00
4	10 pc	front bumper clip	\$ 5.00	\$ 50.00
				\$ 1,321.50
Less 20 %				\$ 264.30
				\$ 1,057.20
<u>LABOUR & MISC. CHARGES</u>				
5		Panel beating, knocking and straighten the necessary portion, remove and renewal of parts, adjust and realign the same.		\$ 350.00
6		Putty and spray painting of the affected portion.		\$ 450.00
				\$ 800.00
Grand Total				\$ 1,857.20

Please conduct the survey at

Pegasus Engineering @ Tan Lim Motor Pte Ltd c/o 51 Defu Lane 10 Singapore 539216