



Consolidated Engineering

320 UBI ROAD 3 SINGAPORE 408649

ACCIDENT REPAIR ESTIMATES

Our Ref:

Type of Claim : TP

Vehicle No. : SJV6921T

Make & Model : TOYOTA VIOS E AUTO

Year of Manufacture : 2009

Chassis No. : MR053HY9305153079

Engine No. : INZY045268

Ins Company : ERGO vs AIG

Policy No. : _____

Excess : _____

Date of Accident : 05/12/17

Time of Accident : _____

Suggested Days of Repair _____

In-house Vehicle Assessor

Repair Estimates

Case Owner : ANIKKA

Signature : _____

Parts (a) Cost / List Price Items \$5,062.31

Plus/Less -20% \$(1,012.46)

Total of Cost / List \$4,049.85

(b) Nett Price Items \$-

Less _____

Total of Nett Item _____

(c) Special Nett Items \$-

Total Parts Cost (Appendix A) \$4,049.85

Labour (Appendix B) \$4,380.00

Total Repair Cost \$8,429.85

Contact No

68438723 – ANIKKA

68438736 – JASMINE CHNG

The above total will be subjected to 7% G.S.T.

Name of Surveyor	:	
Company	:	
Survey conducted on	:	at
<u>Remarks By Surveyor</u>		
(a) The repair of this vehicle is authorized / is not authorized until further notice.		
(b) Recommended Days of Repair :		day(s)
(c) Resurvey	:	Required / Not Required
(d) Excess	:\$	_____
(e) Signature of surveyor	:	Date:

Spark Car Care

ComfortDelGro Engineering Pte Ltd
320 UBI ROAD 3 SINGAPORE 408649
TEL :68438723/68438736 Fax:67436072

Spare Parts

Vehicle No : SJV6921T Case Owner : ANIKKA

Make & Model : TOYOTA VIOS E AUTO Year Manufacture : 2009

Chassis No : MR053HY9305153079 Engine No : 1NZY045268

Sales Order : _____ Supplier : _____

Order By : _____ Type of Claim : TP

S/No	Part Description	QTY	Cost Price	List Price	Nett Price	S/N	Dispositi Surveyor
1	RHR DOOR	1		\$856.60			
2	RHR DOOR MOULDING	1		\$120.92			
4	RHR DOOR LOCK	1		\$487.65			
5	RHR QUATER PANEL	2		\$987.90			
6	RH ROCKER PANEL (OUTER)	1		\$587.70			
7	RHR FENDER INNER SHIELD	1		\$85.50			
8	RHR DOOR MOTOR	1		\$30.00			
9	RHR DOOR REGULATER	1		\$679.80			
10	RHR DOOR TRIM BOARD	1		\$127.90			
11	RHR DOOR HANDLE	1		\$514.70			
12	RHR DOOR WEATHER STRIP	1		\$109.80			
13	RHR DOOR GLASS	1		\$255.14			
14	RHR RIM	1		\$218.70			
15	RHR KNUCKLE ARM	1					
16	RHR LOWER ARM	1					
17	RHR KNUCKLE BEARING	1					
18	RHR DRIVE SHAFT	1					
19		1					
20		1					
21		1					
22		1					
23		1					
24		1					
25		0					
26		0					
27		0					
28		0					
29		0					
30		0					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.

