

**TRANS-CAB AUTO SERVICES PTE LTD**

AAD1712-049

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

**SHD335T -***Not Authored**Recovery B4 paint @ 2201*

Vehicle No.:

**SHD 335T - CANDY**

Chassis No.:

VF1ABL15AUC282700

Vehicle Make:

RENAULT

Vehicle Model:

LATITUDE

Date of Accident :

04.12.2017

Third Party Insurer :

*Fixid***PART****LIST**

1	1	BUMPER COVER REAR	\$	<i>N</i>	1,108.46
2	1	BUMPER LOWER REAR	\$	<i>Sn</i>	768.84
3	1	BUMPER BRACKET CTR REAR	\$	<i>Sn</i>	113.47
4	1	BUMEPR BRACKET SIDE RH REAR	\$	<i>Sn</i>	135.97
5	1	BUMEPR RETAINER RH REAR	\$	<i>Sn</i>	44.99
6	1	BUMPER REFLECTOR RH	\$	<i>Sn</i>	43.61
7	1	BUMEPR BRACKET SIDE LH REAR	\$	<i>Sn</i>	135.97
8	1	BUMEPR RETAINER LH REAR	\$	<i>Sn</i>	44.99
9	1	ROCKER PANEL OUTER RH	\$	<i>N</i>	987.49
10	1	FENDER PANEL REAR RH	\$	<i>N</i>	3,299.13
11	1	WHEELARCH REAR RH	\$	<i>Sn</i>	543.47
12	1	TAILLAMP RH	\$	<i>Sn</i>	552.55
13	1	TAILLAMP PANEL RH	\$	<i>N</i>	986.70
14	1	EXHAUST REAR	\$	<i>N</i>	7,489.05
15	1	EXHAUST CAP REAR	\$	<i>N</i>	230.49
16	1	DOOR PANEL REAR RH	\$	<i>N</i>	2,844.66
17	1	DOOR GUIDE REAR RH	\$	<i>Sn</i>	176.82
18	1	DOOR HINGE UPPER RH	\$	<i>N</i>	274.50
19	1	DOOR HINGE LOWER RH	\$	<i>N</i>	300.55

*X*

<b>TOTAL</b>	<b>\$</b>	<b>20,081.72</b>
<b>10%</b>	<b>\$</b>	<b>2,008.17</b>
	<b>\$</b>	<b>18,073.54</b>

**Specical Nett**

1	1SET	PARKING AID	\$	<i>Sn</i>	700.00
2	1SET	REAR BUMPER CLIP	\$	<i>nn</i>	66.00
3	1SET	BUMPER BRACKET CTR CLIP	\$	<i>nn</i>	33.00
4	1SET	BUMEPR BRACKET SIDE CLIP RH RR	\$	<i>nn</i>	10.00
5	1SET	BUMEPR RETAINER RH CLIP RR	\$	<i>nn</i>	20.00
6	1SET	BUMPER LOWER REAR RIVET	\$	<i>nn</i>	22.00
7	1SET	BUMPER LOWER REAR CLIP	\$	<i>nn</i>	66.00
8	1	EXHAUST MOUNTING REAR	\$	<i>Sn</i>	17.82

*X*

**TRANS-CAB AUTO SERVICES PTE LTD****AAD1712-049**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

**SHD335T -**

9	1	TAILLAMP CLIP RH	\$	~	5.00	}	X
10	1SET	WHEELARCH CLIP RR RH	\$	~	66.00		
11	2	REAR WINDSCREEN SELANT	\$	~	80.00		
12	1	WINDSCREEN MOULDING	\$	5h	100.00		
13	1	REAR WINDSCREEN INNER SPONGE SEAL	\$	~	100.00		
14	1	CAP HUB RH RR	\$	5h	35.00		
15	1	RIM RH RR	\$	5h	385.00		
16	1	TYRE RH RR	\$	5h	330.00		
17	1	DOOR STICKER "Trans-cab"	\$	~	80.00		
18	1	DOOR STICKER "Classic"	\$	~	30.00	}	X
19	1	DOOR STICKER "6555-3333"	\$	~	80.00		

<b>TOTAL</b>	<b>\$</b>	<b>2,225.82</b>
<b>TOTAL PARTS</b>	<b>\$</b>	<b>20,299.36</b>

Putty And Spray Painting Of The Affected Portion.	\$	3,000.00	220
To reinstall rear bumper parking sensor.	\$	~	170.00 X
To Rust-Proofing Of The Affected Areas.	\$	~	170.00 X
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	~	2,800.00 X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	~	170.00 X
To repair and realign rear exhaust pipe.	\$	~	170.00 X
Towing Fees	\$	~	120.00 X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	~	380.00 X
To transfer of rear windscreen fittings and conduct water seepage test.	\$	~	170.00 X
To check steering geometry and computer wheel alignment	\$	~	220.00 X
To transfer of door fittings, attachment and perform water seepage test.	\$	~	170.00 X

**TRANS-CAB AUTO SERVICES PTE LTD****AAD1712-049**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

**SHD335T -**To transfer of tire, rim and on wheel balancing. \$ *nn* 170.00 *X*

TOTAL	\$	7,710.00
Over All Total	\$	28,009.36

**(PARTS BY PARTS)**

Repair Days

*10 Days**1 day*

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and  
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: