

ASS. REC. BY:

REF: CS/MSG17023233/A196⁰²

Special Instruction:

Surveyor: Rasul
Minimen

ASSIGNMENT (Office)

From (Person): Christina Wong

of

MSGDate/Time: 6/12/17 @ 3:54pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

Gy 52031

Insured:

SKW 73052

at Workshop m/s

Woon Meng Motor

Tel:

63161131of 50Bkt Batok - Strt 23 # 01-06, 659578

Policy No:

A29022840AT2

Claim No:

538191

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

22/11/2017

CA / REV / REP. / REV 24 HRS

(wp)

12.12.2017 @ 3pm owner waiting

H.O.D. Endorsement:

Date/Time:

4:45pm @ 6/12/17

Person Contacted:

Ms. HengVehicle: IN/OUT

Date/Time

Action/Instruction (✓) Estimate

Gy 52031 - CC3/AIG 08031693/Yaq1D.O.A.: 29/11/2008SKW 73052-X18/12/17 @ 2pm Informed Christina Wong, we are pending estimate from repairer.22/4/17 @ 2pm Revised to Christina Wong via Minimen.US \$ 2200, 4 days. (Red \$ 2085.97, 49%)

Est. Repairs:

4 days

Res.: Yes or No

D.O.A. 22/4/17D.O.I. 12/12/17

Lum Sum:

%

3 Val.: Yes or No

Survey held at

Woon Meng

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Date:

Person Contacted:

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 30 APR 2018

Date/Time, File Pass to?

☐

Preli. Report

☐

Final Report

Days Of Repair: 4Resurvey No. of Trip: 1

Survey Fee:

Transportation:

20010

Photos

Others

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech. Invs (\$

☐

Weekend (\$

TOTAL

210

Report Format:

MCB-TP

Lump Sum / I.B.I. (\$

2200)