

ASS. REC. BY:

REF: CS/CTI17023236/R196<sup>nt</sup>

Special Instruction:

Surveyor:

Rasul

ASSIGNMENT (Office)

From (Person):

Jawyn Tay

of

CTI

Date/Time: 6/12/17 @ 5:07pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SGD 1222R

Insured:

SLA 8140D

at Workshop m/s

Performance

Tel:

81214600

of

303 Alexander Road

Policy No:

DMPCSN 3027201701

Claim No:

SNM17D06959C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A. 2/12/2017

CA / REV / REP. / REV 24 HRS

(wp)

H.O.D. Endorsement:

Date/Time: 10:04am @ 7/12/17

Person Contacted:

Inthiran

Vehicle IN OUT

Date/Time	Action/Instruction (✓) Estimate
	SGD 1222R - NBA/CTI17023142/Y D.O.A: 2/12/2017
	SLA 8140D - NBA/CTI17023142/Y D.O.A: 2/12/2017
16/1/18 @ 11:07am	Rasul finalised with Caroline final fig \$13077, 9 days. (Red \$ 4170.45, 24%)

*P. Ram*

62060

SGD 1222R

Estimate No. \_\_\_\_\_  
 OD / TR / WS / TR RES / OD RES / EVA / INV / M /  
 To Inspect Vehicle No. **SGD 1222R**  
 at Vehicle No. \_\_\_\_\_  
 of \_\_\_\_\_  
 Insured \_\_\_\_\_  
 Policy No. \_\_\_\_\_  
 Claims No. \_\_\_\_\_  
 Sum Insured \_\_\_\_\_ Excess \_\_\_\_\_  
 Claims Record \_\_\_\_\_  
 Make of Vehicle \_\_\_\_\_



(Policy Condition)  
 Remark: The veh had commenced its repair at the time of inspection.  
 Ball or Market Value \_\_\_\_\_  
 DAD Accident Report \_\_\_\_\_ Consistent? Yes or No  
 OIA / RR / Cash \_\_\_\_\_ Consistent? Yes or No  
 Est. Repair \_\_\_\_\_ days Pass / Yes or No  
 LIT / S / \_\_\_\_\_ Pass / Yes or No  
 OIA / REV / REP / 24 HRS \_\_\_\_\_  
 Date \_\_\_\_\_ Person Contacted \_\_\_\_\_ Vehicle IN / OUT

SGD 1222R 2016 04  
 Type ☒ M Cycle Bus / Van / Long Taxi / Home / Motor  
 Truck / Trailer or  
 Make **B.M.W 1160** 1496  
 Colour **WHITE** A.I. Insured Std / W / NA  
 St. Reading **14821** T.Paid Insured Std / W / NA  
 Engine No. \_\_\_\_\_  
 C.No. **WBA1U72076V 725025**  
 Gen. Cond. Good ☒ Poor / Burnt  
 Steering ☒ Jammed / Leaked / Burnt /  
 Brake ☒ Jammed / Leaked / Burnt /  
 Mod. ☒ N/A / STD Air /  
 Tyre Size **205/55R16**  
 BS / DUN / EXNOVA / GY / RS / LIZA / MIC / GHTSL ☒ SUM  
 TOYO / YOKO or  
 Front \_\_\_\_\_ Rear \_\_\_\_\_  
 R/Sa **6** mm R/Sa **6** mm  
 L/Sa **6** mm L/Sa **6** mm  
 D.O.A. **02/12/17** D.O.A. **06/12/17**  
 Surveyed at **PERFORMANCE**  
 Date of Damages Front / Rear / O/S / N/S / U/O / Roof /  
 The U/O / Chassis frame / Body Structure affected due to collision

RECEIVED 19 JAN 2018

Date Time File Pass of ☐ Prel. Report  
**19/1 Jan 2018** ☐ Final Report  
 Date Time File Return of \_\_\_\_\_

Days Of Repair **9**  
 Resurvey No. of Trip \_\_\_\_\_

Add Fee: ☐ Std Fee \$  
☐ Insur Fee \$  
☐ Tech Fee \$  
☐ At Shop \$

Report Format **TP**  
**13077**





# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS/CT117023236/R1qb

3 ANSON ROAD #16-00  
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 07-12-2017



Code : CTI

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLA 8140D	Veh. Inspected	SGD 1222R
Policy No.	DMPCSN3027201701	Coverage (\$)	0.00
Claim No.	SNM17D06959C02	Excess (\$)	0.00
Assign From	MERIMEN (JOSLIN LIM)	Assign Date	07/12/2017

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	02/12/2017	Inspection Date	07/12/2017
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		

## 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
---

# Survey Department Check List (Case Handler)

Reference No. : CS/CT117023236/R196  
 Policy Type: OD / TP / TP RES / TL / EVA

SGD 1222R.

Case Handler

Typist

**Admin** ( Cath ): Case handler to make sure all information created by the assignment team are **ACCURATE**.

## (1) Office Assign Form

- C Reference No.
- C Customer Code
- N Assign From
- C Assign Date
- C Veh No (Inspected)
- C Veh No (Insured)
- C D.O.A
- C Policy No
- C Claim No
- C Insurance Authorisation (CA /REV/REP)
- C Report Type
- C Weekend Charges
- N Survey held at/Repairer
- C Excess

Y-Date	N-Date	Y-Date	N-Date
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

**Surveyor** ( Roy ): Case handler to make sure the surveyor completed all required information.

## (1) Assignment Form

- C Vehicle No
- C Regn Month/Year
- N Vehicle Type
- N Make & Model
- C Engine Capacity. (C.C)
- N Colour
- C Odometer. (Sp.Reading)
- C Chassis No
- N General Condition
- N Steering
- N Brake
- N Modification (Modi)
- C Tyre Size
- N Tyre Make
- C Tyre Balance
- C Date of Inspection
- N Survey held
- N Des.of Damages

✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			
✓			

## (2) System - (Views/Merimen)

- C Damaged Vehicle Photographs Uploaded

✓			
---	--	--	--

## (3) Workshop Estimate/Assignment Form

- N ALL Parts condition
- C Market Value for OD cases
- C Estimate Repair Cost for PRI (RSI, TMI, MSIG)
- C Days of repair
- C Finalised Amount
- C Re-inspection Cases to Finalize within 5 Days

✓			
✓			

## (4) System - (Views/Merimen)

- C Resurvey photo Uploaded

--	--	--	--

Check By: Cath 18/1/18  
 Case Handler Date

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est. Submitted	Adj. Assigned	Adj. Paid	Adj. Submitted	Ins. Auth'd	Status
Main	06 Dec 2017		06 Dec 2017 17:07 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

#### CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	TAN YOONG HAW		
Main Claimant:	QUEK TECK YEOW, ID: S7320906D		
Vehicle Reg. No.:	SGD1222R	Date of Loss:	02/12/2017 18:00 - :59
Claim Type:	TP / SNM17D06959C02	Policy/Cover Note No.:	DMPCSN3027201701 (Comprehensive)
Vehicle Reg. No. (Insured):	SLA8140D	Policy No. (Claimant):	SD16V14928
		Excess:	\$0.00
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Jowyn Tay - 6389 6174]		
Claimant's Insurer:	Liberty Insurance Pte Ltd (HQ) - Tel: 6221 8611		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 15/12/2017]		
Adj. Asg. Remarks:	PLEASE PROCEED TO SURVEY AND ARRANGE FOR DIRECT SETTLEMENT.		

#### ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

#### ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Shiau Chan (LKKAUTO)

---

**From:** Rasul (LKKAUTO)  
**Sent:** Tuesday, 16 January 2018 11:07 AM  
**To:** PBSP; SUR  
**Subject:** RE: FINAL REPORT / SGD1222R

Hi Caroline,

Finalised amount confirmed

Best Regards,  
Rasul | Assessor  
LKK Auto Consultants Pte Ltd  
Phone: 6256-3561 | email: Rasul@lkkauto.com | fax: 6841-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933) Save the Earth. Print only when necessary.

-----Original Message-----

From: PBSP [mailto:pml-pbsp@sime-darby.com.sg]  
Sent: Thursday, 4 January, 2018 5:48 PM  
To: Rasul (LKKAUTO); SUR  
Subject: FINAL REPORT / SGD1222R

Dear Rasul

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 9,293.00  
Total Parts : 3,784.00  
Total Labour & Parts : 13,077.00

Repair days: 9

Thank you.

Regards,  
Caroline  
C/o Performance Motors Limited - Body and Paint  
303 Alexandra Road Singapore 159941  
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	03/12/2017 15:39
Date Of Accident	02/12/2017 18:25
Exact Location Of Accident	ENTRANCE TO KPE FROM PIE
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SGD1222R
<b>Insured/Policyholder</b>	
Name Of Registered Owner	QUEK TECK YEOW
NRIC No	S7320906D
Email Address	STEVE_QUEK@YAHOO.COM
Mobile Phone No	(LOCAL) +65-96824846
Alternative Phone No	OFFICE-96824846

### Vehicle Particulars

Manufacturer	BMW
Model	116D 5DR HATCHBACK DSC LED
Exact Purpose for which vehicle was being used at time of accident	PRIVATE
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

### Insurance Company

Name of Insurance Company	LIBERTY INSURANCE PTE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	SD16V14928
Cover Note Number	

### Driver

Name of Driver	QUEK TECK YEOW
NRIC No	S7320906D
Date Of Birth	12/06/1973
Occupation	INDOOR
Date Of Driving Pass	19/04/1994
Driving Experience	23 YEARS AND 7 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96824846
Fax Number	
Contact Number	OFFICE-96824846
Email Address	STEVE_QUEK@YAHOO.COM



Address

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OWNER

Vehicle Registration Number of Driver's Own Vehicle -  
-  
-

Insurance Company of Driver's Own Vehicle -  
-  
-

### General Information of the Accident

Type Of Accident COLLISION - HEAD TO REAR

Weather Conditions CLEAR

Road Surface DRY

### Other Information

Was any foreign vehicle involved in this accident? NO

Was any body injured in the Accident? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 6

### Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

### Circumstances of Accident

I (SGD1222R) WAS BRAKING AND STOPPING AT THE ENTRANCE OF KPE FROM PIE WHEN SUDDENLY A CAR (SLA8140D) HIT ME FROM THE BACK. NO INJURIES INVOLVED.

### Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? YES

Remarks/ Reasons: PENDING VIDEO FROM INSURED

Was there any audio recorded? NO

### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SLA8140D

Vehicle Make/Model/Colour TOYOTA/CAMRY 2.0 AUTO ABS AIRBAG/GREY

Details Of Properties

Name of Driver TAN YOONG HAW

NRIC/Passport Number S7970433D

Contact Number 97668886

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

### Details of Witness

Name

Phone Number

Email Address

China tai ping



## Sketch Plan

- allow insurance companies to repudiate policy liability
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**  
 I understand, acknowledge, agree and consent that:  
 (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:  
 (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;  
 (ii) investigating the accident and/or my claims;  
 (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;  
 (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelope/mail packages); and/or  
 (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.  
 (collectively the "Purposes")  
 (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and  
 (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.


VERIFIED BY AJAX MARS  
 REPORTING OFFICER  
 MOHAMMAD SULHANDI BIN  
 MOHD AFFANDI

Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre  
 Personnel

## Sketch Plan



ACCIDENT STATEMENT (2000 characters)

I (SGD1222R) WAS BRAKING AND STOPPING AT THE ENTRANCE OF KPE FROM  
PIE WHEN SUDDENLY A CAR (SLA8140D) HIT ME FROM THE BACK. NO  
INJURIES INVOLVED.

Taxi Voucher No.:

DECLARATION

I/We declare that the above particulars & information provided above are true in every aspect

VERIFIED BY AJAX MARS REPORTING OFFICER -  
MOHAMMAD SULHANDI BIN MOH AFFANDI

MARS Officer



Registered Owner or Driver's Signature

Job Complete Date/Time

3 December 2017 at 3:22 PM

Date/Time:

3 December 2017 at 3:22 PM

SGD1222R

BMW Dealer

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63180888 (AfterSales)  
Fax. 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax. 64796601 (AfterSales)  
64796624 (Motorrad)

04 DEC 2017

GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Rec: 5.48pm

Estimate No. : b1 45046  
Date Estimated : 04/12/2017  
Prepared By : Han Kwan Yong

Page No. : 1 of 2

### - ESTIMATE REPAIR FOR -

Quek Teck Yeow (Guo Deyao)  
21 Lorong 3 Toa Payoh  
#07-06

Singapore 319581

### - ACCOUNT - 40000

Cash Sales - Service  
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGD1222R	V725025	27/10/2016	116d	0

### DESCRIPTION

### VALUE

To replace rear bumper & attachments, boot lid including to knock tail panel, trunk floor panel and dented area caused by the accident

3400 4,250.00

To respray rear bumper, boot lid, tail panel and boot compartment

2877 3,197.00

To carry out body cavity preservation.  
(Per panel).

100 118.00

To remove and install rear windscreen glass including conduct water leak tests.

649.00

To replace front exhaust silencer including align exhaust system and conduct checks for leak.

451 531.00

To replace rear exhaust silencer including alignment system and conduct checks for leak.

451 531.00

To remove and install boot compartment carpet and garnish to facilitate repairs.

231 271.00

To remove and install wire harness, control units and battery at the rear trunk floor panel to facilitate panel repair

451 531.00

To reconnect electrical components and wirings at the rear section including conduct checks for proper function.

300 354.00

To supply rear emboss number plate.

74 83.00

To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.

150 177.00

Sundries.

150 150.00

## Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax: 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax: 63449773

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190533/530 (Motorrad)  
Fax: 64796601 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## ESTIMATE

LKK Auto Consultants hence notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Estimate No. : b1 45046  
Date Estimated : 04/12/2017  
Prepared By : Han Kwan Yong

Page No : 2 of 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SGD1222R	V725025	27/10/2016	116d	0

Acknowledged by Repairer

Signature:

Date:

## DESCRIPTION

## VALUE

Total Labour 1: 10,842.00

## DESCRIPTION

## QTY PRIC

## VALUE

TAILPIPE END PIECE ALU LOOK  
CLAMPING BUSH D=65.2MM  
FRONT PIPE  
MUFFLER CLAMP D=63.2MM  
REAR SILENCER  
BOOTLID  
REAR BUMPER CARRIER  
REAR BUMPER CENTRE GUIDE (M)  
REAR BUMPER TOWING EYE COVER PRIMED  
REAR BUMPER LH MOUNT  
REAR BUMPER RH MOUNT  
# REAR BUMPER PANEL PRIMED  
REAR PDC HOLDER SET  
HEAT INSULATOR REAR SILENCER  
PLAQUE 82MM  
TRUNK LID GASKET  
SENSOR WIRE FOR SMART OPENER TOP  
SENSOR WIRE FOR SMART OPENER BOTTOM  
LH REFLECTOR  
RH REFLECTOR  
THIRD STOPLAMP  
NUMBER PLATE LIGHT LED  
DECOUPLING RING PDC TORQUE CONVERTE  
# PDC SENSOR MINERALWEISS (A96  
(DG) CLEANER R1 (100ML)  
(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)  
(DG) ADHESIVE SET K6  
(DG/SL) GLASS PRIMER 30ML (VP206)

1 99.65  
1 54.30  
1 480.70  
1 41.80  
1 864.80  
1 1,081.40  
1 375.90  
1 56.05  
1 49.10  
1 141.65  
1 141.65  
1 880.25  
1 22.55  
1 60.10  
1 67.80  
1 65.30  
1 42.10  
1 40.50  
1 34.35  
1 34.35  
1 169.90  
2 23.20  
2 4.95  
2 363.05  
1 23.85  
2 131.55  
1 53.05  
1 27.85

99.65  
54.30  
480.70  
41.80  
864.80  
1,081.40  
375.90  
56.05  
49.10  
141.65  
141.65  
880.25  
22.55  
60.10  
67.80  
65.30  
42.10  
40.50  
34.35  
34.35  
169.90  
46.40  
9.90  
726.10  
23.85  
263.10  
53.05  
27.85

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regn No. Claim No.

Date&amp;Time 06/12/17 @ 1440 Excess S\$

Surveyor's Name RAONE Sign

Surveyor's Tel Authorised Yes / No

Authorised Date Time

RESURVEY PARTS PHOTO BY SURVEYOR Yes / No PML Yes / No

Surveyor's E-mail

No. of Working Days Recommend 10-12 days

Total Parts : 5,954.45

Labour 1 : 10,842.00  
Parts : 5,954.45  
Labour 2 : 0.00  
Excess : 0.00  
Total GST @ 7% : 1,175.75  
Grand Total : 17,972.20

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

17,972.20

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## FINAL REPORT

Estimate No. : b1 45046  
Date Estimated : 04/12/2017  
Prepared By : Han Kwan Yong

Page No. :

REPAIR FOR -  
Quek Teck Yeow (Guo Deyao)  
21 Lorong 3 Toa Payoh  
#07-06

Singapore 319581

- ACCOUNT - 135  
China Taiping Insurance (S) Pte Ltd  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE		
SGD1222R	V725025	27/10/2016	116d	0		
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT			
To replace rear bumper and attachments, boot lid and attachments, third stoplamp include making good the tail end panel, trunk floor plate and knocking out dents caused by the accident	3400.00		3,400.00			
To respray rear bumper, boot lid, tail end panel and trunk floor plate	2877.00		2,877.00			
To carry out body cavity preservation. (Per panel).	100.00		100.00			
To remove and install rear windscreen glass include conducting water leak tests	649.00		649.00			
To replace rear exhaust silencer including alignment system and conducting checks for leak.	451.00		451.00			
To remove and install boot compartment carpet and garnish to facilitate repairs	231.00		231.00			
To remove and install wire harness, control units and battery at the rear trunk floor panel to facilitate panel repair	451.00		451.00			
To reconnect electrical components and wirings at the rear section including conduct checks for proper function.	300.00		300.00			
To supply rear emboss number plate.	83.00		83.00			
To remove old PDC assembly, replace damaged parts and reconnect to new bumper including conduct checks for proper function.	150.00		150.00			
# To transfer lock mechanism from old to new boot lid include conducting checks on new boot lid central locking system for proper function	451.00		451.00			67
Sundries	150.00		150.00			

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## FINAL REPORT

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
TAILPIPE END PIECE ALU LOOK	99.65	1.00		99.65
CLAMPING BUSH D=65.2MM	54.30	1.00		54.30
REAR SILENCER	864.80	1.00		864.80
BOOTLID	1,081.40	1.00		1,081.40
REAR BUMPER CARRIER	375.90	1.00		375.90
REAR BUMPER TOWING EYE COVER PRIMED	49.10	1.00		49.10
REAR BUMPER PANEL PRIMED	880.25	1.00		880.25
REAR PDC HOLDER SET	22.55	1.00		22.55
PLAQUE 82MM	67.80	1.00		67.80
TRUNK LID GASKET	65.30	1.00		65.30
THIRD STOPLAMP	169.90	1.00		169.90
(DG) ADHESIVE SET K6	53.05	1.00		53.05

### # SUPPLEMENTARY ITEMS

Total Labour :	9,293.00
Total Parts :	3,784.00
Total Labour & Parts :	13,077.00
Deduction for Excess :	0.00
Total Repair Costs less Excess:	13,077.00
GST @7%:	915.39
Grand Total :	13,992.39

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



## SUPPLEMENTARY

Estimate No. : b1 45046  
Date Estimated : 04/12/2017  
Prepared By : Han Kwan Yong

Page No. :

REPAIR FOR -  
Quek Teck Yeow (Guo Deyao)  
21 Lorong 3 Toa Payoh  
#07-06

- ACCOUNT - 135  
China Taiping Insurance (S) Pte Ltd  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909

Singapore 319581

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE		
SGD1222R	V725025	27/10/2016	116d	0		
DESCRIPTION				ORIGINAL PRICE	DISC. %	NETT
# To transfer lock mechanism from old to new boot lid include conducting checks on new boot lid central locking system for proper function				451.00		451.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
-------------	------------	-----	---------	------

Total Labour :	451.00
Total Parts :	0.00
Total Labour & Parts :	451.00



## LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI17023236/R1QBN2

Date: 19/01/2018

## REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMPCSN3027201701
Claimant Vehicle No :	SGD1222R	Insured Vehicle No :	SLA8140D
Date of Loss:	02/12/2017	Nature of Claim:	TP
		Claim No:	SNM17D06959C02

## DESCRIPTION &amp; IDENTIFICATION OF VEHICLE

Reg No:	SGD1222R	Engine No:	31999653B37D15A
Make & Model:	BMW 116D, 1.5 (A)	Chassis No:	WBA1V72070V725025
Reg. Date:	27/10/2016 (Man. Year: 2016)	Odometer:	14821 km
Colour:	White		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

## CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

## CONDITION OF TYRES

Front Tyre Size:	205/55R16	Rear Tyre Size:	205/55R16
Front Left Side:	Pirelli 6 mm	Rear Left Side:	Pirelli 6 mm
Front Right Side:	Pirelli 6 mm	Rear Right Side:	Pirelli 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	6,187.45	4,017.00	2,170.45	35.08
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,060.00	9,060.00	2,000.00	18.08
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>17,247.45</b>	<b>13,077.00</b>	<b>4,170.45</b>	<b>24.18</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,207.32</b>	<b>915.39</b>	<b>291.93</b>	<b>24.18</b>
<b>Nett Amount (S\$)</b>	<b>18,454.77</b>	<b>13,992.39</b>	<b>4,462.38</b>	<b>24.18</b>

## INSPECTION

Date of Assignment:	06/12/2017	
Date Inspected:	06/12/2017 Inspected At:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre Singapore 159941
Estimated Period of Repair:	9.0 days	

Adjuster: MOHD RASUL

Manager: SHIAU CHAN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

## REPAIR DETAILS

## Reference

<b>Part Source:</b> MRM-SG	Version: 1.0 (Last Synchronised: 19 Jan 2018)
<b>Parts:</b> 144	BMW 116D 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b> Repairer's	(Price-denominated Standard List)
<b>Print Code:</b> (Unsubmitted, no print-code for SGD1222R)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.

## Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*SUNDRIES	Necessary	150.00 FS	*150.00 FS
2	1	*TAILPIPE END PIECE ALU LOCK	Bent	99.65 FS	*99.65 FS
3	1	*CLAMPING BUSH D=65 2MM	Necessary	54.30 FS	*54.30 FS
4	1	*FRONT PIPE	Serviceable	480.70 FS	*- FS
5	1	*MUFFLER CLAMP D=63 2MM	Serviceable	41.80 FS	*- FS
6	1	*REAR SILENCER	Scratched	864.80 FS	*864.80 FS
7	1	*BOOTLID	Bent	1,081.40 FS	*1,081.40 FS
8	1	*REAR BUMPER CARRIER	Bent	375.90 FS	*375.90 FS
9	1	*REAR BUMPER CENTRE GUIDE (M)	Serviceable	56.05 FS	*- FS
10	1	*REAR BUMPER TOWING EYE COVER PRIMED	Missing	49.10 FS	*49.10 FS
11	1	*REAR BUMPER LH MOUNT	Serviceable	141.65 FS	*- FS
12	1	*REAR BUMPER RH MOUNT	Serviceable	141.65 FS	*- FS
13	1	*REAR BUMPER PANEL PRIMED	Deformed	880.25 FS	*880.25 FS
14	1	*REAR PDC HOLDER SET	Necessary	22.55 FS	*22.55 FS
15	1	*HEAT INSULATOR REAR SILENCER	Serviceable	60.10 FS	*- FS
16	1	*PLAQUE 82MM	Necessary	67.80 FS	*67.80 FS
17	1	*TRUNK LID GASKET	Necessary	65.30 FS	*65.30 FS
18	1	*SENSOR WIRE FOR SMART OPENER TOP	Serviceable	42.10 FS	*- FS
19	1	*SENSOR WIRE FOR SMART OPENER BOTTOM	Serviceable	40.50 FS	*- FS
20	1	*LH REFLECTOR	Serviceable	34.35 FS	*- FS
21	1	*RH REFLECTOR	Serviceable	34.35 FS	*- FS
22	1	*THIRD STOPLAMP	Necessary	169.90 FS	*169.90 FS
23	2	*NUMBER PLATE LIGHT LED	Serviceable	46.40 FS	*- FS
24	2	*DECOUPLING RING PDC TORQUE CONVERTE	Not Necessary	9.90 FS	*- FS
25	2	*PDC SENSOR MINERALWEISS (A95)	Serviceable	726.10 FS	*- FS
26	1	*(DG) CLEANER R1 (100ML)	Not Necessary	23.85 FS	*- FS
27	2	*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Not Necessary	263.10 FS	*- FS
28	1	*(DG) ADHESIVE SET K6	Necessary	53.05 FS	*53.05 FS
29	1	*(DG/SL) GLASS PRIMER 30ML (VP206)	Not Necessary	27.85 FS	*- FS
30	1	*REAR EMBOSS NUMBER PLATE	Bent	83.00 FS	*83.00 FS

F=Franchise part. S=SpcNett.

<b>Total Parts (\$\$)</b>	<b>6,187.45</b>	<b>4,017.00</b>
---------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TO REPLACE REAR BUMPER & ATTACHMENTS,BOOT LID INCLUDING TO KNOCK TAIL PANEL,TRUNK FLOORPANEL AND DENTED AREA CAUSED BY THE ACCIDENT	New	4,250.00	3,400.00
2	TO RESPRAY REAR BUMPER,BOOT LID,TAIL PANEL AND BOOT COMPARTMENT	New	3,197.00	2,877.00
3	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	100.00
4	TO REMOVE AND INSTALL REAR WINDSCREEN GLASS INCLUDING CONDUCT WATER LEAK TESTS	New	649.00	649.00
5	TO REPLACE FRONT EXHAUST SILENCER INCLUDING ALIGN EXHAUST SYSTEM AND CONDUCT CHECKS FOR LEAK	New	531.00	-
6	TO REPLACE REAR EXHAUST SILENCER INCLUDING ALIGNMENT SYSTEM AND CONDUCT CHECKS FOR LEAK	New	531.00	451.00
7	TO REMOVE AND INSTALL BOOT COMPARTMENT CARPET AND GARNISH TO FACILITATE REPAIRS	New	271.00	231.00
8	TO RMEOVE AND INSTALL WIRE HARNESS,CONTROL UNITS AND BATTERY AT THE REAR TRUNK FLOOR PANEL TO FACILITATE PANEL REPAIR	New	531.00	451.00
9	TO RECONNECT ELECTRICAL COMPONENTS AND WIRINGS AT THE REAR SECTION INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION	New	354.00	300.00
10	TO REMOVE OLD PDC ASSEMBLY,REPLACE DAMAGED PARTS AND RECONNECT TO NEW BUMPER INCLUDING CONDUCT CHECKS FOR PROPER FUNCTION	New	177.00	150.00
11	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW BOOT LID INCLUDE CONDUCTING CHECKS ON NEW BOOT LID CENTRAL LOCKING SYSTEM FOR PROPER FUNCTION	New	451.00	451.00
Gross Labour Cost (\$\$)			11,060.00	9,060.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >