

Signature

REF: NS/TNC 17023242/Stbez

# ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop m/s \_\_\_\_\_

of \_\_\_\_\_

Insured: GBE 7752S

Policy No: 5078397711-01 230817-220318

Claims No: MT/0973396-002


Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SHC 4121 y.

Yr Regn: 8/4/2013

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius

C.C. 1798

Colour: Maroon

A/C: Insured / Std / NI / NA

Sp. Reading: 458 201

T/Radio: Insured / Std / NI / NA

Eng/No: \_\_\_\_\_

C/No: JTDKN3CU 265702605.

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65R15

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. 5/12/2017

D.O.I. 6/12/2017

Survey held at SMART

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time | Action / Instruction

SHC 4121 Y - NJM / INC 090001734 / Zy1

DN: 021809

THX / 12/17/2012

GBE 7752S - X

Click  
NJMC

lump sum \$1450/- (Red: 4492.52: 75%)

RECEIVED 10 APR 2018.

Date/Time, File Pass to?

☐ : Preli. Report

☒ : Final Report

1) 6/14 Typist  
Date/Time, File Return to?

2) \_\_\_\_\_

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee: 160

Transportation: \_\_\_\_\_

Add Fee: ☐ : Site Insp (\$ \_\_\_\_\_)

☐ : Interview (\$ \_\_\_\_\_)

☐ : Tech. Invs (\$ \_\_\_\_\_)

☐ : Weekend (\$ \_\_\_\_\_)

) \$ + RS. \$ \_\_\_\_\_

) Photos

) Others

)

Report Format: TP

Lump Sum / I.B.I: (\$ 1450/-)

TOTAL

195



# National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC17023242/Stb

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE Date: 07-12-2017



189556

Code: INC4

## 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBE 7752S	Veh. Inspected	SHC 4121Y
Policy No.	5078397711-01	Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	06/12/2017

## 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

## 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

## 4. Description of Damages

--

## 5. General Information

Accident Date	05/12/2017	Inspection Date	06/12/2017
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

## 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

eBaoTech

General Claim

Hello, NAC\_PAYA\_UBI\_800601

[Change Language](#)[Change Password](#)[Log Out](#)[My Desktop](#)  
[Notice of Loss](#)

## Policy Query

Policy No.  Date of Accident   
Vehicle No.(For Motor)

Select	Policy No.	Policyholder Name	Policyholder NRIC	Product	Cover Type	Vehicle No.	Insured Object	Commence Date	Expiry Date
<input type="radio"/>	5078397711-01	S P BEST SERVICE	S3325222M	GCV	Comprehensive	GBE77525	GBE77525	23/03/2017	22/03/2018

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type	Company
Owner ID	5369K
<b>Vehicle Details</b>	
Vehicle No.	SHC4121Y
Vehicle to be Exported	No
Intended De-registration Date	07 Dec 2017
Vehicle Make	TOYOTA
Vehicle Model	PRIUS TAXI (SMRT)
Primary Colour	Maroon
Manufacturing Year	2013
Engine No.	2ZR5941175
Chassis No.	JTDKN36U205702605
Maximum Power Output	100.0 kW (134 bhp)
Open Market Value	\$33,120.00
Original Registration Date	08 Nov 2013
First Registration Date	08 Nov 2013
Transfer Count	0
Actual ARF Paid	\$8,368.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility	Yes
PARF Eligibility Expiry Date	07 Nov 2021
PARF Rebate Amount	\$6,276.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date	07 Nov 2021
COE Category	A - Car (1600cc & below)
COE Period(Years)	8
PQP Paid	\$63,297.00
COE Rebate Amount	\$30,989.00
<b>Total Rebate Amount</b>	<b>\$37,265.00</b>
<b>Message</b>	
Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.	

The information contained herein is correct as at 07 Dec 2017

OK



Please read through the [Privacy Statement](#), [Terms of Use](#), and [Disclaimer](#).

Please do not use the Back or Forward buttons on your browser as this may alter the results of the transactions.

Best viewed with IE 10 and above, Chrome, Firefox, and Safari.

Copyright 2017 LTA [Privacy Statement](#) [Terms of Use](#) [Disclaimer](#) [Rate the Website](#) [Rate this e-Service](#)

Last updated on 19 Nov 2017 at 12:12 AM

# TP Claims against NTUC Income: Follow-Through Survey

Date : 18/12/2017

S/No	Income Reference	Claimant (Owner / Taxi Company)	Claimant Vehicle No.	Income Vehicle No.	Date of Accident	Time of Accident	Estimate
1	MT/0970584-002	SMRT TAXI PTE LTD	SHB 1056C	SLG 4640Y	21/11/2017	16:20	\$ 25,705.79
2	MT/0973050-002	COMFORT TRANSPORTATION	SHD 6523C	SKV 3462J	10/12/2017	12:05	\$ 2,661.58
3	MT/0972731-002	COMFORT TRANSPORTATION	SHD 4966X	SHC 6469G	6/12/2017	16:10	\$ 2,105.88
4	MT/0973500-002	COMFORT TRANSPORTATION	SHD 8566R	SHD 1555T	13/12/2017	6:35	\$ 2,451.58
5	MT/0972998-002	COMFORT TRANSPORTATION	SH 6306L	SIV 6367T	09/12/2017	9:00	\$ 2,307.96
6	MT/0974203-001	COMFORT TRANSPORTATION	SHA 4173H	FBM 1194A	13/12/2017	2:05	\$ 6,108.68
7	MT/0972865-002	SMRT TAXI PTE LTD	SHB 445U	SJW 513Y	7/12/2017	14:45	\$ 4,449.83
8	MT/0970787-002	SMRT TAXI PTE LTD	SHB 1280X	YN 9336C	21/11/2017	16:10	\$ 9,153.61
9	MT/0972556-002	SMRT TAXI PTE LTD	SHC 4121Y	GBE 7752S	5/12/2017	16:45	\$ 4,998.11
10	MT/0972155-002	SMRT TAXI PTE LTD	SHD 6351G	SLT 2327Y	2/12/2017	15:00	\$ 7,617.96
11	MT/0973396-002	COMFORT TRANSPORTATION	SHD 4121S	GBC 3770B	11/12/2017	17:15	\$ 2,422.02

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	06/12/2017 11:51
Date Of Accident	05/12/2017 16:45
Exact Location Of Accident	PUNGGOL ROAD TOWARDS SENGKANG EAST AVE 10
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHC4121Y
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SMRT TAXIS PTE LTD
Co Reg No	198905369K
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-800000000

### Vehicle Particulars

Manufacturer	TOYOTA
Model	PRIUS TAXI-1.8 (A)
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

### Insurance Company

Name of Insurance Company	FIRST CAPITAL INSURANCE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	D-17087562MFSH
Cover Note Number	

### Driver

Name of Driver	HO KIM TENG
NRIC No	S0473361D
Date Of Birth	21/09/1949
Occupation	OUTDOOR
Date Of Driving Pass	13/09/1967
Driving Experience	50 YEARS AND 2 MONTHS
Gender	MALE
Mobile Number	
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

Address

Postcode

Was driver an employee of the Insured's Company NO

If No, Relationship of the Driver with the Insured OTHER - HIRER

Vehicle Registration Number of Driver's Own Vehicle -

Insurance Company of Driver's Own Vehicle -

#### General Information of the Accident

Type Of Accident COLLISION - MAJOR/MINOR RD

Weather Conditions CLEAR

Road Surface DRY

#### Other Information

Was any foreign vehicle involved in this accident? NO

Was any body injured in the Accident? NO

Was any other material or property damaged? YES

I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO

Number of Passengers (Including Driver) 1

#### Details of Police Action

Was the accident reported to the police? NO

If Yes, Please state which Police Station

Was notice of intended Prosecution given? NO

If Yes, against whom?

#### Circumstances of Accident

I WAS TRAVELLING ON THE EXTREME RIGHT LANE ALONG PUNGGOL ROAD TOWARDS SENGKANG EAST AVE 10, SUDDENLY A VEHICLE GBE7752S CAME OUT FROM THE MINOR ROAD (COMPASSVALE BOW) ON MY LEFT AND COLLIDED ONTO THE LEFT REAR PORTION OF MY TAXI.

#### Attachment(s)

Are accident photos available for attachment? YES

Was there any video captured by Car Camera? NO

Was there any audio recorded? NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number GBE7752S

Vehicle Make/Model/Colour

Details Of Properties

Name of Driver SOH KOK SENG

NRIC/Passport Number S1573938Z

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### Details of Witness

Name

Phone Number

Email Address







4-12-17 / 16:00  
APV 11-12-17 / 11:39  
11-12-17 / 15:39

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623


Accident Reporting Number : 68662672

## SMRT Accident Vehicle Repair Estimates

6-12-17 / 15:39

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SH04121Y  
Ref. No : TAX/12/17/2032  
Reg. Date : 08/11/2013  
Vehicle Type : TAXI  
Make : TOYOTA PRIUS  
Model : PRIUS  
Name of Driver : HO KIM TENG  
Type of Accident : HEAD TO SIDE  
Date / Time of Accident : 05/12/2017 04:45:00 PM  
Accident Reported Date / Time : 06/12/2017 12:00:00 AM  
Surveyor is Required? : Yes  
Survey by : Sebastian  
Vehicle is Towed Back? : No  
Towed Back Date/Time :  
Replacement Vehicle issued? : No  
Accident Repair Job Card No : 000024093474  
Special Instruction to ARC, if any :



GBE7752S - NTUC IDAC  
BEFORE PAINT PHOTO AND AFTER PAINT PHOTO, FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL  
SURVEYOR SEBASTIAN (LKK) & Email : sebastianyeang @lkkauto.com HP: 90036121  
LUMPSUM REPAIR

Prepared Date : 06/12/2017 01:00:16 PM

Recording Camera ☐

Radio Antenna ☐

1<sup>st</sup> witness

Date

2<sup>nd</sup> witness

Date

458 200 km  
1 1/4 1/2 3/4 → 2 1/2 3/4

9/12/17 9.49 Pass 458263

LEE SHENG AUTO PTE LTD

Vehicle Return Date:

8-12-2017

Vehicle Return Time:

17:20

SMRT staff sign:

Page:

1

AX/12/17/2032

**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : JTDKN36U20-5702605

Mileage


0

Work Shop :

Repair Completed Date / Time :

**Summary of Repair Estimates**

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,014.00	500.00
Total Spray Painting Charges	: 1,314.00	650.00
Total Material Charges	: 95.62	149.40
Other Charges	: 1,070.32	150.60
<b>TOTAL</b>	<b>: 3,493.94 5942.52</b>	<b>1,450.00</b>
Lum Sum Total	: 0.00	0.00
No. of Repair Days	: 7.00	4.00 /
Prepared / Adjusted By	:	SEBASTIAN (LKK)
Arc / Surveyor Sign Off Date	: 06/12/2017 02:56:15 AM	06/12/2017 03:39:39 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 06/12/2017 02:56:15 AM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No : GN-1712-0342

Invoice No :

Quotation Date : 13/12

Invoice Date :

Invoice Amount :

Prepared Date :

## Section D - Details of Repair Estimates

### Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH REAR PORTION	1,014.00	500.00 /
<b>Total Labour</b>	<b>1,014.00</b>	<b>500.00</b>

### Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESRAY REAR DOOR LH	378.00	200.00 /
TO RESPRAY DOOR HANDLE	180.00	50.00 /
TO RESPRAY REAR FENDER LH	378.00	200.00 /
TO REPSRAY REAR BUMPER	378.00	200.00 /
<b>Total Spray Painting &amp; Panel Beating</b>	<b>1,314.00</b>	<b>650.00</b>

### Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER	445.32	445.32 /
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	30.00 /
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	0.00 nn
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	30.00 /
TO REPLACE SUNDRY PARTS	100.00	20.00 /
TO WASH AND VACUUM	60.00	0.00
TO TRANSFER DOOR MECHANISM	120.00	0.00
Lump Sum Adjustment by Surveyor	0.00	-374.72
<b>Total Other Costs</b>	<b>1,070.32</b>	<b>150.60</b>

6002.52

# Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
67004-47080		6505487	DOOR RR/LH	1	954.50	100.00	0.00	Replace	Repair	No <i>R</i>
69211-74020			DOOR OUTER HANDLE RR/LH	1	69.80	100.00	0.00	Replace	Repair	No <i>R</i>
61602-47091		6505476	FENDER RR/LH	1	766.80	100.00	0.00	Replace	Repair	No <i>R</i>
			STICKER DECAL SMRT	1	7.80	0.00	7.80	Replace	Replace	No <i>NE</i>
			STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No <i>NN</i>
62720-47031			QUARTER GLASS RR/LH	0	168.10	25.00	0.00	Replace	Not given	No <i>X</i>
	COMMO N		SEALANT W/SCREEN	0	37.00	0.00	0.00	Replace	Not given	No <i>X</i>
52159-47905		6505548	BUMPER REAR	1	458.60	100.00	0.00	Replace	Repair	No <i>R</i>
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No <i>NEC</i>
TOTAL MATERIALS							149.40	149.40		
TOTAL MATERIALS(Discounted)							95.62	149.40		

## Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

149.40 /  
+ 500.00 /  
+ 1175.32 /  


---

1824.72 /  
- 20%  


---

1459.78 /  


---

45 \$1450/- /

Sebastian  
18/12/2017.

## SMRT Accident Vehicle Repair Estimates

*NIUE*

### Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4121Y  
 Ref. No : TAX/12/17/2032  
 Reg. Date : 08/11/2013  
 Vehicle Type : TAXI  
 Make : TOYOTA PRIUS  
 Model : PRIUS  
 Name of Driver : HO KIM TENG  
 Type of Accident : HEAD TO SIDE  
 Date / Time of Accident : 05/12/2017 04:45:00 PM  
 Accident Reported Date / Time : 06/12/2017 12:00:00 AM  
 Surveyor is Required? : Yes  
 Survey by :  
 Vehicle is Towed Back? : No  
 Towed Back Date/Time :  
 Replacement Vehicle issued? : No  
 Accident Repair Job Card No : 000024093474  
 Special Instruction to ARC, if any :  
 GBE7752S  
 Prepared Date : 06/12/2017 01:00:16 PM



*Sebastian.*  
*6/12/2017.*

- Lump Sum Repair  
 - Photo After Paint.

#### LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

**Section B - To be Completed by Service Advisor, Accident Repair Centre**

Chassis No : JTDKN36U20-5702605

Mileage : 0

Work Shop :

Repair Completed Date / Time :

**Summary of Repair Estimates****Quotation from ARC****Adjusted by Surveyor, if applicable**

Total Labour Charges : 1,014.00

0.00

Total Spray Painting Charges : 1,314.00

0.00

Total Material Charges : 1,599.79

1,599.79

Other Charges : 1,070.32

0.00

**TOTAL : 4,998.11****0.00****Lum Sum Total : 5,000.00****0.00**

No. of Repair Days : 7.00

0.00

Prepared / Adjusted By :

4 days

Arc / Surveyor Sing Off Date : 06/12/2017 02:56:15 PM

01/01/1900 12:00:00 AM

Prepared / Adjusted Date :

Remarks :

Prepared Date : 06/12/2017 02:56:15 PM

**Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair**

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :

**Section D - Details of Repair Estimates****Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR LH REAR PORTION	1,014.00	0.00 500
<b>Total Labour</b>	<b>1,014.00</b>	<b>0.00</b>

**Part 2 - Spray Painting & Panel Beating Related Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESRAY REAR DOOR LH	378.00	0.00 200
TO RESPRAY DOOR HANDLE	180.00	0.00 30
TO RESPRAY REAR FENDER LH	378.00	0.00 200
TO REPSRAY REAR BUMPER	378.00	0.00 200
<b>Total Spray Painting &amp; Panel Beating</b>	<b>1,314.00</b>	<b>0.00</b>

**Part 3 - Other Costs - Accident and Accident Repair Related Expenses**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO PROVIDE LABOUR & MATERIAL FOR ADVERTISEMENT STICKER	445.32	0.00 ✓
TO APPLY RUST-PROOFING ON AFFECTED AREA	100.00	0.00 30
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	125.00	0.00 X
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 30
TO REPLACE SUNDRY PARTS	100.00	0.00 20
TO WASH AND VACUUM	60.00	0.00 X
TO TRANSFER DOOR MECHANISM	120.00	0.00 X
<b>Total Other Costs</b>	<b>1,070.32</b>	<b>0.00</b>



# Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
67004-47080		6505487	DOOR RR/LH	1	954.50	25.00	715.87	Replace	Replace	No
69211-74020			DOOR OUTER HANDLE RR/LH	1	69.80	25.00	52.35	Replace	Replace	No
61602-47091		6505476	FENDER RR/LH	1	766.80	25.00	575.10	Replace	Replace	No
			STICKER DECAL SMRT	1	7.80	0.00	7.80	Replace	Replace	No
			STICKER DECAL 6555 8888	1	21.60	0.00	21.60	Replace	Replace	No
62720-47031			QUARTER GLASS RR/LH	1	168.10	25.00	126.07	Replace	Replace	No
	COMMO N		SEALANT W/SCREEN	1	37.00	0.00	37.00	Replace	Replace	No
52159-47905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace	No
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace	No
TOTAL MATERIALS								1,999.75	1,999.74	
TOTAL MATERIALS(Discounted)								1,599.79	1,599.79	
Added Spare Parts / Material Usage After Surveyor Signed off										

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									



Thatcham escribe

## National Assessment Centre Services

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



NTUC INCOME INSURANCE CO-OPERATIVE LTD Ref: NS/INC17023242/Stbe2

73 BRAS BASAH ROAD

#05-01 NTUC TRADE UNION HOUSESINGAPORE  
189556

Date: 19-04-2018



Code: INC4

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	GBE 7752S	Veh. Inspected	SHC 4121Y
Policy No.	5078397711-01	Coverage (\$)	0.00
Claim No.	MT/0973396-002	Excess (\$)	0.00
Assign From		Assign Date	06/12/2017

### 2. Vehicle Particulars & Condition

Make & Model	TOYOTA PRIUS	c.c	1798
Engine No.	HIDDEN	Year of Reg.	2013
Chassis No.	JTDKN36U205702605	Colour	MAROON
Odometer	458201	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/65 R15	FALKEN	6 mm
L/H Front Tyre	195/65 R15	FALKEN	6 mm
R/H Rear Tyre	195/65 R15	FALKEN	6 mm
L/H Rear Tyre	195/65 R15	FALKEN	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.
--

### 5. General Information

Accident Date	05/12/2017	Inspection Date	06/12/2017
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	4 Working Days
-------------------------------------	----------------

**National Assessment Centre Services**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6841 0055 FAX: 6841 6315

Reg. No: 52983356E GST Reg. No. 20-0405911-H



Page No.:1 of 1

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHC 4121Y**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	STICKER DECAL SMRT (SN)	NECESSARY	7.80	7.80
1	STICKER DECAL 65558888 (SN)	NECESSARY	21.60	21.60
2	PIXEL STICKER @\$60.00 (SN)	NECESSARY	120.00	120.00
1	ADVERTISEMENT STICKER (SN)	NECESSARY	445.32	445.32
1	SOLAR FILM	NOT NECESSARY	125.00	-
1	QUARTER GLAS RR/LH	NOT NECESSARY	168.10	-
1	SEALANT W/SCREEN	NOT NECESSARY	37.00	-
1	DOOR RR/LH	TO REPAIR	954.50	-
1	DOOR OUTER HANDLE RR/LH	TO REPAIR	69.80	-
1	FENDER RR/LH	TO REPAIR	766.80	-
1	BUMPER REAR	TO REPAIR	458.60	-
			3,174.52	594.72
<b><u>LABOUR</u></b>				
	THATCHAM STANDARD REPAIR TIME ON BODY WORKS.		1,254.00	530.00
	THATCHAM TTS STANDARD SPRAY PAINTING COST AND LABOUR.		1,414.00	680.00
	TO REPLACE SUNDRY PARTS.		100.00	20.00
	TO WASH AND VACUUM.	NOT NECESSARY	60.00	-
			2,828.00	1,230.00
<b>GRAND TOTAL</b>			<b>6,002.52</b>	<b>1,824.72</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (CONFIRMED)</b>				<b>1,450.00</b>

Report Ref No. NS/INC17023242/Stbe2

YEANG WAI KEEN

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,  
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.