MBM WHEELPOWER PTE LTD

Your Ref: SHC3834E

Our Ref:

SKP2E

To:

INDIA INTERNATIONAL INSURANCE SINGAPORE

CC

Email

Fax

ESTIMATE FOR VEHICLE NO. :

SKP2E

DESCRIPTION

FRONT BUMPER

FRONT BUMPER CLIPS

FRONT BUMPER RH SIDE SUPPORT

FRONT BUMPER HOLE COVER

RETAINER, OUTSIDE MOULDING

FRONT RH FENDER INNER SHIELD

Date:

23/11/2017

From:

Kenneth

Fax:

62509015

Contact:

81387188

Make / Model:

TOYOTA VELLFIRE 2.5Z A

wheelpower

Chassis No.:

AGH300001569

Engine No.:

2ARH522223

Year of Make:

2015

Accident Date:

17 November 2017

	List Price
\$	SCR 2,100.00
\$	ner - 60.00
\$	80.00
\$	7 260.00
\$	nec/10.00
\$	₹ 290.00
S	2,800.00
\$	(700.00)
\$	2,100.00
	\$

SPECIAL NETT		N. W.
ANTI RUST COATING	1	\$ × 150.00
BODY SEALANT	1	\$ × 120.00
FRONT BUMPER SENSORS	11	\$ 300.00
CUSTOMIZE FRONT WARAPPING STICKER	1	\$ nev. 800.00
LABOUR		
TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS. INCLUDING TO KNCOK-OUT, STRAIGHTEN, ON THE AFFECTED AREAS		\$ 250 800.00
TO CHECK & RECONNECT ALL NECESSARY WIRING		\$ 60 80.00
TO SPRAY PAINTING ON THE AFFECTED AREA		\$ 250 600.00
	Total:	\$ 4,950.00
7% GST		\$ 346.50
	Grand Total:	\$ 5,296.50

RASUL
46 9 00010068
3 days
9/1
07/12/17/01510

Resury 64 paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from insurance Company

Acknowledged by Repairer

Signature:

Date:

Please survey the vehicle at :-160 SIN MING DRIVE, #06-09 SIN MING AUTOCITY, SINGAPORE 575722 Mbm wheelpower pte ltd 160 SIN MING DRIVE #06-02 SIN MING AUTOCITY

t 62828888 f 64529823

Company Registration Number: 200204110W