

TRANS-CAB AUTO SERVICES PTE LTD

AAD1712-044

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9332S -

*Not Authored
11 Sep 8 1400h*

Vehicle No.:

SHD9332S - JHOW

Chassis No.:

KL1LA69RJBB057348

Vehicle Make:

CHEVROLET

Vehicle Model:

EPICA 2.0

Date of Accident :

03.12.2017

Third Party Insurer :

AXA

PART**LIST**

1	1	Rear Bumper	\$	<i>Bu</i> 1,202.00	✓
2	1	Rear Bumper Beam	\$	<i>B</i> 239.94	X
3	1	Rear Bumper Centre Absorber	\$	<i>Sn</i> 260.00	X
4	1	Rear Bumper Side Retainer RH	\$	<i>Di</i> 68.76	✓
5	1	Rear Bumper Side Retainer LH	\$	<i>Sn</i> 68.76	X
6	1	Rear Bumper Reflectors RH	\$	<i>CM</i> 119.74	✓
7	1	Rear Bumper Reflectors LH	\$	<i>Sn</i> 119.74	} X
8	1	Rear Bumper Tow Hook Cover	\$	<i>Sn</i> 93.00	
9	1	Bootlid	\$	<i>R</i> 973.00	
10	1	Bootlid inner trim board	\$	<i>Sn</i> 400.00	
11	1	Bootlid Weatherstrip	\$	<i>Sn</i> 344.28	
12	1	Bootlid Lock - Top	\$	<i>R</i> 466.56	
13	1	Bootlid 'CHEVROLET' Badge	\$	<i>nn</i> 120.62	
14	1	Bootlid Logo	\$	<i>nn</i> 138.84	
15	1	Bootlid 'EPICA LT' Badge	\$	<i>nn</i> 119.84	
16	1	Bootlid Reflector Centre	\$	<i>Sn</i> 217.97	
17	1	Bootlid Reflector RH	\$	<i>Sn</i> 128.40	
18	1	Bootlid Reflector LH	\$	<i>Sn</i> 128.40	
19	1	Rear Tail Lamp RH	\$	<i>Sn</i> 479.30	
20	1	Rear Tail Lamp Panel RH	\$	<i>R</i> 359.00	
21	1	Rear Exhaust Box (Muffler A-EXH,RR)	\$	<i>R</i> 1,110.00	
22	1	Rear Fender RH	\$	<i>R</i> 1,145.00	
23	1	Rear Fender Inner Trim RH	\$	<i>Sn</i> 418.44	

TOTAL	\$	8,721.59
10%	\$	872.16
	\$	7,849.43

Special Nett

TRANS-CAB AUTO SERVICES PTE LTD**AAD1712-044**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9332S -

1	1Set Licence Plate With Holder	\$	Sn 60.00	X
2	1Set Bootlid inner trim board Clip	\$	nn 40.00	X
3	1Set Rear Bumper Parking Sensor	\$	Sn 300.00	X
4	1Set Rear Bumper Fastener Clip	\$	nn 44.00	
5	1Set Rear Fender Inner Trim Clip RH	\$	nn 30.00	}
6	1Set Rear Bumper End Dust Cover Clip	\$	nn 30.00	
7	1 Rear Boot Sticker 'Trans-cab'	\$	nn 30.00	
8	1 Rear Boot Sticker '6555-3333'	\$	nn 30.00	
9	1 Rear Exhaust Mounting	\$	Sn 10.00	
10	2 Rear Windscreen Sealant	\$	nn 80.00	
11	1 Rear Windscreen Inner Sponge Seal	\$	nn 100.00	}
12	1 Spare Tyre	\$	Sn 180.00	
13	1 Spare Wheel Rim	\$	Sn 126.74	

TOTAL	\$	1,060.74
TOTAL PARTS	\$	8,910.17

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of
Parts, Adjust And Realign The Same

\$ 2,700.00 *200d*

To Check Electrical Lighting Concerned.

\$ 170.00 *10d*

To Rust-Proofing Of The Affected Areas.

\$ nn 170.00 X

Putty And Spray Painting Of The Affected
Portion.

\$ 2,800.00 *200d*

To reinstall rear bumper parking sensor.

\$ 170.00 *60d*

To Remove And Refit Rear W/Screen Glass To
Facilitate Bodywork Repair.

\$ nn 170.00 X

To transfer of boot fittings and conduct water
seepage test.

\$ nn 170.00 X

To transfer of Fender fittings, attachments and
perform water seepage test.

\$ nn 170.00 X

TRANS-CAB AUTO SERVICES PTE LTD**AAD1712-044**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9332S -Towing fees \$ *nn* 120.00 XTo remove and refit interior fittings, trimmings,
garnish, fittings and other, to enable repair. \$ *nn* 380.00 XTo check steering geometry and computer
wheel alignment \$ *nn* 220.00 X

	\$	7,240.00
TOTAL	\$	16,150.17

Repair Days*10 Days**1 1/2 day*

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: