



AUTO PTE LTD

金興(龔)汽車私人有限公司

160 Sin Ming Drive, #02-18/19/20/21,

Sin Ming AutoCity, Singapore 575722

Tel: 6452 7018 Fax: 6458 3895

Email: service@kkinhin.com.sg

No. : 29341

Vehicle Insured : SKV 9887 C

Accident Date : 04-Dec-2017

Date : 06-Dec-2017

Our Ref : 170880 (EQ) / SHUMAN

PAGE : 1

QUACH VAN THIEU (MS)

Singapore

ESTIMATED COST OF REPAIR FOR SUBARU FORESTER 2.0X (2006) SKB8692J

=====

1 pc rear bumper		380.00 c	
10 pcs rear bumper clips	@ S\$ 2.00	20.00 c	
10 pcs rear bumper rivet	@ S\$ 3.00	30.00 c	
2 pcs rear bumper side retainer (LH/RH)	@ S\$ 30.00	60.00 c	
2 pcs rear bumper side bracket (LH/RH)	@ S\$ 30.00	60.00 c	
2 pcs rear bumper lower bracket (LH/RH)	@ S\$ 20.00	40.00 c	
1 pc rear bumper top bracket		75.00 c	
1 pc rear bumper sponge		80.00 c	
1 pc rear bumper reinforcement		290.00 c	
1 pc tailgate "FORESTER" emblem		25.00 c	

		1,060.00	
	Add 20% :	212.00	

			1,272.00
1 pc reverse sensor			220.00 sn
To remove, cut out damaged parts, panel beating, welding, align, refix and to renew affected parts.			500.00
To remove and refit reverse sensor assy.			80.00
To putty and respray on affected portions.			700.00

	Total :	S\$ 2,772.00	
		=====	

Singapore Dollars Two Thousand Seven Hundred and Seventy Two Only

Note: Amount quoted above is subject to prevailing GST at time of tax invoice.