

## COMFORTDELGRO ENGINEERING PTE LTD

## REPAIR ESTIMATE\*

VEHICLE NO : SH 8259B

DATE 6/12/2017 10:15

MAKE :

MODEL : HYUNDAI i40

DOA: 06.12.17

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Rear Bumper ✓			\$ 603.60
	Rear Bumper Reinforcement ?			\$ 504.35
	Rear Bumper Reinforcement Bracket (LH/RH) ?		\$ 180.00	\$ 360.00
	Rear Bumper Side Bracket ?			\$ 49.00
	Rear Bumper Clips ✓			\$ 22.00
	Rear Bumper Sponge ?			\$ 143.40
	Rear Bumper Under Cover ✓			\$ 225.00
	<b>SUB TOTAL</b>			<b>\$ 1,907.35</b>
	<b>LESS 20%</b>			<b>\$ 381.47</b>
	<b>DISCOUNTED TOTAL</b>			<b>\$ 1,525.88</b>
	Rear Bumper Reverse Sensor ✓			\$ 135.70
	Rear Bumper Rubber Mat ✓			\$ 50.00
				<b>\$ 185.70</b>
	<b>Labour Charge</b>			<b>200</b>
	Panel Beating			\$ <del>380.00</del>
	Spray Painting Charge			\$ <del>200.00</del> 180
	Wiring Charge			\$ <del>50.00</del> X
	R/Refix Reverse Sensor			\$ <del>120.00</del> 20
	<b>TOTAL LABOUR</b>			<b>\$ 750.00</b>
	<b>ESTIMATE TOTAL</b>			<b>\$ 2,461.58</b>
	Kalam ICKK 6/12/17 1500 hrs 2 Pags PIP Before Paint & photo			
	LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature:			
	This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.			

Larry Ng