



60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623

Accident Reporting Number : 68662672

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No

SHC4713P

Ref. No

TAX/12/17/2013

Reg. Date

06/08/2014

Vehicle Type

TAXI

Make

TOYOTA PRIUS

Model

PRIUS

Name of Driver

SHEIKH ZAINI BIN SHAHAR

Type of Accident

HEAD TO REAR

Date / Time of Accident

04/12/2017 08:30:00 AM

Accident Reported Date / Time :

04/12/2017 12:00:00 AM

Surveyor is Required?

Yes

Survey by

Vehicle is Towed Back?

No

Towed Back Date/Time

Replacement Vehicle issued? :

Accident Repair Job Card No : 000024093552

Special Instruction to ARC, if any :

SLG7585D - AIG (LKK)

Prepared Date

12/12/2017 08:12:10 AM

Sebastian. 12/12/2017.

- Lung Sun Repair. - Question Mark Itum Moto

- Photo After Paint.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No: JTDKN36U805747368 Mileage : 0

Work Shop : Repair Completed Date / Time :

Summary of Repair Estimates

Quotation from ARC Adjusted by Surveyor, if applicable

 Total Labout Charges
 : 338.00
 0.00

 Total Spray Painting Charges
 : 558.00
 0.00

 Total Material Charges
 : 763.63
 779.22

 Other Charges
 : 280.00
 0.00

 TOTAL
 : 1,939.63
 0.00

 Lum Sum Total
 : 1,950.00
 0.00

 No. of Repair Days
 : 3.00
 0.00

No. of Repair Days : 3.00 -0.00.

Prepared / Adjusted By : 2days .

Arc / Surveyor Sing Off Date : 12/12/2017 02:04:53 PM 01/01/1900 12:00:00 AM

Prepared / Adjusted Date

Remarks :

Prepared Date : 12/12/2017 02:04:53 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No : Invoice No

Quotation Date : Invoice Date :

Invoice Amount : Prepared Date :

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	338.00	0.00 200
Total Labour	338.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY BUMPER BEAM	180.00	7 0.00
Total Spray Painting & Panel Beating	558.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable		
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 30		
TO REPLACE SUNDRY PARTS	100.00	0.00 ×		
TO WASH AND VACUUM	60.00			
Total Other Costs	280.00	0.00		

AX/12/17/2013 Page:

3

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommen d	Surveyor Approved	Photos Attached
52159- 47905		6505548	BUMPER REAR	1	458.60	25.00	343.95	Replace	Replace R	No
			PIXEL STICKER	2	60.00	0.00	120.00	Replace	Replace /NE	No
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace 7	No
52023- 12240		6505547	BUMPER REINFORCEMENT REAR	1	205.70	25.00	154.27	Replace	Replace 7	No
52016- 47030			ARM SUB-ASSY, RR BUMPER LH	1	139.60	25.00	104.70	Replace	Replace 7	No
52576- 47020		6505550	BUMPER SIDE RETAINER RR/LH	1	94.80	25.00	71.10	Replace	Replace 7	No
		Т	OTAL MATERIALS					974.03	974.02	
TOTAL MATERIALS(Discounted)						763.63 779.22				

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

AX/12/17/2013