

GBB 7769 K

1 m R/H tail lamp. in —
panel B7 ✓

1 m rear no plate panel B7 ✓

1 m rear no plate B7 #18 / SN —

1 set reverse sensor in #200 / SN —

2 m tail gates #1800 / X2 = #3600 / SN B7 ✓

2 m — lower hinges #180 / X2 = #360 / SN RX

not authorized

21 Sep 87

GBB 7769K.

- ① R & R ear gate assy, tail lamp,
To straighten, K & R rear end
panel, R & R rear spar-lyre
Repair spar-lyre holder and
realign the same \$1200/ ~~\$800~~ ✓ 9002
- ② Putty & respray ear gate lower
member, no plate panel, tail
lamp panels, and affected area \$280/ ✓ 1801
- ③ Rewrite advertisement Bill \$1300/ ✓ ?