

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9275Z -**AAD1712-037***Not Authored
1/1/17 &*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD9275Z - JHOW**KL1LA69RJBB066177****CHEVROLET****CHEVROLET EPICA 2.0****04.12.2017****III****PART****LIST**

1	1	Front Fender RH	\$	<i>N</i>	837.60	X
2	1	Front Fender Liner RH	\$	<i>Sn</i>	47.00	X
3	1	Front Door RH	\$	<i>N</i>	1,133.00	X
4	1	Front Door Guide RH Chrome Moulding	\$	<i>Sn</i>	60.00	X
5	1	Front Door Outer Handle RH	\$	<i>Sn</i>	125.00	X
6	1	Front Side View Mirror RH	\$	<i>Sn</i>	939.00	X
7	1	Rear Door RH	\$	<i>B</i>	1,133.00	✓
8	1	Rear Door top hinge RH	\$	<i>N</i>	35.00	X
9	1	Rear Door bottom hinge RH	\$	<i>N</i>	35.00	X
10	1	Rear Door Outer Handle RH	\$	<i>Sn</i>	125.00	X
11	1	Rear Door Weatherstrip RH	\$	<i>Sn</i>	138.79	X
12	1	Rear Door outer weatherstrip moulding RH	\$	<i>Sn</i>	85.00	X
13	1	Rear Door power window motor RH	\$	<i>N</i>	274.97	X
14	1	Side Rocker Panel Garnish RH	\$	<i>B</i>	236.40	✓
15	1	Side Rocker Panel Outer RH	\$	<i>N</i>	433.26	X
16	1	Centre pillar outer RH	\$	<i>N</i>	446.00	X
17	1	Rear Fender RH	\$	<i>B</i>	1,145.00	✓
18	1	Rear Fender Inner Wheel House Panel RH	\$	<i>N</i>	2,556.35	X
19	1	Rear Fender Inner Cowling RH	\$	<i>Sn</i>	76.60	X
20	1	Rear shock absorber RH	\$		243.57	?
21	1	Rear shock absorber top mounting RH	\$		51.65	?
22	1	Upr Arm RH (Arm A-Upr RH)	\$		343.00	?
23	1	Rear Knuckle Arm RH	\$		350.00	?
24	1	Rear Bumper	\$	<i>B</i>	1,202.00	✓
25	1	Rear Bumper Side Retainer RH	\$	<i>D.T</i>	68.76	✓
26	1	Rear Bumper Reflectors RH	\$	<i>Sn</i>	119.74	X

TOTAL	\$	12,240.69
10%	\$	1,224.07
	\$	11,016.62

Specical Nett

1	1Set	Rear Bumper Fastener Clip	\$	<i>N</i>	35.00	✓
2	1Set	Rear Bumper Parking Sensor	\$	<i>Sn</i>	300.00	X
3	1	Door Sticker "Trans-cab" RH	\$	<i>N</i>	80.00	<i>60sn</i>
4	1	Door Sticker "6555-3333"	\$	<i>N</i>	80.00	<i>60sn</i>

TRANS-CAB AUTO SERVICES PTE LTD**AAD1712-037**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9275Z -

5	1set	Side Rocker Panel Garnish Clip RH	\$	<i>Mr</i>	60.00	<i>—</i>
6	2	Rear Windscreen Sealant	\$	<i>Mr</i>	100.00	<i>40sn</i>
7	1	Rear Windscreen Inner Sponge Seal	\$	<i>Mr</i>	80.00	<i>30sn</i>
8	1	Rear Tyre RH	\$	<i>Mr</i>	360.00	<i>208sn</i>
9	1	Rear Wheel Rim RH	\$	<i>L.P. R</i>	254.00	<i>50sn</i>
10	1	Hub Cup Rim	\$	<i>Mr</i>	35.00	<i>x</i>

TOTAL	\$	1,384.00
TOTAL PARTS	\$	12,400.62

Panel Beating, Knocking And Straightening The
Necessary Portion, Remove And Renewal Of
Parts, Adjust And Realign The Same

\$ 4,050.00 *900*

To Rust-Proofing Of The Affected Areas.

\$ 220.00 *60*

Putty and Spray Painting Of The Affected

\$ 4,200.00 *1000*

To Check Electrical Lighting Concerned.

\$ 170.00 *20*

To check steering geometry and computer
wheel alignment

\$ 220.00 *60*

To transfer of tire, rim and on wheel balancing.

\$ 170.00 *20*

To transfer of door fittings, attachment and
perform water seepage test.

\$ 170.00 *60*

To Remove And Refit Rear W/Screen Glass To
Facilitate Bodywork Repair.

\$ 170.00 *120*

To Transfer Of Fender Fittings, Attachments
And Perform Water Seepage Test.

\$ 170.00 *100*

To dismantle and refit rear undercarriage parts,
final checking and testing.

\$ 380.00 *?*

TOTAL	\$	9,920.00
Over All Total	\$	22,320.62

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

REPAIR DAYS

Acknowledged by Repairer

Signature:

15 DAYS

7 days