

TRANS-CAB AUTO SERVICES PTE LTD

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9935C -**AAD1712-041***Not Authored
6/1/2017 8 28501*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD9935C - JHOW

VF1ABL15AUC277894

RENAULT

LATITUDE

05.12.2017

III**PART****LIST**

1	1	BUMPER COVER REAR	\$	<i>Reflex</i> 1,108.46	✓
2	1	BUMPER LOWER REAR	\$	<i>CM</i> 768.84	✓
3	1	BUMPER BRACKET CTR REAR	\$	<i>Sn</i> 113.47	X
4	1	BUMEPR BRACKET SIDE LH REAR	\$	<i>Sn</i> 135.97	X
5	1	BUMEPR BRACKET CTR LH REAR	\$	<i>Sn</i> 44.99	X
6	1	BUMEPR BRACKET SIDE RH REAR	\$	<i>CM Sn</i> 135.97	X
7	1	BUMEPR BRACKET CTR RH REAR	\$	<i>CM</i> 44.99	✓
8	1	BUMPER BEAM REAR	\$	<i>R</i> 777.52	
9	1	BUMPER BEAM BRACKET LH REAR	\$	<i>R</i> 225.95	
10	1	BUMPER BEAM BRACKET RH REAR	\$	<i>R</i> 225.95	
11	1	BUMPER REFLECTOR LH	\$	<i>Sn</i> 43.61	
12	1	BUMPER REFLECTOR RH	\$	<i>Sn</i> 43.61	
13	1	BOOT REAR	\$	<i>R</i> 2,872.68	
14	2	BOOT RUBBER PLUG	\$	<i>Sn</i> 221.81	
15	1	BOOT FINISHER	\$	<i>Sn</i> 470.06	
16	1	BOOT SWITCH	\$	<i>Sn</i> 168.13	
17	1	BOOT TRIM BOARD	\$	<i>Sn</i> 914.87	
18	1	BOOT LOCK	\$	<i>R</i> 202.67	
19	1	BOOT LOCK CATCH	\$	<i>R</i> 74.40	
20	1	BOOT LOCK LINKAGE	\$	<i>Sn</i> 34.53	
21	1	BOOT LOCK LINKAGE HOLDER	\$	<i>Sn</i> 154.52	
22	1	BOOT LOCK CATCH TRIM BOARD	\$	<i>Sn</i> 249.24	
23	1	BOOT WHEATERSTRIP	\$	<i>Sn</i> 323.05	
24	1	BOOT REFLECTOR LAMP LH	\$	<i>Sn</i> 493.35	
25	1	BOOT REFLECTOR LAMP RH	\$	<i>Sn</i> 493.35	
26	1	BOOT BADGE 'RENAULT'	\$	<i>Rn</i> 225.36	
27	1	BOOT BADGE	\$	<i>Rn</i> 225.36	
28	1	BOOT STRUT LH	\$	<i>Sn</i> 276.08	
29	1	BOOT STRUT RH	\$	<i>Sn</i> 276.08	
30	1	BOOT HINGE LH	\$	<i>R</i> 367.84	
31	1	BOOT HINGE RH	\$	<i>R</i> 367.84	
32	2	LICENCE PLATE LAMP	\$	<i>Sn</i> 50.52	
33	1	TAILLAMP RH	\$	<i>Sn</i> 552.55	
34	1	TAILLAMP PANEL RH	\$	<i>R</i> 986.70	

TRANS-CAB AUTO SERVICES PTE LTD**AAD1712-041**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9935C -

35	1	FENDER PANEL REAR RH	\$	R	3,299.13	X
36	1	WHEELARCH REAR RH	\$	CR	543.47	✓
37	1	FENDER PANEL INNER TRIM REAR RH	\$	SH	671.45	
38	1	FENDER WHEEL HOUSE PANEL REAR RH	\$	R	3,039.04	
39	1	SPARE WHEEL PANEL (Luggage Floor Panel)	\$	R	2,189.88	
40	1	SPARE WHEEL PANEL TRIM (Luggage Floor Par	\$	SH	612.21	
41	1	SPARE WHEEL PANEL BRACKET LH	\$	R	123.73	
42	1	SPARE WHEEL PANEL BRACKET RH	\$	R	121.36	X
43	1	OUTER PANEL REAR (End Panel)	\$	R	1,471.77	
44	1	OUTER PANEL REAR (End Panel)TRIM	\$	SH	401.02	
45	1	EXHAUST REAR	\$	R	7,489.05	
46	1	EXHAUST CAP REAR	\$	R	230.49	
47	1	EXHAUST MOUNTING REAR	\$	SH	31.97	
48	1	EXHAUST BRACKET REAR	\$	R	39.86	
49	1	EXHAUST HEAT SHIELD REAR	\$	SH	99.06	
50	1	SHIELD - HEAT - TUNNEL	\$	SH	225.16	

TOTAL	\$	34,259.01
10%	\$	3,425.90
	\$	30,833.11

Special Nett

1	1SET	BUMPER RR CLIP	\$	R	66.00	✓
2	1SET	BUMPER BEAM BOLT	\$	RR	22.22	X
3	1SET	PARKING AID	\$	SH	600.00	
4	1	BUMPER BRACKET CLIP CTR REAR	\$	RR	15.00	
5	1	BUMEPR BRACKET SIDE CLIP LH REAR	\$	RR	12.00	
6	1	BUMEPR RETAINER CLIP LH REAR	\$	RR	10.40	
7	1	BUMEPR BRACKET SIDE CLIP RH REAR	\$	RR	12.00	
8	1	BUMEPR RETAINER CLIP RH REAR	\$	RR	10.40	
9	1	CAP HUB LH RR	\$	SH	35.00	
10	1	RIM LH RR	\$	SH	385.00	X
11	1	TYRE LH RR	\$	SH	330.00	
12	1	CAP HUB RH RR	\$	SH	35.00	
13	1	RIM RH RR	\$	SH	385.00	
14	1	TYRE RH RR	\$	SH	330.00	
15	1	SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	SH	385.00	
16	1	SPARE TYRE	\$	SH	330.00	
17	1SET	BOOT FINISHER CLIP	\$	RR	25.10	
18	1	Rear boots sticker "trans-cab"	\$	RR	30.00	
19	1	Rear boots sticker "6555-3333"	\$	RR	30.00	

TRANS-CAB AUTO SERVICES PTE LTD**AAD1712-041**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9935C -

20	1	FENDER PANEL INNER TRIM CLIP REAR RH	\$	nn	22.00	} X
21	1SET	WHEELARCH CLIP RH RR	\$	nn	32.34	
22	2	Rear windscreen sealant	\$	nn	80.00	
23	1	Windscreen moulding	\$	nn	100.00	
24	1	Rear Windscreen Inner Sponge Seal	\$	nn	100.00	
25	1	EXHAUST MOUNTING REAR	\$	sn	65.50	
26	1	EXHAUST BRACKET REAR	\$	sn	22.22	
27	1SET	Front licence plate with holder	\$	sn	80.00	
28	1SET	Rear licence plate with holder	\$	sn	80.00	
29	1	DOOR STICKER "6555-3333" LH	\$	nn	80.00	
30	1	DOOR STICKER "6555-3333" RH	\$	nn	80.00	

TOTAL	\$	3,790.18
TOTAL PARTS	\$	34,623.29

Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same

\$ 4,200.00 *4000*

Towing Fees.

\$ nn 120.00 X

To apply paint protection system (PPS) maintain and enhancement

\$ nn 380.00 X

Putty and spray painting of the affected portion.

\$ 4,500.00 *4400*

To rust-proofing of the affected areas.

\$ nn 170.00 X

To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.

\$ nn 380.00 X

To check steering geometry and computer wheel alignment

\$ nn 220.00 X

To transfer of tire, rim and on wheel balancing.

\$ nn 170.00 X

To transfer of rear end panel fittings, attachment and perform water seepage test.

\$ nn 170.00 X

To transfer of rear luggage floor panel fittings, attachment and perform water seepage test.

\$ nn 170.00 X

To Check Electrical Lighting Concerned.

\$ nn 170.00 *100*

TRANS-CAB AUTO SERVICES PTE LTD**AAD1712-041**

NO.2 ANG MO KIO ST63 SINGAPORE 569111

TEL NO. 6287 6666 FAX NO. 6257 1330

CO/GST REG NO. 201019626G

SHD9935C -

To supply and re-do rear luggage floor panel insulation padding.	\$	380.00 X
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00 X
To transfer of rear fender fittings, attachment and perform water seepage test.	\$	380.00 X
To transfer of tailgate fittings and conduct water seepage test.	\$	170.00 X
To transfer of rear windscreen fittings, attachments and perform water seepage test.	\$	380.00 X
To reinstall rear bumper parking sensor.	\$	170.00 601
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	280.00 X
To repair and realign rear exhaust pipe.	\$	170.00 X

TOTAL	\$	12,750.00
Over All Total	\$	47,373.29

< parts by parts > Repair Days

~~15 DAYS~~

2 day,

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: